

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI  
HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI- 110001

7/5  
भारतीय  
अमृत महोत्सव


No. F6/DFS/MS/School/WZ/2022/ 964

Dated: 5/9/22

**FIRE SAFETY CERTIFICATE**

Certified that the **St. Mark's Girls School** Located at **A-Block, Meera Bagh, New Delhi- 110087**, comprised of **Ground + 03 Upper Floors only** was issued Fire Safety Certificate by this department Vide Letter No. **F6/DFS/MS/2019/1284 Dated 17.06.2019**. The said premise was re-inspected by the officer concerned of this department on 11.08.2022 in the presence of Sh. Rahul Aggarwal (Director) and found that the premises / building have deemed complied with the fire prevention and fire safety requirements in accordance D.O.E., GNCT of Delhi, Circular no.3298-3398 dated 01-03-2011/NBC (Part-IV) and that the premises/building is fit for occupancy class "Educational Building" Group B with effect from 5/9/22 for a period of **three years**, subject to compliance of the conditions, printed below.

Issued on 5/9/22 at New Delhi by.

  
(Dharampall Bhardwaj)  
Dy. Chief Fire Officer  
(West Zone)

Copy to: -

1. The Director, Directorate of Education, GNCT of Delhi, Old Secretariat Delhi – 110054.
2. The Principal, St. Mark's Girls School, A-Block, Meera Bagh, New Delhi-110087.

**Following fire safety directives must be adhered to:-**

1. All the means of escape shall be kept free of all type of obstruction all the time.
2. All the employees shall be acquainted with the use and maintenance of all fire equipments and method of smooth and speedy safe evacuation of occupants in case of emergency.
3. All the fire fighting equipments shall be maintained in perfect working condition all the time and any lapse rendering non-functional if fire safety measures, management shall be responsible.
4. Any deviation, with regards to construction, ventilation, occupation, electric installation etc. may be got verified from the concerned authorities.
5. The Fire Safety Certificate may not be treated in any case for regularizations of unauthorized construction / unauthorized use of land if any.
6. All comments / directions of licensing Department shall always be permitted and followed.
7. The owner /occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rule 2010. The form is available on [www.dfs.delhigovt.nic.in](http://www.dfs.delhigovt.nic.in)
8. The owner / occupier shall apply for renewal of this Fire Safety Certificate to the Director in 'Form J' (sub Rule (1) of Rule 37) along with copy of the certificate, six months prior to its expiry.

# INSPECTION REPORT

M-18

1. Name & address of the building: **St. Mark's Girls School Located at A - Block, Meera Bagh Vihar, New Delhi-110087.**
2. Type of Occupancy : Educational,
3. Type of Case : Renewal (Ground + 03 Upper Floors)
4. Details of previous NOC : F6/DFS/MS/2019/1284 dated 17.06.2019
5. Fire Safety directives Letter No. : D.O.E Cr. No. 262-362 dated 17.01.2005 & Cr. No. 3298-3398 dated 01.03.2011
6. Date of inspection : 11.08.2022
7. Name of the Inspecting Officer : Aman Kumar Lathar, ADO (JWP)
8. Name and designation of Officer from the building side : Sh. Rahul Aggarwal (Director)
9. Year of Construction : 2000
10. Applicant's letter No. : Form 'J' dated 04.07.2022

S No	Minimum standards on fire prevention and fire safety U/R 33	262-362 dated 17.01.2005 & 3298-3398 dated 01.03.2011 Requirement/ as per FSC dated 17.06.2019	Provided at site	Remarks MR/NMR									
1.	Access of building												
	<ul style="list-style-type: none"> <li>• Road width</li> <li>• Gate width</li> <li>• Width of internal road</li> </ul>	<table style="width: 100%; border-collapse: collapse;"> <tr> <td style="width: 30%;">06 mtrs.</td> <td style="width: 70%;">Provided</td> </tr> <tr> <td>4.5 mtrs.</td> <td>Provided</td> </tr> <tr> <td>NA</td> <td>NA</td> </tr> </table>	06 mtrs.	Provided	4.5 mtrs.	Provided	NA	NA		<table style="width: 100%; border-collapse: collapse;"> <tr> <td style="width: 30%;">MR</td> </tr> <tr> <td>MR</td> </tr> <tr> <td>NA</td> </tr> </table>	MR	MR	NA
06 mtrs.	Provided												
4.5 mtrs.	Provided												
NA	NA												
MR													
MR													
NA													
2.	Number, width, Type & Arrangements of exits												
	a. Number of staircases	02	05	MR									
	<ul style="list-style-type: none"> <li>• Upper floors</li> <li>• Basements</li> </ul>	NA	NA	NA									
	b. Width of staircases	1.5 m	1.35 m, 1.24 m, 1.52 m, 1.38 m & 1.52 m	MR									
	<ul style="list-style-type: none"> <li>• Upper floors</li> <li>• Basements</li> </ul>	NA	NA	NA									
	c. Protection of exits	NA	NA	NA									
	<ul style="list-style-type: none"> <li>• Fire check door</li> <li>• Pressurization</li> </ul>	NA	NA	NA									
	d. No of continuous staircase to terrace	02	Provided	MR									
	e. Width Of Corridor	1.5 mtrs.	Provided	MR									
	f. Door Size	Class Room - 1.0 m Audi (Old Case)	1.0 m 1.95 m, 1.35 m, 1.28 m, 1.31, 1.33, 0.92 m x 2	MR(Old Case)									
3.	Compartmentation												
	<ul style="list-style-type: none"> <li>• Fire check door</li> <li>• Sealing of electrical shafts</li> <li>• Fire Rating of shaft door</li> <li>• Water Curtain</li> <li>• Fire Dampers</li> </ul>	NA	NA	NA									
		NA	NA	NA									
		NA	NA	NA									
		NA	NA	NA									
		NA	NA	NA									
4.	Smoke managements System												
	<ul style="list-style-type: none"> <li>• Basements</li> <li>• Upper floors</li> </ul>	NA Required	NA Exhaust Fan	NA MR									

R

5.	Fire Extinguishers				
	<ul style="list-style-type: none"> <li>Total numbers</li> <li>Types</li> <li>IS marking</li> </ul>	24 nos. ABC & CO <sub>2</sub> ISI marked	Provided		MR
			Provided		MR
			Provided		MR
6.	First – Aid Hose Reels				
	<ul style="list-style-type: none"> <li>Total numbers on each floor</li> <li>Length of hose reel hose</li> <li>Nozzle diameter</li> </ul>		02 30m 5mm	Provided Provided Provided	MR MR MR
7.	Automatic fire detection and alarming system (Audi)				
	<ul style="list-style-type: none"> <li>Type of detectors</li> <li>Location of Main Panel</li> <li>Location of Repeater Panel</li> <li>Alternate source of power</li> <li>Hooters' Location</li> </ul>		Smoke On GF NA Required On GF	Provided Provided NA Provided Provided	MR MR NA MR MR
8.	MOEFA		Required	Provided	MR
9.	Public Address System (Audi)		Required	Provided	MR
10.	Automatic Sprinkler System				
	<ul style="list-style-type: none"> <li>Basements</li> <li>Upper Floor/Open.</li> <li>Sprinkler above false ceiling</li> </ul>		NA Required NA	NA Provided NA	NA MR NA
11.	Internal Hydrants:				
	<ul style="list-style-type: none"> <li>Size of riser/down- comer</li> <li>Number of hydrants per floor</li> <li>Hose Box</li> </ul>		100 mm 02 Required	Provided Provided Provided	MR MR MR
12.	Yard Hydrants				
	<ul style="list-style-type: none"> <li>Total number of hydrants</li> <li>Hose Box</li> </ul>		NA NA	NA NA	NA NA
13.	Pumping Arrangements:				
	<ul style="list-style-type: none"> <li>Ground Level</li> <li>Discharge of main pump</li> <li>➤ Head of main pump</li> <li>➤ Number of main pumps</li> <li>➤ Jockey pump out put</li> <li>➤ Jockey pump head</li> <li>➤ Standby Pump out put</li> <li>➤ Standby Pump Head</li> <li>➤ Auto Staring/Manual stopping</li> <li>➤ Pump House Access</li> <li>Terrace level</li> <li>➤ Discharge of pump</li> <li>➤ Head of the pump</li> <li>➤ Power supply</li> <li>➤ Auto starting of pump</li> </ul>		NA NA NA NA NA NA NA NA NA NA NA 900 lpm & 220 lpm 40Mtr Required Required	NA NA NA NA NA NA NA NA NA NA Provided Provided Provided Provided	NA NA NA NA NA NA NA NA NA NA MR MR MR MR
14.	Captive water Storage for fire fighting:				
	<ul style="list-style-type: none"> <li>Under ground tank capacity</li> <li>➤ Draw off connection</li> <li>➤ Fire service inlet</li> <li>➤ Access to tank</li> <li>Overhead Tank capacity</li> </ul>		50,000 ltrs. NA NA NA 10,000Ltrs.	Provided NA NA NA Provided.	MR NA NA NA MR
15.	Exit Signage		Required	Provided	MR
16.	Provision of Lifts				
	<ul style="list-style-type: none"> <li>➤ Pressurization of Lift Shaft</li> <li>➤ Pressurization of lift lobby</li> <li>➤ Communication in lift Car</li> <li>➤ Fireman's Grounding Switch</li> <li>➤ Lift Signage</li> </ul>		NA NA NA NA NA	NA NA NA NA NA	NA NA NA NA NA
17.	Standby power supply		Required	Provided (100 kvs)	MR
18.	Refuge Area				
	<ul style="list-style-type: none"> <li>➤ Total area</li> <li>➤ Location</li> </ul>		NA NA	NA NA	NA NA

19.	Fire control room	NA	NA	NA
	➤ Detector system panel	NA	NA	NA
	➤ Flow Switch Panel	NA	NA	NA
	➤ PA System Panel	NA	NA	NA
	➤ Battery backup	NA	NA	NA
	➤ Building Floor Plans	NA	NA	NA
20.	Special Fire Protection Systems for Protection of special Risks, if any;	NA	NA	NA

The fire protection systems provided in the building were checked and found functional at the time of inspection:

In view of the deemed compliance of the minimum standards on fire prevention and fire safety requirements under the rules, renewal of Fire safety Certificate vide letter no. F6/DFS/MS/2019/1284 dated 17.06.2019 is recommended under rule 37 of the Delhi Fire service Rules 2010 under the DFS Act 2007.

*Amit*  
23/8/22  
Aman Kumar Lathar  
ADO (JWP)

*DO (w)*

I like to visit the School, when I am directed to fix up date & time of inspection. point it for future.

DO (WEST) 391  
DATED: 29/8/2022

*ADO (JWP)*  
*Sir,*

*dy*  
23/8/2022

I would like to inform you that date of inspection was fixed by you on dated 11-08.22. Accordingly, it reached at school. But you could not come being busy elsewhere. And on telephonically talk by yourself allowed to inspect one school of building comprised of G+3 story building. As there was two school of same organisation named St. Mary's school. One school building was G+3 story for renewal & 2nd was G+4 story building being a addition/alteration case.

Submitted for your kind information & further order if any.

391/20/102  
Dt 29/8/2022

*DO (w)*

*dy*  
29/8/2022

*Amit*  
27/8/22  
ADO (w?)

*DO (w)*

*Asst. Insp.*

*ADO (JWP)*