

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI- 110001

No. F6/DFS/MS/WZ/2022/BNQT/ 49

Dated: 25/8/2022

FIRE SAFETY CERTIFICATE

Certified that the M/s. Majestic Crown Banquet (A unit of Divine Hospitality) located at Plot No. 24, Najafgarh Road Industrial Area, Delhi- 110015, comprised of ground plus three upper floors, was granted fire safety certificate by this department vide letter No. F.6/DFS/MS/2018/BNQT/2646 dated 10.12.2018 for ground & first floor only. The banquet hall was re-inspected by the officers concerned of this department on 28/07/2022 in presence of Shri Sanjeev Oberoi (Owner / occupier) and found that the management has added second floor for banquet use and now the banquet hall is running at ground plus two upper floors in a building comprised of ground plus three upper floors (Bridal rooms, offices & kitchen on third floor is sealed by brick wall) and the management have complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the building / premises is fit for occupancy class Assembly - Group D (for Ground Floor plus Two Upper Floors only) with effect from $\frac{25}{8}/2022}$ for a period of three years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of conditions, under rule 38 of the Delhi Fire Service Rules, 2010, printed overleaf.

Issued on $\frac{25}{8}$ 2022 at New Delhi.

Copy to: -

- 1. Sh. Sanjeev Oberoi, M/s. Majestic Crown Banquet (A unit of Divine Hospitality) located at Plot No. 24, Najafgarh Road Industrial Area, Delhi- 110015.
- 2. The DHO, Karol Bagh Zone, Anand Parbat, New Delhi.



Conditions for the validity of Fire Safety Certificate:

- 1. All the fire safety arrangement provided there in shall be maintained in good working conditions at all times.
- 2. Loss of life or property due to non functional fire safety measure shall be at the responsibility of the management.
- 3. The trained fire fighting staff should be available round the clock.
- 4. Any deviation with regard to the construction etc shall be verified by the concerned building sanctioning agency.
- 5. The basement shall be used strictly as per the provision of unified building bye laws.
- 6. This certificate cannot be treated in any case for regularizations of unauthorized construction.
- 7. The management has submitted an undertaking that the basement floor will not be used as Banquet hall and terrace floor as kitchen. If it is used in future, the Fire safety certificate will be null & void.
- 8. <u>"The owner / Occupier shall apply for renewal of this Fire Safety Certificate to the Director in Form 'J' [sub rule (1) of rule37] along with a copy of this Certificate, six months prior to its expiry".</u>
- 9. The owner / occupier shall submit a declaration every year in form "K" provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.Delhigovt.nic.in.
- 10. This FSC is valid for ground plus two upper floors only.
- 11. The bridal rooms, offices and kitchen located at third floor is sealed by brick wall and the management has submitted an undertaking not to use in future. If the brick wall/seal is open in future, FSC will be null & void.

7/29/22, 10 12 AM

ہ ∫ ک INSPECTION REPORT

		INS	PEC HON KELS				
juchu	Name & address of the build	ling: N	M/s. Majestic Crow No. 24, Najafgarh R	n Banquet located at oad Industrial Area, N	GF, FF & SF Plo lew Delhi- 110015		
			quet (Assembly)				
	2. Type of Occupancy	. Dan	ewal & addition of	Second Floor			
	3. Type of Case	: Ren	ewar & addition of	LICHOLONIO CE PEE			
	Datails of previous NOC	: F6/DFS/MS/2018/BNQT/2646 dated 10/12/2018 -for GF & F					
	 5. Fire Safety directives Letter No. : F6/DFS/MS/2018/3122 dated 20/07/2018 						
	(Data of inspection	: 28	.07.2022				
	 Date of hispection Name of the Inspecting Officer : M.K. Chattopadhyay, DO (West), Sarabjeet Singh, ADO (Moti Nagar) 						
	 Name and designation of Officer from the building side : Sh. Sanjeev Oberoi (Owner/Occupier) 						
	9. Year of Construction : 2010						
		A port	al ID 202201109005 d. First & Second Fl	517 oor in a building comj	prised of ground pl		
	three upper floors.	Oroun					
S No	Minimum standards on fire prevention and fire safety U/R 33	Requi 35 (6)	rements as per Claus of DFS Act- 2007	se Provided at site	Remarks MR/NMR		
1.	Access of building			Provided	MR		
	Road width		12 mts	Directly accessible	MR		
	Gate width		05 mts	from the road	NA		
	 Width of internal road 		NA	NA	INA		
2	Number, width, Type & Arrangements of exits						
2.					MR		
	 a. Number of staircases Upper floors Basements b. Width of staircases 		02	03	NA		
			NA	NA			
				Provided	MR		
	II and anno		2.0, 1.9 mts	NA	NA		
	Upper hoorsBasements		NA	INA			
	D of evits			Provided	MR		
	 Fire check door 		Required	NA	NA		
	 Pressurization 		NA		MR		
	c dimensions staircase to ter	rrace	02	Provided	Old Case		
	d. No of continuous stancase to tere. Width Of Corridor		Old Case	Old Case			
	f. Door Size		2 x 2.0 mts	$GF= 2 \times 2.0 \text{ mts } FF= 1 \times 2.2,$ 1 x 2.0 mts, $SF= 2 \times 2.0 \text{ mts}$	MR, Old case		
3. (Compartmentation Provided MR						
	Fire check door		Required	Provided	MR		
	 Fire check door Sealing of electrical shafts 		Required		NA		
	 Fire Rating of shaft door 	F	NA	NA	NA		
	Water Curtain		NA	NA	NA		
	Fire Dampers		NA	NA			
4. 5	Smoke managements System						
т. 2			30 A/C per hour	NA	NA		
	BasementsUpper floor		12 A/C per hour	Provided	MR		
5. F	Fire Extinguishers) (D		
			16	Provided	MR		
	• Total numbers		ABC, CO2 & WCO2	Provided	MR		
	• Types		ISI marked	Provided	MR		
	IS marking		ISI marked	Provided	A start		

First - Aid F	Ose Past	1/29							
				MR					
lota	numbers on each floor	01							
~~~~		01 30 m	Provided	MR					
		5 mm	Provided	MR					
ratomatic f	re detection and alarming sy	vstem	Provided	MR					
- Type	• Type of detectors								
- Loca	tion of Main D	Smoke & Heat	Provided						
LOCA	lion of Report p	Required	Provided	MR					
		Required	Provided	MR					
- 100	ters' Location	Required .	Provided	MR					
MOEFA		Entire building	Provided	MR					
. Public Addr	PSS Stud	Required	Provided	MR					
0 Automatic G	ess System	Required		MR					
Automatic S	Sprinkler System	required	Provided	MR					
	Basements								
• Upp	er Floor	N/A							
Spri	nkler above C	Required	N/A	N/A					
Internal Hyd	drants	N/A	Provided	MR					
			N/A	N/A					
• Nun	of riser/down- comer	100 mm							
• Hos	aber of hydrants per floor e Box	01	Provided	MR					
2 Yard Hydra		01	Provided	MR					
			Provided	MR					
• Tota	ll number of hydrants								
		N/A	N/A						
r uniping A	rrangements	N/A	N/A	N/A					
• Gro	und Level			N/A					
Dise	charge of main								
	u ul main num	2280 lpm	Device						
i vui	ider of main num	70 m	Provided	MR					
5001	CV nump out	01	Provided Provided	MR					
1001	ev pump head	180 lpm	Provided	MR					
Star	dby Pump out -	70 m	Provided	MR					
Stal	uby Pump Head	2280 lpm	Provided	MR					
Aut	o Staring/Manual	70 m	Provided	MR					
> Pup	In House A	Required	Provided	MR					
• Ten	ap House Access	Required	Provided	MR					
> Disc	charge of pump	450 lpm		MR					
> Hea	d of the pump	40 m	Provided	MO					
> Pow	er supply	Required	Provided	MR MR					
- Aut	0 starting of num	Required	Provided	MR					
4 Captive wa	ter Storage for fire fighting	1	Provided	MR					
	erground tank capacity	1,00,000 ltrs							
- Dia	w of connection service inlet	Required	Provided	MR					
	ess to tank	Required	Provided	MR					
• Ove	rhead Tank agent	Required	Provided	MR					
5 Exit Signag	ge	5,000 Ltrs	Provided	MR					
		Required	Provided	MR					
6 Provision o	of Lifts		Provided	MR					
> Pre	ssurization of Lift Shaft								
> Pre	ssurization of lift lobby	NA							
	municotian interior	NA	NA	NA					
	nmunication in lift Car	Required	NA	NA					
	eman's Grounding Switch	Required	Provided	MR					
17 Standby p	t Signage		Provided	MR					
Standby po	ower supply	Required Required	Provided						
		required	Provided	MR					

S

Anva Lotal area	NA NA	NA NA	ΝΑ ΝΑ
<ul> <li>Location</li> <li>Detector system panel</li> <li>Flow Switch Panel</li> <li>PA System Panel</li> <li>Battery backup</li> <li>Building Floor Plans</li> <li>Special Fire Protection Systems for Protection of special Risks, if any;</li> </ul>	ΝΛ ΝΛ ΝΛ ΝΛ ΝΛ	ΝΑ ΝΑ ΝΑ ΝΑ ΝΑ	NA NA NA NA NA

The fire protection systems provided in the building were checked & found functional at the time of inspection.

N30

Note: 1. All the shortcomings pointed out by this department vide letter No. F6/DS/MS/Banquet/WZ/2022/112 dated 04.07.2022 have been complied with by the management.

2. No additional requirements of fire safety arrangements for the addition of second floor as per NBC- 2016 (Part-IV).

In view the compliance of the minimum standards on fire prevention and fire safety measures as required under the rules, the NOC issued vide letter No. F6/DFS/MS/2018/BNQT/2646 Dated 10/12/2018, renewal under rule 35 of the Delhi Fire Service rules 2010, is recommended.

DFA is put up for approval & signature please.

118/20 M

Signature of the Inspecting Officer Sarabjeet Singh ADO (Moti Nagar)

Signature of the Inspecting Officer M.K. Chattopadhyay DO (West Division)

DATED. 16 8 202

EFO(WI) Explore the defail about se comme dufion, flours of

This department is already issued fui Safely quidelines for the above banquet-vide this dept. letter No. F6/DFS/HS/2018/ 3122 deled 20/3/2018-for grownd place two