

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: CONNAUGHT PLACE NEW DELHI-110 001.

No.F.6/DFS/MS/School/2022/SZ/

933

Dated: 1 | 9 | 2 2

FIRE SAFETY CERTIFICATE

Certified that the **S.D.M.C Primary Adarsh Bal/Balika Vidyalaya**, Old Roshanpura (1st & 2nd Shift), New Delhi-110043 comprised of ground plus one upper floor, owned/occupied by S.D.M.C was issued Fire Safety Certificate by this department vide letter No F.6/DFS/MS/School/2019/SZ/1024 dated 14/05/2019. The school building was re- inspected by the officer concerned of this department on 24/08/2022 in the presence of Sh. Virender Kumar Bharti (Principal) and found that the school building have deemed complied with the fire prevention and fire safety requirements in accordance with the Circular No. F.16/Estate/CC/Fire Safety/2011/3298 to 3398 dated 01.03.2011 issued by the Director of Education and that the building/ premises is fit for occupancy class "Educational" w.e.f. the date of issue of this certificate for a period of three years, subject to compliance of the conditions printed as under.

Issued on ... at New Delhi.

(SUNIL CHAWDHARY) Dy. CHIEF FIRE OFFICER

ofer.

Copy to:-

- The Principal,
 S.D.M.C Primary Adarsh Bal/Balika Vidyalaya,
 Old Roshanpura (1st & 2nd Shift), New Delhi-110043
- Director of Education, MCD, Civic Centre, Minto Road, New Delhi-110001.

Following fire safety directives must be adhered to:-

- 1. All the fire safety arrangements provided therein shall be maintained in good working condition at all times.
- 2. The means of escape shall be kept unlocked and unobstructed for unhindered evacuation of occupants in case of emergency.
- 3. Any loss of life or property due to non-functional fire safety measures shall be at the risk and responsibility of the management.
- 4. The trained staff should be available round the clock.
- 5. Any deviations w.r.t. construction shall be verified by the concerned building sanctioning agency.
- 6. The certificate may not be treated in any case for the regularization of the unauthorized construction, if any.
- 7. The owner/occupier shall submit a declaration every year in the form 'K' provided in the first schedule of Delhi Fire Service Rules 2010, form is available on www.dfs.delhigovt.nic.in.
- 8. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in the Form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior to its expiry.

INSPECTION REPORT

S.D.M.C Primary Adarsh Bal/Balika Vidyalaya, Old Roshanpura 1. Name & address of the building

(1st & 2nd Shift), New Delhi-110043

Building comprised of Ground plus one upper floor.

3. Type of Occupancy Educational 4. Type of Case Renewal

5. Details of Previous NOC F.6/DFS/MS/School/2019/SZ/1024 dated 14/05/2019

6. Fire Safety directives letter No Circular No. F.16/Estate/CC/Fire Safety/2011/3298 to 3398 dated 01.03.2011 7. Date of inspection

8. Name of Inspecting Officer A.D.O. R.K.Yadav

9. Name and designation of officers

From the building side Sh. Virender Kumar Bharti (Principal)

S. No.	Applicant's letter No. : Form "J" dated 10/08/2022 Minimum Standards on fire prevention and Dir. of Edu Provided et Provi							
*	fire safety U/R 33	Dir. of Edu. Circular dt. 01.03.2011	Provided at site	Remarks MR/NMR				
1.	Access to building							
	Road width							
	Gate width	Accessible	06 m	MR				
	Width of internal road	4.5 m	, 3.5 m	MR, being old case				
2.	Number, Width, Type & Arrangement of Ex	N/A	N/A	N/A				
	a. Number of staircases							
	Upper Floors	02 no.'s	02					
	Basements	N/A	02 no.'s	MR				
	b. Width of staircases	IN/A	N/A	N/A				
	Upper FloorBasements	150 % 75	1 40 0 : 25					
	- Dasements	1.50 & .75 m	1.40 & 1.36 m	MR				
		N/A	N/A	N/A				
	c. Protection of exits	N1/A						
	Fire check door	N/A	N/A	N/A				
	Pressurization	N/A	N/A	N/A				
	d. No. of continuous staircases to	N/A	N/A	N/A :				
	terrace	N/A	N/A	N/A				
	e. Width of Corridor			N/A				
	f. Class room Door Size	1.0 m	1.10 m (double door)	MR				
3.	Compartmentation		(double door)					
	Fire check door	N/A	N/A	21/4				
	Sealing of electrical shafts	N/A	N/A	N/A				
	 Fire Rating of shaft door 	N/A		N/A				
	Water Curtain		N/A	N/A				
	• Fire Dampers	N/A	N/A	N/A				
4.	Smoke Management System N/A N/A N/A N/A							
	Basements	N/A	N/A					
	Busements		IN/A	N/A				
	Upper floors	Required	Natural Ventilation provided	MR .				
5.	Fire Extinguishers							
	Total numbers	06 No's	Provided	MR				
	• Types	ABC/CO ₂ type	Provided	MR				
	IS marking	ISI marked	ISI marked	MR				
6.	First-Aid Hose Reels							
	Total numbers on each floor	N/A	N/A	N/A				
	• Length of hose reel hose	N/A	N/A	N/A				
	Nozzle diameter	N/A	N/A	N/A				

4.

	Automatic fire detection and alarming system				
	Type of detectors	N/A	N/A	N/A	
	Location of Main Panel	N/A	N/A	N/A	
	Location of Repeater Panel	N/A	N/A	N/A	
	Alternate source of power	N/A	N/A	N/A	
	Hooters' Location	N/A	N/A	N/A	
	MOEFA	N/A	N/A	N/A	
),	Public Address System	N/A	N/A	N/A	
0.	Automatic Sprinkler System		A N/A		
	Basement	N/A		N/A	
	Ground Floor	N/A		N/A	
	Sprinkler above false ceiling	N/A	N/A	N/A	
1.	Internal Hydrants		27/4	27/4	
	Size of riser/down-comer	N/A		N/A N/A	
	Number of hydrants per floorHose Box	N/A N/A		N/A	
2.	Yard Hydrants	IN/A	NA	TVA	
	Total number of hydrants	N/A	N/A	N/A	
	Hose Box	N/A		N/A	
3.	Pumping Arrangements				
	Ground Level				
	Discharge of main Pump	N/A	N/A	N/A	
	➤ Head of Main pump	N/A	N/A	N/A	
	Number of main pumps	N/A		N/A	
	 Jockey Pump out put Jockey pump head 	N/A		N/A	
	> Standby Pump out put	N/A		N/A	
	Standby Pump Head	N/A		N/A	
	Auto Starting/Manual Stopping	N/A		N/A	
		N/A		N/A	
		N/A		N/A	
	 Pump House Access Terrace level 			1	
	➤ Discharge of pump	N/A	N/A	N/A	
	Head of the pumpPower Supply	N/A		N/A	
		N/A	N/A	N/A	
	> Auto Starting of pump	N/A	N/A	N A	
14.	Captive Water Storage for fire fighting		N/A		
	Underground tank capacity	N/A		NA	
	> Draw-off connection	N/A		NA	
	 Fire service inlet Access to tank 	N/A		$N^{i}A$	
	Overhead Tank capacity	N'A		N'A	
1.5		N/A N/A		NA NA	
15.	Exit Signage.	NA	N.A	N.A.	
16.	Provision of Lifts.	(No Lift)			
	Pressurization of Lift Shaft	N'A		EX	
	Pressurization of Lift lobby Communication In lift Car	N/A		N.A.	
	Fireman's Grounding Switch	N'A		X'A	
	Lift Signage	N/A		N A	
17.		N'A		N'A	
	Standby power supply	E'Z	N.A	X.A	
18.	Refuge Area.				
	> Total Area	N/A	E.Z.	N'A	
	> Location			N.A.	

Fire Control Room			
Detector system raner	N/A	N/A	N/A
 Flow Switch Panel PA System Panel Battery backup Building Floor Plans 	N/A	N/A	N/A
	N/A	N/A	N/A
	N/A	N/A	N/A
	N/A	N/A	N/A
Special Fire Protection System for Protection of special Risks, if any:	N/A	N/A	N/A
	 Flow Switch Panel PA System Panel Battery backup Building Floor Plans Special Fire Protection System for Protection of	• Flow Switch Panel	• Detector System Panel • Flow Switch Panel • PA System Panel • Battery backup • Building Floor Plans N/A N/A N/A N/A N/A N/A N/A N/

The fire protection systems provided in the building were tested, checked and found functional at the time of inspection.

In view of the deemed compliance of the minimum standards of fire prevention and fire safety measures as required under the rules the FSC issued vide letter number F.6/DFS/MS/School/2019/SZ/1024 dated 14/05/2019 renewal in accordance with the Circular No. F.16/Estate/CC/Fire Safety/2011/3298 to 3398 dated 01.03.2011 issued by the Director of Education is recommended.

Signature of Inspecting Office

Name:- R.K.Yadav

Designation:- Asstt. Divisional Officer

Divisional Officer (South West)