

THE AD QUARTERS: DELHI FIRE SERVICE: CONNAUGHT PLACE NEW DELHI-110001

No.F.6 DFS/MS/School/2022/SZ/ / 2022

Dated: 13 / 9 / 2022

FIRE SAFETY CERTIFICATE

Certified that SDMC Nigam Pratibha Vidyalaya located at Saidulajab, New Delhi 110030 comprised of Ground plus One upper floor owned / occupied by South Delhi Municipal Corporation was issued Fire Safety Certificate by this department vide letter No. F6/DFS/MS/School/2019/SZ/1757 Dated 12/09/2019. The said premises was re-inspected by officer concerned of this department on 26/08/2022 in presence of Mr. Mohan Yadav (Principal) and found that the said school building have deemed complied with the fire prevention and fire safety requirements in accordance with Directorate of Education Circular No F.16//Estate/CC/Fire Safety/2011/3298 to 3398 dated 01/03/2011 issued by Director of Education, Govt. of NCT of Delhi and that the building is fit for occupancy class "Educational Building Group - B" with effect from 13/9 / 2022 for a period of Three years in accordance with rule 36 unless renewed under rule37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of Delhi Fire Service Rules 2010.

Issued on <u>2</u> <u>2022</u> at New Delhi by

(SUNIL CHAWDHARY) **DY. CHIEF FIRE OFFICER (SZ)**

Copy to: -

- 1. SDMC Nigam Pratibha Vidyalaya located at Saidulajab, New Delhi 110030.
- 2. The Director of Education, South MCD, Civic Centre, Minto Road, New Delhi-110002

Conditions for the validity of Fire Safety Certificate

- 1. All the means of escape/entry/exit shall be kept free from any obstruction.
- 2. All the fire safety arrangements provided therein shall be maintained in good working condition at all time as seen during inspection. Any loss of life or property due to non-functional fire safety measures shall be at the responsibility of the management.
- 3. This certificate cannot be treated as regularization of unauthorized construction, if any.
- 4. The owner/ occupier shall submit a declaration every year in Form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on <u>www.dfs.delhigovt.nic.in</u>
- 5. This fire safety certificate may not in any way be treated as regularization (Clause 2.8 of UBBL-2016) of unauthorized construction or Alteration (Clause 1.4.3 of UBBL-2016), if any.
- 6. "The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in Form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior to its expiry."

if.




| | INSPEC | TION REPORT | | | |
|-------|---|--|--------------------------------|-----------------|--|
| 1 | Name & Address of the Building | SDMC Nices | Drotible 17'1 1 | | |
| | | SDMC Nigam Pratibha Vidyalaya Saidu New Delhi 110030. | | | |
| 2 | Type of Occupancy | | | | |
| 3 | Building Comprised of | Educational, G | roup-B (School) | | |
| 4 | Type of Case | Ground plus on | e upper floor | | |
| 5 | Details of Previous NOC | Renewal | | | |
| 6 | Fire Safety Directives Letter No | F6/DFS/MS/Sc | hool/2019/SZ/1757 Date | d 12/09/2019 | |
| 7 | Date of Inspection | F.16//Estate/CC/Fi | re Safety/2011/3298 to 3398 da | ated 01.03.2011 | |
| 8 | Name of the Inspecting Officers | 26-08-2022 | | | |
| 9 | Name & Designation of Officers | Sh. Rajesh Kumar ADO (BCP) | | | |
| | from the building side | Mr. Mohan Yadav (Principal) | | | |
| 10 | Year of construction | 2012 | | | |
| 11 | Applicant letter No. | | 4 1-4-1 11/00/0000 | | |
| S. No | Minimum standards on Fire Prevention | NPV/Pri/2022/34 dated 11/08/2022 Old NOC Provided at Site Remarks | | | |
| | and Fire Safety U/R 33 | requirements | Provided at Site | Remarks | |
| 1 | Access to Building. | requirements | | MR/NMR | |
| | Road width | Accessible | 06 mtr | MR | |
| | • Gate width | NA | 3.75m | NA | |
| | Width of internal road | -NA- | -NA- | -NA- | |
| 2 | Number, width, type & arrangement of exits. | 1177- | -11/1- | -11/4- | |
| | a) Number of Staircase | | | | |
| | Upper floors. | 02 Nos | 02.11 | 10 | |
| | Basement floor. | -NA- | 02 Nos | MR | |
| | b) Width of Staircase | -11/4- | -NA- | -NA- | |
| | > Upper floors | 1.50 m/0.75m | 2 mtr each | MD | |
| | Basement floor | -NA- | -NA- | MR | |
| | c) Protection of exits | -114- | -INA- | -NA- | |
| | Fire check door | -NA- | -NA- | -NA- | |
| | Pressurization | -NA- | | | |
| | d) No. of continuous staircase to terrace | | -NA- | -NA- | |
| | e) Width of corridor | 1 No 1.50 mtr | Provided | MR | |
| | f) Door size | | Provided | MR | |
| 3 | / | 1 mtr | Provided | MR | |
| 3 | Compartmentation. | NIA | | | |
| | Fire check door. Section of electrical shefts | -NA- -NA- | -NA- | -NA- | |
| | • Sealing of electrical shafts. | -NA- -NA- | -NA- | -NA- | |
| | Fire rating of shaft door. Water curtain | -NA- | -NA- | -NA- | |
| | E E E E E E E E E E E E E E E E E E E | | -NA- | -NA- | |
| 4. | Fire dampers. Smoke Management system | -NA- | -NA- | -NA- | |
| 7. | Smoke Management system. Basement | NIA | N T 4 | | |
| | Basement Upper floors | -NA- | -NA- | -NA- | |
| 5. | | -NA- | -NA- | -NA- | |
| 3. | Fire Extinguishers. | | 07.22 | | |
| | Total numbers Types | 06 No | 07 Nos | MR | |
| | - Jpec | ABC | ABC & Co2 Type | MR | |
| 6. | ISI Marking | ISI mark | Provided | MR | |
| 0. | First Aid Hose Reels. | | | | |
| | • Total numbers on each floor. | -NA- | -NA- | -NA- | |
| | Length of hose-reel hose. | -NA- | -NA- | -NA- | |
| | Nozzle Diameter | -NA- | -NA- | -NA- | |
| 7 | Automatic fire detection & alarming system. | | | | |
| | | | | | |
| | Type of detectors | -NA- | -NA- | -NA- | |

C-15

| 1. | |
|------|---------|
| आज़ा | |
| अमृ | त महोन् |

| | | | 0 | भम्मत महान् |
|-----|--|---|----------|-------------|
| | Location of Main Panel | -NA- | -NA- | NA |
| | Location of Repeater Panel | -NA- | -NA- | -NA- |
| | Alternate source of power | -NA- | -NA- | -NA- |
| 0 | Hooter's location | -NA- | -NA- | -NA- |
| 8. | MOEFA | -NA- | -NA- | -NA- |
| 9. | Public Address System | -NA- | -NA- | -NA- |
| 10. | Automatic Sprinkler System | | -INA- | -NA- |
| | Basement | -NA- | -NA- | |
| | Upper floors | -NA- | | -NA- |
| | Sprinkler above false ceiling | -NA- | -NA- | -NA- |
| 11. | Internal Hydrants. | -1074- | -NA- | -NA- |
| | Size of Riser/Down-comer | -NA- | | |
| | Number of Hydrant per floor | and the second se | -NA- | -NA- |
| | Hose box. | -NA- | -NA- | -NA- |
| 12. | Yard Hydrants. | -NA- | -NA- | -NA- |
| | Total number of hydrants. | | | |
| | Hose box. | -NA- | -NA- | -NA- |
| 13. | Pumping arrangements. | -NA- | -NA- | -NA- |
| | Ground Level | | | |
| | - Ground Level | | | |
| | Discharge of main pump. | -NA- | -NA- | -NA- |
| | Head of main pump. Number of | -NA- | -NA- | -NA- |
| | Number of main pumps. Lockers P | -NA- | -NA- | -NA- |
| | Jockey Pump output. Jockey Pump head. | -NA- | -NA- | |
| | Standby Pump head. | -NA- | -NA- | -NA- |
| | Standby Pump output. | -NA- | -NA- | -NA- |
| | Standby Pump head. Auto Starting (March 1997) | -NA- | -NA- | -NA- |
| | Auto Starting / Manual Stopping. Pump house access. | -NA- | -NA- | -NA- |
| | | -NA- | -NA- | -NA- |
| | Terrace Level | | -11/4- | -NA- |
| | Discharge of pump. | -NA- | NIA | |
| | Head of pump. | -NA- | -NA- | -NA- |
| | Power supply | -NA- | -NA- | -NA- |
| | Auto starting of pump. | -NA- | -NA- | -NA- |
| 14. | Captive water storage for fire fighting. | | -NA- | -NA- |
| | Underground tank canacity | -NA- | NA | |
| | Draw-off connection. | -NA- | -NA- | -NA- |
| | Fire Service Inlet. | -NA- | -NA- | -NA- |
| | Access to tank. | -NA- | -NA- | -NA- |
| - | Overhead tank capacity. | -NA- | -NA- | -NA- |
| 5. | Exit Signage. | Required | -NA- | -NA- |
| 6. | Provision of Lifts. | Indianed | Provided | MR |
| | Pressurization of lift shaft. | -NA | NY 4 | |
| | Pressurization of lift lobby. | -NA- | -NA- | -NA- |
| | Communication in lift car. | -NA- | -NA- | -NA- |
| | Fireman's switch. | -NA- | -NA- | -NA- |
| | Lift signage. | -NA- | -NA- | -NA- |
| 7. | Standby Power Supply | | -NA- | -NA- |
| 8. | Refuge Area | -NA- | -NA- | -NA- |
| | Total area | NIA | | |
| | Location | -NA- | -NA- | -NA- |
| 9. | Fire Control Room. | -NA- | -NA- | -NA- |
| | Detector system panel. | | - | -INA- |
| | Flow switch panel. | -NA- | -NA- | |
| | a low switch panel. | -NA- | | -NA- |
| | | | -NA- | -NA- |

c16



| | PA system panel | | ਼ਾਰ ਜ਼ਿੰਦਿਰਰ |
|-----|--|------|--------------|
| | Battery backup NA | -NA- | -NA- |
| | Building floor plan | -NA- | -NA- |
| 20. | Special Fire Protection System for the | -NA- | -NA- |
| | Protection of special Risk, if any. | -NA- | -NA- |
| | The fire protection and | | |

The fire protection system provided in the building were randomly checked and found functional at the time of inspection.

Keeping in view of the deemed compliance of the minimum standard on fire prevention and fire safety measures as required under the rules, the FSC issued vide letter no F6/DFS/MS/School/2019/SZ/1757 Dated 12/09/2019, renewal under rule 37 of the Delhi Fire Service

Accordingly, DFA is put up for approval and signature please.

Signature of the Inspecting Officer Name: Sh. Rajesh Kumar Design: ADO (BCP)

Dy. CFO (SZ)

·N -N

 $\frac{|\hat{\mathcal{N}}_{\mathcal{N}_{\mathcal{A}}}|}{|\hat{\mathcal{N}}_{\mathcal{A}}|} \frac{|\hat{\mathcal{A}}_{\mathcal{A}}|}{|\hat{\mathcal{A}}_{\mathcal{A}}|} + ||$

As approved Fit. Letter is protof for your synature PI 1/1