

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI- 110001



No. F6/DFS/MS/School/WZ/2022/ 1015

Dated: /5/ 8 /2022

FIRE SAFETY CERTIFICATE

Certified that the Bharti Vidya Niketan Sr. Sec. Public School Located at A-26, Ranjeet Vihar (Chander Vihar), Nilothi Ext. Delhi-110041, comprised of Ground + 02 Upper Floor was issued Fire Safety Certificate by this department Vide Letter No. F6/DFS/MS/School/2019/1429 Dated 12.07.2019. The said premise was re-inspected by the officer concerned of this department on 02.09.2022 in the presence of Ms. Mundrika Mehta (Caretaker) and found that the premises / building have deemed complied with the fire prevention and fire safety requirements in accordance with D.O.E. Cr. No. 262-362 dated 17.01.2005 and that the premises/building is fit for occupancy class 'Educational Building' Group B with effect from 1579/22 for a period of three years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules, 2010, printed below

Issued on _at New Delhi by. 1575/22

> (Dharampal Bhardw Dy. Chief Fire Officer

(West Zone)

Copy to: -

1. The Director, Directorate of Education, GNCT of Delhi, Old Secretariat Delhi-110054.

2. The Principal, Bharti Vidya Niketan Sr. Sec. Public School Located at A-26, Ranjeet Vihar (Chander Vihar), Nilothi Ext. Delhi-110041.

Following fire safety directives must be adhered to:-

- 1. All the means of escape shall be kept free of all type of obstruction all the time.
- 2. All the employees shall be acquainted with the use and maintenance of all fire equipments and method of smooth and speedy safe evacuation of occupants in case of emergency.
- 3. All the fire fighting equipments shall be maintained in perfect working condition all the time and any lapse rendering non-functional if fire safety measures, management shall be responsible.
- 4. Any deviation, with regards to construction, ventilation, occupation, electric installation etc. may be got verified from the concerned authorities.
- 5. The Fire Safety Certificate may not be treated in any case for regularizations of unauthorized construction / unauthorized use of land if any.
- 6. All comments / directions of licensing Department shall always be permitted and followed.
- 7. The owner /occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rule 2010. The form is available on www.dfs.delhigovt.nic.in
- 8. The owner / occupier shall apply for renewal of this Fire Safety Certificate to the Director in Form J (sub Rule (1) of Rule 37) along with copy of the certificate, six months prior to its expiry.

INSPECTION REPORT

1. Name and address of the building: Bharti Vidya Niketan Sr. Sec. Public School Located at A-26, Ranjeet Vihar, (Chander

Vihar), Nilothi Ext. Delhi-110041

2. Type of Occupancy : Educational (G + 02 Upper Floor only)

3. Type of Case Renewal

4. Details of previous NOC: F6/DFS/MS/School/2019/1429 Dated 12.07.2019

5. Fire Safety directives Letter No.: D.O.E. Cr. No. 262-362 dated 17,01.2005

6. Date of inspection : 02.09.2022

7. Name of the Inspecting Officer: Aman Kumar Lathar, ADO (JWP)

8. Name and designation of Officer

from the building side : Ms. Mundrika Mehta (Caretaker)

9. Year of Construction : -----

10. Applicant's letter No. : BVN 1(3)/2022/213 dated 09.07.2022

S No	Minimum standards on fire prevention and fire safety U/R 33	illillulli stalidards on me		Provided at site	Remarks MR/NMR	
1.	Access of building					
	 Road width 	Accessible		Provided	MR	
	 Gate width 	Accessible	ŀ	Provided	MR	
	 Width of internal road 	NA		NA	NA	
2.	Number, width, Type & Arrangements of exits					
	 a. Number of staircases 					
	 Upper floors 	02	F	Provided	MR	
	 Basements 	NA		NA	NA	
	 b. Width of staircases 			0.1.21) (D	
	 Upper floors 	Old Case	1.75	m & 1.24 m	MR	
	Basements	NA		NA	NA	
	c. Protection of exits			N		
	 Fire check door 	NA		NA	NA	
	 Pressurization 	NA		NA	NA_	
	d. No of continuous staircase to terrace	01	1	Provided	MR	
	e. Width Of Corridor	Old Case		1.0 m	MR	
	f. Door Size	Old Case		1.0 m	MR	
	Compartmentation			NA		
	Fire check door	NA		NA	NA	
	 Sealing of electrical shafts 	NΛ		NA	NA	
	 Fire Rating of shaft door 	NA		NA	NA	
	 Water Curtain 	NΛ		NA	NA	
	 Fire Dampers 	NΛ		NA	NA	
	Smoke managements System					
	Basements	NΛ		NA	NA	
	 Upper floors 	NΛ		NA	1	
	Fire Extinguishers					
	Total numbers	12 nos.	1	rovided	NIR	
	• Types	$\Delta BC \& CO_2$	1	rovided	NIR	
	• IS marking	ISI marked	1	rovided	MR	

			N-17	T
T	First - Aid Hose Reels		Provided	MR
+	Total numbers on each floor	01	Provided	MR
	v -t -Channe and bosse	30 m	Provided	MR
	Name diameter	5 mm	Provided	
+	Automatic fire detection and alarming	system	NIA	NA.
-	The state of the s		NA	NA
	- FMain Panel	NA	NA	NA
	C Deportor Pane	NA	NA	NA
	Location of Repeater Fairer	NA	NA	
	Alternate source of power	NA	NA	NA
	Hooters' Location	NA	NA	NA
š	MOEFA	NA	NA	NA
).	Public Address System	1474		
10.	Automatic Sprinkler System	NA	NA	NA
	Basements	NA	NA	NA
	Upper Floor	NA	NA	NA
	Sprinkler above false ceiling	IN/X		
11.	Internal Hydrants:	100	Provided	MR
	Size of riser/down-comer	100 mm	Provided	MR
	 Number of hydrants per 	01	Flovided	, viii
	floor	01	Provided	MR
N. I	Hose Box	01	Flovided	1111
12.	Yard Hydrants	214	NIA	l NA
	 Total number of hydrants 	NA	NA NA	NA
	Hose Box	NA	NA	INA
13.	Pumping Arrangements:			
	Ground Level		214	NIA
	Discharge of main pump	NA	NA	NA
	> Head of main pump	NA	NA	NA
	Number of main pumps	NA	NA	NA
	> Jockey pump out put	NA	NA	NA
	Jockey pump head	NA	NA	NA
	 Standby Pump out put Standby Pump Head 	NA	NA	NA
	> Auto Staring/Manual	NA - NA	NA NA	NA NA
	stopping	NA	NA	NA
	➤ Pump House Access	NA	NA	NA
	Terrace level	INA	INA	INA
	 Discharge of pump 	450 lpm	Provided	MR
	➤ Head of the pump	430 ipin 40 m	Provided	MR
	➤ Power supply	Required	Provided	MR
	➤ Auto starting of pump	Required	Provided	MR
14.	Captive water Storage for fire fighting		Tiovided	IVIIC
	Under ground tank capacity	NA NA	NA	NA
	> Draw off connection	NA	NA	NA
	> Fire service inlet	NA	NA	NA
	> Access to tank	NA	NA	NA
	Overhead Tank capacity	5,000 ltrs. (Old Case)	Provided	MR
15	Exit Signage	Required	Provided	MR
16.	The state of the s		7.0.71.000	IVIIC
	 Pressurization of Lift Shaft 	NA	NA	NA
	 Pressurization of lift lobby 	NA	NA	NA
	Communication in lift Car	NA	NA	NA
	Fireman's Grounding Switch	NA	NA	NA
	➤ Lift Signage	NA	NA	NA
17	Standby power supply	NIA		
11	D C	NA	NA	NA
18	. Refuge Area			
	➤ Total area	NA	NA	NA

10 Fire	control room			
	 Detector system panel 	NA	NA	NA
	Flow Switch Panel PA System Panel	NA	NA	NA
		NA	NA	NA
	 Battery backup 	NA	NA	NA
	 Building Floor Plans 	NA	NA	NA
Sys	cial Fire Protection tems for Protection of	NA	NA	NA had and found
-1	Fire protection system	is provided i	n the building we	ere checked and found
func	tional at the time of inspec	ction.		
	Note: - At ground floo	or of the scho	ool building, 30me	shops are running and

In view of the deemed compliance of the minimum standards on fire prevention and fire safety requirements as per D.O.E. Cr. No. 262-362 dated 17.01.2005, renewal of Fire Safety Certificate issued vide letter no. F6/DFS/MS/School/2019/1429 Dated 12.07.2019 is recommended.

Accordingly DFA is put up for approval please.

ه وحلي)

Aman Kumar Lathar ADO (JWP)

03/00/25

De (w) / 1719 mr

AND TWO P

F.S. letter is met-up for your eignature M.

1111/11/11/22

18/169/22

AND TWO?

(w2)

1419 | 222

.

104