GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI-HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI-110001

NO. F6/DFS/MS/2022/WZ/ 406

Dated: 15/09/2022

FIRE SAFETY CERTIFICATE

Rules, 2010, Issued on ... Slog/por at New Delhi by

(Dharampal Bhardwa))
Dy.Chief Fire Officer
WEST ZONE

ou R

Conditions for the validity of Fire Safety Certificate:

- 1. All the fire safety arrangement provided there-in shall be maintained in good working conditions at all times.
- Loss of life or property due to non functional fire safety measure shall be at the responsibility of the management.
- 3. The trained fire fighting staff should be available round the clock.
- Any deviation with regard to the construction etc shall be verified by the concerned building sanctioning agency.
- 5. This certificate cannot be treated in any case for regularizations of unauthorized construction.
- 6. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director of Form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior to its expiry".
- 7. The owner / occupier shall submit a declaration every year in form "K" provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on <u>WWW.dfs.Delhigovt.nic.in</u>
- 8. All the means of escape shall be kept free of any obstruction all the time to evacuate the occupant, in a safe manner, in the event of emergency.

Copy to:

1. Yadu Green Motel / Resort Building located at Kh. No. 42/25, 52/9, 52/10, 52/11, 53/5 & 53/6 Village Bakoli, Main G.T.K Road, Delhi-36.

INSPECTION REPORT

1 Name & address of the building : Yadu Green Motel / Resort Building, Kh. No. 42/25, 52/9,52/10,52/11,

53/5 & 53/6, Village Bakoli, Main G.T.K Road, Delhi-36.

2 Type of Occupancy : Mixed (Assembly/Residential)

3 Building Comprised : Basement(Storage), Ground floor (Restaurant) & First floor (16 Guest Rooms)

4 Type of Case : Renewal

Details of previous NOC : F6/DFS/MS/2019/1738 dated 06/09/2019
 Fire Safety directives letter No : F6/DFS/MS/BP/2005/2630 dated 21/12/2005

Date of inspection : 13.09.2022
 Name of the Inspecting Officers : ADO, R.K.Sinha

8. Name of the Inspecting Officers : ADO,9. Name and designation of officers

from the building side : Sh. Uttam Duta

9. Year of Construction : 2005

10. Applicant's letter No. : MHA, Application No. 2022081016052 dated 11.08.2022

	Minimum Standards on fire prevention ar fire safety U/R 33	nd NBC/BBL Requirement	Provided at site	Remarks MR/NMR
1	Access to building	ı	. 1	
	Road width	6 m	9 m	MR
	Gate width	05m	05m	MR
	 Width of internal road 	06 m	06 m	MR
2	Number Width, Type & Arrangement of E	xits	ı	
	a. Number of staircases		The second control of	
	Upper Floors	03	03	MR
	Basements	04	04	MR
	b. Width of staircases	1.50 m each	Provided	MR
	Upper Floors	1,50 m cach	Trovided	IVIIX
	Basements	1.50 m each	Provided	MR
	c. Protection of exits		a Bill in page pressure	NAD
	Fire check door	Required	Provided	MR NA
	Pressurization	NA	NA	NA
	d. No. of continuous staircases to terrace	02	Provided	MR
	c. Width of Corridor	Required	Provided	MR
	f. Door Size	2 m	2 m	MR

Re

N-29

3	Compartmentation.				
	Fire check door	Required	Provided	MR	
	 Sealing of electrical shafts 	Required	Provided	MR	
	 Fire Rating of shaft door 	NA	NA	NA	
	Water Curtain	NΛ	NA	NA	
	Fire Dampers	NA	NA	NA	
4	Smoke Management System.				
	Basements	30 a/c per hour	Exhaust fan	MR	
	Upper floors	12 a/c per hour	Natural Ventilated	MR	
5	Fire Extinguishers	9			
	Total numbers	One @ 300 Sq m	30	MR	
	• Types	ABC & Co2	ABC & Co2	MR	
	ISI marking	Yes	Yes	MR	
6	First-Aid Hose Reels.				
	Total numbers on each floor	02	Provided	MR	
	 Length of hose reel hose 	30m	30m	MR	
	Nozzle diameter	5mm	5mm	MR	
	Automatic fire detection and alarming system.				
	Type of detectors	Smoke /Heat	Provided	MR	
	Location of Main Panel	G.F.	Provided	MR	
	Location of Repeater Panel	NA	NA	NA	
	Alternate source of power	Required	Provided	MR	
	Hooters' Location	Required	Provided	MR	
8	MOEFA	Required	Provided	MR	
9	Public Address System.	Required	Provided	MR	
10	Automatic Sprinkler System.				
	Basement	Required	Provided	MR	
	Upper Floor	Required	Provided	MR	
	Sprinkler above false ceiling	Required	Provided	MR	
11	Internal Hydrants				

Ou

4	Size of riser/down-comer	100mm	Provided	MR	
	Number of hydrants per floor	01	Provided	MR	
	Hose Box	01	Provided	MR	
Yar	d Hyd <mark>rants.</mark>				
	Total number of hydrants	Required	Provided	MR	
	Hose Box	Required	Provided	MR	
Pun	Pumping Arrangements.				
	Ground Level				
	Discharge of main Pump	2850 lpm	2850 lpm	MR	
	> Head of Main pump	40 m	Provided	MR	
	Number of main pumps	02	Provided	MR	
	> Jockey Pump out put	180 lpm	Provided	MR	
	Jockey pump head	40 m	Provided	MR	
	Standby Pump out put	2850 lpm	Provided	MR	
	Standby Pump Head	40 m	Provided	MR	
	Auto Starting/ Manual stopping	Required	Provided	MR	
	> Pump House Access	Required	Provided	MR	
	Terrace level				
	Discharge of pump	900 lpm	Provided	MR	
	Head of the pump	40 m	Provided	MR	
	Power Supply	Required	Provided	MR	
	Auto Starting of pump	Required	Provided	MR	
Ca	Captive Water Storage for fire fighting.				
	Underground tank capacity	1,00,000 ltr.	Provided	MR	
	> Draw-off connection	Required	Provided	MR	
	> Fire service inlet	Required	Provided	MR	
	> Access to tank	Required	Provided	MR	
	Overhead Tank capacity	10,000 ltr	Provided	MR	
Ex	cit Signage.	Required	Provided	MR	
Pr	Provision of Lifts.				
		NA	NA	NA	
•		NA	NA	NA	
•	Pressurization of Lift lobby		NIA	NA	
•	Communication In lift Car	NA	NA	INA	

M

	 Fireman's Grounding Switch 	NA	NA	NA
	Lift Signage	NA	NA	NA
7	Standby power supply	Required	Provided	MR
8	Refuge Area.			
	> Total Arca	N/A	N/A	N/A
	> Location	N/A	N/A	N/A
9	Fire Control Room			
	Detector System Panel	Required	Provided	MR
	 Detector System Panel Flow Switch Panel PA System Panel Batter backup Building Floor Plans 	NA	NΛ	NA
		Required	Provided	MR
		Required	Provided	MR
		NA	NΛ	NA
	Special Fire Protection Systems for Protection of special Risks, if any:	NΛ	NA	NA

The fire protection systems provided in the building were tested/ checked randomly and found in good working conditions.

Keeping in view of the deemed compliance of the minimum standards on fire prevention and fire safety measures as required under the rules the FSC issued vide letter no. F.6/DFS/MS/2019/WZ/1738 dated 06.09.2019 renewal under rule 35 of the Delhi Fire Service rules 2010 is recommended.

Signature of the Inspecting Officer
Name: - Rajeev Kumar Sinha

Designation: - ADO/BW

DO(NW) on Dreft

ero (104)

1279 Jon

Assol son F-T letter in Putup for signi pleme

Dycto (ww)

ma all