

No. F6/DFS/MS/2022/EH/ 259 FIRE SAFETY CERTIFICATE

Dated: 14 / 9 /2022

Certified that the M/s Apni Rasoi (Rishab Enterprises) located at Property no. F-18, Ground Floor, Vijay Nagar, Hudson Lanc, Delhi-110009 in the building comprised of basement, ground & 02 upper floors owned/occupied by M/s Apni Rasoi (Rishab Enterprises) have complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules,2010 and verified by the officer concerned of Fire Service on 09.09.2022 in the presence of Sh. Mohit and that the building/ premise is fit for occupancy Class "D Assembly" (Restaurant) at ground floor only with effect from 14/9/2014 or a period of 03 (Three) years in accordance with rule 36 unless renewed under rule/37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fige Service Rules, 2010.

Director Ph-011-23414000

Copy to:-

1. M/s Apni Rasoi located at Property no. F-18, Ground Floor, Vijay Nagar, Hudson Lane, Delhi-110009.

## Conditions for the validity of Fire Safety Certificate:

- 1. This Fire Safety Certificate is valid for restaurant at ground floor for assembly occupancy only. In case of any violation, this FSC will be treated as null & void.
- 2. All the means of escape/entry/exit shall be kept free from any obstruction.
- 3. All the fire safety arrangements provided therein shall be maintained in good working condition at all time as seen during inspection.
- 4. Any loss of life or property due to non-functional fire safety measures shall be at the responsibility of the management.
- 5. All the staff members must know the correct method of operation of firefighting system.
- 6. The owner / occupier shall submit a declaration every year in Form "K" provided in the first of Delhi Fire Service Rules 2010. The form is http://delhi.gov.in./wps/wcm/connect/doit fire/FIRE/Home/Forms.
- 7. This fire safety certificate may not in any way be treated as regularization (Clause 2.8 of UBBL-2016) of unauthorized construction or Alteration (Clause 1.4.3 of UBBL-2016), if any.
- 8. "The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in Form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior to its expiry".

## INSPECTION REPORT

1. Name& address of the building

: M/s Apni Rasoi at Shop No. F-18, Ground Floor, Vijay Nagar, Hudson lane

Delhi-110009.

2. Type of Occupancy

: Assembly (Restaurant)

3. Composition of building

: Basement, Ground & 02 upper floors only, basement-vacant, first floor & second

Floor residence and Restaurant running at ground floor only

4. Type of Case

: New Case

5. Details of previous NOC

: NBC Part-4/BBL

6. Fire Safety directives letter No

: Nil

7. Date of inspection

: 09.09.2022

8. Name of the Inspecting Officers

: ADO (RN)

9. Name and designation of officers

from the building side

: Mr. Mohit

10. Year of Construction

: 1965

11. Applicant's letter No.

: Online MHA Portal I'd. No. 2022082416563 dated 26.08.2022

	Minimum Standards on fire prevention and fire safety U/R 33	NBC Part-4/BBL requirement	Provided at site	Remarks MR/NMR			
1	Access to building						
	Road width	09m	12m approx	MR			
	Gate width	NA	NA	NΛ			
	Width of internal road	NA	NΛ	NΛ			
2	Number, Width, Type & Arrangement of Exit	mber, Width, Type & Arrangement of Exits (Restaurant at GF only)					
	a. Number of staircases						
	Upper Floors	NA	NΛ	NΛ			
	Basements	NA	NΛ	NA			
b. Width of staircases							
	Upper Floors	NA	NA	NA			
	Basements	NA	NA	NΛ			
	c. Protection of exits			N/ A			
	<ul> <li>Fire check door</li> <li>Pressurization</li> <li>d. No. of continuous staircases to terrace</li> </ul>	NA	NΛ	NA			
		NA	NA	NA			
		NΛ	lm	NΛ			
		NA	NA	NA			
	e. Width of Corridor	02nos 1.50m each	1.5m x2	MR			
	f. Door Size						
3	Compartmentation.						
	Fire check door	NΛ	NA NA	NA NA			
	<ul> <li>Sealing of electrical shafts</li> </ul>	NΛ					
	Fire Rating of shaft door	NA	NA	NA			
	Water Curtain	NΛ	NΛ	NΛ			
	Fire Dampers	NΛ	NA	NΛ			
	Smoke Management System.						
	Basements	12 a/c per hour	NA	NΛ			
	Upper floors (Ground floor)	12 a/c per hour	Natural Ventilation	MR			
5	Fire Extinguishers						
	Total numbers	04nos	06nos	MR			
	• Types	ABC/Co2	ABC-04	MR			
	ISI marking	Yes	Yes	MR			

Fi	rst-Aid Hose Reels.	01	01	MR			
	<ul> <li>Total numbers on each floor</li> </ul>		30m	MR			
	<ul> <li>Length of hose reel hose</li> </ul>	30m	5min	MR			
	Nozzle diameter	5mm	1				
A	utomatic fire detection and alarming system.		1	NA			
,,,	Type of detectors	NA	NΛ	NΛ			
	Location of Main Panel	NA	NA	NΛ			
		NΛ		NΛ			
	Location of Repeater Panel	NΛ	NΛ				
	Alternate source of power	NΛ	NΛ	NΛ			
	Hooters' Location	Required	Provided	MR			
	MOEFA	NA	NΛ	NΛ			
1	Public Address System.	INA					
0 /	Automatic Sprinkler System.			NA			
	Basement	NΛ	NΛ	NΛ			
	Upper Floor (Ground floor)	NA	NΛ	NΛ			
	Sprinkler above false ceiling	NΛ	NΛ	NΛ			
11	Internal Hydrants						
	Size of riser/down-comer	100mm	100mm	MR			
	Number of hydrants per floor	01	01	MR			
		01	01	MR			
	Hose Box						
12	Yard Hydrants.	NΛ	NΛ	NΛ			
	Total number of hydrants		NΛ	NA			
	Hose Box	NΛ	14/1				
13							
	Ground Level						
	Discharge of main Pump	N/A	N/Λ	N/A			
	➤ Head of Main pump	N/Λ	N/Λ	N/A			
	> Number of main pumps	N/Λ	N/Λ	N/A			
	➤ Jockey Pump out put	N/Λ	N/Λ	N/A			
	➢ Jockey pump head	N/A	N/A	N/A			
	➤ Standby Pump out put	N/Λ	N/A	N/A			
	> Standby Pump Head	N/A	N/A	N/Λ			
	➤ Auto Starting/ Manual stopping	N/Λ	N/Λ	N/Λ			
	➤ Pump House Access	N/A	N/A	N/A			
	Terrace level		1				
	<ul><li>Discharge of pump</li></ul>	4501	4501	MD			
	➤ Head of the pump	450lpm	450lpm	MR			
	Power Supply	40m	40m	MR			
		Required	Provided	MR			
	➤ Auto Starting of pump	Required	Provided	MR			
14	Captive Water Storage for fire fighting.		.1	1			
	Underground tank capacity	NΛ	NΛ	NΛ			
				++			
	<ul> <li>Draw-off connection</li> </ul>	NΛ	NΛ	NA			
	<ul><li>Draw-off connection</li><li>Fire service inlet</li></ul>	NA NA	NΛ NΛ	NA NA			

0						
1	Overhead Tank capacity	20,000 ltr	Provided	MR		
Exit Si	gnage.	Required	Provided	MR		
Provis	Provision of Lifts.					
•	Pressurization of Lift Shaft	N/Λ	N/Λ	N/Λ		
•	<ul> <li>Pressurization of Lift lobby</li> <li>Communication In lift Car</li> <li>Fireman's Grounding Switch</li> <li>Lift Signage</li> </ul>	N/A	N/Λ	N/Λ		
•		NA	NA ·	NA		
		NA	NA	NA		
•		NA	NA	NΛ		
Standl	by power supply	Required	Provided	MR		
Refug	Refuge Area.					
~	Total Area	N/A	N/A	N/A		
>	Location	N/A	N/A	N/A		
Fire C	Fire Control Room					
	Detector System Panel	N/A	N/A	N/A		
	Flow Switch Panel	N/A	N/A	N/A		
	PA System Panel	N/A	N/A	N/A		
	Batter backup	N/A	N/A	N/A		
	Building Floor Plans	N/A	N/A	N/A		
	al Fire Protection Systems for	NA	NA	NA		

Note:-

 $M_R$ 

(a) The total covered area of the ground floor Restaurant is 130sqm (Approx) including scating area, kitchen area, toilet area,

(b) As per the NBC Part IV, the number of occupants comes out to be approx 72 person's i.e. (130/1.8=72).

The fire protection systems provided in the building were tested/ checked and found in good working order at the time of inspection. The observations/ shortcomings issued and communicated vide this department letter of even no. 505 dated 01.08.2022 have been compiled by the management.

Keeping in view of the substantial compliance of the minimum standards on fire prevention and fire safety required under the rules it is recommended to grant Fire Safety Certificate under rule 35 of the Delhi Fire Service

Rules 2010.

Signature of the Inspecting Officer
Name: - C.L. Meena

Designation:- ADO/RN

12 ta) son

Director 121912

Anyer

Conf --- P.T.C