## GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEAD QUARTERS: DELHI FIRE SERVICE: NEW DELHI - 110001

No. F6/DFS/MS/2022/EH/ 254

Dated/3 / 9 /2022

### FIRE SAFETY CERTIFICATE

Certified that the M/s Invitation K located at Ground & First Floor, North Gate, Gujrawala Town Part-II, Delhi-110009 in the building comprised of Ground & 02 upper floors owned/occupied by M/s Invitation K have complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and verified by the officer concerned of Fire Service on 30.08.2022 in the presence of Mr. Mohit Kakkar and that the building/ premise is fit for occupancy Class "D" Assembly (Restaurant) for ground & first floor only with effect from \[ \begin{array}{c} 3 \\ \end{array} \] \[ \begin{array}{c} 2012 \\ \end{array} \] for a period of \[ \frac{03}{03} \left( \text{Three} \right) \text{ years} \\ \text{in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules, 2010.

Issued on  $\frac{3}{9}$ ,  $\frac{120.12}{20.12}$  at New Delhi by

(Ktul Garg)
Director

Ph-011-23414000

Copy to:-

1. M/s Invitation K located at North Gate, Gujrawala Town Part-II, Delhi-110009.

of Cy

# Conditions for the validity of Fire Safety Certificate:

- 1 This Fire Safety Certificate is valid only for restaurant at ground & first floor for assembly occupancy only. In case of any violation, this FSC will be treated as null & void.
- 2 All the means of escape/entry/exit shall be kept free from any obstruction.
- 3 All the fire safety arrangements provided therein shall be maintained in good working condition at all time as seen during inspection.
- 4 Any loss of life or property due to non-functional fire safety measures shall be at the responsibility of the management.
- 5 All the staff members must know the correct method of operation of firefighting system.
- 6 The owner / occupier shall submit a declaration **every year** in **Form "K"** provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on <a href="http://delhi.gov.in./wps/wcm/connect/doit">http://delhi.gov.in./wps/wcm/connect/doit</a> fire/FIRE/Home/Forms.
- 7 This fire safety certificate may not in any way be treated as regularization (Clause 2.8 of UBBL-2016) of unauthorized construction or Alteration (Clause 1.4.3 of UBBL-2016), if any.
- 8 "The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in Form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior to its expiry".

# INSPECTION REPORT

Name & address of the building M.s. Invitation K located at GE & FE at North Gate, Guirawala Town Part-II,

Type of Occupancy (Assembly) Restaurant

Composition of building : Ground & two upper floors but restaurant is running at ground & first

floor only and second floor is vacant

Type of Case New Case

Details of previous NOC : Nil

Fire Safety directives letter No : Nil

Date of inspection : 30.08.2022

Name of the Inspecting Officers : ADO (RN)

Name and designation of officers

from the building side : Mr. Mohit Kakkar

10. Year of Construction

: 2000 11. Applicant's letter No. : Online LD No. 2022082416549 Dated: 24.08.2022

12. Total covered area : 266sqm

	Minimum Standards on fire prevention and fire safety U/R 33	UBBL/NBC-2016 requirements		Remarks MR/NMR
	Access to building	1		
	Road width	06	12m approx	MR
	Gate width	4.5m	4.5m	MR
	Width of internal road	NΛ	NA	NΑ
2	Number, Width, Type & Arrangement of Exit			1874
	a. Number of staircases	1		
	Upper Floors	02	03	MR
	Basements	NA	NΛ	NΛ
	b. Width of staircases			200 -
	Upper Floors	02m & 1.5m	GF to FF- 3 nos staircase- 02m,1 50m & 1 40m	MR
	Basements	N A		
	c. Protection of exits	NΛ	NΛ	NΛ
	Fire check door	Required	Provided	MR
	Pressurization	NA	NΛ	
	d. No. of continuous staircases to terrace	02	03	NA MR
	e. Width of Corridor	NΛ	NA NA	
	f. Door Size	1.5m	GI -031 xits- 2 10m & 1 50m ea	NA nch MR
3	11-021 xtts - 02m & 150m			
	Fire check door	Required	Provided	MR
	Sealing of electrical shafts	NΛ	NΛ	NΛ
	Fire Rating of shaft door	NΛ	NA	NΑ
	Water Curtain	NA	NΛ	NA
	Fire Dampers			
4	Smoke Management System.	NΛ	NΛ	NA
	Basements	12 a/c per hour	NA NA	. NA
	Upper floors	12 a/c per hour	Natural Ventilation	MR
		per mount	Ventual Ventual	VIIX
5	Fire Extinguishers			

	Lotal numbers	10nos	12nos	MA	
	• Types	ABC Co2	ABC-12	MR	
	ISI marking	Yes	Yes		
	First-Aid Hose Reels.			MR	
		0			
	Total numbers on each floor	Oleach floor	Provided	MR	
	<ul> <li>Length of hose reel hose</li> </ul>	30m	Provided	MR	
	Nozzle diameter	5mm	Provided	MR	
	Automatic fire detection and alarming system.				
	Type of detectors	Required	Provided	MR	
	Location of Main Panel	NΛ	NΛ	NΛ	
	Location of Repeater Panel	NΛ	NΛ	NΛ	
	Alternate source of power	NA	NA	NΛ	
	Hooters' Location	NΛ	NΛ	NA	
	MOEFA	Dogwinad	Provided	MD	
	Public Address System.	Required NA	NA	MR NA	
)	Automatic Sprinkler System.	1		-	
	Basement	NA	NA	NA	
	Upper Floor	Required	Provided	MR	
	Sprinkler above false ceiling	NΛ	NΛ	NΛ	
11	Internal Hydrants	1 1	1		
	Size of riser/down-comer	100mm	Provided	MR	
		01	Provided	MR	
	Number of hydrants per floor	01	Provided	MR	
	Hose Box				
2	Yard Hydrants.				
	Total number of hydrants	01	Provided	MR	
	Hose Box	01	Provided	MR	
13	Pumping Arrangements.				
		1			
	Ground Level	NA	NA	NΛ	
	<ul> <li>Discharge of main Pump</li> </ul>			NA.	
	Head of Main pump	NA NA	NA NA	NA NA	
	Number of main pumps	NΛ	NA		
	Jockey Pump out put	N/A	N/A	N/A	
	Jockey pump head	N/A	N/A	N/A	
	Standby Pump out put	N <sub>1</sub> A	N/A	N/A	
	Standby Pump Head	N/A	N/A	N/A	
	Auto Starting Manual stopping Pump House Access	N/A	N/A	N/A	
	Terrace level				
	<ul> <li>Discharge of pump</li> </ul>	450lpm	450lpm	MR	
	<ul> <li>Head of the pump</li> </ul>	40m	40m	MR	
	Power Supply	Required	Provided	MR	
	<ul> <li>Auto Starting of pump</li> </ul>	Required	Provided	MR	
		Required			

PP

100							
	Underground tank capacity	NΛ	NA	NA			
	Draw-off connection	NΑ	NΆ	NΛ			
	Fire service inlet	NA	NA.	NA -			
	<ul><li>Access to tank</li><li>Overhead Tank capacity</li></ul>	NΛ	NΛ	NA			
		20,000ltr		MD			
Ex	it Signage.	Required	Provided Provided	MR MR			
6 Pr	ovision of Lifts.		Trovided				
	ovision of Lines.	Two Passenger Lift					
•	Pressurization of Lift Shaft	N/A	N/A	N/A			
•	Pressurization of Lift lobby	N/A	$N/\Lambda$	N/A			
	Communication In lift Car	NA	NA	NΛ			
	<ul> <li>Fireman's Grounding Switch</li> </ul>	Required	Provided	MR			
	Lift Signage	Required	Provided	MR			
7 St	tandby power supply	Required	Provided	MR			
8 R	Refuge Area.						
	Total Area	$N/\Lambda$	N/A	$N/\Lambda$			
	Location	N/A	N/A	N/A			
19 <b>F</b>	Fire Control Room						
	Detector System Panel	N/A	N/A	$N/\Lambda$			
	Flow Switch Panel	N/A	N/A	$N/\Lambda$			
	PA System Panel	N/A	N/A	N/A			
	Batter backup	N/A	N/Λ	N/A			
	Building Floor Plans						
		N/A	N/A	N/Λ			
20	Special Fire Protection Systems for Protection of special Risks, if any:	NΛ	NA	, NA			

#### Note:

- (a) The total covered area of the ground floor & second floor Restaurant is 532sqm (Approx) including seating area, kitchen area, toilet area, bar area.
- (b) As per the NBC Part IV, the number of occupants comes out to be approx 295 person's i.e. (532/1.8=295)

The fire protection systems provided in the building were tested/ checked and found some in working order at the time of inspection.

Keeping in view of the substantial compliance of the minimum standards on fire prevention and fire safety required under the rules it is recommended to grant Fire Safety Certificate under rule 35 of the Delhi Fire Service Rules 2010.

DO (140) 108/09/20)

Dur (sto (w)

Signature of the Inspecting

Name: - C.L. Meena

Designation:- ADO/RN

Dêneda 19

AnyKN

Cont - - P.T.D.