




446



GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI- 110001


No. F.6/DFS/MS/WZ/School/2022/ 879

Dated 11/8/2022

FIRE SAFETY CERTIFICATE

Certified that the **N.C. Jindal Public School**, located at **Road No.73, Punjabi Bagh, New Delhi-110026** comprised of two blocks 1st block is (Sr. Sec. Block) Ground + 02 upper floors & 2nd block is (Primary Section) Ground + 02 floors & both are inter connected & one auditorium at ground floor owned/ occupied by **N.C. Jindal Public School** has already issued FSC by this department vide letter No. F.6/DFS/MS/School/2019/1431 dated 12/07/2019. The premises was re-inspected by officer concerned of this department on 30/07/2022 in the presence of Sh. R.K. Sharma (Maintenance) and observed that all the fire prevention and fire safety arrangements provide in the premises found in good working condition. The premises have therefore deemed complied with Director of Education Circular dated 01/03/2011/NBC (Part-IV) and that the building/premises is fit for occupancy class "Educational" Group-B, with effect from 11/8/2022 for a period of three years in accordance with rule 36 unless renewal under rule 37 or sooner cancelled under rule 40 and subject to compliance of the conditions under rule 38 of the DFS rules, 2010 conditions printed overleaf.

Issued on 11/8/2022 at New Delhi by


(Dharampal Bhardwaj)
Dy. Chief Fire Officer
West Zone
OIC BR

Copy to: -

1. The Principal, N.C. Jindal Public School, located at Road No.73, Punjabi Bagh New Delhi-110026.
2. The Director of Education, Govt. of NCT of Delhi, Old Secretariat, New Delhi.

INSPECTION REPORT

1. Name & address of the building : N.C. Jindal Public School Located at Road No. 73. Punjabi Bagh (West), New Delhi-110026.
2. Type of Occupancy : Educational (Ground & 02 Upper Floor)
3. Type of Case : Renewal
4. Details of previous NOC : F6/DFS/MS/School/2019/1431 Dated: 12/07/2019
5. Fire Safety directives letter No : DOE Circular Dated 01/03/2011
6. Date of inspection : 30/07/2022
7. Name of the Inspecting Officers : Sarabjeet Singh, ADO (Moti Nagar)
8. Name and designation of officers from the building side : R.K. Sharma (Maintenance)
9. Year of Construction : 2009 (As Per Prev. Insp. report dated 11/06/2019)
10. Applicant's letter No. : E-mail dated 27/07/2022

S. No.	Minimum Standards on fire prevention and fire safety U/R 33	DOE Circular dated 01/03/2011/ As Per Prev. Insp. report dated 11/06/2022	Provided at site	Remarks MR/NMR
1	Access to building			
	• Road width	6 mts	Provided	MR
	• Gate width	4.5 mts	Provided	MR
	• Width of internal road	N/A	N/A	N/A
2	Number, Width, Type & Arrangement of Exits			
	a. Number of staircases			
	• Upper Floors	2	04 Provided	MR (old case)
	• Basements	N/A	N/A	N/A
	b. Width of staircases			
	• Upper Floors	1.5 mts	1.42mtr, 1.22mtr, 1.37mtr x 2	MR (old case)
	• Basements	N/A	N/A	N/A
	c. Protection of exits			
	• Fire check door	N/A	N/A	N/A
	• Pressurization	N/A	N/A	N/A
	e. No. of continuous staircases to terrace	01	02	MR
	g. Width of Corridor	1.5 mts	Provided	MR
	h. Door Size	1 mts (Class Room) 1.50 mts x 2 (Audi)	1 mts (class room) 2 mts x 3 (Audi)	MR (old case)
3	Compartmentation.			
	• Fire check door	N/A	N/A	N/A
	• Sealing of electrical shafts	N/A	N/A	N/A
	• Fire Rating of shaft door	N/A	N/A	N/A
	• Water Curtain	N/A	N/A	N/A
	• Fire Dampers	N/A	N/A	N/A
4	Smoke Management System.			
	• Basements	N/A	N/A	N/A
	• Upper floors	N/A	N/A	N/A

p/26

75



14

5	Fire Extinguishers	<ul style="list-style-type: none"> Total numbers Types IS marking 	32 nos. CO ₂ , ABC type ISI marked	50 nos. Provided	MR
				Provided	MR
				Provided	MR
6	First-Aid Hose Reels.	<ul style="list-style-type: none"> Total numbers on each floor Length of hose reel hose Nozzle diameter 	01 30 mtr 5 mm	Provided Provided Provided	MR MR MR
7	Automatic fire detection and alarming system.	<ul style="list-style-type: none"> Type of detectors Location of Main Panel Location of Repeater Panel Alternate source of power Hooters' Location 	N/A N/A N/A N/A N/A	Smoke detector (Audi) N/A N/A N/A Provided (Audi)	N/A N/A N/A N/A N/A
8	MOEFA		N/A	N/A	N/A
9	Public Address System.		N/A	N/A	N/A
10	Automatic Sprinkler System.	<ul style="list-style-type: none"> Basement Upper Floor Sprinkler above false ceiling 	N/A Required (on Stage of Audi) N/A	N/A Provided N/A	N/A MR N/A
11	Internal Hydrants	<ul style="list-style-type: none"> Size of riser/down-comer Number of hydrants per floor Hose Box 	N/A N/A N/A	100 mm Provided Provided	N/A N/A N/A
12	Yard Hydrants.	<ul style="list-style-type: none"> Total number of hydrants Hose Box 	N/A N/A	N/A N/A	N/A N/A
13	Pumping Arrangements.	<ul style="list-style-type: none"> Ground Level <ul style="list-style-type: none"> Discharge of main Pump Head of Main pump Number of main pumps Jockey Pump out put Jockey pump head Standby Pump out put Standby Pump Head Auto Starting/ Manual stopping Pump House Access Terrace level <ul style="list-style-type: none"> Discharge of pump Head of the pump Power Supply Auto Starting of pump 	N/A N/A N/A N/A N/A N/A N/A N/A N/A N/A 450 lpm & 180 lpm 40 mtr Required Required	N/A N/A N/A N/A N/A N/A N/A N/A N/A Provided Provided Provided Provided	N/A N/A N/A N/A N/A N/A N/A N/A N/A MR MR MR MR

96

N/27

72

14	Captive Water Storage for fire fighting.			
	• Underground tank capacity	N/A	N/A	N/A
	➤ Draw-off connection	N/A	N/A	N/A
	➤ Fire service inlet	N/A	N/A	N/A
	➤ Access to tank	N/A	N/A	N/A
	• Overhead Tank capacity	15,000 ltrs	Provided	MR
15	Exit Signage.	Required	Provided	MR
16	Provision of Lifts.			
	• Pressurization of Lift Shaft	N/A	N/A	N/A
	• Pressurization of Lift lobby	N/A	N/A	N/A
	• Communication In lift Car	N/A	N/A	N/A
	• Fireman's Grounding Switch	N/A	N/A	N/A
	• Lift Signage	N/A	N/A	N/A
17	Standby power supply	N/A	N/A	N/A
18	Refuge Area.			
	➤ Total Area	N/A	N/A	N/A
	➤ Location	N/A	N/A	N/A
19	Fire Control Room			
	• Detector System Panel	N/A	N/A	N/A
	• Flow Switch Panel	N/A	N/A	N/A
	• PA System Panel	N/A	N/A	N/A
	• Batter backup	N/A	N/A	N/A
	• Building Floor Plans	N/A	N/A	N/A
20	Special Fire Protection Systems for Protection of special Risks, if any:	N/A	N/A	N/A

The fire protection systems provided in the building were test checked and found functional at the time of inspection. The shortcomings issued by this department vide letter no F6/DFS/MS/School/WZ/2022/401 dated 13/07/2022 have been complied.

In view of the deemed compliance of minimum standards on fire prevention and fire safety as required under the rules the NOC issued vide letter no. F6/DFS/MS/School/2019/1431 dated 12/07/2019 renewal under rule 35 of the Delhi Fire Service rule 2010, is recommended.

253/ADO/MN
10/8/2022

~~D.O. (WEST)~~

~~04/8/2022~~
Sarabjeet Singh
ADO (MN)

D.O. (WEST).....
DATED.....

10/08/2022
DFS (WZ)
11/8/2022
Adil Shekhar Per FT



Following fire safety directives must be adhered to:-

1. All the fire safety arrangements provided therein shall be maintained in good working condition at all times.
2. Any loss of life or property due to non-functional fire safety measures shall be at the risk and responsibility of the management.
3. The trained staff should be available round the clock.
4. Any deviations w.r.t. construction shall be verified by the concerned building sanctioning agency.
5. The certificate may not be treated in any case for the regularization of the unauthorized construction, if any.
6. The owner/ occupier shall apply for renewal of this Fire Safety Certificate to the Director in Form 'J' [sub rule (1) of rule 37] along with a copy of this certificate, six months prior to its expiry.
7. The owner/occupier shall submit a declaration every year in the form 'K' provided in the first schedule of Delhi Fire Service Rules 2010, form is available on www.dfs.delhigovt.nic.in.