

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEAD QUARTERS: DELHI FIRE SERVICE: NEW DELHI - 110001

No. F6/DFS/MS/2022/School/ 929

Dated: 3 / 8/2022

FIRE SAFETY CERTIFICATE

Certified that the S.D. Memorial Public School located at 11/22, Kamal Vihar, Kamalpur Mazra, Burari, Delhi-110084 comprised of ground and first floor only owned/ occupied by S.D. Memorial Public School have complied with the fire prevention and safety requirements in accordance with requirements of circular issued by Director of Education letter no. 3298-3398 dated 01.03.2011 and verified by the officer concerned of Fire Service on 18.08.2022 in the presence of Sh. Vikrant Tyagi (Attendant) and that the building/premises is fit for occupancy "Group B Educational" for ground and first floor only with effect from 31.1.8.1.20.2.2.5. for a period of three years, subject to compliance of the conditions mentioned below:

Director Ph:-011-23414000 of c b

Copy to: -

- 1. The Director, Education, Government of N.C.T of Delhi. Old Sectt. Delhi 110054.
- 2. The Principal, S.D. Memorial Public School located at 11/22, Kamal Vihar, Kamalpur Mazra, Burari, Delhi-110084.

Conditions for the validity of Fire Safety Certificate:

- 1. All the means of escape/entry/exit shall be kept free from any obstruction.
- 2. All the fire safety arrangements provided therein shall be maintained in good working condition at all time as seen during inspection.
- 3. Any loss of life or property due to non-functional fire safety measures shall be at the responsibility of the management.
- 4. All the staff members must know the correct method of operation of firefighting system.
- 5. The owner / occupier shall submit a declaration **every year** in **Form "K"** provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on <u>http://delhi.gov.in./wps/wcm/connect/doit fire/FIRE/Home/Forms.</u>
- 6. This fire safety certificate may not in any way be treated as regularization (Clause 2.8 of UBBL-2016) of unauthorized construction or Alteration (Clause 1.4.3 of UBBL-2016), if any.
- "The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in Form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior to its expiry".

INSPECTION REPORT				
Name & address of the building	: S.D. Memorial Public School at Kh. No.11/22, Kamal Vihar. Kamalpur Mazra Burari, Delhi-110084.			
Type of Occupancy	: Educational			
Composition of building	: Ground and First Floor only			
Type of Case	: New Case			
Details of previous NOC	: Nil			
Fire Safety directives letter No	: Director of Education Letter dated 01.03.2011			
Date of inspection	: 18.08.2022			
Name of the Inspecting Officers	: ADO (RN)			
Name and designation of officers				
from the building side	: Mr. Vikrant Tyagi (Attendant)			
0. Year of Construction	: 2007			
	Name & address of the building Type of Occupancy Composition of building Type of Case Details of previous NOC Fire Safety directives letter No Date of inspection Name of the Inspecting Officers Name and designation of officers			

11. Applicant's letter No.

: Online E-Mail I.D dated: 23.02.2022

lot	Area-800sqm Covered Area-400Sqm Minimum Standards on fire prevention and fire safety U/R 33	No of student—123nd Director. Of Education Requirements	Provided at site	Remarks MR/NMR			
	Access to building	·					
1		Accessible	Accessible	MR			
	Road widthGate width	Directly Accessible	Directly Accessible	MR			
	Width of internal road	NA	NA	NA			
	Number, Width, Type & Arrangement of Exits						
2							
	a. Number of staircases	02	02	MR			
	Upper Floors	NA	NA	NA			
	 Basements 						
	b. Width of staircases	1.50m	1.50m & 1.25m	MR			
	Upper Floors	NA	NA	NA			
	• Basements						
	c. Protection of exits		NA	NA			
	 Fire check door 	NA	NA	NA			
	 Pressurization 	NA	02	MR			
	d. No. of continuous staircases to terrace	02					
	e. Width of Corridor	NA	NA	NA			
	f. Door Size	01m	1.10m	MR			
3	Compartmentation.						
,		NA	NA	NA			
	Fire check door	NA	NA	NA			
	• Scaling of electrical shafts	NA	NA	NA			
	Fire Rating of shaft doorWater Curtain	NA	NA	NA			
			NA	NA			
	• Fire Dampers	NA	15A				
1	Smoke Management System. NA						
4		12 a/c per hour	No basement	NA			
	Basements	12 a/c per hour	Natural Ventilation	n MR			
	Upper floors						

				1		
	Fotal numbers	04nos	06nos	MR		
	Eypes	ABC/Co2	ABC-06	MR		
	1S1 marking	Yes	Yes	MR		
	First-Aid Hose Reels.					
	Fotal numbers on each floor	NΛ	NA	NA		
	 Length of hose reel hose 	NA	NA	NA		
	Nozzle diameter	ΝΑ		NA		
		NΛ	NA	19/1		
7	Automatic fire detection and alarming system Automatic fire detectors NA NA					
	• Type of detectors	NA	NA	NA		
	Location of Main Panel	NA	NA	NA		
	Location of Repeater Panel					
	Alternate source of power	NA	NA	NA		
	Hooters' Location	NA	NA	NA		
8	MOEFA	Required	Provided	MR		
)	Public Address System.	NA	NA	NA		
10	Automatic Sprinkler System.					
	Basement	NA	NA	NA		
	Upper Floor	NA	NA	NA		
	• Sprinkler above false ceiling	NA	NA	NA		
	•					
11	Internal Hydrants	NA	NA	NA		
	 Size of riser/down-comer Number of hydrants per floor 	NA	NA	NA		
	 Hose Box 	NA	NA	NA		
12	Yard Hydrants.					
12		NA	NA	NA		
	• Total number of hydrants	NA	NA	NA		
	• Hose Box					
13	Pumping Arrangements.					
	Ground Level					
	 Discharge of main Pump 	N/A	N/A	N/A		
	Head of Main pump	N/A	N/A	N/A		
	Number of main pumps	N/A	N/A	N/A		
	Jockey Pump out put	N/A	N/A	N/A		
	Jockey pump head	N/A	N/A	N/A		
	 Standby Pump out put Standby Pump Head 			N/A		
	 Standby Pump Head Auto Starting/ Manual stopping 	N/A	N/A			
	 Auto Starting/ Manual stopping Pump House Access 	N/A	N/A	N/A		
		N/A	N/A	N/A		
	Terrace level					
	 Discharge of pump 	NA	NA	NA		
	Head of the pump	ΝΛ	NA	NA		
	Power Supply	NA	ΝΛ	NA		
	 Auto Starting of pump 	NΛ	ΝΛ	NA		
14	Captive Water Storage for fire fighting.					
	Underground tank capacity	ΝΛ	NA	NA		
	 Draw-off connection 			NA		
		NA	NA			

	Fire service inlet	NΛ	NΛ	NA	
	Access to tank	NΛ	ΝΛ	NΛ NΛ	
	 Overhead Tank capacity 	ΝΑ	ΝΛ	NA	
15	Exit Signage.	Required			
6	Provision of Lifts.	Kequirea	Provided	MR	
	 Pressurization of Lift Shaft 	N/A	N/A	N/A	
	 Pressurization of Lift lobby 	N/A	N/A	N/A	
	Communication In lift Car	N/A	N/A		
	 Fireman's Grounding Switch 		18/73	N/A	
	• Lift Signage	N/A	N/A	N/A	
17	Standburg	N/A	N/A	N/A	
	Standby power supply	N/A	N/A	N/A	
18	Refuge Area.				
	> Total Area	N/A	N/A	N/A	
	> Location	N/A	N/A	N/A	
19	Fire Control Room				
	 Detector System Panel 	, N/A	N/A	N/A	
	 Flow Switch Panel 	N/Λ	N/A	N/A	
	 PA System Panel 	N/A			
	Batter backup		N/A	N/A	
	Building Floor Plans	N/A	N/A	N/A	
20		N/A	N/A	N/A	
20	Special Fire Protection Systems for Protection of special Risks, if any:	N/A	N/A	N/A	

N3

The fire protection systems provided in the building were tested/ checked randomly and found in good working condition, at the time of inspection.

Keeping in view the satisfactory compliance of the minimum standard on fire prevention and fire safety requirements as stipulated under the circular issued by Director of Education dated 01.03.2011, it is recommended to grant Fire Safety Certificate.

Director 5 γ

Signature of the Inspecting Officer Name:- C.L. Meena Designation:- ADO/RN

P.T.O.

Conf.