C55

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEAD QUARTERS; DELHI FIRE SERVICE: NEW DELHI - 110001

No. F6/DFS/MS/2022 /School/ 930

Dated: 3/ / 8 /2022

FIRE SAFETY CERTIFICATE

Issued on 3.1. /. 8.. / 20.2. 2..... at New Delhi

Director Ph:-011-23414000

Copy to: -

- 1. The Director, Education, Government of N.C.T of Delhi. Old Sectt. Delhi 110054.
- 2. The Principal, Upadhyay Convent School located at D-Block, Main Road, Kadi Vihar, Burari, Delhi-110084.

Conditions for the validity of Fire Safety Certificate:

- 1 All the means of escape/entry/exit shall be kept free from any obstruction.
- 2 All the fire safety arrangements provided therein shall be maintained in good working condition at all time as seen during inspection.
- 3 Any loss of life or property due to non-functional fire safety measures shall be at the responsibility of the management.
- 3. All the staff members must know the correct method of operation of firefighting system.
- The owner / occupier shall submit a declaration **every year** in **Form "K"** provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on http://delhi.gov.in./wps/wcm/connect/doit fire/FIRE/Home/Forms.
- This fire safety certificate may not in any way be treated as regularization (Clause 2.8 of UBBL-2016) of unauthorized construction or Alteration (Clause 1.4.3 of UBBL-2016), if any.
- 6 "The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in expiry".

 Form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior to its

INSPECTION REPORT

Name & address of the building

: Upadhyay Convent School at D- Block, Main Road, Kadi Vihar, Near Nathupura Burari, Delhi-110084.

Type of Occupancy 2.

: Educational

Composition of building 3.

: Ground & Three upper floors only

Type of Case 4.

: Add/Alt

Details of previous NOC

Fire Safety directives letter No 6.

: F-6/DFS/MS/2015/School/WZ/974 dated 10.06.2015 (Ground+02 upper floor)

Date of inspection 7.

: 08.08.2022

Name of the Inspecting Officers 8.

: ADO (RN)

Name and designation of officers

from the building side

: Mr. Himanshu Upadhyay

10. Year of Construction

: 2005-2018

Applicant's letter N.

	Minimum Standards on fire prevention and fire safety U/R 33	BBL/NBC Requirements	Provided at site	Remarks MR/NMR		
1	Access to building					
	Road width	6m	6 m	MR		
	Gate width	4.5m	4.5m	MR		
	Width of internal road	NΛ	NA	NA		
2	Number, Width, Type & Arrangement of Exits					
	a. Number of staircases					
	Upper Floors	02	02	MR		
	Basements	NΛ	NA	NA		
	b. Width of staircases					
	Upper Floors	1.50m	1.50m each	MR		
	Basements	NΛ	NA	NA		
	c. Protection of exits					
	Fire check door	NA	NA	NA		
	Pressurization	NA	NA	NA		
	d. No, of continuous staircases to terrace	02	02	MR		
	c. Width of Corridor	NA	NA	NA		
	f. Dogr Size	1 m	Provided	MR		
3	Compartmentation.					
_		NA	NA	NA		
	Fire check doorSealing of electrical shafts	NΛ	NA	NA		
	Scaling of electrical sharts Fire Rating of shaft door	NA	NA	NA		
	• Water Curtain	NA	NA	NA		
	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	NA	NA	NA		
	• Fire Dampers					
4	Smoke Management System.	12 a/c per hour	NA	NA		
	Basements		Natural Ventilation	MR		
	• Upper floors	12 a/c per hour	Natural Ventilation			
_	Fire Extinguishers			MR		
5		11 nos	11 nos	MR		
	• Total numbers	ABC/Co2	ABC-08 / Co2- 03			
	Types	ISI Marked	Yes	MR		
	• 1SI marking	151 Warked				

7	Total numbers on each floorLength of hose reel hose	01	0	1				
7				•				
7	Nozzle diameter	30n	n 301	m				
		5mn	n 5m	m				
,	Automatic fire detection and alarming system. • Type of detectors NA NA							
	Location of Main Panel	NA	IVA					
		NA	NA	N				
	Location of Repeater Panel	NA	NA	N				
	Alternate source of power	NA	NA	N.				
	Hooters' Location	NA	NA	N,				
8	MOEFA	NA	NA	N/				
9	Public Address System.	NA	NA	NA NA				
10	Automatic Sprinkler System.							
	Basement	NA	NA	NA				
	Upper Floor	NA	NA	NA NA				
	Sprinkler above false ceiling	NA	NA	NA				
1	Internal Hydrants							
	Size of riser/down-comer	NA	NA	NA				
	Number of hydrants per floor	NA	NA	NA NA				
	• Hose Box	NA	NA	NA				
2	Yard Hydrants.							
-	Total number of hydrants	NΛ	NA	NA				
	Hose Box	NA	NA	NA				
	- Nose Dox	NA.	NA.	130				
	Pumping Arrangements.			7				
	Ground Level			*				
	 Discharge of main Pump 	N/A	N/A	N/A				
	Head of Main pump			N/A				
	Number of main pumps	N/A	N/A					
	Jockey Pump out put	N/A	N/A	N/A				
	Jockey pump head	N/A	N/A	N/A				
	 Standby Pump out put 	N/A	N/A	N/A				
	 Standby Pump Head 	N/A	N/A	N/A				
	Auto Starting/ Manual stopping	N/A	N/A	N/A				
	Pump House Access	N/A	N/A	N/A				
	Terrace levelDischarge of pump		450lpm	MR				
	Discharge of pump Head of the pump	450lpm	4301pm	MR				
	Power Supply	40m Required	Provided	MR				
	Auto Starting of pump	Required	Provided	MR				
Co	iptive Water Storage for fire fighting							
Ca		NA	NA	NA				
	Underground tank capacity		NA	NA				
	> Draw-off connection	NA NA	NA NA	NA				
	Fire service inlet	NA NA	NA	NA				
	Access to tank		10,000ltrs	MR				
	Overhead Tank capacity	10,000 ltrs	10,000103					

16	Provision of Lifts.				
10					
-	Pressurization of Lift Shaft	N/A	N/A	N/A	
	Pressurization of Lift lobby	N/A	N/A	N/A	
	Communication In lift Car	N/A	N/A	N/A	
	Fireman's Grounding Switch		1377	IN/A	
	Lift Signage	N/A	N/A	N/A	
		N/A	N/A	N/A	
17	Standby power supply	N/A	N/A	N/A	
18	Refuge Area.				
	Total Area	N/A	N/A	N/A	
	> Location	N/A	N/A	N/A	
19	Fire Control Room				
	Detector System Panel	N/A	N/A	N/A	
	Flow Switch Panel	N/A	N/A	N/A	
	PA System Panel				
	Batter backup	N/A	N/A	N/A	
	Building Floor Plans	N/A	N/A	N/A	
	The state of the s	N/A	N/A	N/A	
)	Special Fire Protection Systems for Protection of special Risks, if any:	N/A	N/A	N/A	

The fire protection systems provided in the building were tested/ checked randomly and found in working condition at the time of inspection. The management has complied all the shortcomings issued and communicated by this department vide letter of even no. 3099 dated 19.07.2018.

Keeping in view the satisfactory compliance of the minimum standards on fire prevention and fire safety required as stipulated in NBC Part 4, it is recommended to renewal of fire safety certificate issued vide this department letter of even no. 974 dated 10.06.2015 (ground + 02 upper floors).

DO(NW) - ON CEQUE

Dy ero (WZ)

01

Signature of the Inspecting Officer

Name :-\C.L. Meena Designation:- ADO/RN

24 81 /20n

Directar 1 18/2

Any RM

As approved, F.T. Letter Petup For your singueture Pl.

26/08/20