



GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEAD QUARTERS: DELHI FIRE SERVICE, NEW DELHI

75
अजादी का
अमृत महोत्सव

No. F6/DFS/MS/EH/WZ/2022/ 265

DPA
(-7)
Dated: 16/9/22

FIRE SAFETY CERTIFICATE

Certified that the M/s. **Tim Hortons (A unit of Apparel Gateway Café India Pvt. Ltd.)** Located at **13, Upper Ground Floor, Punjabi Bagh Extn., New Delhi-110026** in a building Comprised of Basements + Stilt + Upper Ground + Three upper floors was inspected by the officers concerned by this department on 12/09/2022 in the presence of Sh. Aswini Arora (Liaison Manager) and found that the said building have complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rule, 2010. And that the premises is fit for occupancy class "**Assembly**" Group D with effect from 16/9/22 for a period of three years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules, 2010. Printed overleaf.

Issued on 16/9/22..... at New Delhi by.


(Atul Gang)
Director
Delhi Fire Service

Copy to:

1. M/s. **Tim Hortons (A unit of Apparel Gateway Café India Pvt. Ltd.)** Located at **13, Upper Ground Floor, Punjabi Bagh Extn., New Delhi-110026**.
2. The Dy. Health Officer, SDMC, West Zone, Vishal Enclave, Rajouri Garden, New Delhi – 110027. dhowestzone@gmail.com

Following fire safety directives must be adhered to:-

1. All the fire safety arrangements provided therein shall be maintained in good working condition at all times.
2. Any loss of life or property due to non-functional fire safety measures shall be at the risk and responsibility of the management.
3. The trained staff should be available round the clock.
4. Any deviations w.r.t. construction shall be verified by the concerned building sanctioning agency.
5. The certificate may not be treated in any case for the regularization of the unauthorized construction, if any.
6. Basement shall be used as per building bye laws.
7. The owner/ occupier shall apply for renewal of this Fire Safety Certificate to the Director in Form 'J' [sub rule (1) of rule 37] along with a copy of this certificate, six months prior to its expiry.
8. The owner/occupier shall submit a declaration every year in the form 'K' provided in the first schedule of Delhi Fire Service Rules 2010, form is available on www.dfs.delhigovt.nic.in.

INSPECTION REPORT

1. Name & address of the building : M/s Tim Hortons (A unit of Apparel Gateway Café India Pvt. Ltd.), 13, Upper Ground Floor, Punjabi Bagh Extn., New Delhi-110026.
 2. Type of Occupancy : Assembly (Restaurant)
 3. Type of Case : New
 4. Details of previous NOC : NIL
 5. Fire Safety directives letter No : NBC (Part-IV)
 6. Date of inspection : 12/09/2022
 7. Name of the Inspecting Officers : DO (West) & ADO (MN)
 8. Name and designation of officers from the building side : Mr. Aswini Arora (Liaison Manager)
 9. Year of Construction : 2015 (As Per MHA Portal)
 10. Applicant's letter No. : Online Application No. 2022081316116 dated 23/08/2022
- * The Said restaurant is located at Upper Ground Floor in a building comprised of Basement + Stilt + Upper Ground + 3 Upper Floors.**

S. No.	Minimum Standards on fire prevention and fire safety U/R 33	BBL /NBC Requirement	Provided at site	Remarks MR/NMR
1	Access to building			
	<ul style="list-style-type: none"> • Road width • Gate width • Width of internal road 	09 mtr	On Main Road	MR
		On Main Road	On Main Road	MR
		NA	NA	NA
2	Number, Width, Type & Arrangement of Exits			
	a. Number of staircases			
	<ul style="list-style-type: none"> • Upper Floors • Basements 	02 NA	03 NA	MR NA
	b. Width of staircases			
	<ul style="list-style-type: none"> • Upper Floors • Basements 	1.50 mtr x 2 NA	1x 2.0 mts, 1x 1.55 mts & 1.5 mts NA	MR NA
	c. Protection of exits			
	<ul style="list-style-type: none"> • Fire check door • Pressurization 	Required NA	Provided NA	MR NA
	e. No. of continuous staircases to terrace	02	Provided	MR
	f. Width of Corridor	NA	NA	NA
	g. Door Size	1.50 mtr x 2	Provided	MR
3	Compartmentation.			
	<ul style="list-style-type: none"> • Fire check door • Sealing of electrical shafts • Fire Rating of shaft door • Water Curtain • Fire Dampers 	NA NA NA NA NA	NA NA NA NA NA	NA NA NA NA NA
4	Smoke Management System.			
	<ul style="list-style-type: none"> • Basements • Upper floors 	NA Required	NA Provided	NA MR
5	Fire Extinguishers			
	<ul style="list-style-type: none"> • Total numbers • Types • IS marking 	12 nos. ABC & CO2 ISI marked	Provided Provided Provided	MR MR MR


ASW

	<ul style="list-style-type: none"> Total numbers on each floor Length of hose reel hose Nozzle diameter 	1	Provided	MR
		30 m	Provided	MR
		5 mm	Provided	MR
7	Automatic fire detection and alarming system.			
	<ul style="list-style-type: none"> Type of detectors Location of Main Panel Location of Repeater Panel Alternate source of power Hooters' Location 	Smoke & Heat	Provided	MR
		Required	Provided	MR
		NA	NA	NA
		Required	Provided	MR
		Required	Provided	MR
8	MOEFA	Required	Provided	MR
9	Public Address System.	NA	NA	NA
10	Automatic Sprinkler System.			
	<ul style="list-style-type: none"> Basement Upper Floor Sprinkler above false ceiling 	NA	NA	NA
		NA	Provided	NA
		NA	NA	NA
11	Internal Hydrants			
	<ul style="list-style-type: none"> Size of riser/down-comer Number of hydrants per floor Hose Box 	100 mm	Provided	MR
		1	Provided	MR
		1	Provided	MR
12	Yard Hydrants.			
	<ul style="list-style-type: none"> Total number of hydrants Hose Box 	NA	NA	NA
		NA	NA	NA
13	Pumping Arrangements.			
	<ul style="list-style-type: none"> Ground Level <ul style="list-style-type: none"> Discharge of main Pump Head of Main pump Number of main pumps Jockey Pump out put Jockey pump head Standby Pump out put Standby Pump Head Auto Starting/ Manual stopping Pump House Access Terrace level <ul style="list-style-type: none"> Discharge of pump Head of the pump Power Supply Auto Starting of pump 	NA	2280 LPM Provided	NA
		NA	70 MH Provided	NA
		NA	01 Provided	NA
		NA	180 lpm Provided	NA
		NA	70 MH Provided	NA
		NA	2280 LPM Provided	NA
		NA	70 MH Provided	NA
		NA	NA	NA
		NA	NA	NA
		450 lpm	Provided	MR
		40 m	Provided	MR
		Required	Provided	MR
		Required	Provided	MR
14	Captive Water Storage for fire fighting.			
	<ul style="list-style-type: none"> Underground tank capacity Draw-off connection Fire service inlet Access to tank Overhead Tank capacity 	NA	1,00,000 Itrs Provided	MR
		NA	NA	NA
		NA	NA	NA
		NA	NA	NA
		5,000 Itrs	Provided	MR
15	Exit Signage.	Required	Provided	MR


16	Provision of Lifts.			
	• Pressurization of Lift Shaft	NA	NA	NA
	• Pressurization of Lift lobby	NA	NA	NA
	• Communication In lift Car	Required	Provided	MR
	• Fireman's Grounding Switch	Required	Provided	MR
	• Lift Signage	Required	Provided	MR
17	Standby power supply	Required	Provided	MR
18	Refuge Area.			
	➤ Total Area	NA	NA	NA
	➤ Location	NA	NA	NA
19	Fire Control Room			
	• Detector System Panel	NA	NA	NA
	• Flow Switch Panel	NA	NA	NA
	• PA System Panel	NA	NA	NA
	• Batter backup	NA	NA	NA
	• Building Floor Plans	NA	NA	NA
20	Special Fire Protection Systems for Protection of special Risks, if any:	NA	NA	NA

The fire protection systems provided in the building were checked and found functional at the time of inspection.

Keeping in view the substantial compliance of the minimum standards on fire prevention and fire safety required under the rules it is recommended to grant Fire Safety Certificate under rule 35 of the Delhi Fire Service Rules 2010 is recommended.


14/9

Signature of the Inspecting Officer
Name: - M. K. Chattopadhyay
Designation: - DO (West)



13/9/2022


Signature of the Inspecting Officer
Name: - Sarabjeet Singh
Designation: - ADO (MN)

DO/WP
13/09/2022


DO (WZ)


14/9/2022


14/9/2022


15/9/2022

