

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEAD QUARTERS: DELHI FIRE SERVICE: NEW DELHI - 110001

No F 6 / DFS / MS / 2022/WZ/Cos/ 426

Dated: 27/09/2022

FIRE SAFETY CERTIFICATE

Certified that the M/s The Beauticity, located at Plot No.B-96, Sec-2,DSI IDC Bawana, Delhi-110039 comprised of Basement+Ground+One upper floor owned/occupied by M/s The Beauticity was issued fire safety certificate vide Letter No. F6/DFS/MS/2019/1772 dated 13/09/2019 have deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and verified by the officer concerned of fire service on 22/09/2022 in the presence of Mrs. Shruti and that the building premise is fit for occupancy under "Class Industrial Building G-2" for Basement-Storage, Ground & First Floor-Industrial Hall with effect from 27/09/2022 for a period of three years in accordance with the rule 36 unless renewed under rule 37 or sooner cancelled under rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules, 2010,

Issued on 27/09/2022 at New Delhi

(Dharampal Bhardwaj)
Dy.Chief Fire Officer
WEST ZONE

ouk

Conditions for the validity of Fire Safety Certificate:

1. Means of escape shall not be kept locked or bolted from outside and shall be easily open able at the time of emergency.
2. All the fire safety arrangement provided there-in shall be maintained in good working conditions at all times.
3. Loss of life or property due to non functional fire safety measure shall be at the responsibility of the management.
4. The trained fire fighting staff should be available round the clock.
5. Any deviation with regard to the construction etc shall be verified by the concerned building sanctioning agency.
6. This certificate cannot be treated in any case for regularizations of unauthorized construction.
7. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director of Form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior to its expiry".
8. The owner / occupier shall submit a declaration every year in form "K" provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on WWW.dfs.Delhigovt.nic.in

Copy to : -

1. M/s The Beauticity, B-96, Sector-2,DSI IDC Bawana , Delhi-39.
2. Dy. Drug controller /licensing authority Govt. of NCT. Of Delhi, Drug Controller Department, F-17, Karkardooma, Delhi-110032.

INSPECTION REPORT

1. Name & address of the building: M/s The Beautycity, Plot No.-B-96, Sector-2, DSIIIDC Bawana Industrial Area, Delhi-39
2. Type of Occupancy : Industrial G-2
3. Building Comprised : **B+Gr.+01 upper floor**
4. Type of Case : Renewal
5. Details of previous NOC : F.6/DFS/MS/2019/1772 Dated- 13/09/2019
6. Fire Safety directives letter No : F.6/DFS/MS/BP/2019/5154 Dated- 23/08/2019
7. Date of inspection : 22.09.2022
8. Name of the Inspecting Officers : ADO, R.K. Sinha
9. Name and designation of officers from the building side : Smt. Shruti
9. Year of Construction : 2015
10. Applicant's letter No. : Nil. Dated-20/09/2022

S. No	Minimum Standards on fire prevention and fire safety U/R 33	NBC Requirement	Provided at site	Remarks MR/NMR
1	Access to building			
	• Road width	06 m	06 m	MR
	• Gate width	4.5 m	Directly Accessible	MR
	• Width of internal road	NA	NA	NA
2	Number, Width, Type & Arrangement of Exits			
	a. Number of staircases			
	• Upper Floors	02	02	MR
	• Basements	02	02	MR
	b. Width of staircases			
	• Upper Floors	1.50m & 1.25 m	1.50 m & 1.27 m	MR
	• Basements	1.50m & 1.25 m	1.50 m & 1.27 m	MR
	c. Protection of exits			
	• Fire check door	Required	Provided	MR
	• Pressurization	NA	NA	MR
	d. No. of continuous staircases to terrace	01	Provided	MR

AS

2-1/

	c. Width of Corridor	1.50 m	Provided	MR
	f. Door Size	1.00m	Provided	MR
3	Compartmentation.			
	• Fire check door	Required	Provided	MR
	• Sealing of electrical shafts	Required	Provided	MR
	• Fire Rating of shaft door	NA	NA	NA
	• Water Curtain	NA	NA	NA
	• Fire Dampers	N/A	N/A	N/A
4	Smoke Management System.			
	• Basements	30a/c per hour	Exhaust Fan Provided	MR
	• Upper floors	12a/c per hour	Exhaust Fan Provided	MR
5	Fire Extinguishers			
	• Total numbers	08 nos	12 nos	MR
	• Types	ABC	ABC	MR
	• IS marking	Required	Yes	MR
6	First-Aid Hose Reels.			
	• Total numbers on each floor	01	Provided	MR
	• Length of hose reel hose	30m	Provided	MR
	• Nozzle diameter	5mm	Provided	MR
7	Automatic fire detection and alarming system.			
	• Type of detectors	NA	NA	NA
	• Location of Main Panel	NA	NA	NA
	• Location of Repeater Panel	NA	NA	NA
	• Alternate source of power	NA	NA	NA
	• Hooters' Location	NA	NA	NA
8	MOEFA	NA	NA	NA
9	Public Address System.	NA	NA	NA
10	Automatic Sprinkler System.			
	• Basement	Required	Provided	MR

gn

N-12

MR
R

	<ul style="list-style-type: none"> • Upper Floor • Sprinkler above false ceiling 	Required NA	Provided NA	MR NA
11	Internal Hydrants			
	<ul style="list-style-type: none"> • Size of riser/down-comer • Number of hydrants per floor • Hose Box 	NA NA NA	100 mm 01 01	NA NA NA
12	Yard Hydrants.			
	<ul style="list-style-type: none"> • Total number of hydrants • Hose Box 	NA NA	NA NA	NA NA
13	Pumping Arrangements.			
	<ul style="list-style-type: none"> ➤ Ground Level ➤ Discharge of main Pump ➤ Head of Main pump ➤ Number of main pumps ➤ Jockey Pump out put ➤ Jockey pump head ➤ Standby Pump out put ➤ Standby Pump Head ➤ Auto Starting/ Manual stopping ➤ Pump House Access • Terrace level <ul style="list-style-type: none"> ➤ Discharge of pump ➤ Head of the pump ➤ Power Supply ➤ Auto Starting of pump 	NA NA NA NA NA NA NA NA NA NA 450 lpm 40 m Required Required	NA NA NA NA NA NA NA NA NA NA Provided Provided Provided Provided	NA NA NA NA NA NA NA NA NA NA MR MR MR MR
14	Captive Water Storage for fire fighting.			
	<ul style="list-style-type: none"> • Underground tank capacity ➤ Draw-off connection ➤ Fire service inlet ➤ Access to tank • Overhead Tank capacity 	NA NA NA NA 10,000 ltrs	NA NA NA NA Provided	NA NA NA NA MR

Handwritten signature

		Required	Provided	MR
15	Exit Signage.			
16	Provision of Lifts.			
	• Pressurization of Lift Shaft	NA	NA	NA
	• Pressurization of Lift lobby	NA	NA	NA
	• Communication In lift Car	NA	NA	NA
	• Fireman's Grounding Switch	NA	NA	NA
	• Lift Signage	NA	NA	NA
17	Standby power supply	NA	Provided	NA
18	Refuge Area.			
	➤ Total Area	NA	NA	NA
	➤ Location	NA	NA	NA
19	Fire Control Room			
	• Detector System Panel	NA	NA	NA
	• Flow Switch Panel	NA	NA	NA
	• PA System Panel	NA	NA	NA
	• Batter backup	NA	NA	NA
	• Building Floor Plans	NA	NA	NA
20	Special Fire Protection Systems for Protection of special Risks, if any:	NA	NA	NA

The fire protection systems provided in the building were tested/ checked randomly and found functional at the time of inspection.

Keeping in view the deemed compliance of the minimum standard on fire prevention and fire safety required under the rules, the FSC issued vide letter no. F6/DFS/MS/2019/1772 dated 13/09/2019 is recommended for renewal of Fire Safety Certificate under rule 35 of the Delhi Fire Service Rules 2010

(Signature)
 ADO(BW)
 23/9/22

Signature of the Inspecting Officer
 Name: - Rajeev Kumar Sinha
 Designation-ADO/BW

~~Do (NB) on 20/11~~

~~DT (FB) (W2)~~

(Signature)
 26/9/2022

~~ADO/BW~~ F T letter is out for sign please

(Signature)
 ADO(BW)
 26/9/22

~~DT (FB) (W2)~~

(Signature)
 27/9/2022

msf ccf