

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI-110001

ान्य आज़ादी वर अमृत महोत्सव

F6/DFS/MS/GH/SZ/2022/ UU)

Dated: 26/9/2012

FIRE SAFETY CERTIFICATE

Certified that the M/s Rajput Guest House located at 22-A, Nangli Razapur Nizamuddin East, New Delhi-13, comprised of Ground + 03 upper floors: Ground floor- reception + 01 guest room, 1st floor - 03 guest rooms, 2nd floor - 03 guest rooms, 3rd floor - 03 rooms (private use) total 07 guest rooms was granted FSC by this department vide letter no. F6/DFS/MS/GH/2019/SZ/2082 dated 30.10.2019. The building/premises was re-inspected by Assistant Divisional Officer (M. Road) from this department on 09.09.2022 in presence of Mr. Roshan Lal (Manager) and found that the building is comprised of Ground + 04 upper floors: Ground floor- reception + 01 guest room, 1st floor - 03 guest rooms, 2nd floor- 03 guest rooms, 3rd floor - 03 rooms (private use), 4th floor- 01 room (Sealed). The building has deemed complied with the fire prevention and fire safety requirements in accordance with Rule 33 of Delhi Fire Service Rules, 2010 and the owner has submitted an affidavit on 17.09.2022 not to use any floor above third floor for any purpose in accordance with clarification of Gazette Notification dated 27.05.2019. Accordingly, the premises is fit for occupancy of "Residential Sub Division-A-1" for total 07 guest rooms (Ground floor- reception + 01 guest room, 1st period of three years in accordance with Rule 36 unless renewed under Rule 37 or sooner cancelled under Rule 40 and subject to conditions under Rule 38 of Delhi Fire Service Rules, 2010 printed below.

(Sunil Chawdhary)

Dy. Chief Fire Officer Delhi Fire Service

Copy to:-

- 1. The Joint Commissioner of Police (Licensing), 1st Floor, Police Station Defence Colony, New Delhi: w.r. to online I.D. no. 2022082616651 dated 26.08.2022.
- 2. The Licensee, M/s Rajput Guest House located at 22-A, Nangli Razapur Nizamuddin East, New Delhi-13.

Conditions for the validity of Fire Safety Certificate

- 1. All the fire safety arrangements provided therein shall be maintained in good working condition at all times
- 2. Any loss of life or property due to non functional fire safety measures shall be at the responsibility of the management.
- 3. The trained fire fighting staff should be available round the clock.
- 4. Any deviation w.r.t. construction etc. shall be verified by the concerned building sanctioning authority.
- 5. This fire safety certificate may not be treated in any case for regularization of unauthorized construction, if any.
- 6. The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in.
- 7. Basement shall be used as per NBC/UBBL
- 8. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in form 'J' [sub Rule (I) of Rule 37] along with a copy of this Certificate, six month prior to its expiry. Any change in the occupancy shall be intimated to this Deptt. and approval shall be obtained thereto before occupancy of the same.

- 1				CTION	REPORT				
-	Name & address of the building			Raza	M/s Rajput Guest House located at 22-A, Nangli Razapur Nizamuddin East, New Delhi-13.				
	Building is comprised of			Grou	ınd + 04 uppe	r floors			
				Grou	Ground floor- reception + 01 guest room				
				1 st flo	oor - 03 guest i	rooms			
				2"d f1	oor- 03 guest i	ooms			
	•				3 rd floor - 03 rooms (private use)				
	Type of occupancy				4th floor- 01 room (Sealed)				
	Type of case				Residential Group A-1				
;					Renewal F6/DFS/MS/GH/2019/SZ/2082 dated 30.10.2019				
<u>'</u>	Details of Previous FSC Fire Safety direction letter no.				FS/MS/GH/20	19/SZ/2082 dated	1 30.10.2019		
				Nil					
_	Date of inspection			_	9.2022				
3			ne inspecting officers			da ADO (M. Roa	d)		
)	Name of the designation of officer			Mr. l	Roshan Lal (Ma	anager)			
	from the building side								
10			nstruction	2006					
11	Appl	icant	's letter no.	Onli	ne application	no. 2022082	2616651 date		
				26.0	8.2022				
S.I		inim	Standards on mic	Req	uirement as	Provided at	Remarks		
0	Pr	even	tion and fire safe <u>t</u> y	/ per !	Rule 35 (6)	Site	MR/NMR		
	re	quire	ments U/R 33						
1	Ac	ccess	to building						
	A	R	oad width	6.0	mtrs	6.0 mtrs	MR		
	В	G	ate width	N/	١	NA	NA		
	C		idth of internal road	N/		NA	NA .		
2	Nı		r, Width, Type and Arrang	gement	of Exits				
	Α	ı	lumber of staircases		161				
		a	Upper floor		no.	01 no.	MR		
		b	Basement	N/	4	NA	NA		
	В		Width of staircases						
		a	Upper floor	Re	quired	0.90 mtrs	MR (old		
		b	Basement	N	<u> </u>	27.4	case)		
	C		otection of exits	N/	1	NA	NA		
		a	Fire check door	N.	A	NA	NA		
		b	Pressurization	N.		NA NA	NA NA		
		N	o. of continuous staircases		no.	01 no.	MR		
	D								
		te	тасе						
	D E	ter	idth of corridor	N	A	NA	NA		
	E F	W De	idth of corridor oor size		A 0 mtrs	NA 1.10 mtrs (final exits)	NA MR		
3	E F	ter W De	idth of corridor oor size			1.10 mtrs			
3	E F C	ter W De ompa	idth of corridor oor size artmentation e check door	1.	0 mtrs	1.10 mtrs (final exits)			
3	E F C A B	ter W De omps Fir Sea	oor size artmentation e check door aling of electrical shafts	1. N	0 mtrs	1.10 mtrs (final exits)	MR		
3	E F C A B	ompa Fir Sea	artmentation e check door aling of electrical shafts e rating of shaft door	1. N N N	0 mtrs A A	1.10 mtrs (final exits)	MR NA		
3	E F C A B C	ompa Sea	idth of corridor oor size artmentation e check door aling of electrical shafts e rating of shaft door atter curtain	1. N N N	0 mtrs A A A A	1.10 mtrs (final exits)	NA NA		
	E F C A B C D E	ompa Fir Sea Fir Wa	artmentation e check door aling of electrical shafts e rating of shaft door atter curtain e dampers	1. N N N	0 mtrs A A	1.10 mtrs (final exits) NA NA NA	NA NA NA		
3	E F C A B C D E	ompa Fir Sea Fir Wa Fir	artmentation e check door aling of electrical shafts e rating of shaft door atter curtain e dampers Management System.	I. N N N N N	O mtrs A A A A A A	1.10 mtrs (final exits) NA NA NA NA NA	NA NA NA NA		
	E F C A B C D E So	ompa Fir Sea Fir Wa Fir Moke	idth of corridor oor size artmentation e check door aling of electrical shafts e rating of shaft door atter curtain e dampers Management System. sement	1. N N N N N N N N N N N N N N N N N N N	O mtrs A A A A A A A A	1.10 mtrs (final exits) NA NA NA NA NA NA NA NA	NA NA NA NA		
	E F C A B C D E	ompa Fir Sea Fir Wa Fir Moke	artmentation e check door aling of electrical shafts e rating of shaft door atter curtain e dampers Management System.	I. N N N N N N N N N N N N N N N N N N	O mtrs A A A A A A	1.10 mtrs (final exits) NA NA NA NA NA NA NA	NA NA NA NA NA		

5.	Fir	e E	xtinguisher					
	A	Tot	al numbers	06 nos.	07 nos.	MR		
	В	Typ	K.2	CO2 & ABC	CO, & ABC	MR		
	C	181	marking	Required	1SI marked	MR		
6	First-Aid-Hose Reels							
	A	Tot	al numbers of each floor	01 no.	01 no.	MR		
	В		gth of hose reel hose	30 mtrs.	30 mtrs.	MR		
	C		zle diameter	5 mm	5 mm	MR		
7	4							
	Automatic Fire Detection And Alarming System (required as per clause 7.31 UBBL 2016).							
	A	-	pe of detectors	CO detectors	Provided	MR		
	В		cation of main panel	At ground floor	Provided	MR		
	C	Lo	ocation of repeater panel	NA	NA	NA		
	D	-	ternate source of power	NA	NA	NA		
	E	-	ooters	Audible in entire building	Provided	MR		
8	M	OEF	A	Required	Provided	MR		
9	Pu	blic	Address System.	NA	NA	NA		
10	Au	tom	atic Sprinkler System.		The second to the second party of the second p			
	A	Bas	sement	NA	NA	NA		
	В	Up	per floor	NA	NA	NA		
	C	Spr	rinkler above false ceiling	NA	NA	NA		
11	Internal Hydrants							
	A	size	e of riser/down-comer	NA	NA	NA		
	B Number of hydrants per floor			NA	NA	NA		
	C Hose box			NA	NA	NA		
12	Ya	rd I	lydrants.	,				
	A	Tot	tal number of hydrants	NA	NA	NA		
	B Hose box			NA	NA	NA		
13	Pumping Arrangements.							
	A		Ground Level			-		
		a	Discharge of main Pump	NA	NA	NA		
		b	Head of Main Pump	NA	NA	NA		
		c	Number of main pumps	NA	NA	NA		
		d	Jockey pump out put	NA	NA	NA		
		e	Jockey pump head	NA	NA NA	NA NA		
		f	Standby pump out put	NA	NA NA	NA		
		g	Standby pump Head	NA NA	NA NA	NA		
		h	Auto Starting /Manual	INA				
		i	Stopping Pump house access	NA	NA	NA		
	В		errace Level			NAD		
		a	Discharge of pump	450 LPM	450 LPM	MR		
		b	Head of the Pump	40 mtrs.	40 mtrs.	MR		
		c	Power supply	Required	Provided	MR MR		
		d	Auto starting of pump	Required Razapur Nizamuddin, Ne	Provided	IVIIC		

M s Basera Guest House located at 22-A, Nangli Razapur Nizamuddin, New Delhi-13

M/s Basera Guest House located at 22-A, Nangli Razapur Nizamuddin, New Delhi-13

14	Captive Water Storage for Fire Fighting.							
	A Underground tank capacity	NA	NA	NA				
	B Draw-off connection	NA	NA	NA				
	C Fire service inlet	NA	NA	NA				
	D Access to tank	NA	NA	NA				
	E Overhead tank capacity	25,00 ltrs	5,000 ltrs	MR				
15	Exit Signage.	Required	Provided	MR				
16	Provision of Lifts.							
	A Pressurization of lift shaft	NA	NA	NA				
	B Pressurization of lift lobby	NA	NA	NA				
	C Communication in lift car	NA	NA	NA				
	D Firemen's grounding switch	NA	NA _.	NA				
	E Lift signage	NA	NA	NA				
17	Standby Power Supply	Required	Provided (Inverter)	MR				
18	Refuge Area.							
	A Total area	NA	NA	NA				
	B Location	NA	NA	NA				
19	Fire Control Room							
	A Detector system panel	NA	NA	NA				
	B Flow switch panel	NA	NA	NA				
	C PA system panel	NA	NA	NA				
	D Battery backup	NA	NA	NA				
	E Building floor plans	NA	NA	NA				
20	Special Fire Protection Systems For	NA	NA _.	NA				
	Protection Of Special Risks, If Any:							

Meeting Requirement (MR), Not Meeting Requirement (NMR), Not Applicable (NA), Provided but Not Functional (PNF), Not Provided (NP).

The fire protection systems provided in the building were tested, checked at random and found functional at the time of inspections.

The owner has submitted an affidavit on 17.09.2022 not to use any floor above third floor for any purpose in accordance with clarification of Gazette Notification dated 27.05.2019

In view of the deemed compliance of minimum standards of fire prevention and fire safety measures as required under the Rules, the FSC issued vide letter no F6/DFS/MS/GH/2019/SZ/2082 dated 30.10.2019 is recommended to be renewed under Rule 37 of the Delhi Fire Service Rules 2010.

Dy. CFO (SZ)

fî is put up pls

22/9/22

Signature of the Inspecting Officer
Name Rajesh Kumar Shukla
Designation ADO (M. Road)

A OS (MRV)

M.S. W

Isc uploaded when 28/9/