



GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEAD QUARTERS: DELHI FIRE SERVICE: NEW DELHI – 110001

No.F6/DFS/MS/EH/NDZ/2022/ 272

Dated: 23/09/2022

FIRE SAFETY CERTIFICATE

Certified that the **Singla Sweets** located at **A-139, 140 A, 32A, A31, Madhu Vihar, Delhi-110092** comprised of **Basement + Ground + 02 Upper floors and temporary shed at terrace floor, Basement (Storage), Ground floor (Restaurant/sweet shop), 1st floor & 2nd floor (office/store), and temporary shed at terrace floor. (Restaurant running at ground floor only)** owned/occupied by **Singla Sweets** have complied with the fire prevention and fire safety requirements in accordance with Rule 33 of Delhi Fire Service Rule, 2010 and verified by the officers concerned of this department on **18/08/2022** in the presence of Mr. Harish Singla (Owner) and found that the building/premises is fit for occupancy class "**Assembly**" (**Group D**)/ **Eating House**, with effect from ~~23/9/22~~-----for period of **three years** in accordance with Rule 36 unless renewed under Rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under Rule 38 of the Delhi Fire Service Rules, 2010 printed below.

Issued ~~23/9/22~~-----at New Delhi by.


(Anil Darg)
Director
Delhi Fire Service

Copy to:-

1. The Deputy Commissioner (Licensing),
1st Floor, Police Station Defence Colony, New Delhi.
Online application ID no. 2022070614137.
2. The Manager,
Singla Sweets,
A-139, 140 A, 32A, A31, Madhu Vihar, Delhi-110092.

Condition for the validity of fire safety certificate

- 1 Fire Safety Certificate is valid for ground floor only.
- 2 All the fire safety arrangements provided therein shall be maintained in good working conditions at all times.
- 3 Any loss of life or property due to non functional fire safety measures shall be at the responsibility of the management.
- 4 The trained fire fighting staff should be available round the clock.
- 5 Any deviation w.r.t. construction etc. shall be verified by the concerned building sanctioning authority.
- 6 This fire safety certificate may not be treated in any case for regularization of unauthorized construction, if any.
- 7 The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in
- 8 The means of escape shall be kept unobstructed / unlocked for unhindered evacuation in case of an emergency.
- 9 The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in form 'J' [sub rule (I) of rule 37] along with a copy of this Certificate, six month prior to its expiry".
- 10 Any flammable material for interior decoration is prohibited.



N/15

INSPECTION REPORT

1	Name & address of the building	Singla Sweets A-139, 140 A, 32A, A31, Madhu Vihar, Delhi-110092		
2	Type of Occupancy	Assembly Building (Restaurant) B + Gr. + 02 upper floors and temporary shed at terrace floor, Basement (Storage), Ground floor (Restaurant/sweet shop), 1 st floor & 2 nd floor (office/store), and temporary shed at terrace floor (Restaurant running at ground floor only)		
3	Type of Case	New Case		
4	Details of previous FSC	N/A		
5	Fire Safety directives Letter No.	N/A		
6	Date of inspection	18.08.2022		
7	Name of the Inspecting Officer	Sh. A.K. Jaiswal (DO/ED) & Sh. Manoj Kumar Sharma (ADO/LN)		
8	Name and Designation of Officer from the building side	Mr. Harish Singla (Owner)		
9	Year of Construction	2008		
10	Applicant's letter No./ Online Id No.	2022070614137 dated 07.07.2022		
Sr. No.	Minimum Standards on Fire Prevention and Fire Safety U/R 33	Requirements	Provided at Site	Remarks MR/NMR
1	Access to Building			
	1 Road Width	09 mtr.	12 mtr. ✓	MR
	2 Gate Width	N/A	N/A	N/A
	3 Width of Internal Road	N/A	N/A	N/A
2	Number, Width, Type & Arrangements of exits			
	A Number of Staircase			
	1 Upper Floors	N/A	N/A	N/A
	2 Basement	N/A	N/A	N/A
	B Width of Staircase			
	1 Upper Floors	N/A	N/A	N/A
	2 Basement	N/A	N/A	N/A
	C Protection of Exits			
	1 Fire Check door at Gr. floor	Required	Provided	MR
	2 Pressurization	N/A	N/A	N/A
	D No. of Continuous S/C to terrace	N/A	N/A ✓	N/A
	E Width of Corridor	N/A	N/A	N/A
	F Door Size	2 x 1.5 mtr.	01 nos. 2.0 mtr., 01 nos. 1.5 mtr., 02 nos. 1.0 mtr.	MR
3	Compartmentation			
	1 Fire check door	N/A	N/A	N/A
	2 Sealing of electrical shafts	N/A	N/A	N/A
	3 Fire rating of shaft door	N/A	N/A	N/A
	4 Water curtain	N/A	N/A	N/A
	5 Fire Dampers	N/A	N/A	N/A

Me



7/16

75
Azadi Ka
Amrit Mahotsav

4	Smoke Management System			
	1 Basements	N/A	N/A	N/A
	2 Upper floors	12 a/c per hour	Natural	MR
5	Fire Extinguishers			
	1 Total Numbers	06 Nos.	08 Nos.	MR
	2 Types	ABC & CO2	ABC & CO2	MR
	3 ISI Marking	Required	Provided	MR
6	First-Aid Hose Reel			
	1 Total number Gr. floor	02	02	MR
	2 Length of hose reel hose	30 mtr.	30 mtr.	MR
	3 Nozzle diameter	05 mm	05 mm	MR
7	Automatic Fire Detection & Alarming System			
	1 Type of detectors	N/A	N/A	N/A
	2 Location of main panel	N/A	N/A	N/A
	3 Location of repeater panel	N/A	N/A	N/A
	4 Alternate source of power	N/A	N/A	N/A
	5 Hooter's Location	N/A	N/A	N/A
8	MOEFA			
		Required	Provided	MR
9	Public Address System			
		N/A	N/A	N/A
10	Automatic Sprinkler System			
	1 Basement	N/A	Provided	N/A
	2 Upper floors	N/A	N/A	N/A
	3 Sprinkler above false ceiling	N/A	N/A	N/A
11	Internal Hydrants			
	1 Size of riser/down-comer	100 mm	100 mm	MR
	2 Number of hydrants per floor	01 nos.	01 nos.	MR
	3 Hose box	01 nos.	01 nos.	MR
12	Yard Hydrants			
	1 Total number of hydrants	01	02	MR
	2 Hose box	01	02	MR
13	Pumping Arrangement			
	A Ground level			
	1 Discharge of main pump	N/A	N/A	N/A
	2 Head of main pump	N/A	N/A	N/A
	3 Number of main pump	N/A	N/A	N/A
	4 Jockey pump out put	N/A	N/A	N/A
	5 Jockey pump head	N/A	N/A	N/A
	6 Stand by pump output	N/A	N/A	N/A
	7 Stand by pump head	N/A	N/A	N/A
	8 Auto starting/Manual stopping	N/A	N/A	N/A
	B Terrace level			
	1 Discharge of pump	450 LPM	450 LPM	MR
	2 Head of pump	40 mtr.	40 mtr.	MR
3 Power supply	Required	Provided	MR	
4 Auto starting of pump	Required	Provided	MR	
14	Capacity of Water Storage for Fire Fighting			
	1 Underground tank capacity	N/A	N/A	N/A
	2 Draw-off connection	N/A	N/A	N/A
	3 Fire service inlet	N/A	N/A	N/A
	4 Access to tank	N/A	N/A	N/A

Mw 4/19

75 Azadi Ka Amrit Mahotsav

N/A

MR

MR

MR

MR

MR

MR

MR



	5 Over head tank capacity	20,000 ltr.	20,000 ltr.	
15	Exit Signage.	Required	Provided	MR
16	Provision of Lifts.			MR
	1 Pressurization of lift shaft	N/A	N/A	N/A
	2 Pressurization of lift lobby	N/A	N/A	N/A
	3 Communication in lift car	N/A	N/A	N/A
	4 Fireman's switch	N/A	N/A	N/A
	5 Lift signage	N/A	N/A	N/A
17	Stand by Power Supply	Required	Provided	MR
18	Refuge Area	N/A	N/A	N/A
	Total area location	N/A	N/A	N/A
19	Fire Control Room	N/A	N/A	N/A
	1 Detector system panel	N/A	N/A	N/A
	2 Flow switch panel	N/A	N/A	N/A
	3 PA system panel	N/A	N/A	N/A
	4 Battery backup	N/A	N/A	N/A
	5 Building floor plan	N/A	N/A	N/A
20	Special Fire Protection System for Protection of special Risk, if any:			N/A

➤ Earlier observation were issued for whole building as the application received through online MHA portal. Now application received for ground floor only which is meeting requirement.

The fire protection systems provided in the building were randomly tested, checked and found functional at the time of inspection and fire fighting system is common.

Keeping in view the substantial compliance of the minimum standards on fire prevention and fire safety required under the rules, grant of fire Safety Certificate under rule 35 of the Delhi Fire Service Rules 2010 is recommended please.

Mush
 Signature of the Inspection Officer
 Name :- M.K. Sharma
 Designation:- ADO/LN

A.K. Jaiswal
 Signature of the Inspection Officer
 Name :- A.K. Jaiswal
 Designation:- DO/ED

Dy. CFO (NDZ) Rimp
 24/08/22

C.F.O. Please clarify the software status.

Vijay
 31/8/2022

Dy CFO (NDZ) Rimp
 04/09/22

DO (ED) Rimp
 05/09/2022

ADO/L.N.

Mush

(P.FO)