

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE, NEW DELHI-110001

1-8

Dated: 0 3 / 10 /2022 No.F.6/DFS/MS/2022/NDZ/ School / 1104

FIRE SAFETY CERTIFICATE

Certified that the St. Krishna Bodh Public School located at A-84, Gali No.-14, Mandoli Road West Nathu Colony, Shahdara, Delhi-110093, building comprised of Stilt, Ground plus three upper Floors only owned / occupied by St. Krishna Bodh Public School, was issued FSC vide letter No. F6/DFS/MS/School/2018/NDZ/648 Dated 10/04/18. The School building was reinspected by the officer concerned of this department on 23/09/2022 in presence of Mr. Nidhish Bhardwaj and observed that all the fire prevention and fire safety arrangements provided in the premises found in good working condition. The premises have therefore deemed complied with the rule 33 of the Delhi Fire Service rules 2010 and found that the building is fit for occupancy class "Educational" (Group-B) with effect from 03/1 to 12022 for a period of three years in accordance with rule 36 unless renewal under rule 37 or sooner cancelled under rule 40 and subject to compliance of the conditions under rule 38 of the DFS rule 2010.

Issued on 03 10 2022 at New Delhi by.

(S.K. DUA) ¹ ¹ DY. CHIEF FIRE OFFICER DELHI FIRE SERVICE.

Copy to :-

- 1. The Principal, St. Krishna Bodh Public School, A-84, Gali No.-14, Mandoli Road West Nathu Colony, Shahdara, Delhi-110093.
- 2. Director of Education, Govt. of NCT of Delhi, Old Secretariat, Delhi-110054.

Conditions for the validity of Fire Safety Certificate:

- 1. All the fire safety arrangement provided their in shall be maintained in good working conditions at all times.
- 2. Loss of life or property due to non-functional fire safety measure shall be at the responsibility of the management.
- 3. The trained fire fighting staff should be available round the clock.
- 4. Any deviation with regard to the construction etc shall be verified by the concerned building sanctioning agency.
- 5. This certificate cannot be treated in any case for regularizations of unauthorized construction.

6. "The owner / Occupier shall apply for renewal of this Fire Safety Certificate to the Director in Form 'J' [sub rule (1) of rule37] along with a copy of this Certificate, six months prior to its expiry".

7. The owner / occupier shall submit a declaration every year in form "K" provided in the first schedule of Delhi Fire Service Rules 2010. The from is available on <u>WWW.dfs.Delhigovt.nic.in</u>.



INSPECTION REPORT

- 1. Name & address of the building: St. Krishna Bodh Public School, A-84, Gali No.-14, Mandoli Road West Nathu Colony, Shahdara, Delhi-110093. : Stilt, Ground + 3rd Floor only (H-14.86m)
- 2. Building is comprised of
- 3. Type of Occupancy
- 4. Type of Case
- : Educational
- : Renewal : F6/DFS/MS/School/2018/NDZ/648 Dated 10/04/18

N/05

- 5. Details of previous NOC
- 6. Fire Safety directives Letter No.: NBC (Part-IV) 7. Date of inspection : 23/09/2022
- 8. Name of the Inspecting Officer : A.K. Jaiswal, D.O. (E.D.)
- 9. Name and designation of Officer : Mr. Nidhish Bhardwaj from the building side 10. Year of Construction : 2009
- 11. Applicant's letter received through email ID-skbpublicschool@gmail.com dated 12/09/22

S	Minimum standards on fire	Circular	Provided at	Remarks MR/NMR		
No	prevention and fire safety U/R 33	Requirements	Site			
1.	Access of building					
	Road width	6 mtr	8 mtr	MR		
	Gate width	N/A	N/A	N/A		
	Width of internal road	N/A	N/A	N/A		
2.	Number, width, Type & Arrangements of exits					
	a. Number of staircases					
	Upper floors	2 2		MR		
	Basements	N/A N/A		N/A		
	b. Width of staircases) (D (011		
	Upper floors	1.50 m	1.50 m & 1.25 m	MR (Old Excepted)		
	Basements	N/A	N/A	N/A		
	c. Protection of exits					
	Fire check door	N/A	N/A	N/A		
	Pressurization	N/A	N/A	N/A		
	d. No of continuous staircase to terrace	02 nos.	02 nos.	MR -		
	e. Width Of Corridor	1.5 m	2.00 m	N/A		
	f. Door Size	1.00 m	1.00 m	MR		
3.	Compartmentation					
	Fire check door	N/A	N/A	N/A		
	 Sealing of electrical shafts 	N/A	N/A	N/A		
	Fire Rating of shaft door	N/A	N/A	N/A		
	Water Curtain	N/A	N/A	N/A		
	Fire Dampers					
4.	Smoke managements System					
	Basements	N/A	N/A	N/A		
	Upper floors	N/A	N/A	N/A		
5.	Fire Extinguishers					
	Total numbers	10 nos.	12 nos.	MR _		
	• Types	ISI marked ABC/CO ₂	Provided	MR		
	IS marking	Required	Provided	MR		

	1					
6.	First – Aid Hose Reels					
	• Total numbers on each floor	01 nos.	01 nos.	MR		
	• Length of hose reel hose	30 mtrs.	30 mtrs.	MR		
	Nozzle diameter	05 mm	05 mm	MR		
7.	Automatic fire detection and alarming system					
	• Type of detector	N/A	N/A	N/A		
	• Location of Main Panel	N/A	N/A	N/A		
	• Location of Repeater Panel	N/A	N/A	N/A		
	• Alternate source of power	N/A	N/A	N/A		
	Hooters' Location	N/A	N/A	N/A		
	MOEFA	N/A	Provided	N/A		
	Public Address System	N/A	Provided	N/A		
0.	Automatic Sprinkler System					
	• Basements	N/A	N/A	N/A		
	 Upper Floor 	N/A	N/A	N/A		
	• Sprinkler above false ceiling	N/A	N/A	N/A		
1.	Internal Hydrants					
	 Size of riser/down- comer 	100 mm	100 mm	MR		
	• Number of hydrants	2	2			
2	per floor		2	MR		
_	Hose Box	2	2	MR		
2.	Yard Hydrants					
	 Total number of hydrants 	N/A	N/A	N/A		
-	Hose Box	N/A	N/A	N/A		
3.	Pumping Arrangements					
•	Ground Level					
•	Discharge of main pump	N/A	N/A	N/A		
	Head of main pump	N/A	N/A	N/A		
	Number of main pumps	N/A	N/A	N/A		
	Jockey pump out put	N/A	N/A	N/A		
	Jockey pump head	N/A	N/A	N/A		
	 Standby Pump out put Standby Pump Head 	N/A	N/A	N/A		
		N/A	N/A	N/A		
	 Auto Staring/Manual stopping Pump House Access 	N/A	N/A	N/A		
	Terrace level	N/A	N/A	N/A		
	 Discharge of pump 	450.000		/		
	 Head of the pump 	450 LPM	450 LPM	MR		
	 Power supply 	40 m	40 m	MR		
	 Auto starting of pump 	Required	Provided	MR		
14.		Required	Provided	MR		
	 Underground tank capacity Draw of connection 	N/A	N/A	N/A		
	 Fire service inlet 	N/A	N/A	N/A		
	 Access to tank 	N/A N/A	N/A	N/A		
	Overhead Tank capacity	10,000 ltr	N/A Provided	N/A		
15.	Exit Signage.	Required	Provided / Provided	MR MR		
		Ŕ				

NDO

N107

71	-	-	
1 .		-	
Aza	di		
	Man	otsav	/

16.	Provision of Lifts.				
	Pressurization of Lift Shaft	N/A	N/A	N/A	
	Pressurization of lift lobby	N/A	N/A	N/A	
	Communication in lift Car	N/A	N/A	N/A	
	Fireman's Grounding Switch	N/A	N/A	N/A	
	 Lift Signage 	N/A	N/A	N/A	
17.	Standby power supply	N/A	N/A	N/A	
18.	Refuge Area				
	Total area	N/A	N/A	N/A	
	> Location	N/A	N/A	N/A	
19.	Fire control room				
	Detector system panel	N/A	N/A	N/A	
	 Flow Switch Panel 	N/A	N/A	N/A	
	 PA System Panel 	N/A	N/A	N/A	
	 Battery backup 	N/A	N/A	N/A	
	 Building Floor Plans 	N/A	N/A	N/A	
20.	Special Fire Protection Systems for Protection of special Risks, if any;	N/A	N/A	N/A	

The fire protection systems provided in the building were tested, checked and found functional at the time of inspection.

Keeping in view of the deemed compliance of the minimum standards of fire prevention and fire safety measures as required under the rules, The Fire Safety Certificate issued vide letter no. F6/DFS/MS/School/2018/NDZ/648 Dated 10/04/18 renewal under the rule 35 of the Delhi Fire Service rules 2010 is recommended.

Signature of the Inspecting Officer

Name : Ashok Kumar Jaiswal Designation : D.O. (East Division)

F.T. please.

- is added \$

BZL