

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE, CONNAUGHT PLACE

NEW DELHI- 110001

No.F.6/DFS/MS/EH/2022/SZ/ 378

FIRE SAFETY CERTIFICATE

Certified that the M/s Dough and Cream Pvt. Ltd. running at ground floor only in a building comprised of ground plus three upper floors located at C-3/13, Janakpuri, New Delhi-110058, owned/occupied by M/s Dough and Cream Pvt. Ltd have complied with the fire prevention and fire safety requirements in accordance with the Rule 33 of the Delhi Fire Service Rule 2010 and verified by the officers concerned of this department on 07/09/2022 in the presence of Sh. Gaurav and found that the building is fit for occupancy 'Class D "Assembly Building" (Restaurant) at ground floor only with effect from 03. [10. 2022] for a period of three years in accordance with the Rule 36 unless renewed under Rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under Rule 38 of the Delhi Fire Service Rules, 2010, printed below.

Issued on 03/10/2022 at New Delhi by

Director

Dated: 03/10/2022

Delhi Fire Service

295

To,

M/s Dough and Cream Pvt. Ltd, C-3/13, Janakpuri, New Delhi -110058

Copy to:-

The Joint Commissioner of Police, Licensing Unit, First Floor, Police Station, Defence Colony, New Delhi.

Following fire safety directives must be adhered to:-

- · This NOC is valid only for ground floor only.
- The owner /occupier shall apply for renewal of this fire safety certificate to the Director in form J' [sub rule (1) of rule 37] along with a copy of this certificate, six months prior to its expiry.
- All the means of escape shall be kept free of all the type of obstruction all the time.
- All the employees shall be acquainted with the use and maintenance of all fire equipments and method of smooth and speedy safe evacuation of occupants in case of emergency.
- All the fire fighting equipments shall be maintained in perfect working condition all the time and any lapse rendering non-functional of fire safety measures, management shall be responsible.
- The clarification with regards electrical installation, ventilation, structure stability set back areas, occupancy and constructional deviation in building etc. may be got verified from the authorities concerned.
- This Fire Safety Certificate cannot be treated in any case for regularizations of unauthorized construction unauthorized use of land if any.
- The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rule 2010. The form is available on www.dfs.delhigovt.nic.in

Name & address of the building : M/s Dough and Cream Pvt. Ltd., C-3/13,

Janakpuri, New Delhi -110058.

Building is comprised of : Ground plus three upper floors (Eating house

running at ground floor only)

Type of Occupancy : Assembly (Eating)

Type of Case : New

5. Details of Previous NOC letter : Nil

6. Fire Safety direction letter No : NBC Part-IV

7. Date of Inspection : 07/09/2022

8. Name of the Inspecting officers : ADO R.K. Yadav & D.O Vedpal Chhikara

9. Name and designation of Officer

from the building side : Mr. Gaurav

10. Year of Construction : 2000

11. Applicant's letter No : ID No. 2022031003370 Dated 10/08/2022

r. lo.	Minimum Standards on Fire Prevention and Fire Safety U/R33	Requirement	Provided at Site	Remarks MR/NMR				
1	Access to Building.							
+	Road width	06 mtr.	06 mtr.	MR				
	Gate width	N/A	N/A	N/A				
	Width of internal road	N/A	N/A	N/A				
)2	Number, Width, Type and Arrangement of Exits.							
	a. Number of Staircases							
	 Upper floor 	N/A	N/A	N/A				
	 Basement 	N/A	N/A	N/A				
	B. Width of Staircases							
	 Upper floor 	N/A	N/A	N/A				
	Basement	N/A	N/A	N/A				
	c. Protection of Exits							
	Fire check door	N/A	N/A	N/A				
	Pressurization	N/A	N/A	N/A				
	d. No. of Continuous Staircases to Terrace	N/A	N/A	N/A				
	e. Width of Corridor	N/A	N/A	N/A				
	f. Door Size	1.5 m each	1.5 m (2 No's)	MR				
3	Compartmentation.							
	Fire check door	N/A	N/A	N/A				
	 Sealing of electrical shafts 	N/A	N/A	N/A				
	 Fire rating of shaft door 	N/A	N/A	N/A				
	Water curtain	N/A	N/A	N/A				
	 Fire dampers 	N/A	N/A	N/A				
1	Smoke Management System.							
	Basement	N/A	N/A	N/A				
	Upper floor	N/A	N/A					
5.	Fire Extinguishers.							
	Total numbers	04 nos.	04 nos.					
	 Types 	ABC /CO ₂		MI				
	• IS marking	TIDE /CO)	Provided	MI				

06	First-Aid-Hose Reels.							
	Total numbers on each floor	01 No.	Provided	T				
	 Length of hose reel hose 	30 mtr.	Provided	MR				
	 Nozzle diameter 	05 mm	Provided	MR				
07	Automatic Fire Detection and Alarming Sy		Provided	MR				
-	• Type of detectors							
	 Location of main panel 	N/A	Provided	MR				
	Location of repeater panel	N/A	N/A	N/A				
	Alternate source of power	N/A	N/A	N/A				
	Hooter's location	N/A	N/A	N/A				
08	MOEFA	Required	N/A	N/A				
09	Public Address System.	N/A	Provided	MR				
10	Automatic Sprinkler System.	14/74	N/A	N/A				
	•							
	Basement upper floor	N/A	N/A	N/A				
		N/A	N/A	N/A				
11	sprinkler above false ceiling Internal Hydronese	N/A	N/A	N/A				
1 1	Internal Hydrants							
	 size of riser/down-comer 	100 MM	Provided	MR				
	 Number of hydrants per floor 	01 No.	Provided	MR				
	Hose box	01 No.	Provided	MR				
2	Yard Hydrants.		Trovided	IVII				
	 Total number of hydrants 	N/A	N/A	NI/A				
	 Hose box 	N/A	N/A	N/A N/A				
3	Pumping Arrangements.		IVA	IN/A				
	> Ground Level							
	Discharge of main pump	N/A	N/A	NI/A				
	 Head of Main pump 	N/A	N/A	N/A				
	 Number of main pumps 	N/A	N/A	N/A				
	 Jockey pump out put 	N/A	N/A	-				
	Jockey pump head	N/A	N/A	N/A				
	Standby pump out put	N/A	N/A	N/A				
	Standby pump head	N/A	N/A	N/A				
	Auto starting /manual stopping	N/A		N/A				
	Pump house access	N/A	N/A	N/A				
	> Terrace Level	IVA	N/A	N/A				
	Discharge of pump	450 Lpm.	Duo.: 1 - 1	1 10				
	Head of the pump	40 M	Provided	MR				
	Power supply	Required	Provided	MR				
	Auto starting of pump	Required	Provided	MR				
+	Captive Water Storage for Fire Fighting.	Required	Provided	MR				
+	_							
	Underground tank capacityDraw-off connection	N/A	N/A	N/A				
		N/A	N/A	N/A				
	• Fire service inlet	N/A	N/A	N/A				
	• Access to tank	N/A	N/A	N/A				
+	Overhead tank capacity Exit Signage.	20,000 Ltrs.	Provided	MR				
		Required	Provided	MR				
	Provision of Lifts.							
	Pressurization of lift Shaft	N/A	N1/A	1				
	Pressurization of lift lobby	N/A	N/A	N/A				
	Communication in lift car	N/A	N/A	N/A				
	Firemen's grounding switch	N/A N/A	N/A	N/A				
	Lift signage	N/A N/A	N/A	N/A				
	U B-	IN// \	N/A	N/A				



NIS

17	Standby Power Supply	N/A	N/A	N/A
18	Refuge Area. • Total area • Location	N/A N/A	N/A N/A	N/A N/A
20	Detector system panel Flow switch panel PA system panel Battery backup Building floor Plans Special Fire Protection Systems for Protection of Special Risks, if any:	N/A N/A N/A N/A N/A	N/A N/A N/A N/A N/A N/A	N/A N/A N/A N/A N/A N/A

The fire protection systems provided in the building were tested/checked and found functional at

the time of inspection.

Keeping in view the compliance of the minimum standards on fire prevention and fire safety required under the rules it is recommended to grant Fire Safety Certificate under Rule 35 of the Delhi Fire Service Rule 2010.

The total covered area of the eating house at GF is 185 sq. meters. As per Part-IV, NBC-2016, Total the number of persons will come Approx. 103 (185 / 1.8 = 103) for

the restaurant.

Signature of the Inspecting Officer
Name :-R.K.Yadav

Name :-R.K.Yadav Designation:-ADO (JKP) Signature of the Inspecting Officer Name :- Vedpal Chhikara Designation:-D.O (South West)

ec

Derector (South More)

12/1

Line of 2/1

Derector of (21) 27 & 9 014 Para occupation of 2/1

There of 3992 is not all flow by all flow by

TA