

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEAD QUARTERS: DELHI FIRE SERVICE: NEW DELHI - 110001

No. F6/DFS/MS/EH/2022/237チ

Dated: 03/10/2022

FIRE SAFETY CERTIFICATE

Certified that the M/s Moh Maya Café (A Unit of World Food Art) located at Property No. 2527, Ground Floor & First floor, Hudson Line, Kingsway Camp, Delhi- 110009 in the building comprised of basement, ground & 03 upper floors only owned/occupied by M/s Moh Maya Café (A Unit of World Food Art) was issued Fire Safety Certificate by this department vide letter no. F6/DFS/MS/2019/1100 dated 22.05.2019. The premises was re-inspected by the officers concerned of this department on 26.09.2022 in the presence of Sh. Navnit Singh and found the building have deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and building/ premise is fit for occupancy "Class D" Assembly (Restaurant) for Ground & first floor only occupancy with effect from 03/10.1.20.22 for a period of 03 (Three) years in accordance with rule 36 unless renewed under rule '37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules, 2010.

Issued on 0.3/10/2022... at New Delhi by

(Dharampal Bhardwaj) Dy. Chief Fire Officer Ph.-011-23414250

Copy to:-

1. M/s Moh Maya Café (A Unit of World Food Art) located at Property No. 2527, Ground Floor & First floor, Hudson Line, Kingsway Camp, Delhi- 110009

Conditions for the validity of Fire Safety Certificate:

- 1. All the fire safety arrangement provided there-in shall be maintained in good working conditions at all times.
- 2. Loss of life or property due to non functional fire safety measure shall be at the responsibility of the management.
- 3. The trained fire fighting staff should be available round the clock.
- 4. Any deviation with regard to the construction etc shall be verified by the concerned building sanctioning agency.
- 5. This certificate cannot be treated in any case for regularizations of unauthorized construction.
- 6. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director of Form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior to its expiry".
- 7. The owner / occupier shall submit a declaration every year in form "K" provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on WWW.dfs.Delhigovt.nic.in
- 8. All the means of escape shall be kept free of any obstruction all the time to evacuate the occupant, in a safe manner, in the event of emergency.

INSPECTION REPORT

1. Name & address of the building

: Moh Maya Café at 2527, GF & FF, Hudson Lane, Kingway Camp, Delhi-09.

2. Type of Occupancy

: Restaurant (Assembly)

3. Composition of building

: Basement, ground+03 upper floors (Restaurant running at Ground & First

First upper floor only)

4. Type of Case

Renewal

5. Details of previous NOC

: F6/DFS/MS/2019/1100 dated:22.05.2019

6. Fire Safety directives letter No

: Nil

7. Date of inspection8. Name of the Inspecting Officers

: 26.09.2022

9. Name and designation of officers

from the building side

: Mr. Navnit Singh (Owner)

10. Year of Construction

: Since 1980

: ADO (RN)

11. Applicant's letter No.

: Online MHA Portal I'd No.2022091017372 dated 12.09.2022

	Minimum Standards on fire preventing fire safety U/R 33	ntion and UBBL/NBC Requirement	Provided at site	Remarks MR/NMR
1	Access to building			
	Road width	6m	06m	MR
	Gate width	5m	Directly Accessible	MR
	Width of internal road	NA	NA	NA
2	Number, Width, Type & Arrangeme	nt of Exits	•	
	a. Number of staircases			
	Upper Floors	01	02	MR
	• Basements	. NA	NA	NA
	b. Width of staircases		1.50 0.00	MD (ald ages
	Upper Floors	1.50m	1.50m & 90cm	MR (old case)
	• Basements	NA	NA	NA
	c. Protection of exits			NA
	Fire check door	NA	NA	NA
	 Pressurization 	NA	NA	NA
	d. No. of continuous staircases to terrace	NA	NA	NA
	e. Width of Corridor	NA	NA	NA
	f. Door Size	02m each	Provided	MR
	Compartmentation.			
	Fire check door	NA	NA	NA
	Sealing of electrical shafts	NA	NA	NA
	• Fire Rating of shaft door	NA	NA	NA
	Water Curtain	NA	NA	NA
	• Fire Dampers	NA	NA	NA
S	moke Management System.			
- 51	Basements	12 a/c per hour	NA	NA
	Upper floors	12 a/c per hour	Exhaust fan	MR
	Fire Extinguishers			
-	Total numbers	08nos	08nos	MR



_		/
Com	~ 4 /	
-		

	• Types	ABC & Co2	ABC-08	MR			
	ISI marking	Yes	Yes	MR			
	First-Aid Hose Reels.						
-	Total numbers on each floor	01	01	MR			
	 Length of hose reel hose 	30m	30m	MR			
		5mm	5mm	MR			
	Nozzle diameter						
	Automatic fire detection and alarming system.						
	Type of detectors	NA	Provided	NA			
	 Location of Main Panel 	NA	NA	NA			
	 Location of Repeater Panel 	NA	NA	NA			
	 Alternate source of power 	NA	NA	NA			
	 Hooters' Location 	NA	NA	NA			
+	MOEFA	Required	Provided	MR			
	Public Address System.	Required	Provided	MR			
	Automatic Sprinkler System.						
	• Basement	NA	NA	NA			
	Upper Floor	NA	Provided	NA			
	Sprinkler above false ceiling	NA	NA	NA			
	Internal Hydrants						
	Size of riser/down-comer	100mm	100mm	MR			
	Number of hydrants per floor	01	01	MR			
	Hose Box	01	01	MR			
2	Yard Hydrants.						
	Total number of hydrants	NA	NA	NA			
	Hose Box	NA	NA	NA			
3	Pumping Arrangements.						
	Ground Level						
	Discharge of main Pump	N/A	N/A	N/A			
	Head of Main pump	N/A	N/A	N/A			
	Number of main pumps	NA	NA	NA			
	Jockey Pump out put	NA	NA	NA			
	> Jockey pump head	N/A	N/A	N/A			
	> Standby Pump out put	N/A	N/A	N/A			
	Standby Pump HeadAuto Starting/ Manual stopping	N/A	N/A	N/A			
	> Pump House Access	N/A	N/A	N/A			
	Terrace level	·					
	Discharge of pump	450 LPM	450 LPM	MR			
	> Head of the pump	40m	40m	MR			
	Power Supply	Required	Provided	MR			
14	Auto Starting of pump Captive Water Storage for fire fighting.	Required	Provided	MR			
17							
	Underground tank capacity	NA	NA	NA			
	Draw-off connectionFire service inlet	NA	NA	NA			
	Fire service injet	NA	NA	NA			

	> Access to tank	NA	NA			
			1874	NA		
	Overhead Tank capacity	10000 LTR	Provided	MR		
5	Exit Signage.	Required	Provided	MR		
16	Provision of Lifts.					
	Pressurization of Lift Shaft	N/A	N/A	N/A		
	Pressurization of Lift lobby	N/A	N/A	N/A		
	Communication In lift Car	NA	NA	NA		
	Fireman's Grounding Switch	NA	NA	NA		
	Lift Signage	NA	NA	NA		
17	Standby power supply	Required	Provided	MR		
18	Refuge Area.					
	> Total Area	N/A	N/A	N/A		
	Location	N/A	N/A	N/A		
19	Fire Control Room					
	Detector System Panel	N/A	N/A	N/A		
	Flow Switch Panel	N/A	N/A	N/A		
	PA System Panel	N/A	N/A	N/A		
	Batter backup	N/A	N/A	N/A		
	Building Floor Plans	N/A	N/A	N/A		
20	Special Fire Protection Systems for Protection of special Risks, if any:	NA	NA	NA		

The fire protection systems provided in the building were tested/ checked and found in working condition at the time of inspection. The observations/ shortcomings issued and communicated vide this department letter of even no.525 dated.10.08.2022 have been compiled by the management.

Keeping in view of the substantial compliance of the minimum standards on fire prevention and fire safety required under the rules it is recommended to renew Fire Safety Certificate under rule 37 of the Delhi Fire Service Rules 2010.

Signature of the Inspecting Officer

Name :- C.L. Meena

Designation:- ADO/RN

Singuature Pl.