## GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: CONNAUGHT PLACE NEW DELHI-110 001. SOME (Pusiness / 2022/57/ カッ 8 Dated: っつ/し) 20 トニ

No.F.6/DFS/MS/Business/2022/SZ/ 44 8

FIRE SAFETY CERTIFICATE

Certified that the Vishwa Sadan Building, Plot No. 09, District Centre, JanakPuri, New Delhi-110058, comprised of basement, ground floor, upper ground & eight upper floors owned/occupied by Niagara Hotels & Builders Pvt. Ltd. was issued NOC for occupancy of the building by this department vide letter No. F6/DFS/MS/92/1030 dated 02/06//1992. The building was re-inspected by the officers concerned of this department on 20/09/2022 in the presence of Mr. T.N.Singh (Manager) and found that the management have deemed complied with the fire prevention and fire safety requirements in accordance with Rule 33 of the Delhi Fire Service Rules, 2010 and that the building/ premises is fit for occupancy class "Business" w.e.f. the date of issue of this certificate for a period of three years in accordance with Rule 36 unless renewed under Rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under Rule-38 of the Delhi Fire Service Rules, 2010 printed as below.

Issued on at New Delhi.

Director
Delhi Fire Service

Copy to:-

1. The Manager, Vishwa Sadan Building, Plot No. 09, District Centre, JanakPuri, New Delhi-110058.

## Following fire safety directives must be adhered to:-

- All the fire safety arrangements provided therein shall be maintained in good working condition at all times.
- 2. The means of escape shall be kept unlocked and unobstructed for unhindered evacuation of occupants in case of emergency.
- 3. Any loss of life or property due to non-functional fire safety measures shall be at the risk and responsibility of the management.
- 4. The trained staff should be available round the clock.
- 5. Any deviations w.r.t. construction shall be verified by the concerned building sanctioning agency.
- 6. The certificate may not be treated in any case for the regularization of the unauthorized construction, if any.
- 7. Basement shall be used as per the building bye laws.
- 8. The owner/occupier shall submit a declaration every year in the form 'K' provided in the first schedule of Delhi Fire Service Rules 2010, form is available on www.dfs.delhigovt.nic.in.
- 9. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in the Form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior to its expiry.

N/56 INSPECTION REPORT Name & address of the building: Vishwa Sadan Building, Plot No. 09, District Centre, Janak Puri, Building comprised of Basement, ground floor, upper ground & eight upper floors. Type of Occupancy Mixed (Mercantile & Business) Type of Case Renewal Details of Previous NOC F.6/DFS/MS/ 92/1030 Fire Safety directives letter No dated 02/06/1992 F6/DFS/MS/87/397 dated 01/04/1987 Date of inspection Name of Inspecting Officers 20/09/2022 A.D.O. R.K.Yadav & DO Vedpal Chhikara Name and designation of officers From the building side Sh. T.N.Singh (Manager) 0. Year of Construction 1987 👖. Applicant's letter No. Minimum Standards on fire prevention : Nil dated 07/09/2022 S. No. Requirement and fire safety U/R 33 Provided at site Access to building Remarks MR/NMR Road width Accessible Gate width 12 m Width of internal road MR Required Provided MR N/A N/A Number, Width, Type & Arrangement of Exits N/A a. Number of staircases Upper Floors Basements Three Provided MR Two & ramp Width of staircases Provided MR Upper Floor 1.35,1.33 & 1.07 m Basements Provided MR old case 1 30 m, 1.0 m & 2.5 m 1 30 m. 1.0 m & 2.5 c. Protection of exits MR old case ramp m ramp Fire check door Required Provided MR

N/A

Three

N/A

1.0 m

Required

Required

02 hrs.

NIA

N/A

Required Required

	<ul><li>Pire check door</li><li>Pressurization</li></ul>
d.	No. of continuous staircases to terrace
	Wild a

	terrace
e.	Width of Corridor
f.	Door Size
	mpartmentation

١.

2.

3.

4.

5.

•	Fire check door
•	Sealing of electrical shafts
•	Fire Rating of shaft door
•	Water Curtain

	•	Fire Dampers
Sr	noke	Management System
	•	Basements

	•	Upper floors
Fi	re Ex	tinguishers

C E	xunguishers
•	Total numbers
•	Types
	10

• Types	04 no 's at each floor
• IS marking	W/CO <sub>2</sub> / CO <sub>2</sub> /ABC type
	ISI marked
	,

D	VIK	
Provided	MR	
N/A N/A	N/A N/A	
Provided	MR	
Natural ventilation provided	MR	

 $N/\Lambda$ 

Provided

N/A

1.0 m

Provided

Provided

N/A

MR

N/A

MR

MR

MR

Provided MR Provided MR d Provided MR

6.	First-Aid Hose Reels	One	Provided	MR -
	Total numbers on each floor		1	MR
	<ul> <li>Length of hose reel hose</li> </ul>	30 m	Provided	MR
	<ul> <li>Nozzle diameter</li> </ul>	5 mm	Provided	, viii
_	Automatic fire detection and alarming sy	stem in electrical installa	tions	MR
7.	Type of detectors	Required smoke & heat	Provided	MR
	Location of Main Panel	Required	G. Floor	N/A
	Location of Repeater Panel	N/A	N/A	MR
	<ul> <li>Alternate source of power</li> </ul>	Required	Provided	MR
	<ul> <li>Hooters' Location</li> </ul>	Required	Provided	MR
		Required	Provided	MR
8.	MOEFA Public Address System	Required	Provided	
9.	Automatic Sprinkler System			
10.	Automatic Sprinner System		Provided	MR
	Basement	Required	N/A	N/A
	Ground Floor	N/A	1	N/A
	<ul> <li>Sprinkler above false ceiling</li> </ul>	N/A	N/A	
11.	Internal Hydrants			5.413
		150 MM	Provided	MR MR
	Size of riser/down-comer	Onc	Provided	MR
	<ul> <li>Number of hydrants per floor</li> </ul>	One	Provided	VIIC
	<ul> <li>Hose Box</li> </ul>	l	1	
12.	Yard Hydrants	2 Nos.	Provided	MR
	<ul> <li>Total number of hydrants</li> </ul>	Dagwired	Two	MR
	Hose Box	is sommon for Vishwa S	Sadan & Vishwa Deep s	ituated at
13.	Hose Box     Pumping Arrangements ( Pump house)	e is common to: Visiting	· ·	
i i	Vishwa Deep.			
	<ul> <li>Ground Level</li> <li>Discharge of main Pump</li> </ul>	2850 LPM	Provided	MR
	<ul><li>Discharge of main Pump</li><li>Head of Main pump</li></ul>	90 m	Provided	MR
	Number of main pumps	Two	Provided	MR
	Jockey Pump out put	180 LPM	Provided	MR
	Lockey pump head		Provided	MR
	<ul> <li>Standby Pump out put</li> </ul>	40 m	Provided	MR
	Standby Pump Head	2850 LPM		MR
	Auto Starting/Manual	90 m	Provided	MR
	Stopping	Required	Provided	MR
	Pump House Access	Required	Provided	VIIK
	Terrace level		1	N/A
	Discharge of pump	N/A	N/A	N/A
	Head of the pump	N/A	N/A N/A	N/A
	> Power Supply	N/A	N/A	>/^
1	Auto Starting of pump	N/A	18/74	1
14	. Captive Water Storage for fire fight	ing	Provided	MR
i	<ul> <li>Underground tank capacity</li> </ul>	3,58,190 ltrs.		MR
	Draw-off connection	Required	Provided	1
	Fire service inlet	Required	Provided	MR
	Access to tank	Required	Provided	MR
	<ul> <li>Overhead Tank capacity</li> </ul>	63000 Ltrs	Provided	MR
1		Required	Provided	MR
1	5. Exit Signage.	1	1	



6.	Prevision of Lifts  Pressurization of Lift Shaft  Pressurization of Lift lobby  Communication In lift Car  Fireman's Grounding Switch  Lift Signage	N/A N/A Required Required	N/A N/A Provided Provided	N/A N/A MR MR
17.	Standby power supply	Required	Provided	MR
18.	Refuge Area.	-		MR
	<ul><li>Total Area</li><li>Location</li></ul>	Required	Provided	MR
		4 <sup>TH</sup> & 6 <sup>TH</sup> Floor	Provided	MR
19.	Fire Control Room			
	Detector System Panel     Flow Switch Panel	Required	Provided	MR
	PA System Panel	N/A	N/A	N/A
	<ul> <li>Battery backup</li> </ul>	Required	Provided	MR
	Building Floor Plans	Required	Provided	MR
		N/A	N/A	N/A
20.	Special Fire Protection System for Protection of special Risks, if any:	N/A	N/A	N/A

The fire protection systems provided in the building were tested, checked and found functional at the time of inspection. The shortcomings issued vide letter No. F6/DFS/MS/2022/SZ/1270 dated 03/06/2022 has been complied.

In view of the deemed compliance of the minimum standards of fire prevention and fire safety measures as required under the rules the NOC issued vide letter number F6/DFS/MS/92/1030 dated 02/06/2992 renewal under Rule 37 of the Delhi Fire Service Rules 2010 is recommended.

Signature of Inspecting Officer

Name:-R.K.Yadav

Designation:-Asstt.Divisional Officer

Signature of Inspecting Officer

Name:- Vedpal Chhikara

Designation:- Divisional Officer

Dy. C.F.O. (South Zone)

30 91

 $\frac{30}{9}$ 

Folk The

ADD SHP