GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELIII HEAD QUARTERS, DELHI FIRE SERVICE, NEW DELHI - 110001

No.F6/DFS/MS/GH/NDZ/2022/ 459

FIRE SAFETY CERTIFICATE

Certified that the M/s Anchal Guest House located at 2923, Gali No.4, Chuna Mandi, Pahar Ganj, New Delhi comprised of Ground + 03 Upper floors, Ground floor - Shops, 1st floor (02 guest rooms + Reception + Office) 2nd floor (03 guest rooms) & 3rd floor (01 guest rooms), total was earlier granted by this department vide rooms. **FSC** The No.F6/DFS/MS/GH/NDZ/2019/2024 dated 21/10/19, for 06 rooms only. Now, the premises was reinspected by the officer concerned of this department on 27/09/22 in the presence of Manager and found that the said guest house building have deemed complied with the fire prevention and fire safety requirements in accordance with Rule 33 of the Delhi Fire Service Rules, 2010 and that the premiers is fit for occupancy class Residential, (Sub Division-A-1), 1st floor(02 guest rooms + Reception + Office), 2nd floor (03 guest rooms), & 3rd floor (01 guest rooms), total 06 guest rooms up to third floor only, with effect from for period of three years in accordance with Rule 36 unless renewed under Rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under Rule 38 of the Delhi Fire Service Rules 2010, printed below.

Dy. Chief Fire Or cer Delhi Fire Se vice

Dated: .7..//.0/2022

Copy to:-

- 1. The Commissioner, MCD, Civic Centre, New Delhi: to ensure the occupancy as detailed at we.
- 2. The Addl. Commissioner of Police (Lic), First Floor, P.S. Defence Colony New Delhi Online id no. 2022090517111 dated 05.09.2022.
- 3. The Manager, M/s Anchal Guest House, 2923, Gali No.4, Chuna Mandi, Pahar Ganj, New Delhi.

Conditions for the validity of Fire Safety Certificate

- 1. All the fire safety arrangements provided therein shall be maintained in good working conditions at all times
- 2. Any loss of life or property due to non functional fire safety measures shall be at the responsibility the management.
- 3. The trained fire fighting staff should be available round the clock.
- 4. Any deviation w.r.t. construction etc. shall be verified by the concerned building sanctioning authors of
- 5. This fire safety certificate may not be treated in any case for regularization of unauthorized constructions.
- 6. The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Dell Lire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in
- 7. The means of escape shall be kept unobstructed / unlocked for unhindered evacuation in case of an emerging
- 8. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in form 'I' [of rule 37] along with a copy of this Certificate, six month prior to its expiry.
- 9. Any flammable material for interior decoration is prohibited.

INSPECTION REPORT

M/s Anchal Guest House located at 2923, Gali 1. Name & address of the building No.4, Chuna Mandi, Pahar Ganj, New Delhi

Type of occupancy:-Residential, Sub Division-A-1

Ground + 03 Upper floors,(total 06 guest rooms) Ground floor - Shops, 1st floor(02 guest rooms + Reception + Office) 2nd floor (03 guest rooms) &

3rd floor (01 guest rooms),

3. Type of case:-Renewal

F6/DFS/MS/GH/NDZ/2019/2024 dated 4. Details of previous FSC:-

21/10/19.

N/A 5. Fire safety directives No.-

27/09/22 6. Date of inspection:-

Sh. Ravinder Singh (ADO/CC) 7. Name of the inspecting officer:-

8. Name & designation of officer

Manager From the building side:-2009

9. Year of construction:-Online id no. 2022090517111 dated 05.09.2022. 10. Applicant's letter No:-

10.	Applicant's letter No:-	Online id no	. 2022030317111	Old Case
S.No.	Minimum Standards on fire Prevention and fire safety U/R 33	Requirement Existing	Provided at site	Remarks MR/NMR
1.	Access to Building) (D
	1) Road width	N/A	6 mtr.	MR
	2) Gate width	N/A	N/A	N/A
	3)Width of internal road	N/A	N/A	N/A
2	Number, Width Type & Arr	angement of E	xits	
2.	A. Number of staircases) (D)
	1. Upper floors	01 Nos.	01 Nos.	MR
	2. Basements	N/A	N/A	N/A
	B. Width of staircase) (D
	1. Upper floors	80cms.	97 cms.	MR
	2. Basements	N/A	N/A	N/A
	C. Protection of exits		1221	N/A
	1. Fire check door	N/A	N/A	N/A
	2. Pressurization	N/A	N/A	N/A
	D. No. of continuous	N/A	N/A	IN/A
	staircase to terrace		N7/4	N/A
	E. Width of corridor	N/A	N/A	MR
	F. Door size	1 mtr.	1 mtr.	IVIK
3.	Compartmentation			N/A
3.	1) Fire check door	N/A	N/A	N/A
	2) Sealing of electrical shafts	N/A	N/A	N/A
	3) Fire rating of shaft door	N/A	N/A	N/A N/A
	4) Water curtain	N/A	N/A	N/A
	5) Fire Dampers	N/A	N/A	IN/A
4.	Smoke Management System	Tag + CDII	N/A	N/A
	1) Basements	30 ACPH	N/A Natural	MR
	2) Upper floors	12 ACPH	Ivaturai	
5.	Fire Extinguishers	06 Nag	06 Nos.	MR
J.	1) Total numbers	06 Nos.	00 1403.	

M/1~

	2) Types	ABC & CO2	ABC & CO2	MR
	3) ISI marking	Required	Provided	MR
6.	First-Aid Hose Reel			
	1) Total number of eachfloor	01	01	MR
	2) Length of hose reel hose	30 mtr.	30 mtr.	MR
	3) Nozzle diameter	05 mm	05 mm	MR
7.	Automatic Fire Detection &	Alanmina Suat	05 11111	IVIK
	1) Type of detectors CO	Dequired	Provided	1 1 1
	2) Location of main panel	Required Ground floor		MR
	3) Location of repeater panel	N/A	Provided	MR
	4) Alternate source of power		N/A	N/A
	5) Hooter's Location	Required	Provided	MR
8.		Each floor	Provided	MR
9.	MOEFA	N/A	N/A	N/A
9. 10.	Public Address System	Required	Provided	MR
10.	Automatic Sprinkler System			
	1) Basement	N/A	N/A	N/A
	2) Upper floors	N/A	N/A	N/A
	3) Sprinkler above false	N/A	N/A	N/A
11	ceiling			
11.	Internal Hydrants			
	1) Size of riser/down-comer	N/A	N/A	N/A
	2) Number of hydrants per	N/A	N/A	N/A
	floor			
	3) Hose box	N/A	N/A	N/A
12.	Yard Hydrants			
	1) Total number of hydrants	N/A	N/A	N/A
	2) Hose box	N/A	N/A	N/A
13.	Pumping Arrangement			
	Ground level	N/A	N/A	N/A
	a) Discharge of main pump	N/A	N/A	N/A
	b) Head of main pump	N/A	N/A	N/A
	c) Number of main pump	N/A	N/A	N/A
	d) Jockey pump out put	N/A	N/A	N/A
	e) Jockey pump head	N/A	N/A	N/A
	f) Stand by pump output	N/A	N/A	N/A
	g) Stand by pump head	N/A	N/A	N/A
	h) Auto starting/Manual stopping	N/A	N/A	N/A
	2) Terrace level			
	a) Discharge of pump	225 LPM	225 LPM	MR
	b) Head of pump	30 mtr.	30 mtr.	MR
	c) Power supply	Required	Provided	MR
		Required	Provided	MR
	d) Auto starting of pump Captive Water Storage for Fi		1	1
14	1) Under ground tank capacity	N/A	N/A	N/A

N	1	3
,		>

		411	<	
	a) Draw-off connection			
	b) Fire service inlet	N/A	N/A	N/A
	c) Access to tank	N/A	N/A	N/A
	d) Over head tank capacity	N/A	N/A	N/A
15.	Exit Signage.	2500 ltr.	2500 ltr.	MR
16.	Provision of Lifts.	Required	Provided	MR
	a) Pressurization of lift shaft	N/A	N/A	N/A
	b) Pressurization of lift lobby	N/A	N/A	N/A
	c) Communication in lift car	N/A	N/A	N/A
	d) Fireman's switch	N/A	N/A	N/A
17.	e) Lift signage	N/A	N/A	N/A
	Stand by Power Supply	Required	Provided	MR
18.	Refuge Area	N/A	N/A	N/A
	Total area location	N/A	N/A	N/A
19.	Fire Control Room	N/A	N/A	N/A
	a) Detector system panel	N/A	N/A	N/A
	b) Flow switch panel	N/A	N/A	N/A
	c) PA system panel	N/A	N/A	N/A
	d) Battery backup	N/A	N/A	N/A
	e) Building floor plan	N/A	N/A	N/A
20.	Special Fire Protection System i	for Protection	n of special Risk, if	N/A

The fire protection systems provided in the guest house building were randomly tested, checked and found functional at the time of inspection.

In view of the deemed compliance of the minimum standards of fire prevention and fire safety measures as required under the rules, if approved, we may renew the FSC issued vide letter no. F6/DFS/MS/GH/NDZ/2019/2024 dated 21/10/19, up to third floor only under rule 35 of the Delhi Fire Service rules 2010. Accordingly, DFA is put up for kind perusal and signature please.

Signature of the Inspecting Officer

Name: - Ravinder Singh

Designation: - ADO (CC)