

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEAD QUARTERS: DELHI FIRE SERVICE: NEW DELHI - 110001

No.F6/DFS/MS/GH/2022/ 457

Dated 7/19/2022

FIRE SAFETY CERTIFICATE

Certified that the M/s N. K. North Star (A Unit of Parivar Infratech Pvt. Ltd.) Premises No. F-36, Kamla Nagar, Delhi-110007 located at upper ground, first, second & third floor having 16 guest rooms only in a building comprised of basement, stilt, upper ground & 03 upper floors owned/ occupied by M/s N. K. North Star (A Unit of Parivar Infratech Pvt. Ltd.) was issued fire safety certificate vide letter no. F6/DFS/MS/2019/2001 dated 18.10.2019. The premises was re-inspected by the officer concerned of Fire Service on 28.09.2022 in the presence of Sh. Ravi (Manager) and observed that all the fire prevention & fire safety arrangements as provided in the premises found in good working condition The premises have therefore, deemed complied with the requirement under rule 33 of Delhi Fire Service Rules, 2010 and the building is fit for occupancy Class Group A-1 Residential (Rooming & Lodging) for upper ground & three upper floors with total 16 guest rooms only with effect from -7-4+-04-2-2 for a period of 03 (Three) years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi

Issued on7/19/.2.2... at New Delhi by

(Dharampal Bhardwaj) Dy. Chief Fire Officer Ph:-011-23414250

Copy to:-

1. The Owner, M/s N. K. North Star (A Unit of Parivar Infratech Pvt. Ltd.) Premises No. F-36, Kamla Nagar, Delhi-110007.

Conditions for the validity of Fire Safety Certificate:

- 1. All the means of escape/entry/exit shall be kept free from any obstruction.
- 2. All the fire safety arrangements provided therein shall be maintained in good working condition at all time as seen during inspection.
- 3. Any loss of life or property due to non-functional fire safety measures shall be at the responsibility of the management.
- 4. All the staff members must know the correct method of operation of firefighting system.
- 5. The owner / occupier shall submit a declaration every year in Form "K" provided in the first Delhi Fire Service Rules 2010. The form is available http://delhi.gov.in./wps/wcm/connect/doit fire/FIRE/Home/Forms.
- 6. This fire safety certificate may not in any way be treated as regularization (Clause 2.8 of UBBL-2016) of unauthorized construction or Alteration (Clause 1.4.3 of UBBL-2016), if any.
- 7. "The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in Form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior to its expiry".

INSPECTION REPORT

Name & address of the building

: M/s N. K. North Star (A Unit of Parivar Infratech Pvt. Ltd.) Premises no.

F-36, Kamla Nagar, Delhi-110007.

. Composition of building

: Basement, stilt, ground & three upper floors (basement- vacant and guest

house running at ground first, second and third floor only)

3. Type of Occupancy

: Group A-1 Residential

4. Type of Case

: Renewal

5. Details of previous NOC

: F6/DFS/MS/2019/2001 dated: 18.10.2019

6. Fire Safety directives letter No

: Nil

7. Date of inspection

: 28.09.2022

8. Name of the Inspecting Officers

: ADO (RN)

9. Name and designation of officers

from the building side

: Sh. (Ravi) Manager

10. Year of Construction

: 2015

11. Applicant's letter No.

: Online MHA Portal I'd No.20220917173114 Dated 20.09.2022

ľ	Minimum Standards on fire prevention and fire safety U/R 33	UBBL-2016/NBC Requirement	Provided at site	Remarks MR/NMR	
A	ccess to building				
	Road width	06m	18m (approx)	MR	
	Gate width	4.5m	Directly Accessible	MR	
	Width of internal road	NA	NA	NA	
1	Number, Width, Type & Arrangement of Exit	S			
-	a. Number of staircases		02	MR	
		02	02	NA	
	Upper Floors	NA	NA	NA	
	 Basements 				
	b. Width of staircases	1.50m	1.50m & 1.00m	MR (old cas	
	Upper Floors	NA	NA	NA	
	Basements				
	c. Protection of exits	Required	Provided	MR NA	
	 Fire check door 	NA	NA	MR	
	 Pressurization 	01	01		
	d. No. of continuous staircases to terrace	NA	NA	NA MR	
	e. Width of Corridor	90cm as per UBBL-2016	Provided	IVIK	
	f. Door Size	OBBU		MR	
3	Compartmentation.	Required	Provided	IVIIX	
3	Fire check door		NA	NA	
	o sling of electrical shafts	NA NA	NA	NA	
	• Sealing of shaft door • Fire Rating of shaft door	NA	NA	NA	
	• Fire Rating of share	NA	NA	NA	
	Water Curtain	NA			
	Fire Dampers)! 4	NA	
	Smoke Management System.	12 a/c per hour	NA	MR	
4	Basements	12 a/c per hour	Exhaust fan		
	• Upper floors				

Provided and Provided	MR NA
Provided 30m Provided 2d Provided carbon monoxide NA NA NA NA A D Provided NA Provided NA Provided NA NA Provided	MR MR MR MR MR MR MR NA
Provided 30m Provided 2d Provided carbon monoxide NA NA NA NA d Provided NA d Provided NA Provided	MR MR MR MR MR NA
30m Provided ed Provided carbon monoxide NA NA NA NA A Drovided NA NA NA Provided NA Provided	MR MR MR MR NA NA NA NA MR NA NA NA NA
30m Provided ed Provided carbon monoxide NA NA NA NA A Drovided NA NA NA Provided NA Provided	MR MR MR MR NA NA NA NA MR NA NA NA NA
Provided Provided oxide Provided oxide NA NA NA NA NA d Provided NA Provided NA Provided	MR MR NA NA NA NA MR NA MR NA
ed Provided carbon monoxide NA	MR NA NA NA NA MR NA NA NA NA
oxide carbon monoxide NA NA NA NA NA d Provided NA d Provided NA Provided	NA NA NA NA NA MR NA MR NA
oxide carbon monoxide NA NA NA NA NA d Provided NA d Provided NA Provided	NA NA NA NA NA MR NA MR NA
oxide carbon monoxide NA NA NA NA NA d Provided NA d Provided NA Provided	NA NA NA NA NA MR NA MR NA
NA NA NA Provided NA NA Provided NA Provided	NA NA NA NA MR NA MR NA NA
NA NA d Provided NA d Provided NA Provided NA Provided	NA NA MR NA MR NA MR NA
NA d Provided NA d Provided NA Provided NA Provided	MR NA MR NA
d Provided NA d Provided NA NA Provided	MR NA MR NA
NA Provided NA NA Provided	MR NA NA
d Provided NA NA Provided	MR NA NA
NA NA Provided	NA NA
NA NA Provided	NA NA
NA Provided	NA
Provided	
01	MR
	MR
01	MR
NA	NΛ
NA NA	NA
	177
NA	NA
NA	NA
	NA
	NA
NA NA	NA
NA	NA
· NA	NΛ
NA	NA
	-
Provided	MR
40m	MR
Provided	MR
Provided	MR
NA	NA
NA NA	NA NA
	NA NA NA NA NA NA NA NA NA Provided 40m Provided

Jep

6 30				
MR VI	to tank	NΛ	NΛ	NA
7	ccess to tank overhead Tank capacity	10,000ltrs	Provided	MR
		Required	Provided	MR
Exit Signa	ige.			
Provision	of Lifts.			NA
	ressurization of Lift Shaft	NΛ	NΛ	N/A
	ressurization of Lift lobby	N/A	N/A	
	Communication In lift Car	NA	NA	NA
	Fireman's Grounding Switch	NA	NA	NA
	Lift Signage	NA	NA	NA
				NA
		NA	NA	1474
	power supply	NA	NA	1,7,7
Standby Refuge			NA N/A	N/A
		N/A		
Refuge	Area.		N/A	N/A
Refuge /	Area. Total Area	N/A	N/A N/A	N/A N/A
Refuge /	Area. Total Area Location Introl Room	N/A N/A	N/A N/A	N/A N/A
Refuge /	Total Area Location Introl Room Detector System Panel	N/A N/A	N/A N/A N/A N/A	N/A N/A N/A
Refuge /	Total Area Location Introl Room Detector System Panel Flow Switch Panel	N/A N/A	N/A N/A	N/A N/A N/A N/A N/A
Refuge	Total Area Location Introl Room Detector System Panel Flow Switch Panel	N/A N/A N/A N/A	N/A N/A N/A N/A	N/A N/A N/A N/A N/A N/A
Refuge /	Total Area Location Introl Room Detector System Panel Flow Switch Panel PA System Panel	N/A N/A N/A N/A N/A	N/A N/A N/A N/A N/A	N/A N/A N/A N/A N/A

notification The compliance of the provision contained gazette as per Note:-F.5(189)/AD/LB/2016/4053-67 dated 27.05.2019 has been complied

The fire protection systems provided in the building were tested/ checked and found in good working order at the time of inspection. The observations/ shortcomings issued and communicated vide this department letter of even no. 546 dated 08.07.2022 have been compiled by the management.

Keeping in view of the substantial compliance of the minimum standards on fire prevention and fire safety required under the rules it is recommended to renew Fire Safety Certificate under rule 37 of the Delhi Fire Service

Rules 2010.

Signature of the Inspecting Officer Name: - C.L. Meena

Designation:- ADO/RN

As approved F.T. Letter is Putup For your singulare Rl.