RNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADOUARTERS: DELHI FIRE SERVICE, NEW DELHI-110001

No F 6 / DFS / MS / 2022/ U 5 4

Dated/2/10/2022

FIRE SAFETY CERTIFICATE

Certified that the "Unity One" Multi Level Car Parking located at Rohini (West), Rohini, Sector-10, Rohini, Delhi comprised of Basement +Ground +06 upper floors owned/ occupied by Unity Build well Pvt.Ltd. was granted Fire Safety Certificate by this department vide letter no. F6/DFS/MS/2019/1123 dated 24/05/2019. The premises was re-inspected by the officers concerned of this department on 29.09.2022 in the presence of Mr.Sidharth (Mall Manager) and found that the building have complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010. and premises is fit for occupancy Mixed (Mercantile & Assembly) building with effect from 19/10/22 for a period of 03 (Three) years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules, 2010.

Conditions for the validity of Fire Safety Certificate:

- 1. Kiosk in 6 meter road shall be removed within one month from the issue of this certificate.
- 2. All the fire safety arrangement provided there-in shall be maintained in good working conditions at all times.
- 3. Loss of life or property due to non functional fire safety measure shall be at the responsibility of the management.
- 4. The trained fire fighting staff should be available round the clock.
- 5. Any deviation with regard to the construction etc shall be verified by the concerned building sanctioning agency.
- 6. This certificate cannot be treated in any case for regularizations of unauthorized construction.
- 7. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director of Form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior to its expiry".
- 8. The owner / occupier shall submit a declaration every year in form "K" provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on **WWW.dfs.Delhigovt.nic.in**
- 9. All the means of escape shall be kept free of any obstruction all the time to evacuate the occupant, in a safe manner, in the event of emergency.

Issued on ... 1.2/10/12022 at New Delhi by

Copy to:-

Unity Build well Ltd., G-3, Ground floor, Aggarwal Corporate Tower, 23, Rajendra Place, Delhi-110008.

1.	Non	INS	PECTI	ON REPORT		
٠.	rvam	e & address of the building	Unity	One, Multi Level (Car Parking, Rohini (W	est),
2.			Sector	-10, Komm ,Demi	-1 10085. (Basement + G+ 05 upp	
3.	Type		: Renew		(Basement + G+ 05 upp	er floors)
4.	Deta	ils of previous NOC	: F6/DF	S/MS/2019/1123	lated 24.05.2019	
٥.	Fire	Safety directives letter No	: F.6/D	FS/MS/BP/2014/5	Dated 06.02.2014	
0.	Date	e of inspection	: 29.09.	2022		
7.	Nam	ne of the Inspecting Officers	: A. K.	Sharma, ADO (Ro	hini) & D.B Mukherjee	e, DO (NW)
8.	Nan	ne and designation of officers				
٥		the building side	: Sh. Sie	dharth (Mall Mar	nager)	
		of Construction	: 2014			
10.		icant's letter No.		dated 29.09.2022		
	Mini	mum Standards on fire preven	ntion	NBC/ BBL	Provided at site	Remarks
+	A	and fire safety U/R 33		Requirement		MR/NMR
-				40	10) (D
	•	Road width		40m	40m	MR
	•	Gate width		6m	6.0m	MR
					Provided) m
		Width of internal road		6.0m		MR
\dashv	Numb	er, Width, Type & Arrangem	ent of F	vite		
-		nber of staircases	cut UI L	A113		
				04	04	MR
	•	Upper Floors		1 ramp	1 ramp	MR
	1 337	Basements		Tramp	Trump	
	b. Wi	th of staircases		1.50mx 02		MR
	•	Upper Floors		2.00m x 02 & 1	Provided	
				ramp	D 11.155	MR
	•	Basements		lramp	Provided, 5.5 m	MIK
	c. Pro	tection of exits				
		Fire check door		Required	Provided	MD.
				Deguined	provided	MR MR
				Required	·	
				02	02	MRNA
		Pressurization		NA 2m each	NA Provided	MR
	d. N	o. of continuous staircases to te	rrace	2m each	Flovided	WIIC
		idth of Corridor				
	1	or Size	9			
3		partmentation.		T 8 1 1	Dide J	NI A
		Fire check door		Required	Provided	NA
		 Sealing of electrical shafts 		Required	Provided	MR
		Fire Rating of shaft door		NA	NA	NA
		Water Curtain		NA	NA	NA
		Fire Dampers		NA	NA	NA
4	Smo	ke Management System.			Daily and fam	MD
		Basements		30 a/c per hour	Exhaust fan	MR
		Upper floors		12 a/c per hour	Natural Ventilated	MR
5	 ,	Fire Extinguishers				
5	+	Total numbers		70nos	70nos	MR
		Types		Wco2/Co2	Wco2 -40/DCP -30	MR
		ISI marking		Yes	Yes	MR
6	Fire	st-Aid Hose Reels.	or.	04 at each floo	r Provided	MR
		Total numbers on each floo	JI.	30 m	30m	MR
		• Length of hose reel hose		5mm	5mm	MR
		Nozzle diameter		311111		
		tomatic fire detection and ala	!	ctom		

7 T

	Location of Main Panel	Required	Provided	MR
	Location of Main Panel Location of Repeater Panel	Required Each	Provided	MR
		floor	Provided	M
	Alternate source of power	Required		MR
	Hooters' Location	Common areas	Provided	MR
1		Required	Provided	MR
	OEFA Sentem	Required	provided	MR
	blic Address System.			
Au	tomatic Sprinkler System.	Required	Provided	NA
	Basement	•	Provided	MR
	Upper Floor	Required	Provided	MR
	Colintrol on file colling	Required	110.11	
T	Sprinkler above false ceiling			
In	ternal Hydrants	100	100mm	MR
	Size of riser/down-comer	100mm 04	04	MR
	Number of hydrants per floor	-	04	MR
-	Hose Box	04	UT	
Y	ard Hydrants.			MR
	Total number of hydrants	Required	Provided	
	Hose Box	Required	Provided	MR
P	umping Arrangements.			
	Ground Level			
	Discharge of main Pump	2850 lpm	2850 lpm	MR
	➤ Head of Main pump	65m	65m	MR
	Number of main pumps	2850 lpm x 02 &	Provided	MR
	Jockey Pump out put	1800 lpm 180 lpm x02	180 lpm x02	MR
	> Jockey pump head			MR
	> Standby Pump out put	65m	65m	IVIIC
	Standby Pump Head	2850lpm	2850 lpm	MR
	> Auto Starting/ Manual stopping	65m	65m	MR
	Pump House Access	Required	Provided	MR
	• Terrace level			
	Discharge of pump	900 lpm	900 lpm	MR
	Head of the pump	40m	40m	MR
	Power Supply	Required	Provided	MR
	Auto Starting of pump	Required	Provided	MR
14	Captive Water Storage for fire fighting.			
	Underground tank capacity	1,00,000 ltr	1,00,000 ltr	MR
	> Draw-off connection	Required	Provided	MR
	> Fire service inlet	Required	Provided	MR
	> Access to tank	Required	Provided	MR
	 Overhead Tank capacity 	10,000 ltr	10,000 ltrs	MR
15	Exit Signage.	Required	Provided	MR
16	Provision of Lifts.			
10	Pressurization of Lift Shaft	Required	Provided	MR
		Required	Provided	MR
	Pressurization of Lift lobby	Required	Provided	MR
	Communication In lift Car	NA	NA	NA
	Fireman's Grounding Switch	Required	Provided	MR
	Lift Signage	_		
17	Standby power supply	Required	Provided	MR
18	Refuge Area.			
	> Total Area	NA	NA	NA
	> Location	NA	NA	NA
19	Fire Control Room			1
	Detector System Panel	Required	Provided Provided	MR MR
	 Flow Switch Panel 	Required	Provided	IVIN

1 14

N. 6/

Batter backup Building Floor Plans Special Fire Protection Systems for Protection of special Risks, if any: Required Provided MR Required Provided MR Required Provided MR NA NA NA

The fire protection systems provided in the building were tested, checked at random and found functional. Keeping in view of the substantial compliance of the minimum standards on fire prevention and fire safety required under the rules and compliance of shortcomings issued vide letter no. 1303 dated 07.06.2022, it is recommended to renew Fire Safety Certificate issued vide this department letter of even no. 1123 dated 24.05.2019 under rule 35 of the Delhi Fire Service Rules 2010.

Signature of the Inspecting Office

Name: - D.B Mukherjee

Designation:- DO/NW

Signature of the Inspecting Officer

Fi detter is four up for kind penusal and Signature, please.

Name: - Ajay Kumar Sharma

Designation:- ADO/Rohini

an

th