C-SG

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEAD QUARTERS: DELHI FIRE SERVICE: NEW DELHI - 110001

No. F6/DFS/MS/School/2022 / 11 S1

Dated: 8 /10 /2022

FIRE SAFETY CERTIFICATE

Certified that the Murti Devi Public School located at 221, Block-A2, Mandir Marg, Bhagat Colony, West Sant Nagar, Burari, Delhi-110084 comprised of Ground & 02 upper floors only owned/ occupied by Murti Devi Public School was issued Fire Safety Certificated vide this office letter no.F6/DFS/MS/2019/WZ/55 dated 08.01.2019. The premise was reinspected by the officer concerned of this department on 29.09.2022 in the presence of Sh. Ram Shankar Singh /Chairman and observed that all the fire prevention and fire safety arrangements as provided in the premise found in good working condition. The premise have therefore deemed complied with the requirements under rule 33 of the Delhi Fire Service Rules, 2010 and the building premise is fit for occupancy under Educational "Group B" with effect from ...18.10.2022 for a period of three years in accordance with the rule 36 unless renewed under rule 37 or sooner cancelled under rule 40, subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules, 2010,

(Dharampal Bhardwaj) Dy. Chief Fire Officer Ph.-011-23414250

Copy to: -

- 1. The Director, Education, Government of N.C.T of Delhi. Old Sectt. Delhi 110054.
- 2. The Principal, Murti Devi Public School located at 221, Block- A2, Mandir Marg, Bhagat Colony, West Sant Nagar, Burari, Delhi-110084.

Conditions for the validity of Fire Safety Certificate:

- 1. All the means of escape/entry/exit shall be kept free from any obstruction.
- 2. All the fire safety arrangements provided therein shall be maintained in good working condition at all time as seen during inspection.
- 3. Any loss of life or property due to non-functional fire safety measures shall be at the responsibility of the management.
- 4. All the staff members must know the correct method of operation of firefighting system.
- 5. The owner / occupier shall submit a declaration **every year** in **Form "K"** provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on <u>http://delhi.gov.in./wps/wcm/connect/doit</u> fire/FIRE/Home/Forms.
- This fire safety certificate may not in any way be treated as regularization (Clause 2.8 of UBBL-2016) of unauthorized construction or Alteration (Clause 1.4.3 of UBBL-2016), if any.
- "The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in Form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior to its expiry".

	115						
		INSPECTION REPORT					
Ş	Name & address of the building	¹ Murti Devi Pubic School, 221, A-2 Block, Mandir Marg, Bhagat Colony, West Sant Nagar, Burari, Delhi110084.					
2	Type of Occupancy	Educational					
3	Composition of building	: Ground plus 02 upper floors only					
4.	Type of Case	Renewal					
5.	Details of previous NOC	: F6/DFS/MS/2019/WZ/55 dated 08 01.2019					
6.	Fire Safety directives letter No	. Nil					
7.	Date of inspection	29.09.2022					
8.	Name of the Inspecting Officers	: ADO (RN)					
9.	Name and designation of officers						
	from the building side	: Sh. Ram Shankar Singh /Chairman					
10.	Year of Construction	: 2005					
11.	Applicant's letter No.	Letter No. Nil dated 12 09 2022					

Minimum Standards on fire prevention and fire safety U/R 33	NBC Part-4 Requirement	Provided at site	Remarks MR/NMR			
Access to building						
Road width	6m	05m	MR(old case)			
• Gate width	Directly Accessible	Directly Accessible	MR			
 Width of internal road 	NA	NA	NA			
Number, Width, Type & Arrangement of Exits						
a. Number of staircases						
Upper Floors	02	02	MR			
• Basements	NA	NA	NA			
b. Width of staircases						
	1.50m	1.42 m & 1.12m	MR(old case)			
Upper Floors	NA	NA	NA			
• Basements						
c. Protection of exits	NA	NA	NA			
Fire check door	NA	NA	NA			
Pressurization		01	MR			
d. No. of continuous staircases to terrace	01 NA	01 NA	NA			
e. Width of Corridor	1 m	Provided	MR			
f. Door Size	Im	Tiovided				
 Compartmentation.						
Fire check door	NA	NA	NA			
 Sealing of electrical shafts 	NA	NA	NA			
 Fire Rating of shaft door 	NA	NA	NΛ			
Water Curtain	NA	NA	NA			
• Fire Dampers	NA	ΝΛ	NA			
 Smoke Management System.						
Basements	12 a/c per hour	NA	NA			
• Upper floors	12 a/c per hour	Natural Ventilated	MR			
 Fire Extinguishers						
Total numbers	07nos	08nos	MR			
• Types	ABC/Co2	ABC-08	MR			
 ISI marking 	ISI Marked	Yes	MR			


₽P

	K.	116		2		
	First-Aid Hose Reels.					
	 Lotal numbers on each floor 	01	01	MR		
	 Length of hose reel hose 	30m	30m			
	Nozzle diameter			MR		
	Automatic fire detection and alarming syste	5mm	5mm	MR		
	Type of detectors	ni. NA	NA			
	 Location of Main Panel 	NA	NA	NA		
	Location of Repeater Panel	NA	ΝΔ			
				NA		
	 Alternate source of power Hooters' Location 	NA	NA	NΛ		
		NA	NA	NA		
	MOEFA	NA	NA	ΝΛ		
	Public Address System.	NA	NA	NA		
	Automatic Sprinkler System.	1				
	Basement	NA	NA	NA		
	Upper Floor	NA	NA	NA		
	• Sprinkler above false ceiling	NA	NΛ	NA		
	Internal Hydrants					
	Size of riser/down-comer	NA	NA	NA		
	 Number of hydrants per floor Hose Box 	NA	NA	NA		
		NA	NA	NA		
	Yard Hydrants.					
	Total number of hydrants	NA	NA	NA		
	Hose Box	NA	ΝΑ	NA		
	Pumping Arrangements.					
	Ground Level					
	 Discharge of main Pump Head of Main pump 	N/A	N/A	N/A		
	Head of Main pumpNumber of main pumps	N/A	N/A	N 'A		
	 Jockey Pump out put 	N/A	N/A	N/A		
	 Jockey pump head 	Ν/Α	N/A			
	 Standby Pump out put 	N/A	N/A	N/A N/A		
	Standby Pump Head	N/A	N/A	N/A		
	Auto Starting/ Manual stopping	N/A				
	> Pump House Access	N/A N/A	N/A	N/A		
	 Terrace level Discharge of pump 		N/A	N/A		
	 Discharge of pump Head of the pump 	450lpm	Provided	MR		
	 Power Supply 	40m NA	40m NA	MR		
	 Auto Starting of pump 	NA	NA NA	NA NA		
	Captive Water Storage for fire fighting		14/1	1874		
-		ΝΛ	NΛ	NIA		
	 Underground tank capacity Draw-off connection 			NA		
	 Draw-off connection Fire service inlet 	NA NA	NA			
	 Access to tank 	NA	NA	NA NA		
	 Overhead Tank capacity 					
		5,000ltrs	Provided	MR (old case)		

	Provision of Lifts.					
	 Pressurization of Lift Shaft 	N/A	N/A	$\sim \Lambda$		
	 Pressurization of Lift lobby 	N/A	N/A	~ A		
	 Communication In lift Car Fireman's Grounding Switch Lift Signage 	N/A	N/A	· · · · · · ·		
		N/A	NA	$\sim \sim \sim$		
		ΝA	N/Λ	N A		
	Standby power supply	N/A	NA	`^		
	Refuge Area.					
	Total Area	N/A	N/A	NA		
	Location	N/A	N/A	N/A		
)	Fire Control Room					
	Detector System Panel	N/A	N/A	NA		
	Flow Switch Panel	N/A	N/A	N/A		
	PA System Panel	N/A	N/A	NA		
	Batter backupBuilding Floor Plans	N/A	N/A	N/A		
		N/A	ΝA	N A		
20	Special Fire Protection Systems for Protection of special Risks, if any:	N/A	ΝA	ΝA		

The fire protection systems provided in the building were tested/ checked randomly and found in good working condition, at the time of inspection. The management has complied all the shortcomings issued and communicated by this department vide letter of even no. 523 dated 05.09.2022.

Keeping in view the satisfactory compliance of the minimum standards on fire prevention and fire safety required as stipulated in NBC Part 4, the FSC issued vide letter of even no. 55 dated 08.01.2019 renewal under rule 37 of the Delhi Fire Service Rules, 2010 is recommended



1117