C-45

# GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEAD QUARTERS, DELHI FIRE SERVICE, NEW DELHI - 110001

No.F6/DFS/MS/GH/NDZ/2022/ 471

Dated: 1.4./.1.0/2022

### FIRE SAFETY CERTIFICATE

Certified that the M/s Red Rose Inn Guest House located at 803 & 805, Street Chandi Wali, Main Bazar, Pahar Ganj, New Delhi comprised of Ground + 03 Upper floors, Ground floor (reception), 1<sup>st</sup> floor to 3<sup>rd</sup> floor (05 guest rooms at each floor), total 15 guest rooms The FSC was earlier granted by this department vide letter No.F6/DFS/MS/GH/NDZ/2019/691 dated 02/04/19 for 15 guest rooms only, Now, the premises was re-inspected by the officer concerned of this department on 03/10/22 in the presence of Mr. Tosif and found that the said guest house building have deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the premises is fit for occupancy class Residential, (Sub Division-A-1) Ground floor (reception), 1st floor to 3rd floor (05 guest rooms at each floor), total 15 guest rooms up to third floor only, with effect from for sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules 2010, printed below.

(S.K.Dua)
Chief Fire officer

Dy. Chief Fire officer Delhi Fire Service

#### Copy to:-

1. The Commissioner of North, MCD, Civic Centre, New Delhi. Kindly to ensure the occupancy in the building as detailed above.

 The Addl. Commissioner of Police (Lic), First Floor, P.S. Defence Colony New Delhi online id no.2022091817783 dated 18/09/22.

3. The Manager, M/s Red Rose Inn Guest House, 803 & 805, Street Chandi Wali, Main Bazar, Pahar Gani, New Delhi

## Conditions for the validity of Fire Safety Certificate

- 1. All the fire safety arrangements provided therein shall be maintained in good working conditions at all times.
- Any loss of life or property due to non functional fire safety measures shall be at the responsibility of the management.
- The trained fire fighting staff should be available round the clock.
- 4. Any deviation w.r.t. construction etc. shall be verified by the concerned building sanctioning authority.
- 5. This fire safety certificate may not be treated in any case for regularization of unauthorized construction, if any.
- 6. The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on <a href="https://www.dfs.delhigovt.nic.in">www.dfs.delhigovt.nic.in</a>
- 7. The means of escape shall be kept unobstructed / unlocked for unhindered evacuation in case of an emergency.
- 8. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in form 'J' [sub rule (I) of rule 37] along with a copy of this Certificate, six month prior to its expiry.
- 9. Any flammable material for interior decoration is prohibited.

ma 1

## **INSPECTION REPORT**

1. Name & address of the building:- Red Rose Inn situated at 803 & 805,

Street Chandi Wali, Main Bazar, Pahar

Gani, New Delhi.

Residential, Sub Division-A-1 2. Type of occupancy:-

Gr. + 03 Upper floors (total 15 Guest rooms) Ground floor (reception), 1st floor to 3rd floor

(05 guest rooms at each floor)

3. Type of case:-Renewal

No. F6/DFS/MS/GH/NDZ/2019/691 dated 4. Details of previous FSC:-

02/04/19

5. Fire safety directives No.-N/A 03/10/22

6. Date of inspection:-Sh. Ravinder Singh (ADO/CC) 7. Name of the inspecting officer:-

8. Name & designation of officer

From the building side:-

Mr. Tosif

9. Year of construction:-10. Applicant's letter No:-

2) Types

Online id no.2022091817783 dated 18/09/22.

Old Case Remarks Provided at site Minimum Standards on fire Requirement S.No. MR/NMR **PSS** Existing Prevention and fire safety U/R 33 Access to Building 1. MR 06 mtr. N/A 1) Road width N/A N/A N/A 2) Gate width N/A N/A N/A 3)Width of internal road Number, Width Type & Arrangement of Exits 2. A. Number of staircases MR 01 Nos. 01 Nos. 1. Upper floors N/A N/A N/A 2. Basements B. Width of staircase MR 1.20 mtr. 0.80 mtr. 1. Upper floors N/A N/A N/A 2. Basements C. Protection of exits N/A N/A N/A 1. Fire check door N/A N/A N/A 2. Pressurization MR 01 01 D. No. of continuous staircase to terrace N/A N/A N/A E. Width of corridor MR 1 mtr. 1 mtr. F. Door size Compartmentation N/A 3. N/A N/A 1) Fire check door N/A N/A 2) Sealing of electrical shafts N/A N/A N/A 3) Fire rating of shaft door N/A N/A N/A N/A 4) Water curtain N/A N/A N/A 5) Fire Dampers Smoke Management System N/A N/A 4. 30 ACPH 1) Basements Natural/Exhaust MR 12 a/c per 2) Upper floors fan hour Fire Extinguishers MR 10 Nos. 5. 10 Nos. 1) Total numbers MR ABC & CO2 ABC & CO2

	$\sim h$	<u> </u>	D :1-1	MR	
	3) ISI marking	Required	Provided	IVIK	
6.	First-Aid Hose Reel			N/A	
0.	1) Total number of each	N/A	01	14/2	
	floor		20	N/A	
	2) Length of hose reel hose	N/A	30 m 05 mm	N/A	
	2) Nozzle diameter	N/A		14/24	
7.	Automatic Fire Detection &	Alarming Sys	Provided	MR	
	1) Type of detectors Co type	Required	Provided	MR	
	2) Location of main panel	Gr. floor	N/A	N/A	
	3) Location of repeater panel	N/A	Provided	MR	
	4) Alternate source of power	Required	Provided	MR	
	5) Hooter's Location	Gr. floor		N/A	
8.	MOEFA	N/A	N/A	N/A	
9.	Public Address System	N/A	N/A	14/2	
10.	Automatic Sprinkler System		27/4	N/A	
	1) Basement	N/A	N/A	N/A	
	2) Upper floors	N/A	N/A	N/A	
	3) Sprinkler above false	N/A	N/A	14/7	
	ceiling				
11.	Internal Hydrants			N/A	
11.	1) Size of riser/down-comer	N/A	N/A		
	2) Number of hydrants per	N/A	N/A	N/A	
	floor			21/4	
	3) Hose box	N/A	N/A	N/A	
12.	Yard Hydrants			1274	
12.	1) Total number of hydrants	N/A	N/A	N/A	
	2) Hose box	N/A	N/A	N/A	
13.	Pumping Arrangement				
13.	1) Ground level	N/A	N/A	N/A	
	a) Discharge of main	N/A	N/A	N/A	
	,	1			
	b) Head of main pump	N/A	N/A	N/A	
	c) Number of main	N/A	N/A	N/A	
	1 '	1 1 1 1 1			
	pump	N/A	N/A	N/A	
	d) Jockey pump out put	N/A	N/A	N/A	
	e) Jockey pump head	N/A	N/A	N/A	
	<ul> <li>f) Stand by pump output</li> </ul>		N/A	N/A	
	g) Stand by pump head	N/A		N/A	
	h) Auto starting/Manual	N/A	N/A	14/2	
	stopping				
	2) Terrace level				
	a) Discharge of pump	N/A	450 LPM	N/A	
	b) Head of pump	N/A	30 mtr	N/A	
	c) Power supply	N/A	Required	N/A	
	d) Auto starting of pump	N/A	Required	N/A	
	d) Auto starting or pump	- "	•		
4	Captive Water Storage for F	re Fighting			
4.	1) Under ground tank	N/A	N/A	NV	4
	opposite	1			
	capacity	N/A	N/A	NA	4
	a) Draw-off connection		N/A	N/A	
	b) Fire service inlet	N/A			
	c) Access to tank	N/A	N/A	N/A	4

MR N/A N/A

		NIS		
15.	d) Over head tank capacity	2500 ltr.	2500 ltr.	MR
16.	Exit Signage.	Required	Provided	1.45
10.	Provision of Lifts.	quired	Flovided	MR
	<ul><li>a) Pressurization of lift shaft</li></ul>	N/A	N/A	N/A
	b) Pressurization of lift lobby	N/A	N/A	N/A
	c) Communication in lift car	N/A	N/A	N/A
	d) Fireman's switch	N/A	N/A	N/A
17.	e) Lift signage	N/A	N/A	N/A
	Stand by Power Supply	Required	Provided	MR
18.	Refuge Area	N/A	N/A	N/A
	Total area location	N/A	N/A	N/A
19.	Fire Control Room	N/A	N/A	N/A
	a) Detector system panel	N/A	N/A	N/A
	b) Flow switch panel	N/A	N/A	N/A
	c) PA system panel	N/A	N/A	N/A
	d) Battery backup	N/A	N/A	N/A
	e) Building floor plan	N/A	N/A	N/A
20.	Special Fire Protection System for Protection of special Risk, if any:			NA

The fire protection systems provided in the guest house building were randomly tested, checked and found functional at the time of inspection.

In view of the deemed compliance of the minimum standards of fire prevention and fire safety measures as required under the rules, if approved, we may renew the FSC issued vide letter no. F6/DFS/MS/GH/NDZ/2019/691 dated 02/04/19, up to third floor only under rule 35 of the Delhi Fire Service rules 2010. Accordingly, DFA is put up for kind perusal and signature please.

Signature of the Inspecting Officer

Name: - Rayinder Singh Designation: - ADO (CC)

Round and System Please

Dyerrossy

F. P. wing