GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE, NEW DELHI-110001

No. F6/DFS/MS/2022/WZ/ (lege / 17

FIRE SAFETY CERTIFICATE

Certified that the Rukmini Devi Institute of Advance Studies, 2A & 2B, Madhuban Chowk, Outer Ring Road, Phase-I, Delhi-110085, comprised of Basement + Ground + 03 department this by issued FSC been No.F.6/DFS/MS/2019/1292 dated 17.06.2019. The premises was re-inspected by the officer already concerned of this department on 30.09.2022 in the presence of Dr. Raman Garg (Director) and found that the said building have deemed complied with the fire prevention and fire safety requirements in accordance with Rule 33 of the Delhi Fire Service Rules, 2010 and that the premises fit for occupancy class "Group B Educational" with effect from 18 10 2024 for a period of three years in accordance with Rule 36 unless renewed under Rule 37 or sooner cancelled under Rule 40 and subjected to compliance of the conditions under Rule 38 of the Delhi Fire Service Rules, 2010.

Issued on ... 8 ... 2022 at New Delhi by

(Dhrampal Bhardwaj) **Dy.Chief Fire Officer** Tel;-01123414250

CHY

Copy to :-

1. The Director, Rukmini Devi Institute of Advance Studies, 2A & 2B, Madhuban Chowk, Outer Ring Road, Phase-I, Delhi-110085.

Conditions for the validity of fire safety certificate:

- 1. All the fire safety arrangement provided there-in shall be maintained in good working conditions at all times.
- 2. Loss of life or property due to non functional fire safety measure shall be at the responsibility of the management.
- 3. The trained fire fighting staff should be available round the clock.
- 4. Any deviation with regard to the construction etc shall be verified by the concerned building
- 5. This certificate cannot be treated in any case for regularizations of unauthorized
- 6. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director of Form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior to its
- 7. The owner / occupier shall submit a declaration every year in form "K" provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on
- 8. All the means of escape shall be kept free of any obstruction all the time to evacuate the occupant, in a safe manner, in the event of emergency.

http://www.delhi.gov.in/wps/wcm/connect/doit_fire/FIRE/Home/Fire+Safety+Acts+and+Rule s/ http://www.delhi.gov.in/wps/wcm/connect/doit fire/FIRE/Home/Forms

	_								
			INSPECTION REPORT Report Advance Studies, 2A & 2B, Madhuban						
	1. Nam	e & address of the building	address of the building: Rukmini Devi Institute of Advance Studies, 2A & 2B, Madhuban Chowk, Block-A, Outer Ring Road, Phase-I, Delhi-110085.						
			Chowk, Block-A, Outer Ring Teory) Only for A-Block						
	2. Penewal								
	3. Type		E 6/DES/MS	/2019/1292 dated 17.06.2019 /BP/99/2883 dated 11.03.1999 ADO(Rohini)					
	4. Deta	Safety directives letter No	: F.6/DFS/MS/						
	5. Fire	of inspection	: 30.09.2022						
	6. Date	e of Inspecting Officer	: A.K.Sharma						
	7. Nam	e and designation of officers	:						
	6. Nam From	the building side	Dr. Raman G	arg (Director)					
	9 Year	of Construction .	1999						
		0. Applicant's letter No. : On		line e-mail dated 26.08.2022.					
S. N	lo. Mir	nimum Standards on fire p	revention	Rule 35(6)	Provided at site	Remarks MR/NMR			
5. 1	and fire safety U/R 33								
1.		ess to building		00	18m	MR			
		Road width		09m	5.0m	MR			
		Gate width		4.5m	NA	NA			
		Width of internal road		NA	142 x				
2.	N	nber, Width, Type & Arra	ingement of Ex	cits					
۷.	d N	lumber of staircases	J		02	MR			
				02	03 Provided	MR			
	· ·	• Upper Floors		01 SC &	Provided				
	•	Basements		01 ramp					
	e. W	Vidth of staircases		(anth	1.5m (each)	MR			
	-	• Upper Floor		1.5m (exch)	1.6m & ramp 1.5m	MR			
		Basements		1.5m & 01 ramp	1.6m & Tamp 1.5m				
	f. Protection of exits				Provided(only basement)	MR			
	Fire check door			Required					
		n '		Required	Provided	MR			
		No. of continuous staircases	to terrace	01	01	MR			
			to terrace	NA	NA	NA			
		Vidth of Corridor		1.0m	1.0m	MR			
	f. Door Size								
3.	Com	partmentation		- · · · · ·	Provided(only basement	MR			
	•	Fire check door		Required					
		Sealing of electrical shaft	ts	Required	Provided	MR			
		Fire Rating of shaft door		Required	Provided	MR			
		Water Curtain		NA	NA	NA			
		Fire Dampers		NA NA	NA	NA			
		-		14/4	1 17 1	12			
•	Smok	Re Management System Basements		30 a/c per hour	Exhaust fan	MR			
0		Upper floors		12 a/c per hour	Natural ventilated	MR			
Q	•								
	Fire F	Fire Extinguishers		24nos.	25nos.	MR			
	•	Total numbers			ABC-25	MR			
	•	Types		ABC/CO2					
	•	IS marking		ISI marked	Yes	MR			
	First-								
	•	Total numbers on each flo	оог	01	Provided	MR			
		Length of hose reel hose		30mm	Provided	MR			
		Nozzle diameter	ŀ	5m	Provided	MR			
	Nozzle diameter Automatic fire detection and alar		arming system						
	Autom		arming systen		NA	NA			
	•	Type of detectors		NA					
	•	Location of Main Panel		NA	NA	NA			
		Location of Repeater Pane				NA			

6.

7.

	•							
	Alternate source of power	NA	NA	NA				
. мо	Hooters' Location OEFA	NA	NA	NA				
		Required	Provided	MR				
	blic Address System	Required	Provided	MR				
o. Au	Automatic Sprinkler System Basement Required Provided							
		Required	Provided	MR				
	Cround & Opper Floors	NA	NA	NA				
1. In	Sprinkler above false ceiling ternal Hydrants	NA	NA	NA				
-	Size of riser/down-comer	D						
	Number of hydrants per floor	Required	Provided	MR				
	Hose Box	NA NA	01	NA				
2. Ya	ard Hydrants	NA	01	NA				
	Total number of hydrants	NIA						
	Hose Box	NA NA	NA	NA				
13. Pu	imping Arrangements	NA	NA	NA				
	Ground Level							
	Discharge of main Pump	NA	NI A	27.4				
	Head of Main pump		NA NA	NA				
		NA NA	NA	NA				
	Number of main pumps	NA	NA	NA				
	> Jockey Pump out put	NA	NA	NA				
	> Jockey pump head	NA	NA	NA				
	Standby Pump out put	NA	NA	NA				
	Standby Pump Head	NA	NA	NA				
	Auto Starting/Manual Stopping	NA	NA	NA				
	Pump House Access	NA	NA	NA				
	Terrace level							
	Discharge of pump	900lpm	900lpm	MR				
	Head of the pump	40m	40m	MR				
	> Power Supply	Required	Provided	MR				
	Auto Starting of pump	Required	Provided	MR				
14. C	Captive Water Storage for fire fighting							
	 Underground tank capacity 	25,000ltr	25,000ltr	MR				
	Draw-off connection	Required	Provided	MR				
	Fire service inlet	Required	Provided	MR				
	> Access to tank	Required	Provided	MR				
	Overhead Tank capacity	12,500ltr	12,500ltr	MR				
15. E	Exit Signage.	Required	Provided	MR				
	Provision of Lifts.							
	- CI : G Choff	NA	NA	NA				
	 Pressurization of Lift Shart Pressurization of Lift lobby 	NA	NA	NA				
	Communication In lift Car	Required	Provided	MR				
	Fireman's Grounding Switch	Required	Provided	MR				
	 Lift Signage 	Required	Provided	MR				
		Required	Provided	MR				
	Standby power supply							
18. F	Refuge Area.	NA	NA	NA				
	> Total Area	NA NA	NA	NA				
	> Location	1474						
19. I	Fire Control Room	NA	NA	NA				
	 Detector System Panel 	NA NA	NA	NA				
	 Flow Switch Panel 	NA NA	NA	NA				
	PA System Panel	NA NA	NA	NA				
	 Battery backup 	NA NA	NA	NA				
	Building Floor Plans	INA						

Special Fire Protection System for NA NA NA Protection of special Risks, if any: Accordingly, the fire protection systems provided in the building were tested/ checked randomly and found in working condition at the time of inspection. Keeping in view the satisfactory compliance of the minimum standards on fire prevention and fire safety required as stipulated in NBC Part-4, and removal of shortcomings issued vide letter no. 35 dated 25.07.2022, the FSC issued vide letter no. F.6/DFS/MS/2019/1292 dated 17.06.2019, renewal under rule 37 of the Delhi Fire Service Rules, 2010 is recommended. Signature of the Inspecting Officer Ajay Kumar Sharma Name Designation ADO (Rohini)