GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEAD QUARTERS, DELHI FIRE SERVICE, NEW DELHI - 110001

No.F6/DFS/MS/GH/2022/ 492

Dated : 28 / 0./2022

5

FIRE SAFETY CERTIFICATE

Certified that the M/S Krishana Dx. Guest House located at 43, Arakashan Road, Pahar Ganj, New Delhi comprised of Ground + 05 Upper floors, Ground floor (Reception + 08 guest rooms + office), 1st floor to 3rd floor (13 guest rooms at each floor), total 47 guest rooms. The FSC was earlier granted by this department vide letter No.F6/DFS/MS/GH/2019/2200 dated 22/11/19 for 47 guest room upto third floor only. Now, the premises was re-inspected by the officer concerned of this department on 20/10/22 in the presence of Nitin Goel and found that the said guest house building having been given an affidavit dated 05.11.2019 regarding not to use any floor above third floor, has deemed complied with the fire prevention and fire safety requirements in accordance with Rule 33 of the Delhi Fire Service Rules, 2010 and that the premises is fit for occupancy class Residential, Sub Division-A-1 Ground floor (Reception + 08 guest rooms + office), 1st floor to 3rd floor (13 guest rooms at each floor), total 47 guest rooms up to third floor only, with effect from [3, 8, ..., 19, ..., 20, 2..., 20, 2..., 20, 2..., 20, 2..., 20, 2..., 20, 2..., 20, 2..., 20, 2..., 20, 2..., 20, 2..., 20, 2..., 20, 2..., 20, 2..., 20, 2..., 20, 2..., 20, 2..., 20, 2..., 20, 2..., 20, 2..., 20, 2..., 20, 2..., 20, 2..., 20, 2..., 20, 2..., 20, 2..., 20, 2..., 20, 2..., 20, 2..., 20, 2..., 20, 2..., 20, 2..., 20, 2..., 20, 2..., 20, 2..., 20, 2..., 20, 2..., 20, 2..., 20, 2..., 20, 2..., 20, 2..., 20, 2..., 20, 2..., 20, 2..., 20, 2..., 20, 2..., 20, 2..., 20, 2..., 20, 2..., 20, 2..., 20, 2..., 20, 2..., 20, 2..., 20, 2..., 20, 2..., 20, 2..., 20, 2..., 20, 2..., 20, 2..., 20, 2..., 20, 2..., 20, 2..., 20, 2..., 20, 2..., 20, 2..., 20, 2..., 20, 2..., 20, 2..., 20, 2..., 20, 2..., 20, 2..., 20, 2..., 20, 2..., 20, 2..., 20, 2..., 20, 2..., 20, 2..., 20, 2..., 20, 2..., 20, 2..., 20, 2..., 20, 2..., 20, 2..., 20, 2..., 20, 2..., 20, 2..., 20, 2..., 20, 2..., 20, 2..., 20, 2..., 20, 2..., 20, 2..., 20, 2..., 20, 2..., 20, 2..., 20, 2..., 20, 2...

Dy. Chief Fire Officer Delhi Fire Service

Copy to:-

2124/2021

- 1. The Commissioner, MCD, Civic Centre, New Delhi. to kindly ensure the occupancy and deviation if any.
- 2. The Addl. Commissioner of Police (Lic), First Floor, P.S. Defence Colony New Delhi. ID NO. 2022041907500 dated 19.04.2022 & mail id <u>hotelkrishnadeluxe@gmail.com</u> dated 01.09.2022.
- 3. The Manager, M/S Krishana Dx. Guest House, 43, Arakashan Road, Pahar Ganj, New Delhi

Conditions for the validity of Fire Safety Certificate

- 1. All the fire safety arrangements provided therein shall be maintained in good working conditions at all times.
- Any loss of life or property due to non functional fire safety measures shall be at the responsibility of the management.
- 3. The trained fire fighting staff should be available round the clock.
- 4. Any deviation w.r.t. construction etc. shall be verified by the concerned building sanctioning authority.
- 5. This fire safety certificate may not be treated in any case for regularization of unauthorized construction, if any.
- The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on <u>www.dfs.delhigovt.nic.in</u>
- 7. The means of escape shall be kept unobstructed / unlocked for unhindered evacuation in case of an emergency.
- The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in form 'J' [sub rule (I) of rule 37] along with a copy of this Certificate, six month prior to its expiry".
- 9. Any flammable material for interior decoration is prohibited.

136 INSPECTION REPORT

1. Name & address of the building M/S

- 2. Type of occupancy:-
- 3. Type of case:-
- 4. Details of previous FSC:-
- 5. Fire safety directives No.-
- 6. Date of inspection:-
- 7. Name of the inspecting officer:-
- 8. Name & designation of officer From the building side:-
- 9. Year of construction:-
- 10. Applicant's letter No:-

M/S Krishana Dx. Guest House located at 43, Arakashan Road, Pahar Ganj, New Delhi Residential, Sub Division-A-1 Gr. + 05 Upper floors (total 47 Guest rooms) Ground floor (Reception + 08 guest rooms + office), 1st floor to 3rd floor (13 guest rooms at each floor), 4th & 5th floor given an affidavit dated 05.11.2019 regarding not to use any floor above third floor. Renewal

No. F6/DFS/MS/GH/2019/2200 dated 22/11/19 N/A 20/10/22

Sh. Ravinder Singh (ADO/CC)

Sh Nitin Goel

1981

id no. 2022041907500 dated 19.04.2022 & mail id hotelkrishnadeluxe@gmail.com dated 01.09.2022.

Old Case

S.No.	Minimum Standards on fire	Dequirement	D 111	Old Case
0.110.	Prevention and fire safety	Requirement Existing		Remarks
	U/R 33	Existing	PSS	MR/NMR
1.	Access to Building			
	1) Road width	N/A	06 mtr. Approx.	MR
	2) Gate width	N/A	N/A	N/A
	3)Width of internal road	N/A	N/A	N/A
2.	Number, Width Type & Ar	rangement of E	xits	
	A. Number of staircases			
	1. Upper floors	01 Nos.	01 Nos.	MR
	2. Basements	N/A	N/A	N/A
	B. Width of staircase			
	1. Upper floors	1.25 mtr.	1.50 mtr.	MR
	2. Basements	N/A	N/A	N/A
	C. Protection of exits			
	1. Fire check door	Required	Provided	MR
	2. Pressurization	N/A	N/A	N/A
	D. No. of continuous	01	01	MR
	staircase to terrace			
	E. Width of corridor	N/A	125 cms & 150 cms	N/A
	F. Door size	N/A	85x220 cms	N/A
3.	Compartmentation			
	1) Fire check door	N/A	N/A	N/A
	2) Sealing of electrical shafts	N/A	N/A	N/A
	3) Fire rating of shaft door	N/A	N/A	N/A
	4) Water curtain	N/A	N/A	N/A
	5) Fire Dampers	N/A	N/A	N/A
l.	Smoke Management System		1	11/11
	1) Basements	30 ACPH	N/A	N/A
	2) Upper floors	12 a/c per	Natural/exhaust	MR
		hour		

	٨	137		14.
5.				
5.	Fire Extinguishers 1) Total numbers	17 Nos.	17 Nos.	
	2) Types	ABC & CO2	ABC & CO2	MR
	3) ISI marking	Required	Provided	MR
6.	First-Aid Hose Reel	Required	Tiovided	MR
0.	1) Total number of eachfloor	01	01	MR
	2) Length of hose reel hose	30 mtr.	30 mtr.	MR
	3) Nozzle diameter	05 mm	05 mm	MR
7.	Automatic Fire Detection &			IVIN
/.	1) Type of detectors CO	Required	Provided	MR
	2) Location of main panel	Ground	Provided	MR
	3) Location of repeater panel	N/A	N/A	N/A
	4) Alternate source of power		Provided	MR
		Required	Provided	MR
0	5) Hooter's Location	Ground		
8.	MOEFA	Required	Provided	MR
9.	Public Address System	Required	Provided	MR
10.	Automatic Sprinkler System			
	1) Basement	N/A	N/A	N/A
	2) Upper floors	N/A	N/A	N/A
	3) Sprinkler above false	N/A	N/A	N/A
	ceiling			
11.	Internal Hydrants			
	1) Size of riser/down-comer	100 mm	100 mm	MR
	2) Number of hydrants per	01	01	MR
	floor			
	3) Hose box	01	01	MR
12.	Yard Hydrants			
	1) Total number of hydrants	N/A	N/A	N/A
	2) Hose box	N/A	N/A	N/A
13.	Pumping Arrangement			
15.	1) Ground level	N/A	N/A	N/A
	a) Discharge of main	N/A	N/A	N/A
	pump			
	b) Head of main pump	N/A	N/A	N/A
		N/A	N/A	N/A
	c) Number of main pump			
		N/A	N/A	N/A
		N/A	N/A	N/A
		N/A	N/A	N/A
	f) Stand by pump output	N/A N/A	N/A N/A	N/A
	g) Stand by pump head	N/A N/A	N/A N/A	N/A
	h) Auto starting/Manual			11/21
	stopping			
	2) Terrace level	450 1 01 6	450 I DM	MR
	a) Discharge of pump	450 LPM	450 LPM	_
	b) Head of pump	40 mtr.	40 mtr.	MR
	c) Power supply	Required	Provided	MR
	d) Auto starting of pump	Required	Provided	MR

1

~



	.)	~	1	
٨	11	3	ð	

14.	Captive Water Storage for Fi 1) Under ground tank	N/A	N/A	N/A
-	capacity			17/2
	a) Draw-off connection	N/A	N/A	N/A
	b) Fire service inlet	Required	Provided	MR
	c) Access to tank	Required	Provided	MR
	d) Over head tank capacity	50,000 ltr.	50,000 ltr.	MR
15	Exit Signage.	Required	Provided	MR
15. 16.	Provision of Lifts.			
10.	a) Pressurization of lift shaft	N/A	N/A	N/A
	b) Pressurization of lift lobby	N/A	N/A	N/A
	c) Communication in lift car	Required	Provided	MR
	d) Fireman's switch	Required	Provided	MR
	e) Lift signage	Required	Provided	MR
17.	Stand by Power Supply	Required	Provided	MR
	Refuge Area	N/A	N/A	N/A
18.	Total area location	N/A	N/A	N/A
		N/A	N/A	N/A
19.	Fire Control Room	N/A	N/A	N/A
	a) Detector system panel	IN/A	1	
	the Film of the second	N/A	N/A	N/A
	b) Flow switch panel	N/A N/A	N/A	N/A
	c) PA system panel	N/A N/A	N/A	N/A
	d) Battery backup			
	e) Building floor plan	N/A	N/A	N/A
	e) Building noor plan Special Fire Protection System for Protection of special Risk,		N/A	
20.	Special Fire Protection System	a for Protectio	n or special and s	

The fire protection systems provided in the guest house building were randomly tested, checked and found functional at the time of inspection.

In view of the deemed compliance of the minimum standards of fire prevention and fire safety measures as required under the rules, if approved, we may renew the FSC issued vide letter no. no. F6/DFS/MS/GH/2019/2200 dated 22/11/19, upto third floor only under rule 35 of the Delhi Fire Service rules 2010. Accordingly, DFA is put up for kind perusal and signature please.

Signature of the Inspecting Officer

1

5

5

Name: - Ravinder Singh Designation: - ADO (CC)

CGo (NOZ)

F.T. please. 1 Riv f Zejio