

c-6

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEAD QUARTERS: DELHI FIRE SERVICE: NEW DELHI - 110001

No F6/DFS/MS/2022/WZ/EH/BNQT./60

Dated: 27/10/2022

FIRE SAFETY CERTIFICATE

Certified that the M/s Nimantran Dil Se, Hall No.201, 2nd floor, N. N. Mall, Near M2K, Manglam Place, Sector-3, Rohini, Delhi-110085, is running at 2nd floor in building comprised of Double Basement + Gr. + 05upper floors was inspected by the officer concerned of this department on 12.09.2022 in the presence of Mr. Deepak Bubber and found that the said premises have complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules,2010 and that the premise is fit for occupancy Group D 'Assembly'(Banquet Hall) for Hall No.201, 2nd floor with effect from 27/10/2022 for a period of 03 (Three) years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules, 2010.

Issued on 27/10/2022 at New Delhi by


(Atul Garg)
DIRECTOR
Ph; 011-23414000

Conditions for the validity of Fire Safety Certificate:

1. All the fire safety arrangement provided there-in shall be maintained in good working conditions at all times.
2. Loss of life or property due to non functional fire safety measure shall be at the responsibility of the management.
3. The trained fire fighting staff should be available round the clock.
4. Any deviation with regard to the construction etc shall be verified by the concerned building sanctioning agency.
5. This certificate cannot be treated in any case for regularizations of unauthorized construction.
6. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director of Form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior to its expiry".
7. The owner / occupier shall submit a declaration every year in form "K" provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on
8. All the means of escape shall be kept free of any obstruction all the time to evacuate the occupant, in a safe manner, in the event of emergency.

http://www.delhi.gov.in/wps/wcm/connect/doi_fire/FIRE/Home/Fire+Safety+Acts+and+Rules/
http://www.delhi.gov.in/wps/wcm/connect/doi_fire/FIRE/Home/Forms

INSPECTION REPORT

1. Name & address of the building : M/s Nimantran Dil Se, Hall No.201, 2nd floor, N. N. Mall, Near M2K, Manglam Place, Sector-3, Rohini, Delhi-85.
2. Type of Occupancy : Assembly (2nd floor) Hall No. 201) (BANQUET HALL)
3. Type of Case : New Case
4. Details of Previous NOC : NA
5. Fire Safety directives letter No : NBC Part IV
6. Date of inspection : 12.09.2022
7. Name of Inspecting Officer : A.K.Sharma ADO(Rohini)
8. Name and designation of officers
From the building side : Mr. Deepak Babbar.
9. Year of Construction :
10. Applicant's letter No. : Online application no.2022040808630 dated 01.08.2022.

| S. No. | Minimum Standards on fire prevention and fire safety U/R 33 | UBBL/NBC Requirement | Provided at site | Remarks MR/NMR |
|--------|---|----------------------|------------------|----------------|
| 1. | Access to building [N. N. Mall, Manglam Place District Center issued FSC vide letter No.F.6/DFS/MS/2021/WZ/506 dated 14.10.2021] | | | |
| | <ul style="list-style-type: none"> • Road width • Gate width • Width of internal road | Banquet within Mall | As Above | MR |
| 2. | Number, Width, Type & Arrangement of Exits | | | |
| | a. Number of staircases | | | |
| | <ul style="list-style-type: none"> • Upper Floors • Basements | Banquet within mall | As Above | MR |
| | | Banquet within mall | As Above | MR |
| | b. Width of staircases | | | |
| | <ul style="list-style-type: none"> • Upper Floor • Basements | Banquet within mall | As Above | MR |
| | | Banquet within mall | As Above | MR |
| | c. Protection of exits | | | |
| | Fire check door | | | |
| | <ul style="list-style-type: none"> • Pressurization | Banquet within mall | As Above | MR |
| | | Banquet within mall | As Above | MR |
| | d. No. of continuous staircases to terrace | | | |
| | | Banquet within mall | As Above | MR |
| | e. Width of Corridor | | | |
| | | Banquet within mall | As Above | MR |
| | f. Door Size | 1.50m & 2m | Provided | MR |
| 3. | Compartmentation | | | |
| | <ul style="list-style-type: none"> • Fire check door • Sealing of electrical shafts • Fire Rating of shaft door • Water Curtain • Fire Dampers | Banquet within mall | As Above | MR |
| | | Banquet within mall | As Above | MR |
| | | Banquet within mall | As Above | MR |
| | | Banquet within mall | As Above | MR |
| | | Banquet within mall | As Above | MR |
| 4. | Smoke Management System | | | |
| | <ul style="list-style-type: none"> • Basements | Banquet within mall | As Above | MR |
| | <ul style="list-style-type: none"> • Upper floors | 12 ACPH | Exhaust fan | MR |
| 5. | Fire Extinguishers | | | |
| | <ul style="list-style-type: none"> • Total numbers • Types • IS marking | One " 300m2 | 07nos. | MR |
| | | ABC/CO2 | ABC/CO2 | MR |
| | | ISI marked | Yes | MR |
| 6. | First-Aid Hose Reels | | | |
| | <ul style="list-style-type: none"> • Total numbers on each floor • Length of hose reel hose • Nozzle diameter | 01 near to banquet | As Above | MR |
| | | 30mm | As Above | MR |
| | | 5m | As Above | MR |
| 7. | Automatic fire detection and alarming system | | | |
| | <ul style="list-style-type: none"> • Type of detectors • Location of Main Panel | Required | Provided | MR |
| | | NA | As Above | NA |

| | | | |
|--|----|----|----|
| • PA System Panel | NA | NA | NA |
| • Battery backup | NA | NA | NA |
| • Building Floor Plans | NA | NA | NA |
| Special Fire Protection System for Protection of special Risks, if any: | NA | NA | NA |

The fire protection systems provided in the building were test checked and found functional at the time of inspection.

Keeping in view the substantial compliance of the minimum standards on fire prevention and fire safety required under the rules it is recommended to grant Fire Safety Certificate under rule 35 of the Delhi Fire Service Rule 2010

[Signature]
23/9/22

Signature of the Inspecting Officer
Name Ajay Kumar Sharma
Designation ADO(Rohini)

~~DO (NW)~~

[Signature]
28/09/2022

Copy of Mall Nac and area of Hall/restaurant is not mentioned.

[Signature]
29/9/22

~~DO / NW~~

[Signature]
30/09/2022

Copy of main occupancy's FSC is placed at C-4. Resubmitted for approval please.

~~DO (NW/SW)~~

Total covered area of restaurant is 288 m² as per CAF. Recommended for issue of FSC pl

[Signature]
3/10/22

[Signature]
3/10/22