GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEAD QUARTERS: DELHI FIRE SERVICE: NEW DELHI-110001

No. F.6/DFS/MS/GH/SZ/2022/ 498

Dated: 02 /11/2022

FIRE SAFETY CERTIFICATE

Issued 02/11/2022 at New Delhi by.

(Sunil Chaudhary)
Dy. Chief Fire Officer (SZ)
Delhi Fire Service

Application ID No. 2022101419042 dated 17.10.2022

Following Fire Safety Directives must be adhered to: -

- 1. No occupancy used above third floor and basement used for storage purpose only shall be strictly adhered by Owner/Occupier.
- 2. All the means of escape shall be kept free of all type of obstruction all the time.
- 3. All the employees shall be acquainted with the use and maintenance of all fire equipments and method of smooth and speedy safe evacuation of occupants in case of emergency.
- 4. All the fire fighting equipments shall be maintained in perfect working condition all the time and any lapse rendering non-functional of fire safety measures, management shall be responsible.
- 5. Any deviation, with regards to construction, ventilation, occupation, electric installation etc. may be got verified from the concerned authorities.
- 6. The Fire Safety Certificate may not be treated in any case for regularizations of unauthorized construction / unauthorized use of land if any.
- 7. All comments / directions of licensing department shall always be permitted and followed.
- 8. The owner /occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rule 2010. The form is available on www.dfs.delhigovt.nic.in
- 9. The owner / occupier shall apply for renewal of this Fire Safety Certificate to the Director in 'Form J' (sub Rule (1) of Rule 37) along with copy of the certificate, six months prior to its expiry.

INSPECTION REPORT

1. Name & address of the building

: M/s. Hotel Mid Town Guest House, 17A/7, WEA, Karol

Bagh, New Delhi.

2. Type of Occupancy

: Lodging House

3. Building Composition:

: Said guest house building is comprised of basement, ground Plus three upper floors, using basement as storage, ground floor as reception, hall & shops, 1st, 2nd & 3rd floor each

having 07 guest rooms respectively (total 21 guest rooms)

4. Type of Case

: Renewal

: Nil

5. Details of previous NOC

: F.6/DFS/MS/GH/SZ/2019/1873 dated 30.09.2019

6. Fire Safety directives letter No

7. Date of inspection

: 26.10.2022

8. Name of the Inspecting Officers

: P.V. Rathee, Asstt. Div. Officer (SRD)

9. Name and designation of officers

0. /	Applicant's letter No. : A Minimum Standards on fire prevention and fire safety U/R 33	Fire safety arrangements as per FSC dt. 30.09.2019	2022101419042 date	Remarks MR/NMR	
	Access to building	- 111	MR		
-	Road width	06 mts	Provided	N/A	
	• Gate width	N/A	Directly accessible	N/A	
	Width of internal road	N/A	N/A	N/A	
	Number, Width, Type & Arrangemen	t of Exits			
	a. Number of staircases		-	- NAD	
	Upper Floors	01	01	MR	
	Basements	02	02	MR	
	b. Width of staircases	-	-	-	
	Upper Floors	1.25 mts	1.27 mts	MR being old case	
	Basements	1.25 mts	1.25 mts & .80 mts	MR being old case	
	c. Protection of exits	-	-	-	
	• Fire check door	N/A	N/A	N/A	
	Pressurization	N/A	N/A	N/A	
	e. No. of continuous staircases to	01	01	MR	
	terrace	Old case	2.5, 1.30 mts	MR being old case	
	g. Width of Corridor h. Door Size	Old case	0.85 to 204 mts	MR being old case	
	Compartmentation.				
3	Fire check door	N/A	N/A	N/A	
	• Sealing of electrical shafts	Required	Sealed	MR	
	 Fire Rating of shaft door 	N/A	N/A	N/A	
	Water Curtain	N/A	N/A	N/A	
	• Fire Dampers	N/A	N/A	N/A	
4	To word System				
4		30 a/c per hour	Exhaust fan provi		
	BasementsUpper floors	12 a/c per hour		ided MR	
-	5 Fire Extinguishers			146	
F	Total numbers	20	Provided	MR	
	• Types	CO ₂ , ABC, WCO ₂ ISI marked	Provided	MR	
	IS marking	131 Illai ked	Provided	MR	



				MR			
I	First-Aid Hose Reels.	01	Provided	MR			
	Total numbers on each floor	30 m	Provided	MR			
	 Length of hose reel hose 	5 mm	Provided				
	Nozzle diameter			MR			
	Automatic fire detection and alarming s	Carbon Monoxide	Provided				
	 Type of detectors 		Provided near reception	MR			
	 Location of Main Panel 	Required	N/A	N/A			
	 Location of Repeater Panel 	N/A	Provided	MR			
	Alternate source of power	Required N/A	N/A Provided	N/A			
	Hooters' Location			MR			
3	MOEFA	Required	Provided	MR			
)	Public Address System.	Required	Provided				
0	Automatic Sprinkler System.		7 11.1	MR			
	Basement	Required	Provided	N/A			
	Upper Floor	N/A	N/A	N/A			
	 Sprinkler above false ceiling 	N/A	N/A	IN/A			
11	Internal Hydrants			NI/A			
	Size of riser/down-comer	N/A	N/A	N/A			
	 Number of hydrants per floor 	N/A	N/A	N/A			
	Hose Box	N/A	N/A	N/A			
12	Yard Hydrants.						
	Total number of hydrants	N/A	N/A	N/A			
	Hose Box	N/A	N/A	N/A			
13	Pumping Arrangements.						
	Ground Level						
	Discharge of main Pump	N/A	N/A	N/A			
	Head of Main pump	N/A	N/A	N/A			
	Number of main pumps	N/A	N/A	N/A			
	Jockey Pump out put	N/A	N/A	N/A			
	Jockey pump head	N/A	N/A	N/A			
	Standby Pump out put	N/A	N/A	N/A			
	Standby Pump HeadAuto Starting/ Manual stopp	N/A	N/A	N/A			
	Auto Starting/ Manual stopp Pump House Access	1,111	N/A	N/A			
	•	N/A	N/A	N/A			
	Terrace level						
	Discharge of pump	450 LPI	M 450 LPM	MR			
	Head of the pump	40 mts	40 mts	MR			
		Require	ed Provided	MR			
	Power SupplyAuto Starting of pump	Require		MR			
			I TOVIUCU	IVIT			
14	Captive Water Storage for fire fighting.						
	Underground tank capacity Draw off connection	N/A N/A	N/A N/A	N/A N/A			
	Draw-off connectionFire service inlet	N/A N/A	N/A N/A	N/A N/A			
	Access to tank	N/A N/A	N/A N/A	N/A N/A			
	Overhead Tank capacity	5000 lts	5000 lts	MR			
15		Required	Provided	MR			
16	Exit Signage. Required Provided Provision of Lifts.						
10		N/A	N/A	N/A			
	Pressurization of Lift Shaft Pressurization of Lift Inhouse	N/A N/A	N/A	N/A N/A			
	Pressurization of Lift lobby Communication In lift Cor.	Required		MR			
	Communication In lift Car Firaman's Grounding Switch	Required		MR			
	• Fireman's Grounding Switch						
	 Lift Signage 	Required	Provided	MR			

		101 -					
17	Standby power supply	Required	Provided	MR			
18	Refuge Area.						
10	> Total Area	N/A	N/A	N/A			
	Location	N/A	N/A	N/A			
9	Fire Control Room						
	 Detector System Panel 	N/A	N/A	N/A			
	 Flow Switch Panel 	N/A	N/A	N/A			
	 PA System Panel 	N/A	N/A	N/A			
	 Battery backup 	Required	Provided	MR			
	 Building Floor Plans 	N/A	N/A	N/A			
)	Special Fire Protection Systems for Protection of special Risks, if any:	N/A	N/A	N/A			

The fire protection systems provided in the building were checked at random and found satisfactory at the time of inspection.

Note:- Fire Check Door not required as owner/occupier has applied in CAF MHA Portal. Number of beds is less than 10 at each floor

In view the deemed compliance of the minimum standards on fire prevention and fire safety measures as required under the Rules, the FSC issued vide letter F.6/DFS/MS/GH/SZ/2019/1873 dated 30.09.2019, renewal under Rule 37 of the Delhi Fire Service Rules 2010 is recommended.

DFA is put up for approval & signature please.

Signature of the Inspecting Officer
Name P.V. Rathee

Asstt. Div. Officer (SRD)

Ozero (dr.)

1 (1476) C-T. Letter is perter for Sigh. please

DY. CFO (5Z)

M.S. Q

ispoored