

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEAD QUARTERS, DELHI FIRE SERVICE, NEW DELHI - 110001

No.F6/DFS/MS/GH/NDZ/2022/ 494

Dated : 01./.11./2022

FIRE SAFETY CERTIFICATE

Certified that the New Victoria Guest House located at 1342, Sangtrashan, Pahar Ganj, Delhi comprised of Ground + 03 Upper floors, Ground floor (shops others), 1^{st} floor (06 guest rooms + Reception + 01 store), 2^{nd} floor (07 guest rooms), 3^{rd} floor (02 guest rooms + 05 store room closed), total 15 guest rooms. The FSC was earlier granted by this department vide letter No.F6/DFS/MS/GH/2019/331 dated 08/02/19 in the name & style Ms Victoria DX guest house and name changed to New Victoria guest house vide letter F6/DFS/MS/GH/2019/4957 dated 16/08/19 for 15 guest rooms only. Now, The premises was re-inspected by the officer concerned of this department on 13/10/22 in the presence of Mr. Dalip Kumar (Manager) and found that the said guest house building have deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the premises is fit for occupancy class Residential (Sub Division-A-1), 1^{st} floor (06 guest rooms + Reception + 01 store), 2^{nd} floor (07 guest rooms), 3^{rd} floor (02 guest rooms + 05 store room closed) total - 15 guest rooms only with effect from ..., 2^{n} , 2^{n} , 2^{n} , 2^{nd} floor (40 guest rooms + 05 store room closed) total - 15 guest rooms only with effect from ..., 2^{n} , 2^{n} , 2^{n} , 2^{nd} floor (40 guest rooms + 05 store room closed) total - 15 guest rooms only with effect from ..., 2^{n} , 2^{n} , 2^{n} , 2^{n} , 2^{n} floor (9, printed below.

31/15/

(S.K.Dua) Dy. Chief Fire Officer Delhi Fire Service

Copy to:-

- 1. The Commissioner, MCD, Civic Centre, New Delhi
- 2. The Addl. Commissioner of Police (Lic), First Floor, P.S. Defence Colony New Delhi. ID no 2021122129055 dated 21.12.22 & e-mail hotelnewvictoria@gmail.com dated 09.10.2022.
- 3. The Manager,

New Victoria Guest House, 1342, Sangtrashan, Pahar Ganj, Delhi. Conditions for the validity of Fire Safety Certificate

- 1. All the fire safety arrangements provided therein shall be maintained in good working conditions at all times.
- 2. Any loss of life or property due to non functional fire safety measures shall be at the responsibility of the management.
- 3. The trained fire fighting staff should be available round the clock.
- 4. Any deviation w.r.t. construction etc. shall be verified by the concerned building sanctioning authority.
- 5. This fire safety certificate may not be treated in any case for regularization of unauthorized construction, if any.
- 6. The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on <u>www.dfs.delhigovt.nic.in</u>
- 7. The means of escape shall be kept unobstructed / unlocked for unhindered evacuation in case of an emergency.
- 8. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six month prior to its expiry".
- 9. The flammable material for interior decoration shall strictly prohibited.

	NI25			
	INS III III	PECTION REP	PORT	
1.	Name & address of the building	•	oria Guest House	at 1342,
	T (Sangtrasł	ian, Pahar Ganj, D	elhi
2.	Type of occupancy:-	Residenti	al, Sub Division-A	\-1
		Ground + 03	Upper floors (total 15 g	uest rooms)
		+ Recention	or (shops others), 1^{st} f n + 01 store), 2^{nd} floor	loor (06 guest rooms
		3 rd floor (0	2 guest rooms $+$ 05 st	ore room closed as
		per buildi	ng plans)	ere room closed as
	Type of case:-	Renewal		
4.	Details of previous FSC:-	No. F6/DF	S/MS/GH/2019/3	31 dated
		08/02/19.		
	Fire safety directives No	N/A		
	Date of inspection:-	13/10/22		
	Name of the inspecting office		der Singh (ADO/C	CC)
	Name & designation of office	r	•	,
	From the building side:-	Mr. Dalip	Kumar (Manager))
	Year of construction:-	2001		
10.	Applicant's letter No:-	ID no 20211	22129055 dated 21.1	2.22 & e-mail
		hotelnewy	<u>ictoria@gmail.com</u> da	
				Old Case
S.No.	Minimum Standards on fire	Requirement/	Provided at site	
	Prevention and fire safety U/R 33	Existing fire safet	y	MR/NMR
1.	Access to Building			
	1) Road width	N/A	4 mtr. (approx)	MR
	2) Gate width	N/A	N/A	N/A
	3)Width of internal road	N/A	N/A	N/A
2.	Number, Width Type & Arr	rangement of E	xits	
	A. Number of staircases			
	1. Upper floors	01 Nos.	01 Nos.	MR
	2. Basements	N/A	N/A	N/A
	B. Width of staircase			
	1. Upper floors	0.80 mtr.	0.84 to 0.90 mtr.	MR
	2. Basements	N/A	N/A	N/A
	C. Protection of exits			
	1. Fire check door	N/A	N/A	N/A
	2. Pressurization	N/A	N/A	N/A
	D. No. of continuous	01	01	MR
	staircase to terrace			
	E. Width of corridor	N/A	N/A	N/A
2	F. Door size	01 mtr.	01 mtr.	MR
3.	Compartmentation			
	1) Fire check door	N/A N/A	N/A N/A	N/A
	2) Sealing of electrical shafts	N/A N/A		N/A
	3) Fire rating of shaft door4) Water curtain	N/A N/A	N/A N/A	N/A
	5) Fire Dampers	N/A N/A	N/A N/A	N/A
4.	Smoke Management System	11/11		N/A
4.	1) Basements	30 ACPH	N/A	NI/A
	2) Upper floors	12 ACPH	Natural/exhausr	N/A
5.	Fire Extinguishers	12 ACI II	ratural/exhaust	MR
5.	1) Total numbers	08 Nos.	08 Nos.	MD
	2) Types	ABC & CO2	ABC & CO2	MR MR
	3) ISI marking	Required	Provided	MR
6.	First-Aid Hose Reel	required	TIOTICU	IVIN
	IIU IIUJE INEE			

Ģ

N	26
---	----

	.~	1/26			
	1) Total number of eachfloor	01	1 st floor & 3 rd floor	MR	
	2) Length of hose reel hose	30 mtr.	30 mtr.	MR	
	3) Nozzle diameter	05 mm	05 mm	MR	
7.	Automatic Fire Detection & Alarming System				
	1) Type of detectors CO	Required	Provided	MR	
	2) Location of main panel	First floor	Provided	MR	
	3) Location of repeater panel	N/A	N/A	N/A	
	4) Alternate source of power	Required	Provided	MR	
	5) Hooter's Location	At each floor	Provided	MR	
0	MOEFA	N/A	N/A	N/A	
<u>8.</u> 9.	Public Address System	Required	Provided	MR	
	Automatic Sprinkler System	Required			
10.	1) Basement	N/A	N/A	N/A	
	2) Upper floors	N/A	N/A	N/A	
	3) Sprinkler above false	N/A	N/A	N/A	
	ceiling	1.0.1			
11.	Internal Hydrants				
	1) Size of riser/down-comer	N/A	N/A	N/A	
	2) Number of hydrants per	N/A	N/A	N/A	
	floor				
	3) Hose box	N/A	N/A	N/A	
12.	Yard Hydrants				
2.	1) Total number of hydrants	N/A	N/A	N/A	
	2) Hose box	N/A	N/A	N/A	
2	Pumping Arrangement				
13.	1) Ground level	N/A	N/A	N/A	
	a) Discharge of main	N/A	N/A	N/A	
	pump				
	b) Head of main pump	N/A	N/A	N/A	
	c) Number of main pump	N/A	N/A	N/A	
	d) Jockey pump out put	N/A	N/A	N/A	
	e) Jockey pump head	N/A	N/A	N/A N/A	
	f) Stand by pump output	N/A	N/A	N/A N/A	
	g) Stand by pump head	N/A	N/A	N/A N/A	
	h) Auto starting/Manual	N/A	N/A	NA	
	stopping				
	2) Terrace level		225 I DM	MR	
	a) Discharge of pump	225 LPM	225 LPM	MR	
	b) Head of pump	30 mtr.	30 mtr.	MR	
	c) Power supply	Required	Provided	MR	
	1) Auto starting of nump	Required	Provided		
4	Captive Water Storage for F	ire Fighting		N/A	
14.	1) Under ground tank	N/A	N/A		
	capacity			N/A	
	a) Draw-off connection	N/A	N/A	N/A	
	b) Fire service inlet	N/A	N/A	N/A	
	to toply	N/A	N/A	MR	
	-/ Link	2500 ltr.	2500 ltr.		
	d) Over head tank capacity			MR	
		Required	Provided	IVII	
5.	Exit Signage.				

N/27

20.	Special Fire Protection Syste Risk, if any:	m for Prote	ction of special	N/A
	e) Building floor plan	N/A	N/A	N/A
	d) Battery backup	N/A	N/A	N/A
	c) PA system panel	N/A	N/A	N/A
	b) Flow switch panel	N/A	N/A	N/A
	a) Detector system panel	N/A	N/A	N/A
19.	Fire Control Room	N/A	N/A	N/A
	Total area location	N/A	N/A	N/A
18.	Refuge Area	N/A	N/A	N/A
17.	Stand by Power Supply	N/A	N/A	N/A
	e) Lift signage	N/A	N/A	N/A
	d) Fireman's switch	N/A	N/A	N/A
	c) Communication in lift car	N/A	N/A	N/A
	b) Pressurization of lift lobby	N/A	N/A	N/A
	a) Pressurization of lift shaft	N/A	N/A	N/A

The fire protection systems provided in the building were randomly tested, checked and found functional at the time of inspection. Further, 05 store room and 02 guest room is existing at third floor whereas earlier FSC was issued only for 02 guest room only, now 05 store has been closed as per building plans submitted through e- mail dated 09.10.2022.

In view of the deemed compliance of the minimum standards of fire prevention and fire safety measures as required under the rules, if approved, we may renew the FSC issued vide letter no. F6/DFS/MS/GH/2019/331 dated 08/02/19, renewal under rule 35 of the Delhi Fire Service rules 2010 up to third floor only.

Signature of the Inspecting Officer

Name: - Ravinder Singh Designation: - ADO (CC)

h Ja

P

e

21

ne ne cer

egi

rm igo hir Cert or t ibit

(NO02) or I can porus Sepsture

IUC

DOCD

94 1

20