

## C29 GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEAD QUARTERS, DELHI FIRE SERVICE, NEW DELHI - 110001

No.F6/DFS/MS/GH/NDZ/2022/ 502

Dated: 0.4/.11.../2022

## FIRE SAFETY CERTIFICATE

Certified that the M/s Euro Guest House located at 9057 & 9060/1, Multani Dhanda, Pahar Ganj, New Delhi comprised of Ground + 02 Upper floors, Ground floor - reception, 1st floor and 2<sup>nd</sup> floor (06 guest rooms at each floor), total 12 guest rooms The FSC was earlier granted by this department vide letter No. F6/DFS/MS/GH/NDZ/2019/2070 dated 28/10/19 for 12 guest rooms only. Now, the premises was re-inspected by the officer concerned of this department on 26/10/22 in the presence of Mr. Maan Singh (Manager) and found that the said guest house building have deemed complied with the fire prevention and fire safety requirements in accordance with Rule 33 of the Delhi Fire Service Rules, 2010 and that the premises is fit for occupancy class Residential, Sub Division-A-1 Ground floor (reception), 1st floor and 2nd floor (06 guest rooms at each floor), total 12 guest rooms only up to second floor, with effect from for period of three years in accordance with Rule 36 unless renewed under Rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under Rule 38 of the Delhi Fire Service Rules 2010, printed below.

Issued 04 11 20 21 New Delhi by.

Dy. Chief Fire Officer Delhi Fire Service

Copy to:-

1. The Commissioner, MCD, Civic Centre, New Delhi: Kindly to ensure the occupancy as detailed above.

2. The Addl. Commissioner of Police (Lic), First Floor, P.S. Defence Colony New Delhi. Online id no. 2022100418612 dated 05/10/22.

3. The Manager, M/s Euro Guest House 9057 & 9060/1, Multani Dhanda, Pahar Ganj, New Delhi.

## Conditions for the validity of fire safety certificate

1. All the fire safety arrangements provided therein shall be maintained in good working conditions at all times.

2. Any loss of life or property due to non functional fire safety measures shall be at the responsibility of the management.

3. The trained fire fighting staff should be available round the clock.

- 4. Any deviation w.r.t. construction etc. shall be verified by the concerned building sanctioning authority.
- 5. This fire safety certificate may not be treated in any case for regularization of unauthorized construction, if any.
- 6. The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in
- The means of escape shall be kept unobstructed / unlocked for unhindered evacuation in case of an emergency. 7.
- 8. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in form 'J' [sub rule (I) of rule 37] along with a copy of this Certificate, six month prior to its expiry.
- 9. Any flammable material for interior decoration is prohibited.

INSPECTION REPORT

1. Name & address of the building M/s Euro Guest House located at

9057 & 9060/1, Multani Dhanda, Pahar Ganj,

New Delhi.

2. Type of occupancy:-Residential, Sub Division-A-1

Gr. + 02 Upper floors (total 12 Guest rooms) Ground floor -reception, 1st floor & 2nd floor

(06 guest rooms at each floor)

3. Type of case:-Renewal

4. Details of previous FSC:-F6/DFS/MS/GH/NDZ/2019/2070 dated

28/10/19.

5. Fire safety directives No.-

6. Date of inspection:-

7. Name of the inspecting officer:-

8. Name & designation of officer

From the building side:-

9. Year of construction:-

10. Applicant's letter No:-

N/A

26/10/22

Sh. Ravinder Singh (ADO/CC)

Mr. Maan Singh (Manager)

2009

2022100418612 dated 05/10/22.

	rippheant's letter ivo			Old Case
S.No.	Minimum Standards on fire Prevention and fire safety U/R 33	Requiremen Existing	t Provided at site	Remarks MR/NMR
1.	Access to Building			
	1) Road width	N/A	6 mtr.	N/A
	2) Gate width	N/A	N/A	N/A
ŀ	3)Width of internal road	N/A	N/A	N/A
2.	Number, Width Type & An	rrangement of I	Exits	
	A. Number of staircases			
ł	1. Upper floors	01 Nos.	01 Nos.	MR
t	2. Basements	N/A	N/A	N/A
	B. Width of staircase			
ŀ	1. Upper floors	80cms.	95 to 117 cms.	MR
t	2. Basements	N/A	N/A	N/A
ľ	C. Protection of exits			27/4
	1. Fire check door	N/A	N/A	N/A
	2. Pressurization	N/A	N/A	N/A
	D. No. of continuous staircase to terrace	N/A	N/A	N/A
-	E. Width of corridor	N/A	N/A	N/A
	F. Door size	1 mtr.	1 mtr.	MR
	Compartmentation			
	1) Fire check door	N/A	N/A	N/A
13	2) Sealing of electrical shafts	N/A	N/A	N/A
3	3) Fire rating of shaft door	N/A	N/A	N/A
4	) Water curtain	N/A	N/A	N/A
	) Fire Dampers	N/A	N/A	N/A
. S	moke Management System		77/4	NI/A
	) Basements	30 ACPH	2	N/A
	Upper floors	12 ACPH	Natural	MR

NIG

5.	Fire Extinguishers					
	1) Total numbers	OQ Nos				
		08 Nos.	08 Nos.	MR		
	2) Types 3) ISI marking	ABC & CO2	1.1DC & CO2	MR		
	First-Aid Hose Reel	Required	Provided	MR		
6.		101				
	1) Total number of eachfloo		01	MR		
	2) Length of hose reel hose	30 mtr.	30 mtr.	MR		
_	3) Nozzle diameter	05 mm	05 mm	MR		
7.	Automatic Fire Detection & Alarming System					
	1) Type of detectors	N/A	N/A	N/A		
	2) Location of main panel	N/A	N/A	N/A		
	3) Location of repeater pane		N/A	N/A		
	4) Alternate source of power		N/A	N/A		
	5) Hooter's Location	N/A	N/A	N/A		
3.	MOEFA	Required	Provided	MR		
).	Public Address System	Required	provided	MR		
10.	Automatic Sprinkler System	m	provided	IVIIC		
	1) Basement	N/A	N/A	N/A		
	2) Upper floors	N/A	N/A	N/A		
	3) Sprinkler above false	N/A	N/A	N/A		
	ceiling	1771	IV/A	IN/A		
1.	Internal Hydrants					
	1) Size of riser/down-comer	N/A	N/A	N/A		
	2) Number of hydrants per	N/A	N/A	N/A		
	floor	1,112	14/71	I IV/A		
	3) Hose box	N/A	N/A	N/A		
2.	Yard Hydrants	1 1/12	14/21	11//1		
-	1) Total number of hydrants	N/A	N/A	N/A		
	2) Hose box	N/A	N/A	N/A		
	Pumping Arrangement	1,,,,,	1,771	11//1		
•	1) Ground level	N/A	N/A	N/A		
	a) Discharge of main	N/A	N/A	N/A		
	, ,	IV/A	18/74	IVA		
	b) Head of main pump	N/A	N/A	N/A		
	c) Number of main	N/A	N/A	N/A		
	,	IN/A	IN/A	IVA		
	pump	N/A	N/A	N/A		
	d) Jockey pump out put		N/A	N/A		
	e) Jockey pump head	N/A	N/A	N/A		
	f) Stand by pump output	N/A	N/A	N/A		
	g) Stand by pump head	N/A		N/A		
	h) Auto starting/Manual	N/A	N/A	11/1		
L	stopping					
	2) Terrace level	450 1 774	450 I DM	MR		
	a) Discharge of pump		450 LPM	MR		
	b) Head of pump	5 0 111011	30 mtr.	MR		
	c) Power supply	required	Provided	MR		
	d) Auto starting of pump	Required	provided	IVII		

Mo

14.	Captive Water Storage for Fire Fighting				
	Under ground tank     capacity	N/A	N/A	N/A	
	a) Draw-off connection	N/A	N/A	N/A	
	b) Fire service inlet	N/A	N/A	N/A	
	c) Access to tank	N/A	N/A	N/A	
1.5	d) Over head tank capacity	5000 ltr.	5000 ltr.	MR	
15.	Exit Signage.	Required	Provided	MR	
16.	Provision of Lifts.				
	<ul> <li>a) Pressurization of lift shaft</li> </ul>	N/A	N/A	N/A	
	b) Pressurization of lift lobby	N/A	N/A	N/A	
	c) Communication in lift car	N/A	N/A	N/A	
	d) Fireman's switch	N/A	N/A	N/A	
	e) Lift signage	N/A	N/A	N/A	
17.	Stand by Power Supply	Required	Provided	MR	
18.	Refuge Area	N/A	N/A	N/A	
	Total area location	N/A	N/A	N/A	
19.	Fire Control Room	N/A	N/A	N/A	
	a) Detector system panel	N/A	N/A	N/A	
	b) Flow switch panel	N/A	N/A	N/A	
	c) PA system panel	N/A	N/A	N/A	
	d) Battery backup	N/A	N/A	N/A	
	e) Building floor plan	N/A	N/A	N/A	
20.	Special Fire Protection System for Protection of special Risk, if any:				

The fire protection systems provided in the guest house building were randomly tested, checked and found functional at the time of inspection.

In view of the deemed compliance of the minimum standards of fire prevention and fire safety measures as required under the rules, if approved, we may renew the FSC issued vide letter no. F6/DFS/MS/GH/NDZ/2019/2070 dated 28/10/19, up to second floor only under rule 35 of the Delhi Fire Service rules 2010. Accordingly, DFA is put up for kind perusal and signature please.

Signature of the Inspecting Officer

Name: - Ravinder Singh Designation: - ADO (CC)

2/11/22 0.462/002

F.T. please-

KIV 03/11/m

" Ascopoured Assipertub

for Kno forusolace

Syngime (No.

F.P. why

4111/2

DIEFOUNDE

MR MR