



**GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI**  
**HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI- 110001**




No. F6/DFS/MS/School/WZ/2022/1225

Dated: 10/11/22

**FIRE SAFETY CERTIFICATE**

Certified that the **PP International School** located at LD- Block, Pitampura, Delhi- 110034, **running at Ground & First Floor** in a building comprised of Basement, Ground plus four Upper Floor, was issued Fire Safety Certificate by this department Vide Letter No. F6/DFS/MS/WZ/School/2019/645 dated 27.03.2019. The school building was re-inspected by the officer concerned of this department on 02.11.2022 in the presence of Sh. Santosh, admin head of the school and found that the premises / building have deemed complied with the fire prevention and fire safety requirements in accordance with NBC-IV and that the premises/building is fit for occupancy class "Educational Building" Group B (**Ground & First Floor Only**) with effect from 10/11/22 for a period of three years in accordance with Rule 36 unless renewed under Rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under Rule 38 of the Delhi Fire Service Rules 2010, printed overleaf.

Issued on ...10/11/22... at New Delhi by.

  
(Dharampal Bhardwaj)  
Dy. Chief Fire Officer  
(West Zone)

Copy to: -

1. The Director, Directorate of Education, GNCT of Delhi, Old Secretariat Delhi – 54.
2. The Principal, PP International School, LD- Block, Pitampura, Delhi- 110034.

**Following fire safety directives must be adhered to: -**

1. All the means of escape shall be kept free of all type of obstruction all the time.
2. All the employees shall be acquainted with the use and maintenance of all fire equipments and method of smooth and speedy safe evacuation of occupants in case of emergency.
3. All the fire fighting equipments shall be maintained in perfect working condition all the time and any lapse rendering non-functional if fire safety measures, management shall be responsible.
4. Any deviation, with regards to construction, ventilation, occupation, electric installation etc. may be got verified from the concerned authorities.
5. The Fire Safety Certificate may not be treated in any case for regularizations of unauthorized construction / unauthorized use of land if any.
6. All comments / directions of licensing Department shall always be permitted and followed.
7. The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rule 2010. The form is available on [www.dfs.delhigovt.nic.in](http://www.dfs.delhigovt.nic.in)
8. The owner / occupier shall apply for renewal of this Fire Safety Certificate to the Director in 'Form J' (sub Rule (1) of Rule 37) along with copy of the certificate, six months prior to its expiry.
9. This FSC is valid for ground and first floor only.

**INSPECTION REPORT**

1. Name & address of the building : PP International School, LD-Block, Pitampura, New Delhi.
2. Type of Occupancy : Educational
3. Type of Case : Renewal
4. Details of previous NOC : F6/DFS/MS/WZ/School/2019/645 dated 27.03.2019
5. Fire Safety directives letter No : F.6/DFS/MS/BP/2009/835 dated 23.03.2009
6. Date of inspection : 02.11.2022
7. Name of the Inspecting Officers : M.K. Chattopadhyay, DO (West)
8. Name and designation of officers from the building side : Sh. Santosh, Admin Head
9. Year of Construction : 2011
10. Applicant's letter No. : Form 'J'

The school is running at ground & first floor in a building comprised of basement, ground plus four upper floors.

S. No.	Minimum Standards on fire prevention and fire safety U/R 33	Requirement as per Rule 35 (6)	Provided at site	Remarks MR/NMR
1	<b>Access to building</b>			
	<ul style="list-style-type: none"> <li>• Road width</li> <li>• Gate width</li> <li>• Width of internal road</li> </ul>	09 mts 05 mts N/A	Provided Provided N/A	MR MR N/A
2	<b>Number, Width, Type &amp; Arrangement of Exits</b>			
	a. Number of staircases	-----	-----	-----
	<ul style="list-style-type: none"> <li>• Upper Floors</li> <li>• Basements</li> </ul>	04 mts	Provided	MR
	b. Width of staircases	06 & 01 Ramp	Provided	MR
	<ul style="list-style-type: none"> <li>• Upper Floors</li> <li>• Basements</li> </ul>	-----	-----	-----
		1.5 mts each	2.0 mts x 01 no., 1.80 mts x 02 nos., 1.78 mts x 01 no.	MR
		1.5 mts each	1.85mts x 03 nos, 1.55 mts x 02 nos, 1.45mts. x 01	MR
	c. Protection of exits	-----	-----	-----
	<ul style="list-style-type: none"> <li>• Fire check door</li> <li>• Pressurization</li> </ul>	Required N/A	Provided N/A	MR N/A
	e. No. of continuous staircases to terrace	02	02	MR
	g. Width of Corridor	1.5 mts	Provided	MR
	h. Door Size	1.0 mt.	Provided	MR
3	<b>Compartmentation.</b>			
	<ul style="list-style-type: none"> <li>• Fire check door</li> <li>• Sealing of electrical shafts</li> <li>• Fire Rating of shaft door</li> <li>• Water Curtain</li> <li>• Fire Dampers</li> </ul>	Required Required N/A N/A N/A	Provided Provided N/A N/A N/A	MR MR N/A N/A N/A
4	<b>Smoke Management System.</b>			
	<ul style="list-style-type: none"> <li>• Basements</li> <li>• Upper floors</li> </ul>	30 a/c per hour 12 a/c per hour	Provided Natural ventilation	MR MR
5	<b>Fire Extinguishers</b>			
	<ul style="list-style-type: none"> <li>• Total numbers</li> <li>• Types</li> <li>• IS marking</li> </ul>	44 nos. ABC, CO <sub>2</sub> type ISI marked	Provided Provided Provided	MR MR MR

0-26

Standard  
Refuge  
Fi

6	<b>First-Aid Hose Reels.</b>			
	• Total numbers on each floor	03	Provided	MR
	• Length of hose reel hose	30 m	Provided	MR
	• Nozzle diameter	5 mm	Provided	MR
7	<b>Automatic fire detection and alarming system</b>			
	• Type of detectors	Required	Provided	MR
	• Location of Main Panel	Required	Provided	MR
	• Location of Repeater Panel	N/A	N/A	N/A
	• Alternate source of power	Required	Provided	MR
	• Hooters' Location	Required	Provided	MR
8	<b>MOEFA</b>	Required	Provided	MR
9	<b>Public Address System.</b>	Required	Provided	MR
10	<b>Automatic Sprinkler System</b>			
	• Basement	Required	Provided	MR
	• Upper Floor	N/A	N/A	N/A
	• Sprinkler above false ceiling	N/A	N/A	N/A
11	<b>Internal Hydrants</b>			
	• Size of riser/down-comer	100 mm	Provided	MR
	• Number of hydrants per floor	03	Provided	MR
	• Hose Box	03	Provided	MR
12	<b>Yard Hydrants.</b>			
	• Total number of hydrants	N/A	N/A	N/A
	• Hose Box	N/A	N/A	N/A
13	<b>Pumping Arrangements</b>			
	• Ground Level	---	-----	-----
	➤ Discharge of main Pump	N/A	N/A	N/A
	➤ Head of Main pump	N/A	N/A	N/A
	➤ Number of main pumps	N/A	N/A	N/A
	➤ Jockey Pump out put	N/A	N/A	N/A
	➤ Jockey pump head	N/A	N/A	N/A
	➤ Standby Pump out put	N/A	N/A	N/A
	➤ Standby Pump Head	N/A	N/A	N/A
	➤ Auto Starting/ Manual stopping	N/A	N/A	N/A
	➤ Pump House Access	N/A	N/A	N/A
	• Terrace level	---	-----	-----
	➤ Discharge of pump	900 & 220 LPM	Provided	MR
	➤ Head of the pump	40 mts	Provided	MR
	➤ Power Supply	Required	Provided	MR
	➤ Auto Starting of pump	Required	Provided	MR
14	<b>Captive Water Storage for fire fighting</b>			
	• Underground tank capacity	N/A	N/A	N/A
	➤ Draw-off connection	N/A	N/A	N/A
	➤ Fire service inlet	N/A	Provided	---
	➤ Access to tank	N/A	N/A	N/A
	• Overhead Tank capacity	50,000 lts	Provided	MR
15	<b>Exit Signage.</b>	Required	Provided	MR
16	<b>Provision of Lifts.</b>			
	• Pressurization of Lift Shaft	N/A	N/A	N/A
	• Pressurization of Lift lobby	N/A	N/A	N/A
	• Communication In lift Car	N/A	N/A	N/A
	• Fireman's Grounding Switch	N/A	N/A	N/A
	• Lift Signage	N/A	N/A	N/A






Standby power supply		Required	Provided	MR
<b>Refuge Area.</b>				
➤ Total Area		N/A	N/A	N/A
➤ Location		N/A	N/A	N/A
<b>Fire Control Room</b>				
• Detector System Panel		N/A	N/A	N/A
• Flow Switch Panel		N/A	N/A	N/A
• PA System Panel		N/A	N/A	N/A
• Batter backup		N/A	N/A	N/A
• Building Floor Plans		N/A	N/A	N/A
20	Special Fire Protection Systems for Protection of special Risks, if any:	Required 02 ABC type fire extinguishers near elect. panel	Provided	MR

The fire protection systems provided in the building were checked and found functional at the time of inspection.

Note: All the shortcomings pointed out by this department vide letter No. F/DFS/MS/WZ/2022/School/435 dated 27.07.2022, have been complied with by the building management.

In view the deemed compliance of the minimum standards on fire prevention and fire safety measures as required under the rules, the renewal of the NOC issued vide letter No. F6/DFS/MS/WZ/School/2019/645 dated 27.03.2019, is recommended.


Accordingly DFA is put up for approval & signature please.

  
04/11/2022

Signature of the Inspecting Officer  
Divisional Officer (West Division)

D.O. (WEST) 497  
DATED 04/11/22.


~~DCFO (WZ)~~


  
04/11/2022

~~DCFO West~~

F.T. letter is put up for Sign. please:

~~DCFO (WZ)~~

  
04/11/2022

  
04/11/2022

~~DCFO cell~~