C-114

## GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEAD QUARTERS: DELHI FIRE SERVICE: NEW DELHI-110001

No. F.6/DFS/MS/GH/SZ/2022/ 507

Dated: 11 11 2022

#### FIRE SAFETY CERTIFICATE

Certified that the M/s. Hotel Ashoka International located at 3382, Christian Colony D.B.G. Road, Karol Bagh, New Delhi- 110005, was granted Fire Safety Certificate vide this department letter No. F6/DFS/MS/GH/SZ/2019/1919 dated 07.10.2019, comprised of basement, ground floor, mezzanine plus four upper floors, using basement as others property, ground floor as reception & 3 guest rooms, mezzanine floor as office (between staircase area), first, second & third floor each having 06 guest rooms respectively (total 21 guest rooms). The guest house was re-inspected by the officer concerned of this department on 07.11.2022 in presence of Mr. Ashok Kumar (Owner) and found that the guest house management have deemed complied with the fire prevention and fire safety requirements in accordance with Rule 33 of the Delhi Fire Service Rules, 2010 and that the premises is fit for occupancy class residential (guest house) for ground floor as reception & 3 guest rooms, first, second & third floor each having 06 guest rooms respectively (total 21 guest rooms) with effect from 11112227 for a period of three years in accordance with Rule 36 unless renewed under Rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under Rule 38 of the Delhi Fire Service Rules 2010, printed below.

Issued 11 11 2022 at New Delhi by.

(Sunil Chaudhary) Dy. Chief Fire Officer (SZ) Delhi Fire Service

B

# Application ID No. 2022110319717 dated 04.11.2022

### Following Fire Safety Directives must be adhered to: -

- 1. No occupancy used above third floor and basement used for storage purpose only shall be strictly adhered by Owner/Occupier.
- 2. All the means of escape shall be kept free of all type of obstruction all the time.
- 3. All the employees shall be acquainted with the use and maintenance of all fire equipments and method of smooth and speedy safe evacuation of occupants in case of emergency.
- 4. All the fire fighting equipments shall be maintained in perfect working condition all the time and any lapse rendering non-functional of fire safety measures, management shall be responsible.
- 5. Any deviation, with regards to construction, ventilation, occupation, electric installation etc. may be got verified from the concerned authorities.
- 6. The Fire Safety Certificate may not be treated in any case for regularizations of unauthorized construction / unauthorized use of land if any.
- 7. All comments / directions of licensing department shall always be permitted and followed.
- 8. The owner /occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rule 2010. The form is available on www.dfs.delhigovt.nic.in
- 9. The owner / occupier shall apply for renewal of this Fire Safety Certificate to the Director in 'Form J' (sub Rule (1) of Rule 37) along with copy of the certificate, six months prior to its expiry.

NIZT

# **INSPECTION REPORT**

G

	ame &	address of the building	: N	M/s. Hotel Ash Colony, D.B.G	Rd.	, Karol Bagh, 1	New	Delhi- 1100	
, - <b>.</b>		Oscupance	.1.0	adaina House					
A DATE OF ST The sold				st house is com	nris	ed of basemen	t, grou	ınd. mezzan	
				an flaare using b	haser	nent (other's o	whersi	np), ground	
		plus for	ir uppe	n & 03 guest ro	Daser	Mazzanine f	loor (S	sealed) 1" &	
		floor (re	ceptio	n & 03 guest ro	oms	), Mezzamice r	ctively	& 4 <sup>th</sup> floor	
	$2^{nd}$ & $3^{rd}$ floor each having 06 guest rooms respectively & $4^{th}$ flo (Sealed by guest house management) (total 21 guest rooms)								
		(Sealed	by gue	est house manag	geme	ent) (total 21 gi	jest ro	oms)	
a	Type		· D /	· Peneuval					
<ol> <li>Type of Case</li> <li>Details of previous NOC</li> </ol>				: F6/DFS/MS/GH/SZ/2019/1919 dated 07.10.2019					
		afety directives letter No		: Nil : 07.11.2022					
7.	Date o	f inspection	· D	V. Rathee, Ass	u. Di	v. Officer. (SR	D)		
8	Name	of the Inspecting Officers		v. Ramee, riss					
9.		and designation of officers		lr. Ashok Kuma	ar (O	wner)			
	from the bulleting state			2001					
		Construction	: 20	oline Application	n Id	202211031971	7 dated	04.11.2022	
10.				Online Application 1 Existing fire safety		Provided at		Remarks	
	N	linimum Standards on fire		Existing fire safet		site		MR/NMR	
	pre	vention and fire safety U/R	33	FSC dt. 07.10.201	19	site			
	-	s to building			T			MR	
		Road width		06 mts		Provided		N/A	
		Gate width	ſ	N/A		Directly accessibl	e		
	•	Width of internal road		N/A		N/A		N/A	
	•	ber, Width, Type & Arrang	ement	of Exits					
2	Num	mber of staircases	,	-		-		-	
	a. Nu		-	01		01		MR	
	•	Upper Floors		02		02		MR	
	•	Basements	-	-		-		-	
	b. W	idth of staircases		1.25 mts.	1.1	8 to 1.20 mts		ing old case	
	•	Upper Floors	-	1.25 mts.	1.50	0 & 0.88 mts.	MR be	ing old case	
	•	Basements	-			-		-	
	c. Pr	otection of exits		- N/A		N/A		N/A	
		Fire check door	,			N/A		N/A	
		Pressurization	,	N/A		01			
	e. N	to. of continuous staircase	es to	01		01		MR	
	terra	ce		Old case		1.0 mts.	MR	being old case	
	g. W	idth of Corridor		Old case	0.8	87 to 2.0 mts	MR	being old case	
	h. D	oor Size		ond ease					
3	Con	partmentation.		NI/A		N/A		N/A	
		Fire check door		N/A Required		Sealed		MR	
		<ul> <li>Sealing of electrical shafts</li> </ul>	,	N/A		N/A		N/A	
	•	<ul> <li>Fire Rating of shaft door</li> </ul>		N/A		N/A		N/A	
		Water Curtain		N/A		N/A		N/A	
~		<ul> <li>Fire Dampers</li> </ul>							
-			Smoke Management System.		Ex	Exhaust fan provided		MR	
4	Sme	oke Management System.		30 a/c ber nour					
4		<ul> <li>Basements</li> </ul>		30 a/c per hour 12 a/c per hour		haust fan provided		MR	
-		<ul><li>Basements</li><li>Upper floors</li></ul>				haust fan provided		MR	
4		<ul> <li>Basements</li> <li>Upper floors</li> <li>Extinguishers</li> </ul>				Provided		MR	
		<ul><li>Basements</li><li>Upper floors</li></ul>		12 a/c per hour					

B

		N/23.			
	First-Aid Hose Reels.			MR	
	<ul> <li>Lotal numbers on each floor</li> </ul>	01	Provided	MR	
	<ul> <li>Length of hose reel hose</li> </ul>	30 m	Provided		
	<ul> <li>Nozzle diameter</li> </ul>	5 mm	Provided	MR	
	Automatic fire detection and alarmin	g system.			
	• Type of detectors	Carbon Monoxide	Provided	MR	
	• Location of Main Panel	Required	Provided near recepti	on MR	
	<ul> <li>Location of Repeater Panel</li> </ul>	N/A	N/A	N'A	
	<ul> <li>Alternate source of power</li> </ul>	Required	Provided	MR	
	<ul> <li>Hooters' Location</li> </ul>	N/A	N/A	NA	
3	MOEFA	Required	Provided	MR	
9			Provided	MR	
	Public Address System.	Required	Flovided		
10	Automatic Sprinkler System.			N A	
	Basement	N/A		N A	
	Upper Floor	N/A	N/A		
	<ul> <li>Sprinkler above false ceiling</li> </ul>	N/A	N/A	N/A	
11	Internal Hydrants				
	<ul> <li>Size of riser/down-comer</li> </ul>	N/A	100mm	N/A	
	• Number of hydrants per floor	N/A	01	N/A	
	Hose Box	N/A	01	N/A	
12	Yard Hydrants.		l		
	Total number of hydrants	N/A	N/A	N/A	
	<ul> <li>Hose Box</li> </ul>	N/A	N/A	N/A	
13	Pumping Arrangements.				
	Ground Level				
	<ul> <li>Discharge of main Pump</li> <li>Head of Main pump</li> </ul>	N/A	N/A	N/A	
	<ul><li>Head of Main pump</li><li>Number of main pumps</li></ul>		N/A	N/A	
	<ul> <li>Jockey Pump out put</li> </ul>	N/A N/A	N/A	N/A	
	<ul> <li>Jockey pump head</li> </ul>	N/A N/A		N/A	
	<ul> <li>Standby Pump out put</li> </ul>	N/A	N/A N/A	N/A	
	<ul> <li>Standby Pump Head</li> </ul>	N/A	N/A N/A	N/A	
	<ul> <li>Auto Starting/ Manual</li> </ul>	N/A	N/A N/A	N/A	
	stopping			N/A	
	<ul> <li>Pump House Access</li> </ul>	N/A	N/A	N/A	
	Terrace level				
	<ul> <li>Discharge of pump</li> </ul>	450 LPM	450 LPM	MR	
	<ul> <li>Head of the pump</li> </ul>	40 mts	40 mts	MR	
	<ul> <li>Power Supply</li> </ul>	Required	Provided		
	<ul> <li>Auto Starting of pump</li> </ul>	Required	Provided	MR	
14	Captive Water Storage for fire fightin		Frovided	MR	
	Underground tank capacity				
	<ul> <li>Draw-off connection</li> </ul>	N/A N/A	N/A	N/A	
	<ul> <li>Fire service inlet</li> </ul>	N/A	N/A	N/A	
	<ul> <li>Access to tank</li> </ul>	N/A		N/A	
	<ul> <li>Overhead Tank capacity</li> </ul>	5,000 lts	N/A	N/A	
15	Exit Signage.	Required	5,000 lts N	MR being old case	
		required	Provided	MR	

Ro

		N129					
	Pressurization of Lift Shaft	N/A	N/A	N/A			
	<ul> <li>Pressurization of Lift lobby</li> <li>Communication In lift Car</li> <li>Fireman's Grounding Switch</li> </ul>	N/A Required Required	N/A Provided Provided	N/A MR MR			
	<ul> <li>Lift Signage</li> </ul>	Required	Provided	MR			
7	Standby power supply	Required	Provided	MR			
18	Refuge Area.						
	Total Area	N/A	N/A	N/A			
	<ul> <li>Location</li> </ul>	N/A	N/A	N/A			
19	Fire Control Room						
	<ul> <li>Detector System Panel</li> </ul>	N/A	N/A	N/A			
	<ul> <li>Flow Switch Panel</li> </ul>	N/A	N/A	N/A			
	<ul> <li>PA System Panel</li> </ul>	N/A	N/A	N/A			
	<ul> <li>Batter backup</li> </ul>	N/A	N/A	N/A			
	<ul> <li>Building Floor Plans</li> </ul>	N/A	N/A	N/A			
20	Special Fire Protection Systems for Protection of special Risks, if any:	N/A	N/A	N/A			

The fire protection systems provided in the building were checked at random and found satisfactory at the time of inspection.

Note - Fire Check Door not required as owner/occupier has applied in CAF MHA Portal. Number of beds is less than 10 at each floor. Owner/Occupier has submitted an undertaking that Basement have others ownership , entry & exit are separate from guest house building. mezzanine floor is sealed by Brick wall & also sealed 4<sup>th</sup> floor placed at C-112.

In view the deemed compliance of the minimum standards on fire prevention and fire safety measures as required under the Rules, the FSC issued vide letter F6/DFS/MS/GH/SZ/2019/1919 dated 07.10.2019, renewal under Rule 37 of the Delhi Fire Service Rules 2010 is recommended.

DFA is put up for approval & signature please.

olso ghilor

refo(/sz

Ball 911122

Signature of the Inspecting Officer Name P.V. Rathee Asstt. Div. Officer (SRD)

トチー