GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: CONNAUGHT PLACE NEW DELHI-110 001.

-21

No.F.6/DFS/MS/School/2022/SZ / \ 2 4 1

Dated: (8 11) 2022

Delhi Fire Sar

FIRE SAFETY CERTIFICATE

Certified that the **Rashtra Shakti Vidyalaya**, Gandhi Nidhi, Hastsal, Uttam Nagar, New Delhi-110059, comprised of two blocks block A having ground plus three upper floors & block B having ground floor plus two upper floors, owned/occupied by Rashtra Shakti Vidyalaya was issued FSC by this department vide letter F.6/DFS/MS/2017/SZ/134 dated 02/02/2017 (Ground plus two upper floors). The School building was re-inspected by the officer concerned of this department on 02/11/2022 in the presence of Smt. Shashi Tyagi (Principal) and found that the school building have complied the fire prevention and fire safety requirements in accordance with Rule 33 of the Delhi Fire Service Rules, 2010 and that the building/ premises is fit for occupancy class "Educational" for a period of three years in accordance with Rule 36 unless renewed under Rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under Rule-38 of the Delhi Fire Service Rules, 2010 printed as below.

Copy to:-

3

1. The Principal,

Rashtra Shakti Vidyalaya, Gandhi Nidhi, Hastsal, Uttam Nagar, New Delhi-110059

2. Director of Education, Govt. of NCT of Delhi, Old Secretariat, New Delhi-110054.

Following fire safety directives must be adhered to:-

- 1. All the fire safety arrangements provided therein shall be maintained in good working condition at all times.
- 2. The means of escape shall be kept unlocked and unobstructed for unhindered evacuation of occupants in case of emergency.
- 3. Any loss of life or property due to non-functional fire safety measures shall be at the risk and responsibility of the management.
- 4. The trained staff should be available round the clock.
- 5. Any deviations w.r.t. construction shall be verified by the concerned building sanctioning agency
- 6. The certificate may not be treated in any case for the regularization of the unauthorized construction, if any.
- 7. The owner/occupier shall submit a declaration every year in the form 'K' provided in the first schedule of Delhi Fire Service Rules 2010, form is available on <u>www.dfs.delhigovt.nic.in</u>.
- 8. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in the Form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior to its expiry.

	Mr
 Name & address of the building : Building comprised of Type of Occupancy Type of Case Details of Previous NOC Fire Safety directives letter No Date of inspection Name of Inspecting Officer Name and designation of officers 	INSPECTION REPORT Rashtra Shakti Vidyalaya, Gandhi Nidhi, Hastsal, Uttam Nagar, New Delhi-110059. 2 blocks (A block G+3 & B block G+2 Upper floors) Educational Addition/alteration F.6/DFS/MS/School/2017/SZ/134 dated 02/02/2017 (G+2) N/A 02/11/2022 A.D.O. R.K.Yadav
From the building side 10. Year of Construction 11. Applicant's letter No.	 Smt. Shashi Tyagi (Principal) Before 2010 & 2021 RSV/FIRE DEPOT/HARI NGR/2022/779 dated 19/10/2022

Ve

	fire saf	um Standards on fire prevention and ety U/R 33	Requirement	Provided at	Remarks
	Access	to building		site	MR/NMR
		o o unung			
	•	Road width			
	•	Gate width	Accessible 06 mtrs	08 mtrs	M/R
	•	Width of internal road	4.5 mtrs	4 5 mtrs	M/R
2.	Numb	er, Width, Type & Arrangement of Exit	N/A	N/A	N/A
			8		
	a. Nur	nber of staircases			
	•	Upper Floors			
	•	Basements	03 No.'s	03 No.'s	M/R
			N/A	N/A	N/A
	b. Wi	dth of staircases			
	•	Upper Floor	1.50 m each	1.50 m each	M/R
	•	Basements	N/A	N/A	N/A
	c. Pro	otection of exits			N/A
	•	Fire check door	N/A	N/A	
	•	Pressurization	N/A		N/A
		ressuitzation		N/A	N/A
	d. N	o. of continuous staircases to	Dit		
	te	rrace	Required	Provided	M/R
	e. W	idth of Corridor	1.50 m	2.40m	M/R
			1.0 m	1.0 m	M/R
-		Door Size			IVD K
3.	Com	partmentation			
	•	Fire check door	N/A	N/A	
	•	Seaming of electrical sharts	N/A		N/A
	•	The reating of shart door		N/A	N/A
	•	trater Curtain	N/A	N/A	N/A
	•	Fire Dampers	N/A	N/A	N/A
4.	Smo	ke Management Sect	N/A	N/A	N/A
		ke Management System			
	•	Basements	N/A	N/A	N/A
		Linner flages	D i i i		
		• Upper floors	Required	Natural ventilation	n M/R
5	F .			provided	
5.	Fire Extinguishers				
		i otal indiffoers	14 no's	Provided	MR
		• Types	ABC/CO ₂ type	Provided	MR
	•	 IS marking 	ISI marked	Provided	
			131 marked	riovided	MR

		N/13		
).	First-Aid Hose Reels			•
	Total numbers on each floor	03 no.'s per floor	Provided	MR
	 Length of hose reel hose 	30 mtrs	Provided	MR
		5 mm	Provided	MR
	Nozzle diameter Automatic fire detection and alarming system	1		
7.		N/A	N/A	N/A
	 Type of detectors Location of Main Panel 	N/A	N/A	N/A
	 Location of Repeater Panel 	N/A	N/A	N/A
	Alternate source of power	N/A	N/A N/A	N/A
	Hooters' Location	N/A	N/A N/A	N/A
3.	MOEFA	N/A	N/A N/A	N/A
).	Public Address System	N/A	Provided	MR
10.	Automatic Sprinkler System			
	• Basement	N/A	N/A	N/A
	Ground Floor	N/A	N/A	N/A
	 Sprinkler above false ceiling 	N/A	N/A	N/A
11.	Internal Hydrants			
	 Size of riser/down-comer 	N/A	100 mm	MR
	Number of hydrants per floor	N/A	One	MR
7	Hose Box	N/A	One	MR
12.	Yard Hydrants			
	Total number of hydrantsHose Box	N/A	N/A	N/A
13.	Pumping Arrangements	N/A	N/A	N/A
	Ground Level			
	 Discharge of main Pump 	N/A		
	 Head of Main pump 		N/A	N/A
	Number of main pumps	N/A	N/A	N/A
	Jockey Pump out put	N/A	N/A	N/A
	 Jockey pump head Standby Pump out put 	N/A	N/A	N/A
	 Standby Fump out put Standby Pump Head 	N/A	N/A	N/A
	 Auto Starting/Manual Stopping 	N/A	N/A	N/A
		N/A	N/A	N/A
		N/A	N/A	N/A
	Pump House Access	N/A	N/A	N/A
	Terrace level			
	Discharge of pump	450 LPM	Provided	MR
	Head of the pump	& 180 LPM 40 mtrs	D : L L	
	 Power Supply Auto Starting of pump 	Required	Provided Provided	MR
	Auto Starting of pump	N/A	N/A	MR
				N/A
4.	Captive Water Storage for fire fighting			
	 Underground tank capacity 	N/A	N/A	
	Draw-off connection	N/A N/A	N/A N/A	N/A
	Fire service inlet	N/A N/A		N/A
	 Access to tank Overhead Tark 	N/A N/A	Provided	MR
	Overhead Tank capacity		N/A	N/A
5.	Exit Signage.	10,000 ltrs	Provided	MR
		Required	Provided	MR

NIIY

Sovision of Lifts.

•	Line Shan	N/A		No Lift
- •			N/A	N/A
•	 Communication In lift Car 	N/A	N/A	N/A
	 Fireman's Grounding Switch 	N/A	N/A	N/A
•	• Lift Signage	N/A	N/A	N/A
Star	adhy now a	N/A	N/A	N/A
Star	ndby power supply	N/A	N/A	N/A N/A
Ref	uge Area.			
	> Total Area			
	 Location 	N/A	N/A	N/A
Fir	re Control Room	N/A	N/A	N/A
	Detector System PanelFlow Switch Panel	N/A	N/A	N/A
	 PA System Panel 	N/A	N/A	N/A
	 Battery backup 	N/A	N/A	N/A N/A
	 Building Floor Plans 	N/A	N/A	N/A N/A
		N/A	N/A	N/A N/A
	pecial Fire Protection System for Protection of			13/A

The fire protection systems provided in the building were tested, checked and found functional at the time of inspection. The shortcomings issued vide letter no.F.6/DFS/MS/School/2022/SZ/619 dated 30/09/2022 Keeping in view the cell is used.

Keeping in view the substantial compliance of the minimum standards on fire prevention and fire safety measures as required under the Rules the FSC issued vide letter no. F.6/DFS/MS/school/2017/SZ/134 Dt.-02/02/2017 renewal under the Rule 35 of the Delhi Fire Service Rules 2010 is recommended.

Signature of the Inspecting Officer 11/2007 Name- R.K.Yadav Designation- A.D.O (JKP)

DO(South West)

141 14 20 Line