GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEAD QUARTERS: DELHI FIRE SERVICE NEW DELHI

No: F6/DFS/MS/School/WZ/2022/ College / 21

Dated: 18 /11 /2022

FIRE SAFETY CERTIFICATE

Certified that the Guru Nanak Institute of Management Located at Road No. 75, West Punjabi Bagh, New Delhi -110026 in a building comprised of Basement + Ground + 02 Upper floors, was issued FSC vide letter No. F6/DFS/MS/WZ/2019/1632 dated 19/08/2019, the premises was re-inspected by the officer concerned by this department on 27/09/2022 in the presence of Dr. Maninder Kaur (Director, GNIM) and the premises have deemed complied with fire prevention & fire safety requirements in accordance with rule 33 of the Delhi Fire Services Rules, 2010 and that the building/premises is fit for Class-B-2 (Educational) occupancy with effect from 18/11/2022 for a period of three years in accordance with rule 36 unless renewed under 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules, 2010 condition mentioned below:-

(Dharampal Bhardwaj)/ Dy. Chief Fire Officer

West Zone

Copy to:

The Director, Guru Nanak Institute of Management located at Road No. 15 West Punjabi Bagh, New Delhi -110026

Director of Education, Old Sectt. Delhi-110054.

Following fire safety directives must be adhered to:-

- 1. All the fire safety arrangements provided therein shall be maintained in good working condition at all times.
- 2. Any loss of life or property due to non-functional fire safety measures shall be at the risk and responsibility of the management.

3. The trained staff should be available round the clock.

4. Any deviations w.r.t. construction shall be verified by the concerned building sanctioning agency.

5. The certificate may not be treated in any case for the regularization of the unauthorized construction, if any.

6. The owner/ occupier shall apply for renewal of this Fire Safety Certificate to the Director in Form 'J' [sub rule (1) of rule 37] along with a copy of this certificate, six months prior to its expiry.

7. The owner/occupier shall submit a declaration every year in the form 'K' provided in the first schedule of Delhi Fire Service Rules 2010, form is available on www.dfs.delhigovt.nic.in.

Amrit Mahotsav

INSPECTION REPORT

1. Name & address of the building : Guru Nanak Institute of Management Located at Road No.

75, Punjabi Bagh (West), New Delhi-110026.

Type of Occupancy

: Educational

3. Type of Case

: Renewal

4. Details of previous NOC

: F6/DFS/MS/WZ/2019/1632 Dated: 19/08/2019

5. Fire Safety directives letter No

: Shortcomings letter no.F6/MS/DFS/2007/429-A dated

12/02/2007

6. Date of inspection

: 27/09/2022

7. Name of the Inspecting Officers: Sarabjeet Singh, ADO (Moti Nagar)

8. Name and designation of officers

from the building side

: Dr. Maninder Kaur (Director, GNIM)

9. Year of Construction

: 2001 (As Per Prev. Insp. report dated 12/07/2019)

10. Applicant's letter No.

: Letter No. GNIM/2022/16788 dated 30/08/2022

* The Said Institute is running in Ground + 02 upper floors in a building comprised of Basement + Ground + 02 Upper floors

S. No.	Minim	um Standards on fire ention and fire safety U/R 33	re RRI /NDC D		Provided at site		Remarks MR/NMR	
1		cess to building						
		Road width Gate width		Accessib		40 feet Provided		MR
		Width of internal road		4.5 mts	5	On Road		MR
2		Number, Width, Type & Arrangeme		N/A		N/A		N/A
	a. Num	per of staircases	gemen	t of Exits				
		Upper Floors	-					
		Basements	_	02		03 Provided		MR
	1	h of staircases	_	02		03 Provided	MR	(old case)
		Upper Floors		1.5 mts		n, 140cm & 100cm Prov		MR
		Basements		1.5 mts	180cı	m,147cm & 137cm Prov	ided	MR
		ection of exits						
		Fire check door		N/A		N/A		N/A
	1	Pressurization		N/A		N/A		N/A
		continuous staircases to ter	rrace	01		02 Provided		MR
	_	h of Corridor		1.5 mtr		Provided		MR
	h. Door	Size		1 mts		Provided including door frame	N	MR (old case)
3	Compa	rtmentation.						
	•	Fire check door		N/A		N/A		N/A
	•	Sealing of electrical shafts	s	N/A		N/A		N/A
	•	Fire Rating of shaft door		N/A		N/A		N/A
	•	Water Curtain		N/A		N/A		N/A
	•	Fire Dampers		N/A		N/A		N/A
4	Smoke Management System.							
	•	Basements		Required		Provided		MR
	•	Upper floors		Require	d	Provided		MR

40	* 1
4	1
্ব	18-8
1. 4	12/1
150	135
	July Co.

5	Fire Extinguishers			
	Total numbers	16 nos.	Provided	MR
	• Types	CO ₂ , ABC type	Provided	MR
	IS marking	ISI marked	Provided	MR
			Provided	
6	First-Aid Hose Reels.			MR
	 Total numbers on each floor 	02	Provided	MR
	 Length of hose reel hose 	30 mtr	Provided	MR
	Nozzle diameter	5 mm	Provided	IVIK
7	Automatic fire detection and alarmin		27/4	N/A
	Type of detectors	N/A	N/A	N/A
	 Location of Main Panel 	N/A	N/A	N/A
	Location of Repeater Panel	N/A N/A	N/A N/A	N/A
	Alternate source of power	N/A	N/A	N/A
	Hooters' Location		Provided	MR
8	MOEFA	Required		N/A
9	Public Address System.	N/A	N/A	14/21
10	Automatic Sprinkler System.			
	Basement	Required	Provided	MR
	Upper Floor	N/A	N/A	N/A
	Sprinkler above false ceiling	N/A	N/A	N/A
11	Internal Hydrants			
	Size of riser/down-comer	Required	02 Provided	MR
	Number of hydrants per floor	Required	02 Provided	MR
	Hose Box	Required	02 Provided	MR
12	Yard Hydrants.			
	Total number of hydrants	N/A	N/A	N/A
	Hose Box	N/A	N/A	N/A
13	Pumping Arrangements.			
	Ground Level			
	Discharge of main Pump	N/A	N/A	N/A
	Head of Main pump	N/A	N/A	N/A
	Number of main pumps	N/A	N/A	N/A
	> Jockey Pump out put	N/A	N/A	N/A
	> Jockey pump head	N/A	N/A	N/A
	> Standby Pump out put	N/A	N/A	N/A
	> Standby Pump Head	N/A	N/A	N/A
	> Auto Starting/ Manual stopping	N/A	N/A	N/A
	Pump House Access	N/A	Ň/A	N/A
	> Terrace level		₹7.	
	Discharge of pump	450 lpm & 180 lpm	Provided	MR
	Head of the pump	40 mtr	Provided	MR
	Power Supply	Required	Provided	MR
	> Auto Starting of pump	Required	Provided	MR
	,		-₹	

W

			A COMMON L			
	St for fire figh	ting.				
14	Captive Water Storage for fire figh	N/A	N/A	N/A		
	Underground tank capacity	N/A	N/A	N/A		
	> Draw-off connection	N/A	N/A	N/A		
	Fire service inlet	N/A	N/A	N/A		
	> Access to tank	20,000 ltrs	Provided	MR		
	 Overhead Tank capacity 	Required	Provided	MR		
15	Exit Signage.	•				
16	Provision of Lifts. (Lift provided from ground to upper floor only)					
		N/A	N/A	N/A		
	Pressurization of Lift Shaft	N/A	N/A	N/A		
	Pressurization of Lift lobby	N/A	N/A	N/A		
	Communication In lift Car	N/A	N/A	N/A		
	• Fireman's Grounding Switch	Required	Provided	MR		
	Lift Signage	N/A	N/A	N/A		
17	Standby power supply					
18	Refuge Area.					
	> Total Area	N/A	N/A			
	> Location	N/A	N/A	N/A		
19	Fire Control Poom					
17	Detector System Panel	N/A	N/A	N/A		
	Flow Switch Panel	N/A	N/A	N/A		
	PA System Panel	N/A	N/A	N/A		
	Batter backup	N/A	N/A	N/A		
	Building Floor Plans) / A	N/A		
	Summing 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	N/A	N/A			
20	Special Fire Protection Systems for	N/A	N/A	N/A		
	Protection of special Risks, if any:					

The fire protection systems provided in the building were test checked and found functional at the time of inspection.

In view of the deemed compliance of minimum standards on fire prevention and fire safety as required under the rules the NOC issued vide letter no. F6/DFS/MS/WZ/2019/1632 dated: - 19/08/2019 renewal under rule 35 of the Delhi Fire Service Rules 2010 is recommended.

Signature of the Inspecting Officer Name: Sarabjeet Singh

Designation: ADO (MN)

Med-W.N Correction has been don in D. P. A & Symin put up for your kind pursual & Synahus please. 1 get