

C- 23 <u>GOVERNMENT OF NATIONAL CAPITAL TERRITOTY OF DELHI</u> <u>HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI- 110001</u>

No. F.6/DFS/MS/WZ/School/2022/ 1294

Dated 02/12/2022

FIRE SAFETY CERTIFICATE

Certified that the H.D. Sehrawat Public School, located at Plot No. 71-72 Satyam Vihar, Chanchal Park, Najafgarh Road, New Delhi - 110043 comprised of Ground plus letter no. department FSC vide this issued 03 upper floors. was F6/DFS/MS/School/WZ/2019/213 dated 28/01/2019. The premises was re inspected by officer concerned of this department on 21/11/2022 in the presence of Sh. Ravinder Sehrawat and observed that all the fire prevention and fire safety arrangements provide in the premises found in good working condition. The premises have deemed complied with fire prevention & fire safety requirements in accordance with Director of Education Circular No. F-16/estate/CC/Fire safety/2011/ 3298-3398 dated 01/03/2011/NBC (Part-IV) and that the building/premises is fit for occupancy class "Educational" Group-B, with effect from ... O > / 12 / 20 > 2 for a period of three years in accordance with rule 36 unless renewal under rule 37 or sooner cancelled under rule 40 and subject to compliance of the conditions under rule 38 of the DFS rules, 2010 conditions printed overleaf.

Issued on 02/12/222 at New Delhi by

(Dharampal Bhardwaj) Dy. Chief Fire Officer West Zone

Copy to: -

- 1. The Principal, H.D. Sehrawat Public School, located at Plot No. 71-72 Satyam Vihar, Chanchal Park, Najafgarh Road, New Delhi 110043.
- 2. The Director of Education, Govt. of NCT of Delhi, Old Secretariat, New Delhi.





Following fire safety directives must be adhered to:-

- 1. All the fire safety arrangements provided therein shall be maintained in good working condition at all times.
- 2. Any loss of life or property due to non-functional fire safety measures shall be at the risk and responsibility of the management.
- 3. The trained staff should be available round the clock.
- 4. Any deviations w.r.t. construction shall be verified by the concerned building sanctioning agency.
- 5. The certificate may not be treated in any case for the regularization of the unauthorized construction, if any.
- 6. The owner/ occupier shall apply for renewal of this Fire Safety Certificate to the Director in Form 'J' [sub rule (1) of rule 37] along with a copy of this certificate, six months prior to its expiry.
- 7. The owner/occupier shall submit a declaration every year in the form 'K' provided in the first schedule of Delhi Fire Service Rules 2010, form is available on <u>www.dfs.delhigovt.nic.in</u>.

				N/23			
1				CTION REPO			
	1. N	ame & address of the building	Sat). Sehrawat Publi yam Vihar, Char 0043.	ic Schoo Ichal Pa	ol Located at Plot N rk, Najafgarh Road	o.71-72 , New Delhi-
2	2. Ty	pe of Occupancy	: Educa	tional			
3	3. T	pe of Case :	Renew	al			
4		etails of previous NOC	: F6/DF	S/MS/School/W	Z/2019	/213 dated 20/01/20	19
	1	re Safety directives letter No			D , 2 01 <i>)</i> ,	210 44104 20101-1	
	- 1	•	21/11/2				
		ame of the Inspecting Officers					
	- 1	ame and designation of office		oject singli (ADC	J WIN)		
		om the building side		avinder Sehrawat			
9). Yea	ar of Construction :	2013-1	7 (As per prev. Iı	nsp repo	ort dated 11/01/2019	<i>)</i>)
1	0. Ap	plicant's letter No.	: Email	dated 15/11/2022	2		
S. No.		linimum Standards on fire prevention and fire safety	As p	/NBC Requirer per prev. Insp re	eport	Provided at site	Remarks MR/NMI
1		U/R 33		dated 11/01/2019	9		
1	AC	cess to building Road width		6 mtr		Provided	MR
		Gate width		4.5 mtr		Provided	MR
		 Width of internal road 				NA	NA
2	N			NA NA		INA	1471
2		mber, Width, Type & Arran	ngemen	t of Exits			
	a. 1	Upper Floors		02 03 Provided			MR
		 Basements 		NA		NA	NA
	b.	Width of staircases		1471			
		Upper Floors		1.5m x 1 &	1.5m	x 2 & 1.25m x 1	MR (old
				1.35mtr x 1		(GF ++ F.F)	case)
		• Basements		NA		NA	NA
	c. I	Protection of exits	-				
		• Fire check door		NA NA		NA NA	NA
		Pressurization		01		Provided	NA MR
		lo. of continuous staircases to ter vidth of Corridor	race	1.5m		Provided	MR
		Door Size	ŀ	1 mtr	lm	x 2 Provided	MR
3		npartmentation.					
5		Fire check door		NA		NA	NA
		 Sealing of electrical shafts 	s	NA		NA	NA
		 Fire Rating of shaft door 		NA		NA	NA
		 Water Curtain 		NA		NA	NA
		• Fire Dampers		NA		NA	NA
4	Sm	oke Management System.					
	• Basements		F	NA		NA	NA
		Upper floors		NA		NA	NA
5	Fire	Extinguishers Total numbers		07 nos.		0.0	
		Total numbersTypes				9 Provided	MR
		1 1 1 1 5		CO ₂ , ABC type		Provided	MR
		IS marking		ISI marked		Provided	WIIX

\$41

1110

NIXY	N	24	
------	---	----	--

6	First-Aid Hose Reels.			
	• Total numbers on each floor	01	Provided	MR 🖌
	 Length of hose reel hose 	30 m	Provided	
	Nozzle diameter	5 mm	Provided	MR
7	Automatic fire detection and alarmin	g system.		MR
	 Type of detectors 	NA	NA	NA
	 Location of Main Panel 	NA	NA	NA
	 Location of Repeater Panel 	NA	NA	NA
	• Alternate source of power	NA	NA	NA
	 Hooters' Location 	NA	NA	NA
8	MOEFA	NA	NA	NA
9	Public Address System.	NA	NA	NA
10	Automatic Sprinkler System.			NA
	Basement	NIA		
	Upper Floor	NA	NA	NA
	Sprinkler above false ceiling	NA	NA	NA
11	Internal Hydrants	NA	NA	NA
	• Size of riser/down-comer	NA	NA	NA
	• Number of hydrants per floor	NA	NA	NA
12	Hose Box	NA	NA	NA
12	Yard Hydrants.			
	• Total number of hydrants	NA	NA	NA
	Hose Box	NA	NA	NA
13	Pumping Arrangements.			NA
	Ground Level			
	Discharge of main Pump	NA		
	 Head of Main pump 	NA	NA	NA
	Number of main pumps	NA	NA	NA
	 Jockey Pump out put 	NA		NA
	 Jockey pump head 	NA	NA NA	NA
	 Standby Pump out put 	NA		NA
	 Standby Pump Head 	NA	NA NA	NA
	 Auto Starting/ Manual stopping 	NA	NA	NA
	 Pump House Access 	NA		NA
	Terrace level		NA	NA
	 Discharge of pump 	450 lpm	Provided	MR
	Head of the pump	40 m	Provided	MR
	Power Supply	Required	Provided	MR
	 Auto Starting of pump 	Required	Provided	MR
14	Captive Water Storage for fire fightin	g.		
	 Underground tank capacity 	NA	NA	NA
	 Draw-off connection 	NA	NA	NA
	Fire service inlet	NA	NA	NA
	Access to tank	NA	NA	NA
	 Overhead Tank capacity 	10,000 Ltrs	Provided	MR
15	Exit Signage.	Required	Provided	MR

- Star

Prot

10

		N/25		
16	Provision of Lifts.			
17	 Pressurization of Lift Shaft Pressurization of Lift lobby Communication In lift Car Fireman's Grounding Switch Lift Signage Standby power supply	NA NA NA NA Required	NA NA NA NA	NA NA NA NA
18	Refuge Area.		Provided	MR
10	Total AreaLocation	NA NA	NA	NA
19	Fire Control Room		NA	NA
	Detector System PanelFlow Switch Panel	NA NA	NA	NA
	PA System Panel	NA	NA	NA
	 Batter backup 	NA	NA	NA
	Building Floor Plans	NA	NA	NA
20	Special Fire Protection Systems for Protection of special Risks, if any:	NA	NA NA	NA NA

MR MR MR

 $\frac{N_A}{N_A}$

The fire protection systems provided in the building were test checked and found functional at the time of inspection.

Keeping in view of the substantial compliance of the minimum standards on fire prevention and fire safety required under the rules it is recommended to grant Fire Safety Certificate under rule 35 of the Delhi Fire Service Rules 2010 is recommended.

(tae) \mathcal{D} 0 - 4/11/20 12 Signature of the Inspecting 4 392/ADO/MOD 241/11/2022 Name: - Sarabjeet Singh Designation: - ADO (MN) 26 Ch wr) put up for your kind persual & S flegse. r(fo(wi) 1 mm 1