C-22



No.F.6/DFS/MS/School/2022/SZ/1314

Dated: 14/12/22

FIRE SAFETY CERTIFICATE

Certified that the A.E.S N.T. Rama Rao Memorial Sr. Sec. School, B-3B Block, Janak Puri, New Delhi-110058, comprised of ground plus three upper floors, owned/occupied by A.E.S N.T. Rama Rao Memorial Sr. Sec. School was issued FSC vide letter No. F.6/DFS/MS/2008/1029 dated 10.04.08 (for G+2). The school building was re-inspected by the officer concerned of this department on dated 01/12/2022 in the presence of Mrs. E. Anitha (Principal) and found that the school building have deemed complied with the fire prevention and fire safety requirements in accordance with Rule 33 of the Delhi Fire Service Rules, 2010 and that the building is fit for occupancy class "Educational" w.e.f. the date of issue of this certificate for a period of **three years** in accordance with Rule 36 unless renewed under Rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under Rule-38 of the Delhi Fire Service Rules, 2010 printed as below.

Issued on.....at New Delhi by

DIRECTOR
Delhi Fire Service

Copy to:-

The Principal,
 A.E.S N.T. Rama Rao Memorial Sr. Sec. School, B-3B Block,
 JanakPuri, New Delhi-110058,

Director of Education,
 Govt. of NCT of Delhi, Old Secretariat, New Delhi – 110054.

Following fire safety directives must be adhered to:-

- 1. All the fire safety arrangements provided therein shall be maintained in good working condition at all times.
- 2. The means of escape shall be kept unlocked and unobstructed for unhindered evacuation of occupants in case of emergency.
- 3. Any loss of life or property due to non-functional fire safety measures shall be at the risk and responsibility of the management.
- 4. The trained staff should be available round the clock.
- 5. Any deviations w.r.t. construction shall be verified by the concerned building sanctioning agency.
- 6. The certificate may not be treated in any case for the regularization of the unauthorized construction, if any.
- 7. The owner/occupier shall submit a declaration every year in the form 'K' provided in the first schedule of Delhi Fire Service Rules 2010, form is available on www.dfs.delhigovt.nic.in.
- 8. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in the Form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior to its expiry.
- 9. In case of usage of third floor for schooling purpose then this FSC will be null and void.

INSPECTION REPORT vame & address of the building :

A.E.S N.T. Rama Rao Memorial Sr. Sec. School, B-3B Block, Janak

Puri, New Delhi-110058

Building comprised of Ground plus three upper floors. Type of Occupancy Educational

Type of Case
Details of Previous NOC Addition/alteration

F.6/DFS/MS/2008/1029 dated 10.04.08 6. Fire Safety directives letter No

N/A 7. Date of inspection 01/12/2022

8. Name of Inspecting Officer A.D.O. R.K. Yadav

9. Name and designation of officers

From the building side Mrs. E. Anitha (Principal) 10. Year of Construction

Before-2008 (GF +II) & addition of Lab block (04 rooms) on each

floor before 2018 11. Applicant's letter No.

	Minimum Standards on fire prevention and fire safety U/R 33		Requirements a per NBC/UBBI 16/ NOC dt. 10.04.08	Provided at site	Remarks MR/NMR			
1.	Access to building							
	•	Road width	Accessible	Provided	M/R			
	•	Gate width	4.5 mtrs	Directly accessible	M/R			
	•	Width of internal road	N/A	from road	N/A			
2.	Number, Width, Type & Arrangement of Exits							
	a. Number of staircases							
	•	Upper Floors						
		Basements	04 No.'s	Provided	M/R			
			N/A	N/A	N/A			
	b. Wi	dth of staircases						
	•	Upper Floor	1.5 m &.75 m	1.30 m (04 no.'s)	M/R old case			
		Basements	N/A	N/A	N/A			
	o Pro	otection of exits						
	c. Pro	Fire check door	N/A	N/A	N/A			
		Pressurization	N/A	N/A	N/A			
	•	Flessurization	1.771	14/74	IN/A			
	d. No	o. of continuous staircases to	Required	Provided	1470			
	terrace				M/R			
	e. W	idth of Corridor	1.50 m.	2.0 m	M/R			
	f. Cl	ass Room Door Size	1.0 M & 1.0 M for additional rooms	.90 M/1.0 M	MR			
3.	Compartmentation							
	•	Fire check door	N/A	N/A	N/A			
	•	Sealing of electrical shafts	N/A	N/A	N/A			
	•	Fire Rating of shaft door	N/A	N/A	N/A			
	•	Water Curtain	N/A					
	•	Fire Dampers	N/A N/A	N/A N/A	N/A			
4.	Smoke	Management System	IVA	IN/A	N/A			
	-		NI/A	27/4				
	•	Basements	N/A	N/A	N/A			
	•	Upper floors	Required	Natural ventilation provided	M/R			
5.	Fire Extinguishers							
	•	Total numbers	12 no's	Provided	MR			
	•	Types	ABC/CO ₂ type	Provided	MR			
	1	IS marking	ISI marked	Provided	MR			

6	First-Aid Hose Reels			
	 Total numbers on each floor 	02 no.'s	Provided	
	 Length of hose reel hose 	30 mtrs	Provided	MR
	Nozzle diameter	5 mm	Provided	MR
	Automatic fire detection and alarming system		Trovided	MR
	 Type of detectors 	N/A	N/A	
	 Location of Main Panel 	N/A		N/A
	Location of Repeater Panel	N/A	N/A	N/A
	Alternate source of power	N/A	N/A	N/A
	Hooters' Location	N/A	N/A	N/A
	MOEFA	N/A	N/A	N/A
0.	Public Address System	N/A	N/A	N/A
0	Automatic Sprinkler System	IVA	N/A	N/A
	• Basement	N/A	N/A	
	• Ground Floor	N/A	N/A	N/A
1.	Sprinkler above false ceiling Internal Hadrage	N/A	N/A	N/A
	Internal Hydrants		IN/A	N/A
	Size of fiser/down-comer	N/A	N/A	N/A
	Number of hydrants per floorHose Box	N/A	N/A	N/A N/A
2.	Yard Hydrants	N/A	N/A	N/A
				IVA
	Total number of hydrantsHose Box	N/A	N/A	N/A
3.	Pumping Arrangements	N/A	N/A	N/A
	Ground Level			14/74
	Discharge of main Pump			
	Head of Main pump	N/A	N/A	N/A
	Number of main pumps	N/A	N/A	N/A
	Jockey Pump out put	N/A	N/A	N/A
	beacy pump nead	N/A	N/A	N/A
	Standby Pump out putStandby Pump Head	N/A	N/A	
	Auto Starting/Manual Stopping	N/A	N/A	N/A
	S amount stopping	N/A	N/A	N/A
		N/A	N/A	N/A
	> Pump House Access	N/A	N/A N/A	N/A
	Terrace level			N/A
	Discharge of nump	450 LPM	450 & 180	MD
	Head of the pump		LPM provided	MR
	Power Supply	30 mtrs	Provided	MR
	Auto Starting of pump	Required	Provided	MR
1.4		Required	Provided	MR
14.	Captive Water Storage for fire fighting			
	 Underground tank capacity 	N/A	3 1/4	
	Draw-off connection	N/A	N/A	N/A
	Fire service inlet Access to tank	N/A	N/A	N/A
	Overhead Tank capacity	N/A N/A	N/A	N/A
15.		10000 ltrs	N/A	N/A
	Exit Signage.	Required	Provided	MR
		required	Provided	MR

	• Pressurization of Lift Shaft • Pressurization of Lift lobby		No Lift				
			N/A	N/A	N/A		
R			N/A	N/A	N/A		
R	Con	Communication In lift Car Fireman's Grounding Switch Lift Signage y power supply	N/A N/A	N/A N/A	N/A N/A		
-							
	• l		N/A	N/A	N/A		
Sta	Standby		N/A	N/A	N/A		
Re	fuge A	ge Area.					
+-	> 7	Total Area	N/A	N/A	N/A		
	> 1	ocation	N/A	N/A	N/A		
Fin	Fire Control Room						
	•	Detector System Panel	N/A	N/A	N/A		
		Flow Switch Panel	N/A	N/A	N/A		
		PA System Panel	N/A	N/A	N/A		
		Battery backup	N/A	N/A	N/A		
	•	Building Floor Plans	N/A	N/A	N/A		
		Fire Protection System for Protection of Risks, if any:	N/A	N/A	N/A		

The fire protection systems provided in the building were tested, checked and found functional at the time of inspection. The Shortcomings issued vide letter No.F6/DFS/MS/School/2018/SZ/2504 dated 13/06/2018 has been complied

Keeping in view of the above compliance of the minimum standards of fire prevention and fire safety measures under Rule 35 of the Delhi Fire Service Rules 2010 it is recommended to grant Fire Safety Certificate.

Note:- Earlier FSC was issued vide letter no. F.6/DFS/MS/2008/1029 dated 10.04.08 for ground plus two upper floors.

Signature of Inspecting Officer 2012

Name:- R.K. Yadav

Designation:- Asstt. Divisional Officer

Divisional Officer (South West)

,

8 12 202

/()0)/

01/8/

of Fregrai)