

### GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI <u>HEAD QUARTERS: DELHI FIRE SERVICE: NEW DELHI - 110001</u>

No.F6/DFS/MS/2022 /School/ 1320

Dated: 14 /12/2022

#### FIRE SAFETY CERTIFICATE

(Dharmpal Bhardwaj) Dy. Chief Fire Officer Ph:-011-23414250

Copy to: -

- 1. The Director, Education, Government of N.C.T of Delhi. Old Sectt. Delhi  $\frac{1}{10054}$ .
- 2. The Manager, Divyansh Public School located at Pusta Road, Near Jharoda Police Chowki, Sangam Vihar, Delhi-110084.

#### Conditions for the validity of Fire Safety Certificate:

- 1. All the means of escape/entry/exit shall be kept free from any obstruction.
- 2. All the fire safety arrangements provided therein shall be maintained in good working condition at all time as seen during inspection.
- 3. Any loss of life or property due to non-functional fire safety measures shall be at the responsibility of the management.
- 4. All the staff members must know the correct method of operation of firefighting system.
- 5. The owner / occupier shall submit a declaration every year in Form "K" provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on http://delhi.gov.in./wps/wcm/connect/doit fire/FIRE/Home/Forms.
- 6. This fire safety certificate may not in any way be treated as regularization (Clause 2.8 of UBBL-2016) of unauthorized construction or Alteration (Clause 1.4.3 of UBBL-2016), if any.
- "The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in Form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior to its expiry".

C18

0		N(12-
1.	Name & address of the building	INSPECTION REPORT : Divyansh Public School at Pusta Road, Near Jharoda Police Chowki, Sangam
2. 3. 4. 5. 6. 7. 8.	Type of Occupancy Composition of building Type of Case Details of previous NOC Fire Safety directives letter No Date of inspection Name of the Inspecting Officers	Vihar, Delhi-110084 : Educational : Ground & first floor only : Renewal : F6/DFS/MS/2017/WZ/1403 Dated: 22.09.2017 : Nil : 05.12.2022 : ADO (RN)
9. 10	Name and designation of officers from the building side . Year of Construction	: Sh. R.K Tyagi ( Manager ) : 2003
11	Applicant's letter No.	: Letter No. DPS/11/2022 dated 14.11.2022

Plot Area-3216Sq.y

Covered Area:1216 sq.yard class rooms -12 nos

students – 200nos

	Access to building		S		MR/NMF		
	Access to building						
	Road width	6m	6m		MR		
	Gate width	4.5m		4.0m	MR(old case)		
	• Width of internal road	NA		NA	NA		
	Number, Width, Type & Arrangement of Exits						
	a. Number of staircases						
	Upper Floors	01		02	MR		
	Basements	ΝΑ		NA	NA		
	b. Width of staircases						
	Upper Floors	1.50m	1.50	0m & 1.20m	MR		
	Basements	NA		NA	NA		
	c. Protection of exits			1			
	• Fire check door	NA		NA	NA		
	Pressurization	NA		NA	NA		
	d. No. of continuous staircases to terrace	NA		NA	NA		
	e. Width of Corridor	NA		NA	NA		
	f. Door Size	l m		1.04 m	MR		
3	Compartmentation.						
	Fire check door	NA		NΛ	NA		
	Sealing of electrical shafts	ΝΛ		NΔ	NA		
	Fire Rating of shaft door	NΛ		NΛ	NA		
	Water Curtain	NA		NA	NA		
	Fire Dampers	NA		NΛ	NΛ		
4	Smoke Management System.						
	Basements	12 a/c per hour		NA	NA		
	• Upper floors	12 a/c per hour	Natu	al Ventilated	MR		
5	Fire Extinguishers		-				

H

# 4/3

	<ul> <li>Total numbers</li> </ul>	05nos	06nos	MR				
	• Types	ABC/CO2	ABC = 06	MR				
	ISI marking		Yes	MR				
F	First-Aid Hose Reels.	ISI Marked						
			01	MR				
	Four numbers on each floor	01						
	<ul> <li>Length of hose reel hose</li> </ul>	30m	Provided	MR				
	Nozzle diameter	5mm	Provided	MR				
	Automatic fire detection and alarming system.							
	Type of detectors	NΛ	NΛ	NA				
	<ul> <li>Location of Main Panel</li> </ul>	NΛ	NΛ	NΛ				
	Location of Repeater Panel	NΛ	NΛ	NΛ				
	Alternate source of power	NA	NA	NĂ				
	<ul> <li>Hooters' Location</li> </ul>							
	- Honers Location	NΛ	NΛ	NΛ				
	MOEFA	NΛ	NA	NA				
	Public Address System.	NΛ	NA	NA				
0	Automatic Sprinkler System.							
	Basement	NΛ	NA	NA				
	• Upper Floor	NΛ	NΛ	NA				
	• Sprinkler above false ceiling	ΝΛ	NA	NA				
11	Internal Hydrants							
	Size of riser/down-comer	ΝΛ	NA	NΛ				
	• Number of hydrants per floor	ΝΛ	NA	NA				
	Hose Box	NΛ	NΛ	NΛ				
12	Yard Hydrants.							
	Total number of hydrants	NΛ	NΛ	NA				
	• Hose Box	NΛ	NA	NA				
12	D							
13	Pumping Arrangements.							
	Ground Level	N/A	N/A	N/A				
	<ul> <li>Discharge of main Pump</li> </ul>							
	Head of Main pump	N/A	N/A	N/A				
	Number of main pumps	N/A	N/A	N/A				
	Jockey Pump out put	N/A	N/A	N/A				
	Jockey pump head	N/A	N/A	N/A				
	Standby Pump out put Standby Pump Uaad	N/A	N/A	Ν/Δ				
	<ul> <li>Standby Pump Head</li> <li>Auto Starting/ Manual stopping</li> </ul>	Ν/Α	N/A	N/A				
	<ul> <li>Auto Starting/ Manual stopping</li> <li>Pump House Access</li> </ul>	N/A	N'A	N/A				
	Terrace level							
	<ul> <li>Discharge of pump</li> </ul>	220 LPM	220 LPM	MR				
	Head of the pump	40m	40m	MR				
	Power Supply	Required	Provided	MR				
	<ul> <li>Auto Starting of pump</li> </ul>	N/A	NA	N/A				
14	Captive Water Storage for fire fighting.			(S/A				
	Underground tank capacity	NA	NA	NA				
	Draw-off connection	NΛ	NA	NA				
	<ul> <li>Fire service inlet</li> </ul>	NA	NA	NA				
	<ul><li>Access to tank</li><li>Overhead Tank capacity</li></ul>	NA	NA	NA				
	<ul> <li>Overhead Tank capacity</li> </ul>	2500 L.FR	2500 L TR	MR				

1

24)

## relig

5	Exit Signage.	Required	Provided	MR			
16	Provision of Lifts.						
	Pressurization of Lift Shaft	N/A	N A	N/Λ			
	<ul> <li>Pressurization of Lift lobby</li> </ul>	N/A	$N/\Delta$	N⊬A			
	Communication In lift Car	N/A	N/A	N/A			
	Fireman's Grounding Switch	N/A	N/A	N/A			
	<ul> <li>Lift Signage</li> </ul>	N/A	N/A	N/A			
17	Standby power supply	N/A	N/A	N/A			
18	Refuge Area.						
	> Total Area	N/A	N/A	N/A			
	Location	N/A	N/A	N/A			
19	Fire Control Room						
	Detector System Panel	N/A	N/A	N/A			
	Flow Switch Panel	_N/A	N/A	N/A			
	PA System Panel	N/A	N/A	N/A			
	Batter backup	N/A	N/A	N/A			
	Building Floor Plans	N/A	N/A	N/A			
20	Special Fire Protection Systems for Protection of special Risks, if any:	N/A	N/A	N/A			

The fire protection systems provided in the building were tested/ checked randomly and found in working condition at the time of inspection.

Keeping in view the satisfactory compliance of the minimum standards on fire prevention and fire safety required as stipulated in Director of Education Circular dated 17.01.2005 the FSC issued vide letter of even no 1403 dated 22.09.2017 renewal under rule 35 of the Delhi Fire Service Rules, 2010 is recommended

DONW Signature of the Insp Name - C.L. Meena Designation:- ADO/RN 7/12/2 As approved, F.T. letter is Putup for your singuature Pl. N 2. (WZ (000 12/12/2022 00(RH)