

**GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI-110001**

No. F.6/DFS/MS/EH/2022/SZ/ 346

Dated: 12/12/2022

FIRE SAFETY CERTIFICATE

Certified that the Restaurant in the name & style of M/s **Le Cantine** Situated at **301 & 301A, Second Floor, DLF Promenade Mall, Nelson Mandela Marg, Vasant Kunj, New Delhi-110070** in a building comprised of Two Tiers Basement, Lower Ground, Upper Ground floor and 02 Upper Floors owned/ occupied by Unit of Sisters food craft Pvt Ltd, was issued Fire Safety Certificate by this department vide letter No. F6/DFS/MS/EH/2019/SZ/2110 dated 05/11/2019. The restaurant premise was re-inspected by the officer concerned of this department on 01/12/2022 in the presence of Mr. Rajender Kumar (Manager) and found that the said premise have deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the premises is fit for occupancy **Class D "Assembly Building"** (Restaurant running at 2nd floor only) with effect from 12/12/2022 for a period of three years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules, 2010.

Issued on 12/12/2022 at New Delhi by

(SUNIL CHAUDHARY)
DY. CHIEF FIRE OFFICER (SZ)

Copy to: -

1. The DHO, (South Zone), SDMC, Public Health Department, Aurobindo Marg, Green Park, New Delhi-110016. (Ref. MHA Portal ID 2022091717713 dated 05/11/2022)

Conditions for the validity of Fire Safety Certificate: -

1. All the means of escape/entry/exit shall be kept free from any obstruction.
2. All the fire safety arrangements provided therein shall be maintained in good working condition at all time as seen during inspection. Any loss of life or property due to non-functional fire safety measures shall be at the responsibility of the management.
3. All the staff members must know the correct method of operation of fire-fighting system.
4. The owner/ occupier shall submit a declaration every year in Form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in
5. This fire safety certificate may not in any way be treated as regularization (Clause 2.8 of UBBL-2016) of unauthorized construction or alteration (Clause 1.4.3 of UBBL-2016), if any.
6. "The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in Form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior to its expiry."
7. This FSC will become null & void, if the FSC of the main premise is not renewed under Rule 37 of DFS Rules- 2010.

INSPECTION REPORT

M/11



1	Name & Address of the Building	M/s Le Cantine (Unit of Sisters food craft Pvt Ltd.) Situating at 301 & 301A, Second Floor , DLF Promenade Mall, Nelson Mandela Marg, Vasant Kunj, New Delhi-110070		
2	Type of Occupancy	Assembly Building "Group-D" Restaurant		
3	Building Comprised of	Two tier Basement, LGF, UGF, & 02 upper Floor		
4	Type of Case	Renewal		
5	Details of Previous NOC	F6/DFS/MS/EH/2019/SZ/2110 dated 05/11/2019		
6	Fire Safety Directives Letter No	Nil		
7	Date of Inspection	01/12/2022		
8	Name of the Inspecting Officers	Sh. Rajesh Kumar ADO (BCP)		
9	Name & Designation of Officers from the building side	Mr. Manoj		
10	Year of construction	2005	Restaurant running at 2 nd Floor in DLF Promenade Mall building.	
11	Applicant letter No.	MHA Portal ID 2022091717713 dated 05/11/2022		
S. No.	Minimum standards on Fire Prevention and Fire Safety U/R 33	Requirement/ Existing Fire Protection	Provided at Site	Remarks MR/NMR
1	Access to Building. FSC No.F/DFS/MS/Mall/2020/SZ/58 Dated 22/01/2020 of DLF Promenade Mall			
	<ul style="list-style-type: none"> • Road width • Gate width • Width of internal road 	Restaurant within Mall	<ul style="list-style-type: none"> *Provided *Provided *Provided 	<ul style="list-style-type: none"> MR MR MR
2	Number, width, type and arrangements of exits.			
	a. Number of Staircase	Provided & Maintained by DLF Promenade Mall		
	<ul style="list-style-type: none"> • Upper floors • Basement floor 	<ul style="list-style-type: none"> 02 Nos N/A 	<ul style="list-style-type: none"> *Provided *Provided 	<ul style="list-style-type: none"> MR MR
	b. Width of Staircase	Provided & Maintained by DLF Promenade Mall		
	<ul style="list-style-type: none"> • Upper floors • Basement floor 	<ul style="list-style-type: none"> Required N/A 	<ul style="list-style-type: none"> *Provided *Provided 	<ul style="list-style-type: none"> MR MR
	c. Protection of exits	Provided & Maintained by DLF Promenade Mall		
	<ul style="list-style-type: none"> • Fire check door • Pressurization 	<ul style="list-style-type: none"> Required N/A 	<ul style="list-style-type: none"> *Provided *Provided 	<ul style="list-style-type: none"> MR MR
	d. No. of continuous staircase to terrace	Required	*Provided	MR
	e. Width of corridor	N/A	N/A	N/A
	f. Door size	02 Exits 2m/1m	2m	NMR
3	Compartmentation.	Provided & Maintained by DLF Promenade Mall		
	<ul style="list-style-type: none"> • Fire check door. • Sealing of electrical shafts. • Fire rating of shaft door. • Water curtain • Fire dampers. 	<ul style="list-style-type: none"> Required N/A N/A N/A N/A 	<ul style="list-style-type: none"> *Provided As above N/A N/A N/A 	<ul style="list-style-type: none"> MR N/A N/A N/A N/A
4.	Smoke Management system.	Provided & Maintained by DLF Promenade Mall		
	<ul style="list-style-type: none"> • Basement • Upper floors 	<ul style="list-style-type: none"> N/A Required 	<ul style="list-style-type: none"> As above Exhaust fans provided 	<ul style="list-style-type: none"> N/A MR
5.	Fire Extinguishers.			
	<ul style="list-style-type: none"> • Total numbers • Types • ISI Marking 	<ul style="list-style-type: none"> 06 Nos ISI marked 	<ul style="list-style-type: none"> 06 Nos. ABC-04, W.CO₂-02 Provided 	<ul style="list-style-type: none"> MR MR MR
6.	First Aid Hose Reels.	Provided & Maintained by DLF Promenade Mall		
	<ul style="list-style-type: none"> • Total numbers on each floor. • Length of hose-reel hose. • Nozzle Diameter 	Hose Reel	<ul style="list-style-type: none"> One in Restaurant 30m 5mm 	<ul style="list-style-type: none"> MR MR MR

M/B



20

7	Automatic Fire Detection and Alarming system. (Provided & Maintained by DLF Promenade Mall			
	<ul style="list-style-type: none"> Type of detectors 	Required	Smoke & Heat	MR
	<ul style="list-style-type: none"> Location of Main Panel 	Required	*Provided	MR
	<ul style="list-style-type: none"> Location of Repeater Panel 	N/A	N/A	N/A
	<ul style="list-style-type: none"> Alternate source of power 	Required	*Provided	MR
	<ul style="list-style-type: none"> Hooter's location 	Required	*Provided	MR
8.	MOEFA	Required	*Provided	MR
9.	Public Address System	Required	*Provided	MR
10.	Automatic Sprinkler System	Provided & Maintained by DLF Promenade Mall		
	<ul style="list-style-type: none"> Basement 	Required	*Provided	MR
	<ul style="list-style-type: none"> Upper floors 	Required	Provided in Restt.	MR
	<ul style="list-style-type: none"> Sprinkler above false ceiling 	N/A	N/A	N/A
11.	Internal Hydrants.	Provided & Maintained by DLF Promenade Mall		
	<ul style="list-style-type: none"> Size of Riser/Down-comer 	Required	*Provided	MR
	<ul style="list-style-type: none"> Number of Hydrant per floor 	Required	*Provided	MR
	<ul style="list-style-type: none"> Hose box. 	Required	*Provided	MR
12.	Yard Hydrants.	Provided & Maintained by DLF Promenade Mall		
	<ul style="list-style-type: none"> Total number of hydrants. 	N/A	*Provided	MR
	<ul style="list-style-type: none"> 2. Hose box. 	N/A	*Provided	MR
13.	Pumping arrangements.	Provided & Maintained by DLF Promenade Mall		
	<ul style="list-style-type: none"> Ground Level 	Provided & Maintained by DLF Promenade Mall		
	<ul style="list-style-type: none"> ➤ Discharge of main pump. 	4500 LPM	*Provided	MR
	<ul style="list-style-type: none"> ➤ Head of main pump. 	70 mtrs	*Provided	MR
	<ul style="list-style-type: none"> ➤ Number of main pumps. 	Two	*Provided	MR
	<ul style="list-style-type: none"> ➤ Jockey Pump output. 	450 LPM	*Provided	MR
	<ul style="list-style-type: none"> ➤ Jockey Pump head. 	70 mtrs	*Provided	MR
	<ul style="list-style-type: none"> ➤ Standby Pump output. 	4500 LPM	*Provided	MR
	<ul style="list-style-type: none"> ➤ Standby Pump head. 	70 mtrs	*Provided	MR
	<ul style="list-style-type: none"> ➤ Auto Starting / Manual Stopping. 	Required	*Provided	MR
	<ul style="list-style-type: none"> ➤ Access to pump house 	Required	*Provided	MR
	<ul style="list-style-type: none"> Terrace Level 	Provided & Maintained by DLF Promenade Mall		
	<ul style="list-style-type: none"> ➤ Discharge of pump. 	N/A	N/A	N/A
	<ul style="list-style-type: none"> ➤ Head of pump. 	N/A	N/A	N/A
	<ul style="list-style-type: none"> ➤ Power supply. 	N/A	N/A	N/A
	<ul style="list-style-type: none"> ➤ Auto starting of pump. 	N/A	N/A	N/A
14.	Captive water storage for Fire Fighting.	Provided & Maintained by DLF Promenade Mall		
	<ul style="list-style-type: none"> Underground tank capacity. 	5,00,000 Ltrs	*Provided	MR
	<ul style="list-style-type: none"> ➤ Draw-off connection. 	Required	*Provided	MR
	<ul style="list-style-type: none"> ➤ Fire Service Inlet. 	Required	*Provided	MR
	<ul style="list-style-type: none"> ➤ Access to tank. 	Required	*Provided	MR
	<ul style="list-style-type: none"> Overhead tank capacity. 	20,000 Ltrs	*Provided	MR
15.	Exit Signage.	Required	*Provided	MR
16.	Provision of Lifts.	Provided & Maintained by DLF Promenade Mall		
	<ul style="list-style-type: none"> Pressurization of lift shaft. 	N/A	N/A	N/A
	<ul style="list-style-type: none"> Pressurization of lift lobby. 	N/A	N/A	N/A
	<ul style="list-style-type: none"> Communication in lift car. 	N/A	N/A	N/A
	<ul style="list-style-type: none"> Fireman's switch. 	N/A	N/A	N/A
	<ul style="list-style-type: none"> Lift signage. 	N/A	N/A	N/A
17	Standby Power Supply	Required	Provided (DG Set)	MR
18.	Refuge Area	Provided & Maintained by DLF Promenade Mall		
	<ul style="list-style-type: none"> Total area 	N/A	N/A	N/A
	<ul style="list-style-type: none"> Location 	N/A	N/A	N/A
19.	Fire Control Room.	Provided & Maintained by DLF Promenade Mall		
	<ul style="list-style-type: none"> Detector System Panel. 	N/A	As above	N/A

M

N/13

	• Flow Switch Panel.	N/A	As above	N/A
	• PA system Panel.	N/A	As above	N/A
	• Battery backup	N/A	As above	N/A
	• Building floor plan	N/A	As above	N/A
20.	Special Fire Protection System for the Protection of special Risk, if any :	N/A	As above	N/A

Note fire safety arrangement provided and maintained by DLF Promenade Mall Vasant Kunj, Delhi

The fire protection system provided in the building were randomly checked and found functional at the time of inspection.

Further, the party has complied all the observation / Shortcoming already issued & communicated by this department vide letter of even no 629 dated 21/10/2022.

Keeping in view of the deemed compliance of the minimum standard on fire prevention and fire safety measures as required under the rules, the FSC issued vide letter no F6/DFS/MS/EH/2019/SZ/2110 dated 05/11/2019, renewal under rule 37 of the Delhi Fire Service rules, 2010 is recommended.

Accordingly DFA is put up for approval and signature please.

[Handwritten Signature]
21/12/22

Signature of the Inspecting Officer
Name: Rajesh Kumar
Designation: ADO / BCP

DO (SD)

[Handwritten Signature]
05/11/22

~~DO (SZ)~~

F, T.
[Handwritten Signature]

ADO (SIP)

As approved, F.T. letter is put up for your signature pl

[Handwritten Signature]
08/11/22

[Handwritten Signature]
24/11/22

M.S. *[Handwritten Signature]*

Updated
19/12/22
[Handwritten Signature]