



FIRE SAFETY CERTIFICATE

Certified that the M/s Al-Saudia Guest House located at 954, Gali Shyamlal, Bazar Matia Mahal, Jama Masjid, Delhi- 06, comprised of Ground + 06 upper floors: ground floor- (03 guest rooms + reception cum office), 1st floor (03 guest rooms), 2nd floor- (03 guest rooms), 3rd floor & 4th floor – (owner residence), total 09 guest rooms was earlier granted FSC by this department vide letter No. F6/DFS/MS/GH/NDZ/2019/765 dated 09.04.2019. Now, the premise was re-inspected by the officer concerned of this department on 01.12.2022 in presence of Mr. Sazzad (Manager) and found that the building is comprised of Basement + ground + 06 upper floors and now the floor wise occupancy is Basement – not in use for any purpose as per affidavit dated 22.06.22, ground floor- (03 guest rooms + reception cum office), 1st floor (03 guest rooms), 2nd floor- (03 guest rooms) & 3rd floor – (owner residence) & 4th to 6th floor – not in use for any purpose as per affidavit dated 22.06.2022. The building have deemed complied with the fire prevention and fire safety requirements in accordance with Rule 33 of Delhi Fire Service Rules, 2010. Accordingly, the premises is fit for occupancy class of “Residential (Sub Division-A-1), ground floor – (03 guest rooms), 1st floor - (03 guest rooms) & 2nd floor - (03 guest rooms) for total 09 guest rooms up to 2nd floor only, with effect from 13/12/2022 for a period of three years in accordance with Rule 36 unless renewed under Rule 37 or sooner cancelled under Rule 40 and subject to conditions under Rule 38 of Delhi Fire Service Rules, 2010 printed below.

Issued on 13/12/2022 at New Delhi by.

13/12/22
(S.K. Dua)

Dy. Chief Fire Officer
Delhi Fire Service o/c
Tel No.- 011-23412222

14/12

Copy to:-

1. The Joint Commissioner of Police (Licensing), 1st Floor, Police Station Defence Colony, New Delhi. w.r.to ID No. 2022053011659 dated 30.05.2022.
2. Al-Saudia Guest House at 954, Gali Shyamlal, Bazar Matia Mahal, Jama Masjid, Delhi- 06.
3. The Commissioner, MCD:- to kindly ensure the occupancy as detailed above & deviation, if any.

Conditions for the validity of Fire Safety Certificate

1. All the fire safety arrangements provided therein shall be maintained in good working condition at all times.
2. Any loss of life or property due to non functional fire safety measures shall be at the responsibility of the management.
3. The trained fire fighting staff should be available round the clock.
4. Any deviation w.r.t. construction etc. shall be verified by the concerned building sanctioning authority.
5. This fire safety certificate may not be treated in any case for regularization of unauthorized construction, if any.
6. The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in
7. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in form 'J' [sub Rule (1) of Rule 37] along with a copy of this Certificate, six month prior to its expiry. Any change in the occupancy shall be intimated to this Deptt. and approval shall be obtained thereto before occupancy of the same.
8. The occupancy of any floor above third floor not allowed as per clause 7.31 in UBBL-2016.

INSPECTION REPORT

1	Name & address of the building	M/s Al Saudia Guest House located at 954, Gali Shyamlal, Bazar Matia Mahal, Jama Masjid, Delhi- 06.		
2	Building is comprised of	Basement + Ground + 06 upper floors Basement – (not in use as per affidavit dated 22.06.2022) Ground floor – (03 guest rooms + reception) 1st floor (03 guest rooms) 2nd floor (03 guest rooms) 3rd floor – (Owner residence) 4th to 6th floor (not in use as per affidavit dated 22.06.2022)		
3	Type of occupancy	Residential Group A-1		
4	Type of case	Renewal (old case)		
5	Details of previous FSC	F6/DI S/MS/GH/NDZ/2019/765 dated 09.04.2019		
6	Fire safety direction letter no.	Nil		
7	Date of inspection	01.12.2022		
8	Name of the inspecting officers	Sh. Sumit Kumar ADO (SPM)		
9	Name of the designation of officer from the building side	Mr. Sazzad (Manager)		
10	Year of construction	1992		
11	Applicant's letter no.	Online application no. 2022053011659 dated 30.05.2022 & email dated 30.11.2022		
S.No	Minimum Standards on fire Prevention and fire safety requirements U/R 33	Requirement/ Existing fire safety arrangements	Provided at Site	Remarks MR/ NMR
1	Access To Building:			
	Road width	NA	03 mtrs. (spl. area)	NA
	Gate width	NA	NA	NA
	Width of internal road	NA	NA	NA
2	Number, Width, Type and Arrangement of Exits:			
	A Number of staircases			
	a Upper floor	01 nos.	01 nos.	MR
	b Basement	NA	NA	NA
	B Width of staircases			
	a Upper floor	0.80 mtrs.	1.05 mtrs.	MR
	b Basement	NA	NA	NA
	C Protection of exits			
	a Fire check door	NA	NA	NA
	b Pressurization	NA	NA	NA
	D No. of continuous staircases to terrace	01 nos.	01 nos.	MR
	E Width of corridor	NA	NA	NA
	F Door size	1.0 mtrs.	1.0 mtrs.	MR
3	Compartmentation:			
	A Fire check door	NA	NA	NA
	B Sealing of electrical shafts	NA	NA	NA
	C Fire rating of shaft door	NA	NA	NA
	D Water curtain	NA	NA	NA
	E Fire dampers	NA	NA	NA
4	Smoke Management System:			
	A Basements	30 ACPH	NA	NA
	B Upper floors	12 ACPH	Natural /Ventilated	MR

5.	Fire Extinguisher:				
	A	Total numbers	06 nos.	06 nos.	MR
	B	Types	CO ₂ & ABC	CO ₂ & ABC	MR
	C	ISI marking	Required	Provided	MR
6	First-Aid-Hose Reels:				
	A	Total numbers of each floor	01 nos.	01 nos.	MR
	B	Length of hose reel hose	30 mtrs.	30 mtrs.	MR
	C	Nozzle diameter	5 mm	5 mm	MR
7	Automatic Fire Detection And Alarming System:				
	A	Type of detectors (CO type)	Required	Provided	MR
	B	Location of main panel	Required	Provided at reception	MR
	C	Location of repeater panel	NA	NA	NA
	D	Alternate source of power	Required	Provided	MR
	E	Hooters	Required	Provided	MR
8	MOEFA:				
			NA	NA	NA
9	Public Address System:				
			Required	Provided	MR
10	Automatic Sprinkler System:				
	A	Basement	NA	NA	NA
	B	Upper floor	NA	NA	NA
	C	Sprinkler above false ceiling	NA	NA	NA
11	Internal Hydrants:				
	A	size of riser/down-comer	NA	NA	NA
	B	Number of hydrants per floor	NA	NA	NA
	C	Hose box	NA	NA	NA
12	Yard Hydrants:				
	A	Total number of hydrants	NA	NA	NA
	B	Hose box	NA	NA	NA
13	Pumping Arrangements:				
	A	Ground level			
	a)	Discharge of main pump	NA	NA	NA
	b)	Head of main pump	NA	NA	NA
	c)	Number of main pumps	NA	NA	NA
	d)	Jockey pump out put	NA	NA	NA
	e)	Jockey pump head	NA	NA	NA
	f)	Standby pump out put	NA	NA	NA
	g)	Standby pump head	NA	NA	NA
	h)	Auto starting /manual stopping	NA	NA	NA
	i)	Pump house access	NA	NA	NA
	B	Terrace level			
	a)	Discharge of pump	225 LPM	225 LPM	MR
	b)	Head of the pump	25 mtrs.	25 mtrs.	MR
	c)	Power supply	Required	Provided	MR
	d)	Auto starting of pump	Required	Provided	MR

- 7/32

14	Captive Water Storage For Fire Fighting:				
A	Underground tank capacity	NA	NA	NA	
B	Draw-off connection	NA	NA	NA	
C	Fire service inlet	NA	NA	NA	
D	Access to tank	NA	NA	NA	
E	Overhead tank capacity	2,500 ltrs.	2,500 ltrs.	MR	
15	Exit Signage:		Required	Provided	MR
16	Provision of Lifts:				
A	Pressurization of lift shaft	NA	NA	NA	
B	Pressurization of lift lobby	NA	NA	NA	
C	Communication in lift car	NA	NA	NA	
D	Firemen's grounding switch	NA	NA	NA	
E	Lift signage	NA	NA	NA	
17	Standby Power Supply:		Required	Provided	MR
18	Refuge Area:				
A	Total area	NA	NA	NA	
B	Location	NA	NA	NA	
19	Fire Control Room :				
A	Detector system panel	NA	NA	NA	
B	Flow switch panel	NA	NA	NA	
C	Pa system panel	NA	NA	NA	
D	Battery backup	NA	NA	NA	
E	Building floor plans	NA	NA	NA	
20	Special Fire Protection Systems For Protection of Special Risks, If Any:			NA	NA

Note:- The Building is comprised of Basement + ground + 06 upper floors and has been declared high rise (24.10 mtr.) by North DMC building department however the guest house is running only on ground + 02 upper floors. The owner has submitted an affidavit dated 22.06.2022 stating not to use any floor above 3rd floor for any purpose.

The fire protection systems provided in the building were tested, checked at random and found functional at the time of inspections.

Shortcomings communicated vide letter No.F6/DFS/MS/GH/NDZ/2021/847 dated 25/11/2021 have been rectified.

In view of the deemed compliance of minimum standards of fire prevention and fire safety measures as required under the Rules, the FSC issued vide letter no. F6/DFS/MS/GH/NDZ/2019/765 dated 09.04.2019 is recommended to be renewed up to 2nd floor only, under Rule 35 of the Delhi Fire Service Rules 2010.

Sumit Kumar
02/12/2022

Signature of the Inspecting Officer
Name Sumit Kumar
Designation ADO (SPM)

~~DO (CD)~~

[Signature]
2/12/22

~~Dy. C.F.O (G-2)~~

~~DO (CD) + ADO (SPM)~~

P1. spk about letter dt. 12/07/22, placed at C-64.

[Signature]
05/12

contd. -