CHS

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEAD QUARTERS: DELHI FIRE SERVICE: NEW DELHI - 110001

No. F6/DFS/MS/School/2022/ 1321

Dated: 19/12/2022

FIRE SAFETY CERTIFICATE

(Dharampal Bhardwaj) Dy. Chief Fire Officer Ph:-011-23414250

Copy to: -

1. The Director, Education, Government of N.C.T of Delhi. Old Sectt. Delhi – 110054.

2. The Principal, Govt. Sarvodaya Kanya Vidyalaya (I.D 1309167) located at Vijay Nagar, Delhi-110009

Conditions for the validity of Fire Safety Certificate:

1. All the means of escape/entry/exit shall be kept free from any obstruction.

- 2. All the fire safety arrangements provided therein shall be maintained in good working condition at all time as seen during inspection.
- 3. Any loss of life or property due to non-functional fire safety measures shall be at the responsibility of the management.

4. All the staff members must know the correct method of operation of firefighting system.

5. The owner / occupier shall submit a declaration every year in Form "K" provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on http://delhi.gov.in./wps/wcm/connect/doit fire/FIRE/Home/Forms.

6. This fire safety certificate may not in any way be treated as regularization (Clause 2.8 of UBBL-2016) of unauthorized construction or Alteration (Clause 1.4.3 of UBBL-2016), if any.

7. "The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in Form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior to its expiry".

INSPECTION REPORT

Name & address of the building

Type of Occupancy

: Govt. Sarvodaya Kanya Vidyalaya at Vijay Nagar, Delhi-07. (1.D no.1309167)

: Educational

Composition of building 3.

: Ground plus 03 upper floors

Type of Case

: Renewal

Details of previous NOC 5.

: F6/DFS/MS/2019/WZ/1017 dated 15.05.2019

Fire Safety directives letter No

: Nil

Date of inspection

: 02.12.2022

Name of the Inspecting Officers

: ADO (RN)

Name and designation of officers

from the building side

: Smt. Alka Rani, Vice Principal

10. Year of Construction

: 1947

11. Applicant's letter No.

: Online E-mail dated: 28.04.2022

	Minimum Standards on fire prevention and	No of class rooms -17 No of students750					
	fire safety U/R 33	NBC Requirement	Provided at site	MR/NMR			
	Access to building						
	Road width	6m	6m	MR			
	Gate width	4.5m	5m	MR			
	Width of internal road	6m	6m	MR			
	Number, Width, Type & Arrangement of Exits						
	a. Number of staircases						
	Upper Floors	02	02	MR			
	Basements	NA	NA	NA			
	b. Width of staircases						
	Upper Floors	1.5 m	1.35 m & 2m	MR			
	Basements	NA	NA	NA			
	c. Protection of exits						
	Fire check door	NA	NA	NA			
	Pressurization	NA	NA NA	NA NA			
	d. No. of continuous staircases to terrace	02	02	MR			
	e. Width of Corridor	NA					
	f. Door Size	NA	NA	NA			
		1 m	1.05m	MR			
3	Compartmentation.						
	Fire check door	NA	NA	NA			
	Sealing of electrical shafts	NA	NA	NA			
	Fire Rating of shaft door	NA	NA	NA			
	• Water Curtain	NA .	NA	NA			
	Fire Dampers	NA	NA	NA			
4	Smoke Management System.						
	Basements	12 a/c per hour	NA	NA			
	Upper floors	12 a/c per hour	Natural Ventilated	MR			
5	Fire Extinguishers						
	Total numbers	10nos	10nos	MR			
	Types	ABC/Co2	ABC-06/Co2-04	MR			



				-	
	ISI marking	ISI Marked	Provided	MI	
_	First-Aid Hose Reels.				
	Total numbers on each floor	01	Provided	MF	
	Length of hose reel hose	30m	30m	MR	
	Nozzle diameter	5mm	5mm	MR	
	Automatic fire detection and alarming syste	m,	are combination and the second of the second		
	Type of detectors	NA	NA	NA	
	Location of Main Panel	NA	NA	NA	
	Location of Repeater Panel	NA	NA	NA	
	Alternate source of power	NA	NA	NA	
	Hooters' Location	NA	NA	NA	
	MOEFA	NA	NA	NA	
_	Public Address System.			-	
	Automatic Sprinkler System.	Laurent Lauren	L	-	
	Basement	NA NA	NA NA	NA NA	
	Upper Floor	NA	NA NA	NA	
	Sprinkler above false ceiling	NA	NA NA	NA	
	Internal Hydrants				
	Size of riser/down-comer	100mm	100mm	MR	
	Number of hydrants per floor	01	01	MR	
	Hose Box	01	01	MR	
	Yard Hydrants.				
	Total number of hydrants	I NA			
	Hose Box	THE RESERVE OF THE PARTY OF THE	NA	NA	
	Tiose Box	NA	NA	NA	
	Pumping Arrangements.				
	Ground Level			1	
	Discharge of main Pump	N/A	N/A	N/A	
	> Head of Main pump	N/A	N/A	N/A	
	Number of main pumps	N/A	N/A	N/A	
	> Jockey Pump out put	NA	NA	NA	
	Jockey pump head	NA	NA	NA NA	
	Standby Pump out put	N/A	N/A		
	 Standby Pump Head Auto Starting/ Manual stopping 	N/A	N/A	N/A	
	> Pump House Access	N/A	N/A	NA NA	
	Terrace level				
	 Discharge of pump 	4501pm	450Lpm	MR	
	> Head of the pump	40m	40m	MR	
	> Power Supply	Required	Provided	MR	
-	Auto Starting of pump	Required	Provided		
	Captive Water Storage for fire fighting.	1	Provided	MR	
***************************************	Underground tank capacity	NA I	50,000 LTR		
	> Draw-off connection	NA NA	NA NA	NA NA	
- Constitution	Fire service inlet	NA .	NA NA	1 11	
-	- Access to tank	NA	NA NA	NA NA	
-	Overhead Tank capacity	10,000 LTR	10.000 LTR	MR	
1			4.150	3 10100	

Exit Signage.	Required	Provided	MR		
Provision of Lifts.		N/A	N/A		
Pressurization of Lift Shaft	N/A	N/A	N/A		
Pressurization of Lift lobby	N/A	N/A			
	N/A	N/A	N/A		
Communication In lift Car	18/74		N/A		
Fireman's Grounding Switch	N/A	N/A			
Lift Signage	N/A	N/A	N/A		
		N/A	N/A		
Standby power supply	N/A .	14//			
D.C. Arra					
Refuge Area.	N/A	N/A			
> Total Area	N/A	N/A	N/A		
> Location					
Fire Control Room					
Detector System Panel	N/A	N/A	N/A		
	N/A	N/A	N/A		
Flow Switch Panel	N/A		N/A		
PA System Panel	N/A	N/A	N/A		
Batter backup	N/A	N/A	N/A		
Building Floor Plans		21/4	N/A		
	N/A	N/A	1077		
Special Fire Protection Systems for					
Protection of special Risks, if any:					

The fire protection systems provided in the building were tested/ checked randomly and found in good working condition, at the time of inspection. The management has complied all the shortcomings issued and communicated by this department vide letter of even no. 341 dated 23.06.2022.

Keeping in view the satisfactory compliance of the minimum standards on fire prevention and fire safety required as stipulated in NBC Part 4, the FSC issued vide letter of even no. 1027 dated 15.05.2019 renewal under rule 37 of the Delhi Fire Service Rules, 2010 is recommended

DOWW

Signature of the Inspecting Name: - C.L. Meena

Designation:- ADO/RN

As approved, F.T. letter is butup for your sings floare.