

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: CONNAUGHT PLACE NEW DELHI-110001

No. F.6/DFS/MS/GH/2022/SZ/ 535

Dated: Q.S.././.2.12022

FIRE SAFETY CERTIFICATE

Certified that the Guest house in the name & style of M/s Rockland Hotel at B- 209, C R Park, New Delhi- 110019 comprised of Basement:-Storage only, Stilt:-Parking, ground:-Reception & Office, 1st Floor: - 07 G/Rooms, 2nd Floor: - 07 G/Rooms, 3rd Floor: - 05 G/Rooms, Total- 19 Guest Rooms owner/occupied by Unit of Rockland Hotels Limited was issued Fire Safety Certificate by this department vide letter No. F.6/DFS/MS/GH/2019/SZ/1613 dated 13-08-2019. The premise was re-inspected by the officer concerned of this department on 28/11/2022 in the presence of Mr. Aditya Bhandari and found that the said premises have deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the premises is fit for occupancy class "Residential, Group-A" with effect from the date of issue 29/12/2022 for a period of Three years in accordance with Rule 36 unless renewed under Rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under Rule 38 of the Delhi Fire Service Rules, 2010

Issued on 69/12/22/2022 at New Delhi by

(SUNIL CHAWDHARY)

DY. CHIEF FIRE OFFICER (SZ)


Copy to: -

1. The Addl. Commissioner of Police (Lic.), 1st Floor, P.S. Defence Colony, New Delhi–110049 (Ref. MHA Portal ID 2022082316492 dated 26/08/2022)

Conditions for the validity of Fire Safety Certificate: -

- All the means of escape/entry/exit shall be kept free from any obstruction.
- 2. All the fire safety arrangement provided therein shall be maintained in good working condition at all time as seen during inspection. Any loss of life property due to non-functional fire safety measures shall be at the responsibility of the management.
- 3. The basement shall be used as per the provisions of BBL /NBC Part- IV.
- 4. All the staff members must know the correct method of operation of fire fighting system.
- 5. The owner/occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in
- 6. This fire safety certificate may not in any way be treated as regularization (Clause 2.8 of UBBL-2016) of unauthorized construction or Alteration (Clause 1.4.3 of UBBL-2016), if any.
- 7. "The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in form 'J' [sub rule (I) of rule 37] along with a copy of this Certificate, six month prior to its expiry."





	INSPECTION						
1	Name & Address of the Building	M/s Rockland Hotel (Unit of Rockland Hotel					
			Limited) at B- 209, C R Park, New Delhi-19				
2	Type of Occupancy	Group	Group-A "Residential & Lodging"				
3	Building Comprised of	Basement, Ground + 03 Upper Floors.					
4	Type of Case	Renewal					
5	Details of Previous NOC	F.6/DFS/MS/GH/2019/SZ/1613 dated 13-08-2019.					
6	Fire Safety Directives Letter No	Nil					
7	Date of Inspection	28/11/2022					
8	Name of the Inspecting Officers	Sh. Rajesh Kumar ADO (BCP)					
9	Name & Designation of Officers	Mr. Aditya Bhandari					
10	from the building side	1996 Basement -Storage only, Stilt:-Parking, ground -Reception					
10	Year of construction	& Office. 1st Floor: - 07 G/Rooms, 2nd Floor: - 07 G/Rooms,					
		3 rd Floor: - 05 G/Rooms, Total- 19 Guest Rooms					
11	Applicant letter No.	MHA Portal ID 2022082316492 dated 26/08/202					
S. No.	Minimum standards on Fire Prevention		Old NOC Provided at Site Remarks Requirements MR/NMF				
	and Fire Safety U/R 33	Requi	irements		MINTAINIK		
1	Access to Building.			12	100		
	Road width		mtr	12 mtr	MR		
	Gate width		N/A	N/A	N/A		
	Width of internal road	<u> </u>	V/A	N/A	N/A		
2	Number, width, type & arrangement of exits.						
	a) Number of Staircase		> T	02.5	M		
	> Upper floors.		Nos	02 Provided	MR		
	Basement floor.	02	Nos	Provided	MR		
4	b) Width of Staircase	1.0		1.42 0.1) (D		
	Upper floors		25 m	1.43m & 1m	MR		
	Basement floor	1.2	25 m	1.43m & 1m	MR		
	c) Protection of exits	Don	mirad	Provided	MR		
	Fire check door as per clause 7.31		uired	Provided	MR		
	in UBBL-2016 Pressurization	Rec	quired	riovided	IVIK		
	d) No. of continuous staircase to terrace		01	Provided	MR		
	e) Width of corridor		J/A	N/A	N/A		
	f) Door size		mtr	1.40 mtr (final exit)	MR		
3	Compartmentation.						
-	Fire check door.	N	I/A	N/A	N/A		
	Sealing of electrical shafts.		J/A	N/A	N/A		
	 Fire rating of shaft door. 		I/A	N/A	N/A		
	Water curtain		I/A	N/A	N/A		
	Fire dampers.		J/A	N/A	N/A		
4.	Smoke Management system.	As per clause 7.31 of UBBL -2016			14/11		
	Basement		ACPH	Exhaust fan provided	MR		
	Upper floors	12 /	ACPH	Natural ventilation	MR		
5	Fire Extinguishers.	P	i i r	10.31	1 m		
The second of the second of the second	Total numbers	1	ble Fire	12 Nos	MR		
	• Types		guishers narked	ABC/Co2 type	MR		
(ISI Marking First Aid Hose Books	131 1	narkeu	Yes	MR		
6	First Aid Hose Reels.		ne	Denvid 1	MD		
	Total numbers on each floor. Length of hose real hose.	And the second s		Provided	MR		
	 Length of hose-reel hose. Nozzle Diameter 		0m	Provided	MR		
7		-	mm	Provided	MR		
7	Automatic fire detection & alarming system.	and the second second	As per clause 7.31 of UBBL -2016 Co./Mo./type Provided MR				
	 Type of detectors Location of Main Panel 			Provided	MR		
	 Location of Main Panel Location of Repeater Panel 		quired	Provided	MR		
	Alternate source of power		N/A	NA NA	N/A		
	Hooter's location		Required Provided		MR		
			uired	Provided	MR		
8	MOEFA	Rec	quired	Provided	MR		





9	Public Address System	N/A	N/A	N/A
10	Automatic Sprinkler System			
	Basement	Required	Provided	MR
	Upper floors	N/A	N/A	N/A
	 Sprinkler above false ceiling 	N/A	N/A	N/A
11	Internal Hydrants.	1		
	 Size of Riser/Down-comer 	N/A	N/A	N/A
	 Number of Hydrant per floor 	N/A	N/A	N/A
	Hose box.	N/A	N/A	N/A
12	Yard Hydrants.			1
	Total number of hydrants.	N/A	N/A	N/A
	Hose box.	N/A	N/A	N/A
13	Pumping arrangements.			1
	Ground Level			
	Discharge of main pump.	N/A	N/A	N/A
	Head of main pump.	N/A	N/A	N/A
	Number of main pumps.	N/A	N/A	N/A
	Jockey Pump output.	N/A	N/A	N/A
	Jockey Pump head.	N/A	N/A	N/A
	Standby Pump output.	N/A	N/A	N/A
	Standby Pump head.	N/A	N/A	N/A
14	Auto Starting/Manual Stopping.Pump house access.	N/A	N/A	N/A
	•	N/A	N/A	N/A
	Terrace Level	000 1 DM	D	MR
	Discharge of pump.	900 LPM 40 m	Provided Provided	MR
	Head of pump.Power supply.	Required	Provided	MR
	Auto starting of pump.	Required	Provided	MR
	Captive water storage for fire fighting.	Required	TTOTIGUE	1722
14	Underground tank capacity.	N/A	N/A	N/A
	> Draw-off connection.	N/A	N/A	N/A
	Fire Service Inlet.	N/A	N/A	N/A
	Access to tank.	N/A	N/A	N/A
	 Overhead tank capacity. 	10,000 Lts	15,000 Lts	MR
15	Exit Signage.	Required	Provided	MR
16	Provision of Lifts.	D 1 1	D :1.1) (D
	 Pressurization of lift shaft. 	Required	Provided	MR N/A
	 Pressurization of lift lobby. 	N/A	N/A	
	 Communication in lift car. 	Required	Provided	MR MR
	 Fireman's switch. 	Required Required	Provided Provided	MR
	 Lift signage. 	Required	Tiovided	IVIIC
17	Standby Power Supply	Required	Provided	MR
18	Refuge Area			
	Total area	N/A	N/A	N/A
	• Location	N/A	N/A	N/A
19	Fire Control Room.		A	
19	Detector system panel.	N/A	N/A	N/A
		N/A	N/A	N/A
	• Flow switch panel.	N/A	N/A	N/A
	PA system panel.	N/A	N/A	N/A
	 Battery backup. 		N/A	N/A
		NI/A		
20	Building floor plan. Special Fire Protection System for the	N/A N/A	N/A	N/A

an





M's Rockland Hotel (Unit of Rockland Hotels Limited) at B- 209, C R Park, New Delhi-19

The fire protection system provided in the building were randomly checked and found functional at the time of inspection.

Keeping in view of the deemed compliance of the minimum standard on fire prevention and fire safety measures as required under the rules, the FSC issued vide letter no F.6/DFS/MS/GH/2019/SZ/1613 dated 13-08-2019, renewal under rule 37 of the Delhi Fire Service rules, 2010 is recommended.

Accordingly, DFA is put up for approval and signature please.

Signature of the Inspecting Officer Name: - Rajesh Kumar Designation: - ADO/BCP

proved F.T. letter in pritipe your sprotuse Pl 1.