

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELIII HEADQUARTERS: DELIII FIRE SERVICE: NEW DELIII- 110001



111 722

D

Ph: 01125156707 ♥⊂∲

(Dharampal Bhardwaj) Dv. Chief Fire Officer

No.F6/DFS/MS /2022/ 582

FIRE SAFETY CERTIFICATE

Certified that the M/s Valentine Hotels And Resorts Pvt. Ltd. located at Khasra No. 40, 41, Nangli Poona, Opp. Siras Pur Gurudwara, G.T.K. Road, Delhi-110036 comprised of basement, ground and 01 upper floor with 08 guest rooms owned/ occupied by M/s Valentine Hotel And Resorts Pvt. Ltd. was issued fire safety certificate vide letter no. F6/DFS/MS/2019/Motel/2311 dated 12.12.2019. The premise was re-inspected by the officer concerned of this department on 12.12.2022 in the presence of Sh. Manish Gupta (Manager) and observed that all the fire prevention and fire safety arrangements as provided in the premise found in good working condition. The premise have therefore deemed complied with the requirements under rule 33 of the Delhi Fire Service Rules, 2010 and the building premise is fit for occupancy under "Class Assembly/Residential Buildings" with effect from 2s.12/2.022... for a period of three years in accordance with the rule 36 unless renewed under rule 37 or sooner cancelled, under rule 40, subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules, 2010.

Issued on 20./2/222.... at New Delhi by

Copy to:-

1. The Director, M/s Valentine Hotel And Resorts Pvt. Ltd. located at Khasra No. 4041, Nangli Poona, Opp. Siras Pur Gurudwara, G.T.K. Road, Delhi-110036

Conditions for the validity of Fire Safety Certificate:

- 1. All the means of escape/entry/exit shall be kept free from any obstruction.
- 2. All the fire safety arrangements provided therein shall be maintained in good working condition at all time as seen during inspection.
- 3. Any loss of life or property due to non-functional fire safety measures shall be at the responsibility of the management.
- 4. All the staff members must know the correct method of operation of firefighting system.
- 5. The owner / occupier shall submit a declaration every year in Form "K" provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on http://delhi.gov.in./wps/wcm/connect/doit fire/FIRE/Home/Forms.
- 6. This fire safety certificate may not in any way be treated as regularization (Clause 2.8 of UBBL-2016) of unauthorized construction or Alteration (Clause 1.4.3 of UBBL-2016), if any.
- "The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in Form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior to its expiry".

Dated: 20 / 12/2022

INSPECTION REPORT

2

5

			<u>FION REPORT</u>			
1,	Name & address of the building	: M/s Valenti	ne Hotel And Resort P	vt. Ltd., at Khasra No. 4	041, G.T. Karnal	
		Nangli Poor	na, Delhi-110036.			
2.	Type of Occupancy	: Assembly D	0-5			
3.	Composition of building	: Basement, C	Ground & One upper f	oor with guest rooms		
4.	Type of Case	: Renewal				
5.	Details of previous NOC		/2019/Motel/2311 date			
6.	Fire Safety directives letter No	: F6/MS/DFS	/BP/2003/3054/(GH)	dated 16.12.2003		
7.	Date of inspection	: 12.12.2022				
8.	Name of the Inspecting Officers	: ADO (RN)				
9.	Name and designation of officers					
	from the building side	: Sh. Manish	Gupta (Manager)			
10). Year of Construction	;				
1	1. Applicant's letter No.	: MHA Portal	I I.D No. 20221118203	text dated 23.11.2022		
	Minimum Standards on fire pre fire safety U/R 33	vention and	NBC Part-IV Requirements	Provided at site	Remarks MR/NMR	
	Access to building					
	Road width		09m	09m	MR	
	Gate width		5m	5m	MR	
	• Width of internal road		6m	6m	MR	
	Number, Width, Type & Arrangement of Exits					
	a. Number of staircases					
	Upper Floors		03	03	MR	
			03	03	MR	

Basements	03	03	WIK	
b. Width of staircases				
Upper Floors	1.50m	2.40m & 1.50 each	MR	
Basements	1.50m	2.40m & 1.50 each	MR	
c. Protection of exits				
Fire check door	Required	Provided	MR	
Pressurization	NA	NA	NA	
d. No. of continuous staircases to terrace	02	02	MR	
e. Width of Corridor	NA	NA	NA	
f. Door Size	1.50m	Provided	MR	
Compartmentation.				
Fire check door	Required	Provided	MR	
Sealing of electrical shafts	NA	NA	NA	
• Fire Rating of shaft door	NA	NA	NA	
Water Curtain	NA .	NA	NA	
Fire Dampers	NA	NA	NA	
Smoke Management System.				
Basements	12 a/c per hour	Exhaust fan	MR	
Upper floors	12 a/c per hour	Natural Ventilated	MR	

Fire Extinguishers 16nos 18nos MR Total numbers • ABC/Co2 ABC/Co2 MR Types • ISI marking Yes . Yes MR

\$

N	32

-	irst-Aid Hose Reels.	02:20	Provided	MR	
	• Total numbers on each floor	02nos		MR	
	Length of hose reel hose	30 m	30m		
	Nozzle diameter	5mm	5mm	MR	
+	Automatic fire detection and alarming system.			NA	
F	Type of detectors	NA	NA	NA	
	Location of Main Panel	NA	NA		
	Location of Repeater Panel	NA	NA	NA	
	Alternate source of power	NA	NA	NA	
	Hooters' Location	NA	NA	NA	
	MOEFA	Required	Provided	MR	
	Public Address System.	Required	Provided	MR	
,	Automatic Sprinkler System.	· · · · · · · · · · · · · · · · · · ·			
	Basement	Required	Provided	MR	
	Upper Floor	Required	Provided	MR	
	Sprinkler above false ceiling	NA	NA	NA	
	Internal Hydrants				
	Size of riser/down-comer	100mm	100mm	MR	
	Number of hydrants per floor	02	02	MR	
	Hose Box	02	02	MR	
2	Yard Hydrants.		L		
	Total number of hydrants	Required	Provided	MR	
	• Hose Box	Required	Provided	MR	
3	Pumping Arrangements.				
	Ground Level				
	 Discharge of main Pump 	2280 LPM	2280 LPM	MR	
	Head of Main pump	60m	60m	MR	
	 Number of main pumps 	02nos	02nos	MR	
	 Jockey Pump out put 	180 LPM	180 LPM	MR	
	 Jockey pump head 	60m	60m	MR	
	Standby Pump out put	2280 LPM (Diesel operative)	2280 LPM (Diesel operative)	MR	
	Standby Pump Head	80m	80m	MR	
	 Auto Starting/ Manual stopping Pump House Access 	Required	Provided	MR	
	Terrace level				
	 Discharge of pump 	NA	450 LPM	NA	
	Head of the pump	NA	60m	NA	
	Power Supply	NA	NA	NA	
	Auto Starting of pump	NA	NA	NA	
14	Captive Water Storage for fire fighting.				
	Underground tank capacity	1,00,000 LTR.	Provided	MR	
	> Draw-off connection	Required	Provided	MR	
	> Fire service inlet	Required	Provided	MR	
	> Access to tank	Required	Provided	MR	
	Overhead Tank capacity	10,000 LTR	Provided	MR	
		Required	Provided	MR	

Sp



-	Provision of Lifts.			NIA	
16	Pressurization of Lift Shaft Pressurization of Lift lobby	NA	NA	NA	
		NA	NA	NA	
	Communication In lift Car	NA	NA	NA	
	Fireman's Grounding Switch	NA	NA	NA	
	• Lift Signage	NA	NΛ	NA	
7	Standby power supply	Required	Provided	MR	
8	Refuge Area.				
10	> Total Area	N/A	N/A		
	> Location	N/A	N/A	N/A	
19	Fire Control Room				
	Detector System Panel	Required	Provided	MR	
	• Flow Switch Panel	N/A	N/A	N/A	
	PA System Panel	Required	Provided	MR	
	Batter backup	Required	Provided	MR	
	Building Floor Plans	N/A	N/A	N/A	
20		NA	NA	NA	

The fire protection systems provided in the building were tested/ checked and found in good working order at the time of inspection.

Keeping in view of the substantial compliance of the minimum standards on fire prevention and fire safety required under the rules. It is recommended to renew Fire Safety vide this department letter of even no.2311 dated 12.12.2019 Certificate under rule 37(3) of Delhi Fire Service Rules 2010.

Signature of the Inspecting Officer Name: - C.L. Meena Designation:- ADO/RN

15/12/2022

DOAW

enfron 1

L Recours . Later V

There core total 58 quest Rooms at First Floor of the building. DEA is resubmitted Pl.

-- . P.T.C