


GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEAD QUARTERS: DELHI FIRE SERVICE, NEW DELHI-110001



Dated: 20 12 2022

FIRE SAFETY CERTIFICATE

Certified that the Wave Cinema (Audi I-IV), located at TDI Paragon Mall, Plot No. 02, Distt. Centre, Raja Garden, New Delhi-110027, building comprised of Lower Basement, Upper Basement, Ground + 03 upper floors was issued FSC vide this department letter no. F6/DFS/MS/WZ/2019/2049 dated 24/10/2019. The premises was re-inspected by the officers concerned of this department on 15-12-2022 in the presence of Sh. Razi Hasan (Cinema Manager) found that the said building have deemed complied with fire prevention and fire safety requirements in accordance with Rule 33 of the Delhi Fire service Rules, 2010 & found that the said building is fit for occupancy class "Assembly Building" (Cinema) with effect from for a period of three years in accordance with Rule 36 unless renewed under Rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under Rule 38 of the Delhi Fire Service Rules, 2010 conditions mentioned below.

Issued on 20/12/2011 at New Delhi by.

Copy to: -

- 1. The SDM/HQ/DDMA, District West, 3, Shivaji palace, Raja Garden, New Delhi- 27.74
- 2. The Authorized Signatory, Wave Cinema (Wave Infratech Pvt. Ltd.), 2nd Floor, TDI Paragon Mall, Plot No. 02, Shivaji Palace, Raja Garden, New Delhi 110027.

Following fire safety directives must be adhered to:-

- 1. All the fire safety arrangements provided therein shall be maintained in good working condition at all times.
- 2. Any loss of life or property due to non-functional fire safety measures shall be at the risk and responsibility of the management.
- 3. The trained staff should be available round the clock.
- 4. Any deviations w.r.t. construction shall be verified by the concerned building sanctioning agency.
- 5. The certificate may not be treated in any case for the regularization of the unauthorized construction, if any.
- 6. Basement shall be used as per building bye laws.
- 7. The owner/ occupier shall apply for renewal of this Fire Safety Certificate to the Director in Form 'J' [sub rule (1) of rule 37] along with a copy of this certificate, six months prior to its expiry.
- 8. The owner/occupier shall submit a declaration every year in the form 'K' provided in the first schedule of Delhi Fire Service Rules 2010, form is available on www.dfs.delhigovt.nic.in.

INSPECTION REPORT

Name & address of the building: Wave Cinema, (Wave infratech Pvt. Ltd.), TDI Paragon

Mall, Plot No. 02, Shivaji Palace, Raja Garden, New Delhi

110027.

2. Type of Occupancy

: Assembly (Cinema)

3. Type of Case

: Renewal

4. Details of previous NOC

: F6/DFS/MS/WZ/2019/2049 dated 24/10/2019

5. Fire Safety directives letter No : F6/DFS/MS/BP/2004/2529 dated 21/10/2004 (For the Mall)

6. Date of inspection

: 15/12/2022

7. Name of the Inspecting Officers : DO (West) & ADO(MN)

8. Name and designation of officers

from the building side

: Sh. Razi Hasan (Cinema Manager)

9. Year of Construction

: 2004 - 05 (As per insp. Report dtd - 09/10/2019)

				22				
			l dated- 28/11/20 rement as per R		Remarks			
S. No.		-	NBC-IV	uie Trovided at site	MR/NMR			
1	Access to building			,				
	Road width		12 mts	Provided	MR			
	Gate width		4.5 mts	Provided	MR			
	Width of internal road		06 mts	Provided	MR			
2	Number, Width, Type & Arrangement of Exits							
	a. Number of staircases							
	• Upper Floors		07nos	07 nos Provided	MR			
	Basements		07 + 2 ramp	Provided	MR			
	b. Width of staircases							
	Upper Floors			35cm,149cm, 198cm, 195cm, 87cm, 141cm, 135cm Provided	MR being old case			
	Basements c. Protection of exits		NA	NA	NA			
	Fire check door							
	Pressurization		Required	Provided	MR			
	e. No. of continuous staircases to terrace		Required	Provided	MR			
	f. Width of Corridor	iacc	Required	Provided	MR			
	g. Door Size		NA	NA	NA			
			4 exit in each Au	V CAR III Cacii Audi Provid	led MR			
3	Compartmentation.		Common With Mall					
	Fire check door		Required	Provided	MR			
	 Sealing of electrical shafts 	3	Required	Provided	MR			
	• Fire Rating of shaft door		Required	Provided	MR			
	• Water Curtain		Required	Provided	MR			
	• Fire Dampers		NR	Provided	NR			
4	Smøke Management System.	Common With Mall						
	Basements		30 a/c per hour	riovided	MR			
	• Upper floors (Audi 1 to 6))	12 a/c per hour	Provided	MR			
5	Fire Extinguishers							
	• Total numbers		15 nos. per Aug	Frovided	MR			
	TypesIS marking		CO ₂ , ABC type	Provided	MR			
			ISI marked	Provided	MR			

6	First-Aid Hose Reels.						
	Total numbers on each floor	08 (02 in each Audi)	Provided	MR			
	 Length of hose reel hose 	30 mm	Provided	MR			
	Nozzle diameter	05 mm	Provided	MR			
7	Automatic fire detection and alarming system.						
	Type of detectors	Smoke & Beam	Provided	MR			
	 Location of Main Panel 	G.F.	Provided	MR			
	 Location of Repeater Panel 	G.F.	Provided	MR			
	 Alternate source of power 	Required	Provided	MR			
	Hooters' Location	Required	Provided	MR			
8	MOEFA	Required	Provided	MR			
9	Public Address System.	Required	Provided	MR			
10	Automatic Sprinkler System.						
	Basement	Required at Mall	Provided	MR			
	Upper Floor	Required at cinema	Provided	MR			
	Sprinkler above false ceiling	Required	Provided	MR			
11	Internal Hydrants						
	 Size of riser/down-comer 	08 (02 in each Audi) Provided	MR			
	Number of hydrants per floor	Required	Provided	MR			
	Hose Box	08 Required	Provided	MR			
12	Yard Hydrants.						
	 Total number of hydrants 	06 of Mall	Provided	MR			
	Hose Box	06 of Mall	Provided	MR			
13	Pumping Arrangements. Common With Mall						
	Ground Level	4500 L DV4	Provided				
	Discharge of main Pump	4500 LPM		MR			
	Head of Main pump	60 MH 1 Electric pump = wet riser	Provided	MR			
	Number of main pumps	1 Electric pump = sprinkler 1 Diesel driven pump = stand by Provided		MR			
	Jockey Pump out put	Two 180 LPM each	Two 180 LPM Provided				
	Jockey pump head	60 MH 4500 LPM	Provided Provided	MR			
	> Standby Pump out put			MR			
	> Standby Pump Head	60 MH Required	Provided Provided	MR MR			
	Auto Starting/ Manual stopping	Required	Provided	MR			
	> Pump House Access						
	Terrace level	450 lpm	Provided	MR			
	Discharge of pump		Provided				
	Head of the pump	40 MH Required	Provided	MR			
	Power Supply	•		MR			
	Auto Starting of pump	Required	Provided	MR			
14	Captive Water Storage for fire fighting. Common With Mall						
	Underground tank capacity	03 Lakh ltrs	Provided	MR			
	> Draw-off connection	Required	Provided	MR			
	Fire service inlet	Required	Provided	MR			
	> Access to tank	Required	Provided	MR			
	 Overhead Tank capacity 	30,000 ltrs	Provided	MR			

	1/							
		Required	Provided	MR				
Rice.	Exit Signage.							
15		Required	Provided	MR				
-1	• Pressurization of Lift Shaft	Required	Provided	MR				
-	Pressurization of Lift lobby Communication In lift Car	Required	Provided	MR				
I	Communication in the Car Fireman's Grounding Switch	Required	Provided	MR				
	Lift Signage	Required	Provided	MR				
		Required	Provided 125 KVS	MR				
17	Standby power supply							
18	Refuge Area.							
	> Total Area	NR	NR	NR				
	> Location	NR	NR	NR				
19	Fire Control Room							
19	Detector System Panel	Required	Provided	MR				
	Flow Switch Panel	Required	Provided	MR				
	PA System Panel	Required	Provided	MR				
	Batter backup	Required	Provided	MR				
	Building Floor Plans	Required	Provided	MR				
20	Special Fire Protection Systems for Protection of special Risks, if any:	NR	NR	NR				

The fire protection systems provided in the building were checked and found functional at the time of inspection.

Keeping in view the deemed compliance of the minimum standards of fire prevention and fire safety measures as required under the rules, the NOC vide letter No. F6/DFS/MS/WZ/2019/2049 dated 24/ 0/2019 renewal under rule 35 of the Delhi Fire Service rule 2010 is recommended.

DFA is put up for approval & signature please

Signature of the Inspecting Officer

Name: - M. K. Chattopadhyay

Designation: - DO (W)

Signature of the Inspecting Officer Name: - Sarabjeet Singh

Designation: - ADO (MN)

412/ADO/MA 16/14/2022