

1-35
C-37

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS: DELHI FIRE SERVICE: CONNAUGHT PLACE
NEW DELHI-110 001.

No. F.6/DFS/MS/EH/2022/SZ/ 358

Dated: 21/12/22

FIRE SAFETY CERTIFICATE

Certified that the **M/s AMPM CAFÉ & BAR** (previously known as Decode Social Dinning), J-2/1, BK Dutta Market, Rajouri Garden, New Delhi-110027 comprised of basement, ground floor plus three upper floors but the restaurant is running at ground floor plus two upper floors owned/occupied by M/s AMPM CAFÉ & BAR was issued FSC Vide letter No. F6/DFS/MS/EH/2018/SZ/1303 Dated 05/06/2018. The building was inspected by the officers concerned of this department on 07/12/2022 in the presence of Sh. Pawan Kumar and found that the building have deemed complied with the fire prevention and fire safety requirements in accordance with Rule 33 of the Delhi Fire Service Rules, 2010 and that the building/ premises **(Ground floor plus two upper floors)** is fit for occupancy class Group D "Assembly Building" w.e.f. the date of issue of this certificate for a period of **three years** in accordance with Rule 36 unless renewed under Rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under Rule-38 of the Delhi Fire Service Rules, 2010 printed below.

Issued on.....21/12/22.....at New Delhi.


(SUNIL CHAUDHARY)
DY. CHIEF FIRE OFFICER

Copy to:-

1. The Deputy Health Officer,
West Zone (SDMC), Public Health Department,
Vishal Enclave, New Delhi.
2. The Manager,
M/s AMPM CAFÉ & BAR, J 2/1, BK Dutta Market,
Rajouri Garden, New Delhi-110027.

Following fire safety directives must be adhered to:-

1. All the fire safety arrangements provided therein shall be maintained in good working condition at all times.
2. The means of escape shall be kept unlocked and unobstructed for unhindered evacuation of occupants in case of emergency.
3. Any loss of life or property due to non-functional fire safety measures shall be at the risk and responsibility of the management.
4. The trained staff should be available round the clock.
5. Any deviations w.r.t. construction shall be verified by the concerned building sanctioning agency.
6. The certificate may not be treated in any case for the regularization of the unauthorized construction, if any.
7. Basement shall be used as per the building bye laws.
8. The owner/occupier shall submit a declaration every year in the form 'K' provided in the first schedule of Delhi Fire Service Rules 2010, form is available on www.dfs.delhigovt.nic.in.
9. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in the Form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior to its expiry.

INSPECTION REPORT

1. Name & address of the building : M/s AMPM CAFE & BAR (previously known as Decode Social Dinning). J- 2/1. BK Dutta Market. Rajouri Garden. New Delhi-27
2. Building comprised of : B.G+3 but restaurant is running at ground plus two upper floors only and third floor is used for personal use and the basement is closed by wall
3. Type of Occupancy : Group D (Assembly Building)
4. Type of Case : New
5. Details of Previous NOC : F6/DFS/MS/EH/2018/SZ/1303 Dated 05/06/2018
6. Fire Safety directives letter No : N/A
7. Date of inspection : 07/12/2022
8. Name of Inspecting Officers : ADO R.K.Yadav & DO Vedpal Chhikara
9. Name and designation of officers
From the building side : Sh. Pawan Kumar
10. Year of Construction : 2018
11. Applicant's letter No. : ID No. 2022110519803 dated 12/11/2022

S. No.	Minimum Standards on fire prevention and fire safety U/R 33	NBC Requirement	Provided at site	Remarks MR/NMR
1.	Access to building			
	<ul style="list-style-type: none"> Road width Gate width Width of internal road 	09 mtrs 4.5 mtrs N/A	Provided Directly accessible from road N/A	MR MR N/A
2.	Number, Width, Type & Arrangement of Exits			
	a. Number of staircases			
	<ul style="list-style-type: none"> Upper Floors Basements 	02 no.'s N/A	Provided N/A	MR N/A
	b. Width of staircases			
	<ul style="list-style-type: none"> Upper Floor Basements 	1.50 & 1.14 m N/A	Provided N/A	MR N/A
	c. Protection of exits			
	<ul style="list-style-type: none"> Fire check door Pressurization 	N/A N/A	N/A N/A	N/A N/A
	d. No. of continuous staircases to terrace	N/A	One	N/A
	e. Width of Corridor	N/A	Opening in hall	N/A
	f. Door Size	2.0 & 1.0 m	Provided	MR
3.	Compartmentation			
	<ul style="list-style-type: none"> Fire check door Sealing of electrical shafts Fire Rating of shaft door Water Curtain Fire Dampers 	N/A N/A N/A N/A N/A	N/A N/A N/A N/A N/A	N/A N/A N/A N/A N/A
4.	Smoke Management System			
	<ul style="list-style-type: none"> Basements Upper floors 	N/A Required	N/A Provided	N/A MR
5.	Fire Extinguishers			
	<ul style="list-style-type: none"> Total numbers Types ISI marking 	09 No.'s ABC CO ₂ ISI marked	Provided Provided ISI marked	MR MR MR

6.	First Aid Hose Reels			
	• Total numbers on ground floor	One	Provided	MR
	• Length of hose reel hose	30 mtrs	Provided	MR
	• Nozzle diameter	≤ mm	Provided	MR
	Automatic fire detection and alarming system			
	• Type of detectors	N/A	N/A	N/A
	• Location of Main Panel	N/A	N/A	N/A
	• Location of Repeater Panel	N/A	N/A	N/A
	• Alternate source of power	N/A	N/A	N/A
	• Hoisters Location	N/A	N/A	N/A
8.	MOEFA			
9.	Public Address System	Required	Provided	MR
10.	Automatic Sprinkler System	N/A	Provided	MR
	• Basement	N/A	N/A	N/A
	• Ground Floor	N/A	N/A	N/A
	• Sprinkler above false ceiling	N/A	N/A	N/A
11.	Internal Hydrants			
	• Size of riser/down-comer	100 mm	Provided	MR
	• Number of hydrants	01 No	Provided	MR
	• Hose Box	01 No	Provided	MR
12.	Yard Hydrants			
	• Total number of hydrants	N/A	N/A	N/A
	• Hose Box	N/A	N/A	N/A
13.	Pumping Arrangements			
	• Ground Level			
	➤ Discharge of main Pump	N/A	N/A	N/A
	➤ Head of Main pump	N/A	N/A	N/A
	➤ Number of main pumps	N/A	N/A	N/A
	➤ Jockey Pump out put	N/A	N/A	N/A
	➤ Jockey pump head	N/A	N/A	N/A
	➤ Standby Pump out put	N/A	N/A	N/A
	➤ Standby Pump Head	N/A	N/A	N/A
	➤ Auto Starting Manual Stopping	N/A	N/A	N/A
	➤ Pump House Access	N/A	N/A	N/A
	• Terrace level			
	➤ Discharge of pump	450 LPM	Provided	MR
	➤ Head of the pump	40 mtrs	Provided	MR
	➤ Power Supply	Required	Provided	MR
	➤ Auto Starting of pump	Required	Provided	MR
14.	Captive Water Storage for fire fighting			
	• Underground tank capacity	N/A	N/A	N/A
	➤ Draw-off connection	N/A	N/A	N/A
	➤ Fire service inlet	Required	Provided	MR
	➤ Access to tank	N/A	N/A	N/A
	• Overhead Tank capacity	20,000 ltrs	Provided	MR
15.	Exit Signage.	Required	Provided	MR


M1 Provision of Lifts.


	<ul style="list-style-type: none"> • Pressurization of Lift Shaft • Pressurization of Lift lobby • Communication In lift Car • Fireman's Grounding Switch • Lift Signage 	N/A	N/A	N/A
		N/A	N/A	N/A
		N/A	N/A	N/A
		Required	Provided	MR
		N/A	N/A	N/A
17.	Standby power supply	Required	Provided	MR
18.	Refuge Area.			
	<ul style="list-style-type: none"> ➤ Total Area ➤ Location 	N/A	N/A	N/A
		N/A	N/A	N/A
19.	Fire Control Room			
	<ul style="list-style-type: none"> • Detector System Panel • Flow Switch Panel • PA System Panel • Battery backup • Building Floor Plans 	N/A	N/A	N/A
		N/A	N/A	N/A
		N/A	N/A	N/A
		N/A	N/A	N/A
		N/A	N/A	N/A
		N/A	N/A	N/A
20.	Special Fire Protection System for Protection of special Risks, if any:	N/A	N/A	N/A

The fire protection systems provided in the building were tested, checked and found functional at the time of inspection.

Keeping in view of the above substantial compliance of the minimum standards of fire prevention and fire safety measures as required under the rules, the FSC issued vide letter No. F6/DFS/MS/EH/2018/SZ/1303 Dated 05/06/2018 renewal under the Rule 35 of the Delhi Fire Service Rules 2010 is recommended.



Note:- As per letter submitted by the Director (placed at C-26) restaurant is running at ground floor plus two upper floors and third floor is been used for personal use. Basement has been shut from outside by putting a wall and it is not been used in any manner whatsoever. The height of the building from ground floor to second floor is 09 meters.


 Signature of Inspecting Officer
 Name:- R.K. Yadav
 Designation:- ADO (JKP)


 Signature of Inspecting Officer
 Name:- Vedpal Chhikara
 Designation:- Divisional Officer


 Dy. C.F.O. (South Zone)


 ADO (JKP)

F T letter to put up for sign please

 Dy. C.F.O. (South Zone)
 M.S. ell

 13/12/2022