## GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE, NEW DELHI-110001 E6/DES/MS/2022/School/WZ/ 1262 Dated: 28/12/22

No. F6/DFS/MS/2022/School/WZ/ 1363 <u>FIRE SAFETY CERTIFICATE</u>

Certified that the New Bal Bharti Secondary School, Sector-7, M2K Road, (Opp. Manglam Place) Rohini, Delhi-110085, comprised of building Ground + 02 upper floor (School is running at  $2^{nd}$  floor only) has already been issued FSC by this department vide letter No. F.6/DFS/MS/School/2016/WZ/1760 dated 06.12.2016. The premises was re-inspected by the officer concerned of this department on 14.12.2022 in the presence of Mr. Sanjeev Dahiya (Manager) and observed that all the fire prevention & fire safety arrangement as provided in premises found in good working condition. The premises have therefore deemed complied with the requirements of Circular No.F.16/Estate/CC/Fire/2011/3298-3398 dated 01.03.2011 issued by Director of Education /NBC-Part IV and verified by the officer concerned of Fire Service and the building /premise is fit for occupancy of Group Class B (Educational) with effect from ... 25.4127/22... for a period of three years subject to compliance of the conditions mentioned below.

Issued on ... 28/1.2. ..... at New Delhi by

(Dhrampal Bhardwaj) Dy.Chief Fire Officer Tel;-01123414250

orc

MN

C-32

Copy to :-

- 1. The Manager, New Bal Bharti Secondary School, Sector-7, M2K Road, (Opp Manglam Place) Rohini, Delhi-110085.
- 2. The Director, Education, Government of N.C.T of Delhi. Old Sect. Delhi 54.

## Conditions for the validity of fire safety certificate:

- 1. All the fire safety arrangement provided there-in shall be maintained in good working conditions at all times.
- 2. Loss of life or property due to non functional fire safety measure shall be at the responsibility of the management.
- 3. The trained fire fighting staff should be available round the clock.
- 4. Any deviation with regard to the construction etc shall be verified by the concerned building sanctioning agency.
- 5. This certificate cannot be treated in any case for regularizations of unauthorized construction.
- 6. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director of Form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior to its expiry".
- 7. The owner / occupier shall submit a declaration every year in form "K" provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on
- 8. All the means of escape shall be kept free of any obstruction all the time to evacuate the occupant, in a safe manner, in the event of emergency.

## http://www.delhi.gov.in/wps/wcm/connect/doit\_fire/FIRE/Home/Fire+Safety+Acts+a

nd+Rules/ http://www.delhi.gov.in/wps/wcm/connect/doit\_fire/FIRE/Home/Forms

M-16

	1				
1	INSPECTIC	ON REPORT			
1. 1	Name & address of the building : New Bal Bha	arti Secondary Schoo	ol, Sector-7, M2K Roa	ad, (Opp.	
	Time i Co	ice), Rohini, Delhi-1	110085.		
3. 7	Type of Case : Renewal(Cro			+ 2 <sup>nd</sup> floor)	
4. I	Details of Previous NOC : F.6/DFS/MS/	/School/2016/WZ/1	oor school is running 760 dated 06.12.2016.	at 2 moor	
5. H	Fire Safety directives letter No : Director of Fo	Education Cir dated			
6. I	Date of inspection : 14.12.2022		JIII JIMO		
7. 1	Name of Inspecting Officer : A.K.Sharma	ADO(Rohini)			
ð. 1	Name and designation of officers				
	11 0.7	Dahiya (Manager)			
		l dated 03.12.2022.			
S. No.	Minimum Standards on fire prevention and	NBC	Provided at site	Remarks	
	fire safety U/R 33	Requirement		MR/NMR	
1.	Access to building				
	Road width	Accessible	Accessible	MR	
	Gate width				
	• Width of internal road	NA	NA	NA	
2.	Number, Width, Type & Arrangement of E				
	a. Number of staircases				
	• Upper Floors	02	02	MR	
	• Basements	NA	NA	NA	
	b. Width of staircases				
	• Upper Floor	1.5m	1.5m & 1.25m	MR(Old case)	
	Basements	NA	NA	NA	
	c. Protection of exits				
	Fire check door	NA	NA	NA	
	Pressurization	NA	NA	NA	
	d. No. of continuous staircases to terrace	02	02	MR	
	e. Width of Corridor	NA	NA	NA	
	f. Door Size	1.0m	1.0m	MR	
3.	Compartmentation				
	<ul> <li>Fire check door</li> </ul>	NA	NA	NA	
	<ul> <li>Sealing of electrical shafts</li> </ul>	NA	NA	NA	
	• Fire Rating of shaft door	NA	NA	NA	
	Water Curtain	NA	NA	NA	
	• Fire Dampers	NA	NA	NA	
4.	Smoke Management System		L		
	Basements	30 a/c per hour	NA	NA	
	Upper floors	12 a/c per hour	Natural ventilated	MR	
5.	Fire Extinguishers				
5.	Total numbers	08nos.	12nos.	MR	
	• Types	ABC/CO2	ABC-12	MR	
	• IS marking	ISI marked	Yes	MR	
6.	First-Aid Hose Reels				
	Total numbers on each floor	01	Provided	MR	
	<ul> <li>Length of hose reel hose</li> </ul>	30mm	Provided	MR	
	Nozzle diameter	5m	Provided	MR	
7.	Automatic fire detection and alarming system				
	Type of detectors	NA	NA	NA	
	<ul> <li>Location of Main Panel</li> </ul>	NA	NA	NA	
		1			
	<ul> <li>Location of Repeater Panel</li> <li>Alternate source of power</li> </ul>	NA	NA	NA NA	

	M/17	_		C-3
				O-L
		NA	NA	N./.
	Hooters' Location	NA	NA	NA-
•	MOEFA	NA	NA	NA
•	Public Address System			
0.	Automatic Sprinkler System	NA	NA	NA
	• Basement		NA	NA
	Ground & Upper Floors	NA	NA	NA
	Sprinkler above false ceiling	NA	A *= -	
11.	Internal Hydrants		NA	NA
	<ul> <li>Size of riser/down-comer</li> </ul>	NA	NA	NA
	• Number of hydrants per floor	NA	NA	NA
	Hose Box	NA	ING	
12.	Yard Hydrants		NTA	NA
	Total number of hydrants	NA	NA	NA
	<ul> <li>Hose Box</li> </ul>	NA	NA	147.
13.	Pumping Arrangements			ΝΙΔ
15.	Ground Level	NA	NA	NA
	<ul> <li>Oround Level</li> <li>Discharge of main Pump</li> </ul>	NA	NA	NA
	<ul> <li>Head of Main pump</li> </ul>	NA	NA	NA
	<ul> <li>Number of main pumps</li> </ul>	NA	NA	NA
	<ul> <li>Jockey Pump out put</li> </ul>	NA	NA	NA
	<ul> <li>Jockey pump head</li> </ul>	NA	NA	NA
	<ul> <li>Standby Pump out put</li> </ul>	NA	NA	NA
	<ul> <li>Standby Pump Head</li> </ul>	NA	NA	NA
	<ul> <li>Auto Starting/Manual Stopping</li> </ul>	NA	NA	NA
	<ul> <li>Pump House Access</li> </ul>	NA	NA	NA
	Terrace level			
	<ul> <li>Terrace level</li> <li>Discharge of pump</li> </ul>	2 x 4501pm	Provided	MR
	<ul> <li>Discharge of pump</li> <li>Head of the pump</li> </ul>	40m	Provided	MR
	Power Supply	Required	Provided	MR
	Auto Starting of pump	Required	Provided	MR
14.	Captive Water Storage for fire fighting			
1	Underground tank capacity	NA	NA	NA
	<ul> <li>Onderground tank capacity</li> <li>Draw-off connection</li> </ul>	NA	NA	NA
	<ul> <li>Fire service inlet</li> </ul>	NA	NA	NA
	<ul> <li>Access to tank</li> </ul>	NA	NA	NA
	<ul> <li>Overhead Tank capacity</li> </ul>	5,000ltr	Provided	MR
15.	Exit Signage.	Required	Provided	MR
15. 16.	Provision of Lifts.	Inquire		
10.		NT A	NT A	NIA
	Pressurization of Lift Shaft	NA	NA	NA
	Pressurization of Lift lobby	NA	NA	NA
	Communication In lift Car	NA	NA	NA
	• Fireman's Grounding Switch	NA	NA	NA
	Lift Signage	NA	NA	NA
17.	Standby power supply	NA	NA	NA
18.	Refuge Area.			
	> Total Area	NA	NA	NA
	> Location	NA	NA	NA
19.	Fire Control Room			
	Detector System Panel	NA	NA	NA
	Flow Switch Panel	NA	NA	NA
	PA System Panel	NA	NA	NA
	Battery backup	NA	NA	NA

-

NA	NA	NA
NA	NA	NA
	NA NA	NA NA

1/18

Accordingly, the fire protection systems provided in the building were tested/ checked randomly and found in working condition at the time of inspection.

Keeping in view the satisfactory compliance of the minimum standards on fire prevention and fire safety required as stipulated in NBC Part-4, and removal of shortcomings issued vide letter no7889 dated 27.12.2019, the FSC issued vide letter no. F.6/DFS/MS/School/2016/WZ/1760 dated 06.12.2016, renewal under rule 37 of the Delhi Fire Service Rules, 2010 is recommended.

Signature of the Inspecting Officer Ajay Kumar Sharma Name Designation ADO(Rohini)

DO (NW)

-

Alto Pohuni FT letter is put up for kind Rignateur please.

22/12/2022

pousal and

12H1422

