



FORM 'H': FORM FOR ISSUING FIRE SAFETY CERTIFICATE

[See sub-rule (1) of rule 35]

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS: DELHI FIRE SERVICE, NEW DELHI-110001

No. F6/DFS/MS/EH/2022/NDZ/366

Dated: 30/12/2022

FIRE SAFETY CERTIFICATE

Certified that the M/s Quest Sprits located at Shop No. 30, Ground Floor, DLF Galleria Mall Mayur Vihar Ph-1, Delhi-110091, building comprised of Basement Ground plus two upper Floor, but restaurant is running at Ground Floor only owned / occupied by Quest Sprits, have complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rule, 2010 and verified by the officer concerned of this department on 09/11/2022 in the presence of Sh. Shrey Ahuja (Owner) and found that the building / premises is fit for the occupancy class "Assembly" (Group-D) / **Eating House** with effect from 30.12.22... for a period of three years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules, 2010.

Issued on 30/12/22 at New Delhi.


(ATUL GARG)
DIRECTOR.

DELHI FIRE SERVICE.

Copy to :-

1. The Joint Commissioner of Police (Lic.), First Floor, Police Station Defence Colony, New Delhi-49 w.r.t. MHA Portal ID- 2022100418647 dated 12/10/2022.
2. The Manager, M/s Quest Sprits, Shop No. 30, Ground Floor, DLF Galleria Mall Mayur Vihar Ph-1, Delhi-110091

Conditions for the validity of Fire Safety Certificate:

1. All the fire safety arrangement provided their in shall be maintained in good working conditions at all times.
2. Any Loss of life or property due to non functional fire safety measure shall be at the responsibility of the management.
3. The trained fire fighting staff should be available round the clock.
4. Any deviation with regard to the construction etc shall be verified by the concerned building sanctioning agency.
5. This certificate cannot be treated in any case for regularizations of unauthorized construction.
6. "The owner / Occupier shall apply for renewal of this Fire Safety Certificate to the Director in Form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior to its expiry".
7. The owner / occupier shall submit a declaration every year in form "K" provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on WWW.dfs.Delhigovt.nic.in.

INSPECTION REPORT

1. Name & address of the building: M/s Quest Sprits, Shop No. 30, DLF Galleria Mall, Mayur Vihar Ph-1, Delhi-91.
2. Building is comprised of : Basement, Gr.+ 02 upper floors, Restaurant at Ground floor only.
3. Type of Occupancy : Restaurant (Assembly)
4. Type of Case : New
5. Details of previous NOC : N/A
6. Fire Safety directives Letter No. : NBC (Part-IV)
7. Date of inspection : 09/11/2022
8. Name of the Inspecting Officer : A.K. Jaiswal, D.O. (East)
9. Name and designation of Officer from the building side : Sh. Shrey Ahuja (Owner)
10. Year of Construction : 2008

11. Applicant's letter received through MHA portal ID-2022100418647 dated 12/10/2022

S No	Minimum standards on fire prevention and fire safety U/R 33	NBC Requirements	Provided at site	Remarks MR/NMR
1.	Access of building			
	• Road width	12 mtr	24 mtr.	MR
	• Gate width	N/A	N/A	N/A
	• Width of internal road	N/A	N/A	N/A
2.	Number, width, Type & Arrangements of exits			
	a. Number of staircases	N/A	N/A	N/A
	• Upper floors	N/A	N/A	N/A
	• Basements	N/A	N/A	N/A
	b. Width of staircases			
	• Ground floor	N/A	N/A	N/A
	• Basements	N/A	N/A	N/A
	c. Protection of exits			
	• Fire check door	N/A	N/A	N/A
	• Pressurization	N/A	N/A	N/A
	d. No of continuous staircase to terrace	N/A	N/A	N/A
	e. Width Of Corridor	N/A	N/A	N/A
	f. Door Size	1.5 mtr.	Provided	MR
3.	Compartmentation			
	• Fire check door	N/A	N/A	N/A
	• Sealing of electrical shafts	N/A	N/A	N/A
	• Fire Rating of shaft door	N/A	N/A	N/A
	• Water Curtain	N/A	N/A	N/A
	• Fire Dampers	N/A	N/A	N/A
4.	Smoke managements System			
	• Basements	N/A	N/A	N/A
	• Upper floors	N/A	N/A	N/A
5.	Fire Extinguishers			
	• Total numbers	02 nos.	02 nos.	MR
	• Types	ABC/CO ₂	ABC/CO ₂	MR
	• IS marking	ISI marked	ISI marked	MR

1112			
6.	First – Aid Hose Reels		
	• Total numbers on each floor	01	01 MR
	• Length of hose reel hose	30 Mtr.	30 Mtr. MR
	• Nozzle diameter	5 mm	5 mm MR
7.	Automatic fire detection and alarming system		
	• Type of detector	N/A	N/A N/A
	• Location of Main Panel	N/A	N/A N/A
	• Location of Repeater Panel	N/A	N/A N/A
	• Alternate source of power	N/A	N/A N/A
	• Hooters' Location	N/A	N/A N/A
8.	MOEFA	Required	Provided MR
9.	Public Address System	N/A	N/A N/A
10.	Automatic Sprinkler System		
	• Ground Floor	N/A	N/A N/A
	• Upper Floor	N/A	N/A N/A
	• Sprinkler above false ceiling	N/A	N/A N/A
11.	Internal Hydrants (Provided by Mall)		
	• Size of riser/down- comer	150 mm	Provided MR
	• Number of hydrants per floor	01 Nos.	Provided MR
	• Hose Box	01 Nos.	Provided MR
12.	Yard Hydrants		
	• Total number of hydrants	N/A	N/A N/A
	• Hose Box	N/A	N/A N/A
13.	Pumping Arrangements		
	• Ground Level	(Provided by Mall)	
	➤ Discharge of main pump	N/A	900 LPM N/A
	➤ Head of main pump	N/A	40 mtr N/A
	➤ Number of main pumps	N/A	02 nos. N/A
	➤ Jockey pump out put	N/A	180 LPM N/A
	➤ Jockey pump head	N/A	40 mtr. N/A
	➤ Standby Pump out put	N/A	900 LPM N/A
	➤ Standby Pump Head	N/A	40 mtr N/A
	➤ Auto Starting/Manual stopping	N/A	Provided N/A
	➤ Pump House Access	N/A	Provided N/A
	• Terrace level	(Provided by Mall)	
	➤ Discharge of pump	450 LPM	900 LPM MR
	➤ Head of the pump	40 m	Provided MR
	➤ Power supply	Required	Provided MR
	➤ Auto starting of pump	Required	Provided MR
14.	Captive water Storage for fire fighting (Provided by Mall)		
	• Underground tank capacity	N/A	4,50,000 Ltrs. N/A
	➤ Draw of connection	N/A	Provided N/A
	➤ Fire service inlet	N/A	Provided N/A
	➤ Access to tank	N/A	Provided N/A
	• Overhead Tank capacity	20,000 Ltrs.	Provided MR

N/3

15	Exit Signage	Required	Provided	MR
16.	Provision of Lifts			
	➤ Pressurization of Lift Shaft	N/A	N/A	N/A
	➤ Pressurization of lift lobby	N/A	N/A	N/A
	➤ Communication in lift Car	N/A	N/A	N/A
	➤ Fireman's Grounding Switch	N/A	N/A	N/A
	➤ Lift Signage	N/A	N/A	N/A
17.	Standby power supply	Required	Provided	MR
18.	Refuge Area	N/A	N/A	
	➤ Total area	N/A	N/A	N/A
	➤ Location	N/A	N/A	N/A
19.	Fire control room			
	➤ Detector system panel	N/A	N/A	N/A
	➤ Flow Switch Panel	N/A	N/A	N/A
	➤ PA System Panel	N/A	N/A	N/A
	➤ Battery backup	N/A	N/A	N/A
	➤ Building Floor Plans	N/A	N/A	N/A
20.	Special Fire Protection Systems for Protection of special Risks, if any;	N/A	N/A	N/A

The Fire Protection System provided in the building were tested, checked and found functional at the time of inspection.

Keeping in view the non compliance of the minimum standards on fire prevention and fire safety required under the rules, it is recommended to grant Fire Safety Certificate under the rule 35 of Delhi Fire Service Rules 2010.

Ashok
09/11/2022

Signature of the Inspecting Officer
Name : Ashok Kumar Jaiswal
Designation : D.O. (East Division)

By: ~~CFO (NDZ)~~

Place/Attach IIR report of DLF Galleria Mall on the file.

15/11/22

~~DO (ED)~~ IIR is attached (DLF Galleria Mall)

By: ~~CFO (NDZ)~~

15/11/22

Ashok
14/11/2022

C.F.O.

Area / No of seats are not matching as per drawing. More over drawing is also not clear as no dimension is shown. Clarify

By: ~~CFO (NDZ)~~

16/11

15/11/2022