

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELIII HEADQUARTERS: DELIII FIRE SERVICE: NEW DELIII- 110001



134

No. F6/DFS/MS/EH/2022/ 357 FIRE SAFETY CERTIFICATE

Dated: 21 / 1242022

(Dharampal Bhardiwaj) Dy. Chief Fire Officer Ph.-011-23414250

Certified that the M/s Ricos (A Unit of Jumbo Restaurants Pvt. Ltd.) located at Premises No. UA-24, Upper Ground Floor, Jawahar Nagar, Malka Ganj Chowk, Kamla Nagar, Delhi-110007 in the building comprised of basement, stilt, upper ground & two upper floors only owned/occupied by M/s Ricos (A Unit of Jumbo Restaurants Pvt. Ltd.) was issued Fire Safety Certificate by this department vide letter no. F6/DFS/MS/2019/2345 dated 19.12.2019. The premises was re-inspected by the officers concerned of this department on 07.12.2022 in the prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules. 2010 and building/ premise is fit for occupancy Class- "D Assembly" (Restaurant) for upper ground floor only occupancy with effect from. Al. Assembly" (Restaurant) for upper in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules, 2010.

Issued on 2.1. /.1.2. /.2.2..... at New Delhi by

Copy to:-

1. The Manager, M/s Ricos (A Unit of Jumbo Restaurants Pvt. Ltd.) located at Premises No. UA-24, Upper Ground Floor, Jawahar Nagar, Malka Ganj Chowk, Kamla Nagar, Delhi-110007.

Conditions for the validity of Fire Safety Certificate:

- 1. This Fire Safety Certificate is valid for restaurant at upper ground floor for assembly occupancy only. In case of any violation, this FSC will be treated as null & void.
- 2. All the fire safety arrangement provided there-in shall be maintained in good working conditions at all times.
- 3. Loss of life or property due to non functional fire safety measure shall be at the responsibility of the management.
- 4. Any deviation with regard to the construction etc shall be verified by the concerned building sanctioning agency.
- 5. This certificate cannot be treated in any case for regularizations of unauthorized construction.
- 6. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director of Form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior to its expiry".
- 7. The owner / occupier shall submit a declaration every year in form "K" provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on <u>WWW.dfs.Delhigovt.nic.in</u>
- 8. All the means of escape shall be kept free of any obstruction all the time to evacuate the occupant, in a safe manner, in the event of emergency.

1100

NB

4

20								
~		INSPEC	TION REPORT					
1.	Name & address of the building : M/s Ricos (A Unit of Jumbo Restaurants Pvt. Ltd.) at Premises no. U/							
				owk, Kamla Nagar, Delhi				
,	2. Type of Occupancy : Restaurant (Assembly)							
3.	Composition of building	: Basement.	stilt, ground & 2 uppo	er floors, but restaurant	running at ground			
5.	e competition e recentrary	floor only,	basement, stilt- vacant a	and first floor & second floo	or other property			
4.								
5.	Type of Case Details of previous NOC	: F6/DFS/MS	5/2019/2345 dated: 1	9 12.2019				
6.	Fire Safety directives letter No	: Nil						
7.	Date of inspection	: 07.12.2022						
8.	Name of the Inspecting Officers	: ADO (RN)						
9	Name and designation of officers							
	from the building side	Sh. Harsh ((Manager)					
10). Year of Construction	: 2018						
1	1. Applicant's letter No.	: Online MH.		112120485 dated 23.11.2	2022			
	Minimum Standards on fire prev	ention and	UBBL/ NBC Part-	IV Provided at site	Remarks MR/NMR			
	fire safety U/R 33		Requirement					
1	Access to building	Constanting of						
	Road width		6m	06m	MR			
	Gate width		5m	Directly Accessible	MR			
	• Width of internal road		NΛ	NA	NA			
2	Number, Width, Type & Arrange	ment of Exits						
-	a. Number of staircases							
	Upper Floors		02	02	MR			
	Basements		NA	NA	NA			
	b. Width of staircases							
	Upper Floors		02m & 1.35m	03m &1.40m	MR			
	Basements		NΛ	NA	NA			
	c. Protection of exits							
	Fire check door		NA	NA	NA			
	Pressurization		NA	NA	NA NA			
	d. No. of continuous staircases to te	пасе	ΝΛ	NA NA	NA			
	e. Width of Corridor f. Door Size		NA 02m & 1 35m	02m & 1.50m	MR			
	and the second		02m & 1.35m	02111 & 1.3011				
3	Compartmentation.		ΝΛ	NA	NA			
	Fire check door		ΝΛ	NA	NA			
	 Sealing of electrical shafts Fire Rating of shaft door 		NA	NA	NA			
	Water Curtain							
	Fire Dampers		NA	NA	ΝΛ			
			ΝΛ	NA	NA			
4	Smoke Management System.		12 a/c per hour	ΝΛ	NA			
	Basements		12 a/c per hour	Natural Ventilated	MR			
	Upper floors		12 a/c per nour	Natural ventilated	WIK			
5	Fire Extinguishers		06nos	10nos	MR			
	Total numbers		ABC & Co2	ABC-10	MR			
	• Types							
	ISI marking		Yes	Yes	MR			

T	First-Aid Hose Reels.	01	Provided	MR
T	Total numbers on each floor	30m	30m	MR
	Length of hose reel hose	5mm	5mm	MR
	Nozzle diameter			
	Automatic fire detection and alarming system.	NA	Provided	NA NA
1	Type of detectors	NA	GF	
	Location of Main Panel	NA	GF	NA
	Location of Repeater Panel	NA	Provided	NA
	Alternate source of power	NA	GF	INA
	Hooters' Location	Required	Provided	MR
8	MOEFA	Required	Provided	MR
9	Public Address System.	Requires		Charles State
10	Automatic Sprinkler System.	NA	NA	NA
	Basement	Required	Provided	MR
	Upper Floor (ground floor)	-	Provided	MR
	 Sprinkler above false ceiling 	Required		
11	Internal Hydrants	Durning 1	Provided	MR
	 Size of riser/down-comer 	Required 01	01	MR
	 Number of hydrants per floor 	01	01	MR
	Hose Box	01		
12	Yard Hydrants.	NA	NA	NA
	Total number of hydrants		NA	NA
	Hose Box	NA		
13	Pumping Arrangements.			
13	Ground Level		NA	N/A
	 Ground Level Discharge of main Pump 	N/A		NA
	 Head of Main pump 	N/A	NA NA	NA
	 Number of main pumps 	NA	NA	NA
	 Jockey Pump out put 	NA	N/A	N/A
	 Jockey pump head 	N/A	N/A	NA
	 Standby Pump out put 	N/A		N/A
	Standby Pump Head	N/A	N/A	
	> Auto Starting/ Manual stopping	N/A	N/A	N/A
	Terrace level	450 LPM	450 LPM	MR
	> Discharge of pump			MR
	> Head of the pump	40m	40m	MR
	> Power Supply	Required	Provided Provided	MR
	 Auto Starting of pump 	Required	Provided	1
14	Captive Water Storage for fire fighting.			NA
14	tonk capacity	NA	NA	
	- Compation	NΛ	NA	NA
	 Fire service inlet 	NA	NA	NA
	a second	NA	ΝΛ	NA
		20,000 LTR	20,000 LTR	MR
	Overhead Tank capacity	20.000 LTR Required	Provided	MR
1		Kequirea		
1	6 Provision of Lifts.	N/A	N/A	NA
	Pressurization of Lift Shaft	94		

-	 Pressurization of Lift lobby 	ΝA	NA	N/A	
	Communication In lift Car	NΛ	NA	NA	
	 Fireman's Grounding Switch 	NA	NA	NA NA	
	Lift Signage	NA	NA	NA	
17	Standby power supply	Required	Provided	MR	
18	Refuge Area.				
	 Total Area Location 	ΝΛ	N/A	N/A	
		N/A	NA	NA	
19	Fire Control Room				
	Detector System Panel	N/A	N/A	N/A	
	 Flow Switch Panel PA System Panel Batter backup Building Floor Plans 	N/A	N/A	N/A	
		NA	NA	N/A	
		N/A	N/A	N/A	
		N/A	N/A	N/A	
20	Special Fire Protection Systems for Protection of special Risks, if any:	NA	NA	NA	

Note:-

(a) The total covered area of the Restaurant is 110sqm (Approx) including seating area, kitchen area, toilet area, & store area.

(b) As per the NBC Part IV, the number of occupants comes out to be approx 61 person's i.e. (110/1.8=61)

The fire protection systems provided in the building were tested/ checked and found some in working order at the time of inspection.

Keeping in view of the substantial compliance of the minimum standards on fire prevention and fire safety required under the rules. It is recommended to renew FSC vide this department letter of even no.2345 dated 19.12.2019 Certificate under rule 37(3) of Delhi Fire Service Rules 2010

Signature of the Inspecting Officer DOD Name - C.L. Meena Designation - ADO RN 3/12/2 As approved, F.T. letter is But up for your singusture PL. N 0 (W2)