DEA

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE, NEW DELHI – 110001

No. F6/DFS/MS/GH/NDZ/2022/ 03

Dated: 0 3/ 01 /2023

FIRE SAFETY CERTIFICATE

Certified that the M/s Bukhara Inn Guest House situated at 1066-67, Paiwalan, Dariba, Jama Masjid, Delhi - 06, comprised of Ground + 04 upper floors, ground floor- (commercial). 1st floor - (03 guest rooms + reception), 2nd floor - (04 guest rooms) & 3rd floor - (04 guest rooms), total 11 guest rooms was granted FSC by this department vide letter no. F6/DFS/MS/GH/NDZ/2019/2216 dated 26:11.2019. Now, the building/ premises was re-inspected by the officer concerned of this department on dated 21.12.2022 in presence of Mr. Abuhasnain (Manager) and found that the building is comprised of ground + 04 upper floors and now the floor wise occupancy is ground floor- (commercial), 1st floor (03 guest rooms + reception), 2nd floor-(04 guest rooms), 3rd floor- (04 guest rooms) & 4th floor - not in use as per affidavit dated 23.12.2022. The building has deemed complied with the fire prevention and fire safety requirements in accordance with Rule 33 of Delhi Fire Service Rules, 2010. Accordingly, the premises is fit for occupancy of "Residential (Sub Division-A-1), 1st floor (03 guest rooms), 2nd floor - (04 guest rooms) & 3rd floor - (04 guest rooms), total 11 guest rooms up to third floor only, with effect under Rule 37 or sooner cancelled under Rule 40 and subject to conditions under Rule 38 of Delhi Fire Service Rules, 2010 printed below.

Issued on ...03/11/1202-3.....at New Delhi by

(S. K. Dua) of Fire Officer

Dy. Chief Fire Officer
Delhi Fire Service
Tel: 011-23412222

Copy to:-

- 1. The Commissioner, MCD:- to kindly ensure the occupancy as detailed above & deviation, if any.
- 2. The Joint Commissioner of Police (Licensing), 1st Floor, Police Station Defence Colony, New Delhi. w.r.to ID No. 2022112920794 dated 08.12.2022.
- 3. The Licensee, M/S Bukhara Inn Guest House at 1066-67, Paiwalan, Dariba, Jama Masjid, Delhi. Conditions for the validity of Fire Safety Certificate
- 1. All the fire safety arrangements provided therein shall be maintained in good working condition at all times.
- 2. Any loss of life or property due to non functional fire safety measures shall be at the responsibility of the management.
- 3. The trained fire fighting staff should be available round the clock.
- 4. Any deviation w.r.t. construction etc. shall be verified by the concerned building sanctioning authority.
- 5. This fire safety certificate may not be treated in any case for regularization of unauthorized construction, if any.
- 6. The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in.
- 7. The means of escape shall be kept unobstructed / unlocked for unhindered evacuation in case of an emergency.
- 8. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in form 'J' [sub Rule (I) of Rule 37] along with a copy of this Certificate, six month prior to its expiry. Any change in the occupancy shall be intimated to this Deptt. and approval shall be obtained thereto before occupancy of the same.
- 9. The occupancy of 4th floor not allowed as per clause 7.31 in UBBL-2016.

-N/12 -

INSPECTION REPORT

		INSPI	ECHON KINON	Const House	at 1066-67,				
1	N	ame & address of the building	M/s Bukhara In	I Guest Masiid, E	elhi – 06.				
			Daiwolan Dariba, Jama Wasjie,						
2	В	uilding is comprised of							
			Ground + 04 upper Hoose) Ground floor - commercial (mercantile) 1st floor - (03 guest rooms + reception)						
			1st floor (03 gues	t rooms + recepti	1011)				
	1		2 nd floor (04 guest rooms)						
			3 rd floor (04 guest rooms) 4 th floor-(not in use as per affidavit						
	1.		23 12 2022)						
	1		Residential, Sub Division-A-1						
3		ype of occupancy	Danawal (old case)						
4		ype of case	F6/DFS/MS/GH/NDZ/2019/2216 dated						
5	D	etails of previous FSC							
			26.11.2019						
6	Fi	re safety direction letter no.	Nil						
7		ate of inspection	21.12.2022						
8		ame of the inspecting officers	Sumit Kumar ADO (SPM)						
9	N:	ame of the designation of office	Mr. Abuhasnain (Manager)						
		om the building side							
10		ear of construction	1987	202	2112020704				
11		pplicant's letter no.	Online application	LD. No. 202	2112920794				
11	A	ppheant's letter no.	dated on 08.12.2022						
	1		Requirement/	Provided at	Remarks				
S.N	M	inimum Standards on fire revention and fire safety	Existing fire	Site	MR/				
0	PI	quirements U/R 33	safety		NMR				
	1 C	quirements of tess	arrangements						
1	A	ccess To Building:			1 200				
		oad width	Accessibility	06 mtrs.	MR				
		ate width	NΛ	NΛ	NA NA				
	W	idth of internal road	NΛ	NA	INA				
2	Ni	imber, Width, Type and Arran	igement of Exits:		1				
	A	Number of staircases		02 nos.	MR				
	1	a Upper floor	01 nos.	NA	NA				
		b Basement	NA	NA	177				
	B	Width of staircases	0.00	1	MR				
		a Upper floor	0.80 mtr.	1 mtr., 1 mtr. (upto 1 st floor)	MR				
			\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\	NA	NA				
		b Basement	NΛ	11/1	14/4				
	C	Protection of exits	NA	NΛ	NA				
		a Fire check door	NA NA	NA	NΛ				
	-	b Pressurization No. of continuous staircases	01 nos.	01 nos.	MR				
	D	to terrace	01 1103.	01 1103.	WIK				
	E	Width of corridor	NA	NA	NΛ				
-	F	Door size	01 mtrs.	01 mtrs.	MR				
3	-	mpartmentation:	or mus.	or mus.	MIK				
3	1	Fire check door	NA I	NA	I NA				
	A	Sealing of electrical shafts	NA .	NA NA	NA				
-	B				NΛ				
147	C	Fire rating of shaft door	NΛ	NΛ	NA				
	D	Water curtain	NΛ	NA	NA				
	E	Fire dampers	NΛ	NA	NA				
1	:	oke Management System:	1						
1	A	Basement	NA .	N/A	N/A				
	B	Upper floor	12 ACPH	Natural/	MR				
	1		0	Ventilated					
			84						

	A	Fire Extinguisher: A Total numbers		08 nos.		08 nos.	MR
	B	Types		CO, & ABC	CC	O. & ABC	MR
	C	ISI marking		Required	Pr	ovided	MR
,	Firs	t-Aid-Hose Reels:			1		
	A	Total numbers of each floor		1 nos.	01	nos.	MR
1	В	Length of hose reel hos	e	30 mtrs.	30	mtrs.	MR
1	C	Nozzle diameter		05 mm	05	mm	MR
1	Auto	matic Fire Detection A	nd A	larming Syste	m:		
1	Λ	Type of detectors CO ty		Required		vided	MR
	В	Location of main panel		Required		vided at	MR
	1				rec	eption	
1	C	Location of repeater par	nel	NΛ	NA		NA
I)	Alternate source of pow		Required		vided	MR
F	-	Hooters		Required		vided	MR
	4OE			NΛ		vided	NΛ
P	ublic	Address System:		NΛ	NΛ		NΛ
Λ	uton	natic Sprinkler System:					
Λ	11	Basement		NA .	NΛ		NΛ
В		Jpper floor		NΛ	NΛ		NA .
C		Sprinkler above false		NA	NΛ		NΛ
-		eiling					
n		al Hydrants:					
٨		ize of riser/down-comer	.	NΛ	NΛ		NΛ
3		lumber of hydrants per		NA	NΛ		NΛ
,		oor		Kland File			
7	-	ose box	N	١٨	NΛ		NΛ
		ydrants:	- 1				
		otal number of hydrants	IN	IA	NA		NA
		ose box		Λ	NA		NA
			1.		1		
u		g Arrangements:					
		ound level	L	^	NA	1	NA
	-	ischarge of main pump	N.		1		NA
)		ead of main pump	N.		NA		
		umber of main pumps	N/		NΛ		NΛ
)	Jo	ckey pump out put	N/		NΛ		NΛ
		ckey pump head	N/		NΛ		NΛ
		andby pump out put	N/		NΛ	Cally Seed Seed	NΛ
	St	andby pump head	N/	Manual International Control of the	NΛ		NA
	A	uto starting /manual opping	NA		NΛ		NΛ
		mp house access	INA		NΛ]]	NA
3 Terrace level					il and		
		scharge of pump		LPM	450 LP		MR
	The state of the last	ead of the pump		mtrs.	35 mtrs		MR
)	1	wer supply	0 1 6 m 3 E	luired	Provided		MR
)	A	nto starting of pump	Rec	uired	Provide	d N	1R

- 4/14 -

4 Ca	ptive Water Storage For Fire Fi	ighting:					
A	Underground tank capacity	INA	NA .	NΛ			
B	Draw-off connection	NA	NA	NA			
C	Fire service inlet	NA	NΛ	NA			
D	Access to tank	Required	Provided	MR			
E	Overhead tank capacity	5,000 ltrs.	5,000 ltrs.	MR			
5 E	sit Signage:	Required	Provided	MR			
6 P1	rovision of Lifts:						
A	Pressurization of lift shaft	NA	NΛ	NA			
В	Pressurization of lift lobby	NA	NA	NΛ			
C		NA	NΛ	NΛ			
D		NA	NA	NA			
E		NA	NA	NΛ			
-	tandby Power Supply:	Required	Provided	MR			
	Refuge Area:						
A		NA.	NA	NΛ			
F		NA	NΛ	NA.			
-	Fire Control Room:						
1	Detector system panel	NΛ	NΛ	NΛ			
	3 Flow switch panel	NA	NΛ	NA			
	C Pa system panel	NA	NΛ	NA			
1000	D Battery backup	NA	NΛ	NA			
	E Building floor plans	NΛ	NΛ	NA NA			
20	Special Fire Protection Systems I Special Risks, If Any:	For Protection of	NA	INA			

The fire protection systems provided in the building were tested, checked at random and found functional at the time of inspection.

In view of the deemed compliance of minimum standards of fire prevention and fire safety measures as required under the Rules, the FSC issued vide letter no. F6/DFS/MS/GH/NDZ/2019/2216 dated 26.11.2019 is recommended to be renewed under Rule 35 of the Delhi Fire Service Rules 2010.

Signature of the Inspecting Officer Name Sumit Kumar

Designation

ADO (SPM)

DO (CD)
27/12/22

F.T. please

Dico (2005)

28/12

ADO (APM)

F.T. letter is Put up for Signature, Please

Dy. (Po. (NDI)

Kir oyellas

uploaded white