







No. F6/DFS/MS/School/2023/ 20

Dated: \\ /@ | / 2023

FIRE SAFETY CERTIFICATE

Certified that the Govt. Sarvodaya Vidyalaya located at Lancer's Road Near University Metro Station, Delhi-110054 comprised of 01 New block, Ground & first floor only owned/occupied by North Govt. Sarvodaya Vidyalaya have complied with the fire prevention and safety requirements in accordance with requirements of circular issued by Director of Education letter no. 3298-3398 dated 01.03.2011 and verified by the officer concerned of Fire Service on 26.12.2022 in the presence of Mrs. Sapna Rani and that the building/premises is fit for years, subject to compliance of the conditions mentioned below:

Issued on at New Delhi

Ph:-011-23414000

Copy to: -

1. The Director, Education, Government of N.C.T of Delhi. Old Sectt. Delhi – 110054.

2. The Principal, Govt. Sarvodaya Vidyalaya located at Lancer's Road Near University Metro Station, Delhi-110054

Conditions for the validity of Fire Safety Certificate:

1. All the means of escape/entry/exit shall be kept free from any obstruction.

2. All the fire safety arrangements provided therein shall be maintained in good working condition at all time as seen during inspection.

3. Any loss of life or property due to non-functional fire safety measures shall be at the responsibility of the management.

4. All the staff members must know the correct method of operation of firefighting system.

5. The owner / occupier shall submit a declaration every year in Form "K" provided in the first Fire Service Rules 2010. The form is schedule Delhi http://delhi.gov.in./wps/wcm/connect/doit fire/FIRE/Home/Forms.

6. This fire safety certificate may not in any way be treated as regularization (Clause 2.8 of UBBL-

2016) of unauthorized construction or Alteration (Clause 1.4.3 of UBBL-2016), if any.

7. "The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in Form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior to its expiry".

INSPECTION REPORT

Name & address of the building

Govt Sarvodaya Vidyalaya located at Lancer's Road Near University Metro Station, Delhi-110054

2 Type of Occupancy

: Educational

Type of Case 3

: New Case

Composition of building 4.

: 01 New block, Ground & first floor only

5. Details of previous NOC

: Nil

6. Fire Safety directives letter No

: Nil

7. Date of inspection

: 30.12.2022

8. Name of the Inspecting Officers

: ADO (RN)

Name and designation of officers from the building side

: Mrs. Sapna Rani

10. Year of Construction

: 2013

11. Applicant's letter No.

: Online E-mail Dated: 21.12.2021

0.	Minimum Standards on fire prevention and fire safety U/R 33	Director of Education Circular Dated 01.03.2011 Requirements	Provided at site	Remarks MR/NMR			
	Access to building						
	Road width	06m	09m	MR			
	Gate width Width of internal road	4.5m	06m	MR			
2		NA	NA	NA			
	Number, Width, Type & Arrangement of Exits						
	a Number of staircases						
	Upper Floors	01	01	MR			
	Basements Width of staircases	NA	NA	NA			
	Upper Floors						
	Basements	1.50m	1.50m NA	MR			
	c. Protection of exits		N/A	NA			
	Fire check door	NA I	NA	NA			
	Pressurization	NA	NA	NA NA			
	d. No. of continuous staircases to terrace	NA	NA	NA			
	e. Width of Corridor	NA	NA	NA			
	f. Door Size	01m	01m	MR			
3	Compartmentation.						
	Fire check door	NA	NA	NA			
	Scaling of electrical shafts	NA	NA	NA			
	Fire Rating of shaft door	NA	NA	NA			
	Water Curtain	NA	NA	NA			
	Fire Dampers	NA NA	NA	NA			
4	Smoke Management System.						
	Basements	12 a/c per hour	NA	NA			
	Upper floors	12 a c per hour	Natural Ventilated	MR			
5	Fire Extinguishers						
	Total numbers	04nos	04nos	MR			
	• Types	ABC/Co2	ABC-04	MR			
	ISI marking	ISI Marked	Provided	MR			
6	First-Aid Hose Reels.						

1

				-			
	Total numbers on each floor	NA	NA	NA			
	Length of hose reel hose	NA	NA	NA			
	Nozzle diameter	NA NA	NA	NA			
	Automatic fire detection and alarming system.						
	Type of detectors	NA	NA	NA			
	Location of Main Panel	NA	NA	NA			
	Location of Repeater Panel	NA	NA	NA			
	Alternate source of power	NA	NA	NA			
	Hooters' Location	NA	NA	NA			
	MOEFA	NA	NA	NA			
	Public Address System.						
0	Automatic Sprinkler System.						
	Basement	NA	NA	NA			
	Upper Floor	NA	NA	NA			
	Sprinkler above false ceiling	NA	NA	NA			
11	Internal Hydrants						
	Size of riser/down-comer	NA	NA	NA			
	Number of hydrants per floor Hose Box	NA	NA	NA			
		NA	NA	NA			
12	Yard Hydrants.						
	Total number of hydrants	NA	NA	NA			
	Hose Box	NA	NA	NA			
13	Pumping Arrangements.			-			
	Ground Level						
	> Discharge of main Pump	N/A	NA	N/A			
	> Head of Main pump	N/A	N/A	N/A			
	Number of main pumps						
	> Jockey Pump out put	N/A	N/A	N/A			
	> Jockey pump head	NA	NA	NA			
	Standby Pump out put	NA	NA	NA			
	 Standby Pump Head Auto Starting/ Manual stopping 	N/A	N/A	N/A			
	> Pump House Access	N/A	N/A	N/A			
	Terrace level	N/A	N/A	N/A			
	> Discharge of pump						
	> Head of the pump	NA	NA	NA NA			
	> Power Supply	NA	NA	NA			
	> Auto Starting of pump	NA	NA	NA			
		NA	NA NA	NA NA			
14	Captive Water Storage for fire fighting.	1		-			
1	Underground tank capacity	NA	NA NA	NA			
1	> Draw-off connection	NA	NA	NA			
	> Fire service inlet	NA	NA	NA			
	> Access to tank	NA	NA	NA			
	Overhead Tank capacity	NA	NA	NA			
15	Exit Signage.	NA NA	- NA	NA.			
13	Exit orginage.	, wa					

6	Provision of Lifts.						
	Pressurization of Lift Shaft	N/A	N/A	N/A			
	Pressurization of Lift lobby	N/A	N/A	N/A			
	Communication In lift Car	N/A	N/A	N/A			
	 Fireman's Grounding Switch Lift Signage 	N/A	N/A	N/A			
		N/A	N/A	N/A			
7	Standby power supply	N/A	N/A	N/A			
18	Refuge Area.						
	Total Area	N/A	N/A				
	Location	N/A	N/A	N/A			
19	Fire Control Room						
	Detector System Panel	N/A	N/A	N/A			
	Flow Switch Panel	N/A	N/A	N/A			
	PA System Panel	N/A	N/A	N/A			
	Batter backup	N/A	N/A	N/A			
	Building Floor Plans	N/A	N/A	N/A			
20	Special Fire Protection Systems for Protection of special Risks, if any:	N/A	N/Λ	N/A			

The fire protection systems provided in the building were tested/ checked randomly and found in working condition, at the time of inspection. The management has complied all the shortcomings issued and communicated by this department vide letter of even no. 2436 dated 24.11.2015.

Keeping in view the satisfactory compliance of the minimum standard on fire prevention and fire safety requirements as stipulated under the circular issued by Director of Education dated 01.03.2011, it is recommended to grant Fire Safety Certificate

DOWW

(W2)

Juli verz

Director / 1/2

Apo (LA)

As approved, F.T. letter is butup for your singueture U. ____ Coup

Signature of the Inspecting Officer

Name :- C.L. Meena Designation - ADO/RN