



GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI- 110001



No. F6/DFS/MS/EH/NDZ/2023/ 14

Dated: 13/01/2023

FIRE SAFETY CERTIFICATE

Certified that the M/s Asia 21 Restaurant located at F-21, Main Road Vikas Marg, Preet Vihar, Delhi-110092, building comprises of Ground + 03 Upper Floors but Restaurant is running at 1st Floor only owned/occupied by M/s Asia 21 Restaurant, was earlier issued Fire Safety Certificate by this department vide letter No. F6/DFS/MS/EH/2019/NDZ/1875 Dated 30/09/2019. The premises was re-inspected by the officer concerned of this department on 26/12/2022 in the presence of Dr. K.K. Juneja and observed that all the Fire prevention and Fire Safety arrangements provided in the premises found in good working condition. The premises have therefore, deemed complied Rule 33 of the Delhi Fire Service Rules, 2010 and that the premises fit for occupancy class "Assembly Building" Eating House (Group D) with effect from 13/01/2023 for period of three years in accordance with Rule 36 unless renewed under Rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under Rule 38 of the Delhi Fire Service Rules, 2010 printed below.

Issued on 13/01/2023 at New Delhi by.


(S.K. DUA)

**DY. CHIEF FIRE OFFICER
DELHI FIRE SERVICE.**

Copy to: -

1. The Manager, M/s Asia 21 Restaurant, F-21, Main Road Vikas Marg, Preet Vihar, Delhi- 110092.
2. The Deputy Commissioner (Licensing), 1st Floor, Police Station Defence Colony, New Delhi-110024.

Online Application ID no. 2022093018454.

Conditions for the validity of Fire Safety Certificate:

1. All the fire safety arrangement provided there in shall be maintained in good working conditions at all times.
2. Loss of life or property due to non-functional fire safety measure shall be at the responsibility of the Management.
3. The trained fire fighting staff should be available round the clock.
4. Any deviation with regard to the construction etc shall be verified by the concerned building sanctioning agency.
5. This certificate cannot be treated in any case for regularizations of unauthorized construction.
6. The means of escape shall be kept unobstructed / unlocked for unhindered evacuation in case of an emergency.
7. "The owner / Occupier shall apply for renewal of this Fire Safety Certificate to the Director in Form 'J' [subrule (1) of rule 37] along with a copy of this Certificate, six months prior to its expiry".
8. The owner / occupier shall submit a declaration every year in form "K" provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in.
9. Any flammable material for interior decoration is prohibited.

INSPECTION REPORT

1. Name & address of the building: M/s Asia 21 Restaurant running at 1st floor at F-21, Main Road Vikas Marg, Preet Vihar, Delhi-110092
2. Building is comprised of : Ground plus Three upper floors (Restaurant is running on 1st floor only.)
3. Type of Occupancy : Assembly (Restaurant)
4. Type of Case : Renewal
5. Details of previous NOC : F6/DFS/MS/EH/2019/NDZ/1875 Dt. 30/09/2019
6. Fire Safety directives Letter No.: N/A
7. Date of inspection : 26/12/2022
8. Name of the Inspecting Officer : D.O. (E.D.)
9. Name and designation of Officer from the building side : Sh. K.K. Juneja
10. Year of Construction : 1996
11. Applicant's E-Mail dated. : 16/12/2022

S.No.	Minimum Standards on fire prevention and fire safety U/R 33	Requirement	Provided at Site	Remarks
1	Access to building			
	• Road width	9.0 m	24 m	MR
	• Gate width	N/A	N/A	N/A
	• Width of internal road	N/A	N/A	N/A
2	Number, Width, Type and Arrangement of Exits			
	a. Number of Staircases			
	• Upper Floor	02 Nos.	02 Nos.	MR
	• Basement	N/A	N/A	N/A
	b. Width of Staircases			
	• Upper Floor	1.50 & 2.00 m	2.0 m (G to 1st Floor), 1.5 m & 0.90 m (G to Terrace) & 0.90 m (1st to Terrace)	MR
	• Basement	N/A	N/A	N/A
	c. Protection of exits			
	• Fire check door	N/A	N/A	N/A
	• Pressurization	N/A	N/A	N/A
	d. No. of continuous staircases to terrace	01 Nos.	03 Nos.	MR
	e. Width of Corridor	2.0 m	2.0 m	MR
	f. Door size	2.0 m & 1.5 m	2.0 m x 2 & 0.70 m x 2	MR
3	Compartmentation			
	• Fire check Door	N/A	N/A	N/A
	• Sealing of electrical Shafts	N/A	N/A	N/A
	• Fire rating of Shaft Door	N/A	N/A	N/A
	• Water Curtain	N/A	N/A	N/A
	• Fire Dampers	N/A	N/A	N/A
4	Smoke Management System			
	• Basement	N/A	N/A	N/A
	• Upper Floor	12 a/c per hour	Natural	MR
5	Fire Extinguishers			
	• Total Numbers	06 Nos.	08 Nos.	MR
	• Types	ABC & Co2	ABC & Co2	MR
	• IS Marking	ISI Marked	ISI Marked	MR

DR

N/20

6	First-aid-Hose Reels			
	Total numbers of each floor	01 Nos.	02 Nos.	MR
	• Length of hose reel hose	30 M	30 M	MR
	• Nozzle diameter	05 mm	05 mm	MR
7	Automatic fire detection and alarming system			
	• Type of detectors	N/A	Provided	N/A
	• Location of main panel	N/A	Provided	N/A
	• Location of repeater panel	N/A	Provided	N/A
	• Alternate source of power	N/A	Provided	N/A
	• Hooter's Location	N/A	Provided	N/A
8	MOEFA	Required	Provided	MR
9	Public address System	N/A	N/A	N/A
10	Automatic Sprinkler System			
	• Basement	N/A	N/A	N/A
	• Upper Floor	N/A	N/A	N/A
	• Sprinkler above false Ceiling	N/A	N/A	N/A
11	Internal Hydrants			
	• Size of rise/down-comer	100 mm	100 mm	MR
	• Number of Hydrants per Floor	01 nos.	01 nos.	MR
	• Hose Box	01 nos.	01 nos.	MR
12	Yard Hydrants			
	• Total number of Hydrants	N/A	N/A	N/A
	• Hose Box	N/A	N/A	N/A
13				
	• Ground Level			
	➤ Discharge of main Pump	N/A	N/A	N/A
	➤ Head of Main Pump	N/A	N/A	N/A
	➤ Number of main Pumps	N/A	N/A	N/A
	➤ Jockey pump output	N/A	N/A	N/A
	➤ Jockey pump head	N/A	N/A	N/A
	➤ Standby pump output	N/A	N/A	N/A
	➤ Standby pump head	N/A	N/A	N/A
	➤ Auto starting/Manual stopping	N/A	N/A	N/A
	➤ Pump house access	N/A	N/A	N/A
	• Terrace Level			
	➤ Discharge of pump	450 LPM	450 LPM	MR
	➤ head of the pump	40 MH	40 MH	MR
	➤ Power supply	Required	Provided	MR
	➤ Auto Starting of pump	Required	Provided	MR
	Captive Water Storage for Fire Fighting			
	• Underground tank capacity	N/A	N/A	N/A
	➤ Draw-off connection	N/A	N/A	N/A
	➤ Fire service inlet	N/A	N/A	N/A
	➤ Access to tank	Required	Provided	MR
	• overhead Tank capacity	20,000 Ltrs.	Provided	MR
	Exit Signage	Required	Provided	MR


1/2

16	Provision of Lifts			
	• Pressurization of Lift Shaft	N/A	N/A	N/A
	• Pressurization of Lift lobby	N/A	N/A	N/A
	• Communication in lift car	N/A	N/A	N/A
	• Firemen's grounding switch	N/A	N/A	N/A
	• Lift Signage	N/A	N/A	N/A
17	Standby power supply	Required	Provided	MR
18	Refuge Area			
	• Total area	N/A	N/A	N/A
	• Location	N/A	N/A	N/A
19	Fire Control Room			
	• Detector system panel	N/A	N/A	N/A
	• Flow switch panel	N/A	N/A	N/A
	• PA system panel	N/A	N/A	N/A
	• Battery backup	N/A	N/A	N/A
	• Building floor plans	N/A	N/A	N/A
20	Special Fire Protection systems for protection of special Risks, if any:	N/A	N/A	N/A

Note:-Shortcomings issued by letter No. F6/DFS/MS/EH/NDZ/2022/654 Dated 09/11/2022 have been complied.

The fire protection systems provided in the building were tested, checked and found functional at the time of inspection.

In view of the deemed compliance of the minimum standards of fire prevention and fire safety measures as required under the rules the FSC issued vide letter No. F6/DFS/MS/EH/2019/NDZ/1875 Dt. 30/09/2019, renewal under Rule 35 of the Delhi Fire Service Rules 2010, is recommended.


 Signature of the Inspecting Officer
 Name : Ashok Kumar Jaiswal
 Designation : D.O. (East. Div.).

DY. CFO / (NDZ)

f.T. please-

Ring
05/01/23


DO (E) Sir,

F.T. is added for sign. please.

DY. CFO / (NDZ)

Ring
13/01/23

F.P. wing


 13/01/2023